



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014654/K1tb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 13-08-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 6659L	Veh. Inspected	SH 7441Y
Policy No.	5088380782-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/08/2018	Inspection Date	13/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No. (For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5088380782-01		ABDUL AZIZ BIN JONID	S1052790B	GPC	drive CLASSIC	SKM6659L	SKM6659L	27/03/2018	26/03/2019

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1007447-001	COMFORT TRANSPORTATION PTE LTD	SH 7642J	SGW 6777Z
2	MT/1006907-002	COMFORT TRANSPORTATION PTE LTD	SHC 8126H	SJP 2296Y
3	MT/1007096-002	CITYCAB PTE LTD	SHB 3420X	SHC 6930R
4	MT/1007261-002	COMFORT TRANSPORTATION PTE LTD	SH 7441Y	SKM 6659L
5	MT/1006877-002	COMFORT TRANSPORTATION PTE LTD	SHD 3503E	SLW 9739E
6	MT/1007260-002	COMFORT TRANSPORTATION PTE LTD	SHD 6683Z	SLW 2952B
7	MT/1007452-001	COMFORT TRANSPORTATION PTE LTD	SHD 4255P	SKL 9885K
8	MT/1004057-002	SMRT TAXIS PTE LTD	SHF 1011K	SJH 2414R
9	MT/1004374-002	SMRT TAXIS PTE LTD	SHB 1621X	YN 5815M

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/08/2018 09:19
Date Of Accident	11/08/2018 01:10
Exact Location Of Accident	ROCHOR CANAL TOWARDS OPHIR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7441Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	CHOO SOONG HENG
NRIC No	S6920956D
Date Of Birth	16/06/1969
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83548069
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 66 CIRCUIT ROAD #07-319
Postcode	370066
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM6659L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KADIR BIN A RAHMAN
NRIC/Passport Number	S0065567H
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHOO SOONG HENG
------	-----------------

Approximate Age

49

Injuries Sustain

NECK, BACK AND SHOULDER PAIN

Injured person in which vehicle?

SH7441Y

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199203321R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 11-8-18 @ 0110hr, I was driving along Rochor Canal towards Ophir rd straight road. Suddenly Vehicle (B) SKM 6659L change lane and hit my taxi (A) SH 7441Y Front RH Cause damage.

There is Video Footage on the Scene.
No Pax on board at my taxi.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 192003321R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.08.2018

Time: 09:04:54

REPAIR ESTIMATE

Page: 1/2

TS

NHC-45
LKE-Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305198588
 REGN NO : SH 7441Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 14.04.2011
 DATE/TIME IN : 11.08.2018 08:10
 ACCIDENT DATE : 11.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	REMARKS
0001	04-01-0101-0003-U	FRONT BUMPER	1	538.80 20.00 431.04	X 1/2 in
0002	04-01-0101-0030-G	FRT BUMPER UPR BRKT RH	1	20.10 20.00 16.08	X 5/8
0003	04-01-0101-0074-G	FRT BUMPER RETAINER RH	1	9.20 20.00 7.36	X 5/8
0004	04-01-0101-0017-U	FRONT FENDER RH	1	593.00 20.00 474.40	- Part
0005	04-01-0101-0026-U	HEADLAMP RH	1	797.90 20.00 638.32	- head
0006	03-01-0101-0002-U	FRT WHEEL CAP RH	1	145.00 20.00 116.00	- head

SUB-TOTAL : 1,683.20

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 17-01	CHECK ALL LIGHTING
0003 20-00	TUFF COAT ON AFFECTED PARTS.

560.00 300
 400.00 36
 40.00 30
 40.00 X 17

SUB-TOTAL : 1,040.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.08.2018

Time: 09:04:54

REPAIR ESTIMATE

NFTUC-45

Page: 2/2

TS

LKK - Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305198588
REGN NO : SH 7441Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 14.04.2011
DATE/TIME IN : 11.08.2018 08:10
ACCIDENT DATE : 11.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lmfs

TOTAL : 2,723.20

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin 1 UCLG
13/8/18 1025L
2 Rg
L/s
After Repair p LK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

OMFORTDELGRO
ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

905 Boodell Road Singapore 579701
Mobile: + 65 8383 5280 Fax: + 65 8382 8755
Workshops
88 Loyang Drive Singapore 508969 24 Serangoon Singapore 758158
383 Sin Ming Drive Singapore 575717 7 Sengkang Way Singapore 758791
45 Pandan Road Singapore 608585 501 Yuhon Industrial Park A Singapore 758732
200 Ulu Pandan Singapore 670002

Date/Time: 11.08.2018 11:26 Page : 1

Team: AE ARC Repair TP(CLSO)1

JOB CARD

Sales Order: (Sat) JC NO: 305198588

OMER

S

OMER NO.
ESS

(R)
(P)

JUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)


REGN NO.	SH 7441Y	MILEAGE
MAKE	HYUNDAI	FUEL E 1/2 F
MODEL	SONATA	DATE/TIME IN 11.08.2018 08:10
YR OF MANU	14.04.2011	TARGET DATE
CHASSIS CODE	KMHET41VMBA807319	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 11.08.2018
NA JRE: 3P 11.08.18

S/NO LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SH 7441Y LIMITS

Vehicle No.: SH 7441Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305198588
Date : 15/08/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM


To : LKK
Attn : KALVIN ANG
Vehicle Reg No. : SH 7441Y


Fax :
Date of Accident : 11-Aug-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SKM6659L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,550.00
Final Lumpsum Repair cost \$1,550.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 15/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: FRT FENDER RH - REPLACED



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014654/K1tbn2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-08-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 6659L	Veh. Inspected	SH 7441Y
Policy No.	5088380782-01	Coverage (\$)	0.00
Claim No.	MT/1007261-002	Excess (\$)	0.00
Assign From		Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMBA807319	Colour	BLUE
Odometer	385053	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HANKOOK	7 mm
L/H Front Tyre	215/60 R16	HANKOOK	7 mm
R/H Rear Tyre	215/60 R16	HANKOOK	7 mm
L/H Rear Tyre	215/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/08/2018	Inspection Date	13/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7441Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	538.80	-
1	FRT BUMPER UPR BRKT RH	SERVICEABLE	20.10	-
1	FRT BUMPER RETAINER RH	SERVICEABLE	9.20	-
1	FRONT FENDER RH	DENTED	593.00	593.00
1	HEADLAMP RH	GRAZED	797.90	797.90
1	FRT WHEEL CAP RH	GRAZED	145.00	145.00
	LESS 20% DISCOUNT		-420.80	-307.18
			1,683.20	1,228.72
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		560.00	300.00
	SPRAYPAINT ON AFFECTED AREA.		400.00	360.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	40.00	-
			1,040.00	690.00
GRAND TOTAL			2,723.20	1,918.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,550.00

Report Ref No. NS/INC18014654/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.