

108/1113

Surveyor: Kelvin

REF: NS/INC18014655/Klrbrn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop no/s _____

of _____

Insured: FBJ 24386

Policy No. 5079821537-02 120518-11052019

Claims No. MT/1006972-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN/OUT

Veh No: SHA 3174 L Yr Regn: 31 May 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe C.C. 194

Colour: Blk A/C: Insured / Std / NI / NA

Sp. Reading: 993325 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHET410MBA81133X

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / SB A/Rim or _____

Tyre Size: F: 215/60R16

R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or Westlake

Front: 7 mm Rear: 7 mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 8/8/12 D.O.I. 13/8/12

Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 3174 L - (04/10) 8006402 / Ttpb3q2
	FBJ 24386 - x
15/8/18	Confirm PIP \$550/20% Red: \$1772.02, 76%.
	RECEIVED 23 AUG 2018

Date/Time, File Pass to? : Prel. Report

1) typist : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: TP

Lump Sum / I.B.I.: (\$ 550)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS. _____ \$

Photos: 160

Others: _____

TOTAL: _____



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014655/K1rb			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 13-08-2018	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBJ 2438G	Veh. Inspected	SHA 3174L
Policy No.	5079821529-02	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/08/2018	Inspection Date	13/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Hello, NAC_PAYA_UBI_800601

[Change Language](#)

[Change Password](#)

[Log Out](#)

[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="08/08/2018 17:46"/>
Vehicle No.(For Motor)	<input type="text" value="FBJ2438G"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5079821529-02		WANG MING JIE	S9131147Z	GMC	Third Party	FBJ2438G	FBJ2438G	12/05/2018	11/05/2019

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1006965-002	COMFORT TRANSPORTATION	SHC 8254X	SLS 8288S	13/08/2018	\$ 4,074.56	\$ 2,250.00
2	MT/1007237-002	CITYCAB PTE LTD	SHB 2334T	SJJ 2802T	13/08/2018	\$ 2,718.07	\$ 1,930.13
3	MT/1006666-002	COMFORT TRANSPORTATION	SHD 6654H	SDM 9111M	09/08/2018	\$ 5,938.92	\$ 4,450.00
4	MT/1007040-002	COMFORT TRANSPORTATION	SHD 3514Z	SLA 7725Z	13/08/2018	\$ 10,997.38	\$ 4,039.39
5	MT/1006499-002	CITYCAB PTE LTD	SHC 7177S	FR 7356L	05/08/2018	\$ 3,290.60	\$ 300.00
6	MT/1006972-002	COMFORT TRANSPORTATION	SHA 3174L	FBI 2438G	08/08/2018	\$ 2,322.02	\$ 550.00
7	MT/1006547-002	CITYCAB PTE LTD	SHA 9457G	SLJ 9702D	09/08/2018	\$ 1,639.23	\$ 1,319.23
8	MT/1005643-002	COMFORT TRANSPORTATION	SHA 7917I	SDP 7075G	01/08/2018	\$ 3,936.00	\$ 1,600.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 10:24
Date Of Accident	08/08/2018 11:50
Exact Location Of Accident	ADAM RD > LORNIE RD NEAR PIE(TUAS) EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3174L
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	AHADAN B MUJER
NRIC No	S2045966B
Date Of Birth	01/11/1947
Occupation	OUTDOOR
Date Of Driving Pass	26/01/1981
Driving Experience	37 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84550231
Fax Number	
Contact Number	
Email Address	AHADANMUJER@HOTMAIL.COM

Address	466C 20-337 SEMBAWANG DRIVE
Postcode	753466
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SEMBAWANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ2438G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	WANG MING JIE KEN
NRIC/Passport Number	S9131147Z
Contact Number	98262630
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	WANG MING JIE KEN
------	-------------------

Approximate Age

Injuries Sustain

BRUISES ON BODY

Injured person in which vehicle?

FBJ2438G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Police Report Attached.
T/20180809/2034

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE L.
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

[Signature]
SR 160/8/18
CSG

GIARTAC SketchPlanForm_V3



**SINGAPORE
POLICE FORCE**



T/20180809/2034

1 of 4

Report No. T/20180809/2034

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/08/2018 11:33		Vide Report No.: E/20180808/0091	Station Diary No.: 24
Informant's Particulars			
Name of Informant: AHADAN BIN MUJER		Address: APT BLK 466C SEMBAWANG DRIVE #20-337 SINGAPORE 753466	
ID Type / ID No.: NRIC NO / S2045966B		Contact No.:	Mobile: 84550231
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 70	Date of Birth: 01/11/1947	Type of Informant: Driver
Race: Javanese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/08/2018 11:50	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 ADAM ROAD LORNIE ROAD Along Adam road towards Lornie Road exiting PIE (Tuas)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ2438G	Motorcycle				Slightly Damaged	0
SHA3174L	TAXI				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20180809/2034

2 of 4

Report No. T/20180809/2034

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT

Rider			
Name	WANG MING JIE KEN	ID No.	S9131147Z
Related Vehicle	FBJ2438G (Motorcycle)	Contact No.	98262630
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	AHADAN BIN MUJER	ID No.	S2045966B
Related Vehicle	SHA3174L (TAXI)	Contact No.	84550231
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 08.08.2018 at about 1150hrs, I was driving my vehicle bearing VRN SHA3174L along Adam Road towards Lornie Road. At that point of time, I was travelling on the 3rd lane from the right and I did not have any passenger inside my vehicle. Subsequently, when I was approaching an exit into PIE (Tuas), I change lane to the left into the 4th lane of the said road wanted to exit into PIE (Tuas). After I change lane, suddenly the vehicle in front jammed the brakes. As such, I applied my brakes and managed to stop in time.

Subsequently, I felt an impact from behind. I then get down from my vehicle to make a check and discovered that there was a motorcycle bearing VRN FBJ2438G had collided onto the rear of my vehicle. I wish to informed that my vehicle sustained damages onto the rear of my vehicle. After which, I spoke to the rider and decided to call for the ambulance as he had bruises on his body.

Subsequently, ambulance came followed by Traffic police. Ambulance paramedics checked on the rider and the rider was then conveyed to hospital. The traffic police officer took my statement and after which he also took the SD card from my In-car vehicle for further investigation and issued me a form. The traffic police officer gave me a report card reference E/20180808/0091of in charge IO Lim Hong Lee c/n: 65476438 and advised me to lodged a traffic accident report.



**SINGAPORE
POLICE FORCE**



T/20180809/2034

3 of 4

Report No. T/20180809/2034

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

CONTINUATION OF REPORT



SINGAPORE
POLICE FORCE



T/20180809/2034

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

4 of 4
Report No. T/20180809/2034

CONTINUATION OF REPORT



Sketch Plan





Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD ZAID BIN ZAILAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/08/2018 11:33 
Officer in Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case:

Authentication Stamp
 NP168
 Signature: 
 Singapore Police Force





NTUC / LKK

FZ

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 3174L

DATE 8/10/2018 10:08

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X MR</i>			\$ 578.40
	Rear Bumper Reinforcement <i>X SC</i>			\$ 483.30
	Rear Bumper Clip <i>X 22</i>			\$ 22.00
	Rear Bumper Sponge <i>X SC</i>			\$ 137.40
	Rear Bumper Under Cover <i>X SC</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X SC</i>		\$ 38.00	\$ 76.00
SUB TOTAL				\$ 1,482.90
LESS 20% DISCOUNTED TOTAL				\$ 1,186.32
	Rear Bumper Reverse Sensor <i>X SC</i>			\$ 135.70 Nett
	Rear Bumper Advertisement Logo <i>SC</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>SC</i>		\$ 100.00	\$ 200.00 Nett
TOTAL				\$ 385.70
Labour Charge				
	Panel Beating (Repair)			\$ 350.00 <i>10-</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 30.00 <i>X 22</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X 22</i>
TOTAL LABOUR				\$ 750.00
ESTIMATE TOTAL				\$ 2,322.02

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Ka liu 11/10/18
13/8/18 11:00h
201
Y's Auto Repair Ltd

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 756156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

A member of COMFORTDELGRO

Date/Time: 13.08.2018 10:30

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3847153

JG NO.: 305199050

Customer: COMFORT TRANSPORTATION PTE LTD
 Motor No: 7010045
 Address: 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (O)

REGN NO.: SHA3174L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 13.08.2018 09:40
YR OF MANU 31.05.2011	TARGET DATE
CHASSIS CODE KMHET41VMB A811334	COMPLETION DATE/TIME:

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 08.08.2018
 NATURE: 3P 08.08.18/C

NTUC

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No.: **SHA3174L** FZ NTUC LKK

Vehicle No.: **SHA3174L**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.08.2018

REPAIR ESTIMATE

Time: 18:08:28

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305199050
REGN NO : SHA3174L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 31.05.2011
DATE/TIME IN : 13.08.2018 09:40
ACCIDENT DATE : 08.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 20-05	RENEW ADVERTISEMENT REAR BUMPER	50.00
0001 20-05	RENEW ADVERTISEMENT REAR FENDER LH	100.00
0002 20-05	RENEW ADVERTISEMENT REAR FENDER RH	100.00
0003 L	PANEL BEATING	100.00
0004 L	SPRAY PAINTING CHARGE	200.00

SUB-TOTAL : 550.00

TOTAL : 550.00

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305199050

Date : 14.08.2018

ComfortDelGro Engineering Pte Ltd
59 Loyal Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA3174L

Date of Accident : 08.08.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBJ2438G
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$0.00</u>
(b) Labour Charges	<u>\$550.00</u>
Total for Part-By-Part Repair Cost	<u>\$550.00</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$0.00</u>
Final Lumpsum Repair cost	<u>\$0.00</u>

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : FAUZY BIN MOKHTAR

Tel : 62148319

Fax : 65468156

Signature : 

Name : Calvin

Date : 15/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014655/K1rbn2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 29-08-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBJ 2438G	Veh. Inspected	SHA 3174L
Policy No.	5079821529-02	Coverage (\$)	0.00
Claim No.	MT/1006972-002	Excess (\$)	0.00
Assign From		Assign Date	13/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHET41VMBA811334	Colour	BLUE
Odometer	993375	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/08/2018	Inspection Date	13/08/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No. 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3174L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	578.40	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	483.30	-
10	REAR BUMPER CLIP	NOT NECESSARY	22.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @\$38.00	SERVICEABLE	76.00	-
	LESS 20% DISCOUNT		-296.58	-
			1,186.32	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			385.70	250.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		350.00	100.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			750.00	300.00
GRAND TOTAL			2,322.02	550.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				550.00

Report Ref No. NS/INC18014655/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.