

ASS. REC. BY:

REF:

CS3/MSG18014698/R1240302

Special Instruction:

Surveyor:
Mennen

Pasu

ASSIGNMENT (Office)

From (Person):

Irene Sun

of

MSG

Date/Time:

13/8/18 @ 4:27pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SDN 52D

Insured:

8FK 2366C

at Workshop m/s

Empire / merge

Tel:

9742 5441

of

NO-4 punden loop (Blk 1 / Blk K)

Policy No:

276886 218MP

Claim No:

566997

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/8/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:10am @ 14/8/18

Person Contacted:

Mr. kenny

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SDN 52D - CS3/AXA14017126/K16K3
	8FK 2366C - X
	Dismantle: 15/8/2018
	After repair: 17/8/2018

DOA: 28/8/2014

(08/11/13)

REF:

Surveyor: *Pras*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SON 520*at Workshop m/s *EMPIRE IMAGE*of *No. 4 Pandan Loop BUK 1/k*Insured: *MSLH*

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SON 520* Yr Regn: *Jul / 2010*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Volkswagen Scirocco* c.c. *1390*Colour: *WHITE* A/C: Insured / Std / NI / NASp. Reading: *99566* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WVWZZZ132AV448900*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *225/40ZR18*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / *YOKO* or

Front

R/Bal. *6* mmL/Bal. *6* mm

D.O.A. _____

Rear

R/Bal. *6* mmL/Bal. *6* mmD.O.I. *14/08/18*Survey held at *EMPIRE IMAGE*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Estimated repair range \$2,800 - \$3,500.**19/18 submit PRS Report**Range & No. of days**Pras*
21/8/2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final ReportResurvey No. of Trip: *2*

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$)

Transportation:

☐ : Interview (\$)

S + RS, SI

☐ : Tech. Invs (\$)

Photos

☐ : Weekend (\$)

Others

Report Format : *PRS*

Lump Sum / I.B.I. (\$) _____

TOTAL

130




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18014698/R1z4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-08-2018	
Code : MSG			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SFK 2366C	Veh. Inspected	SDN 52D
Policy No.	27688621SMP	Coverage (\$)	0.00
Claim No.	566997	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	14/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/08/2018	Inspection Date	14/08/2018
Survey held at	EMPIRE IMAGE NO.4 PANDAN LOOP (BLK K / BLK 1) SINGAPORE 128222		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		13 Aug 2018 16:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WONG KOK KEONG KELVIN, ID: S1612622E			
Main Claimant:	WONG JEOK KENG, ID: S1418542I			
Vehicle Reg. No.:	SDN52D	Date of Loss:	07/08/2018 07:00 - :59 [96 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 566997	Policy/Cover Note No.:	27688621SMP Coverage: 01/04/2018 - 31/03/2019	
Vehicle Reg. No. (Insured):	SFK2366C	Policy No. (Claimant):		
		Excess:		
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2018]			
Adj Asg. Remarks:	OI non reporting. Liability unclear. TP reject SJE - assign LKK Auto Consultants Pte Ltd. contact: Mr Kenny Lim - 9742 5441			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SDN52D		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	SCIROCCO 1.4L AT TSI 1372Q5		
Chassis No. :	WVWZZZ13ZAV448900		
Propellant :	Petrol		
Engine No. :	CAV199323		
Engine Capacity :	1390 cc		
Maximum Power Output :	118.0 kW (158 bhp)		
Maximum Laden Weight :	1730 kg		
Unladen Weight :	1285 kg		
Year Of Manufacture :	2010		
Original Registration Date :	22 Jul 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$28,389.00		
COE Expiry Date :	21 Jul 2020		
Road Tax Expiry Date :	21 Jan 2019		
PARF Eligibility Expiry Date :	21 Jul 2020		
Inspection Due Date :	21 Jul 2019		
Intended Transfer Date :	16 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8542I
Vehicle Details	
Vehicle No.:	SDN52D
Vehicle to be Exported:	No
Intended De-registration Date:	21 Aug 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CAV199323
Chassis No.:	WVWZZZ13ZAV448900
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$23,881.00
Original Registration Date:	22 Jul 2010
First Registration Date:	22 Jul 2010
Transfer Count:	1
Actual ARF Paid:	\$23,881.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2020
PARF Rebate Amount:	\$13,134.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$28,389.00
COE Rebate Amount:	\$5,441.00
Total Rebate Amount:	\$18,575.00

The information contained herein is correct as at 21 Aug 2018

OK

Empire

MBHH18102032 / Afox Mars Pte Ltd - BUA Merah
 ENTRY DATE & TIME: 08/08/2018 14:53
 SUBMITTED BY: Boey Lake

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/08/2018 14:53
 Date Of Accident 07/08/2018 07:55
 Exact Location Of Accident LORONG 22 GEYLANG TOWARDS GUILLEMARD RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDN52D
 Insured/Policyholder
 Name Of Registered Owner WONG JEOK KENG
 NRIC No S1418542I
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-93887243
 Alternative Phone No OTHERS-93887243

Vehicle Particulars
 Manufacturer VOLKSWAGEN
 Model SCIROCCO 1.4L
 Exact Purpose for which vehicle was being used at time of accident PRIVATE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company
 Name of Insurance Company FWD SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number PNPV2018-00001521
 Cover Note Number N.A.

Driver
 Name of Driver LEONG HONG YAO
 NRIC No S8740321A
 Date Of Birth 07/12/1987
 Occupation INDOOR
 Date Of Driving Pass 25/09/2005
 Driving Experience 11 YEARS AND 10 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93887243
 Fax Number
 Contact Number
 Email Address REI.LEONG@GMAIL.COM

Address ONE ROBEY, 1 ROBEY CRESCENT #05-03
 Postcode 546256
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was driving along Lorong 22 Gaylang towards Guillemard Road on the right most lane and the other vehicle, 8FK2386C, suddenly rear ended me from the middle lane. Refer to the video provided for more details.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFK2386C
 Vehicle Make/Model/Colour BMW 318I 1.8 AT D/AB 4DR ABS HID / BLK
 Details Of Properties NIL
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver) 2
 Passenger 1
 NAME: : PASSENGER 1
 GENDER: : FEMALE

Sketch Plan



Page 3 of 27

Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was driving along Lorong 22 Geylang towards Guillemard Road on the right most lane and the other vehicle, SFK2366C, suddenly rear ended me from the middle lane. Refer to the video provided for more details.

Taxi Voucher No.:

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 August 2018 at 12:30 PM

Date/Time:

8 August 2018 at 12:30 PM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		13 Aug 2018 16:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WONG KOK KEONG KELVIN , ID: S1612622E		
Main Claimant:	WONG JEOK KENG , ID: S1418542I		
Vehicle Reg. No.:	SDN52D	Date of Loss:	07/08/2018 07:00 - :59 [96 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566997	Policy/Cover Note No.:	27688621SMP Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	SFK2366C	Policy No. (Claimant):	
		Excess:	
Repairer:	Empire Image (HQ) NO 4 PANDAN LOOP (BLK 1/ BLK K), 128222 West Coast - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 14/08/2018]		
Adj Asg. Remarks:	OI non reporting. Liability unclear. TP reject SJE - assign LKK Auto Consultants Pte Ltd. contact: Mr Kenny Lim - 9742 5441		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)




































There are no mail for this case.


















ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDN52D (566997)
[SFK2366C]
TP
WONG JEOK KENG
Aug 7 2018 7:00AM
[WONG KOK KEONG KELVIN]
Empire Image

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
3	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
4	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
5	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
6	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
7	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
8	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
9	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
10	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
11	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
12	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
13	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
14	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
15	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
16	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
17	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
18	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
19	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
20	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
21	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
22	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
23	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
24	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
25	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
26	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
27	16/08/18 16:14	General View							Load JPG	<input checked="" type="checkbox"/>
28	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
29	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
30	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
31	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
32	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
33	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
34	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
35	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
36	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>
37	21/08/18 14:00	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/18 14:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	24/08/18 09:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/08/18 11:47	pri notice	 Load PDF	
2	13/08/18 11:57	TP reject SJE	 Load PDF	
3	13/08/18 12:00	tp reject SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014698/R1Z4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27688621SMP

Claimant Vehicle
No : SDN52D

Insured Vehicle No : SFK2366C

Date of Loss: 07/08/2018

Nature of Claim: TP

Claim No: 566997

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDN52D

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 L (A)

Engine No: CAV199323

Reg. Date: 22/07/2010 (Man. Year: 2010)

Chassis No: WWWZZZ13ZAV448900

Colour: White

Odometer: 99566 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/08/2018

Date Inspected: 14/08/2018 Inspected At:

Empire Image (HQ)
NO 4 PANDAN LOOP (BLK 1/ BLK K)
Singapore 128222

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 -\$3,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2018)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDN52D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >