

7/03/2002

ASS. REC. BY:

REF: CS3/MSG18014701/T1240322

Initial Instruction:

Survivor  
Menmen

## ASSIGNMENT (Office)

From (Person): Christina Wong

of

MSG

Date/Time: 13/8/18 @ 4.10pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 6105A

Insured:

SLM 1727U

at Workshop m/s

Equefor Brotherhood

Tel:

90 113391

of

25 Kaki Bkt Rd 4 # 03-79

Policy No: A28795104 MCX

Claim No:

566670

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS (up)

Date/Time:

9:50am @ 14/8/2018

Person Contacted:

Chang

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBM 6105A - X
	SLM 1727U - X
	Dismantle: 20/8/2018

Surveys

Tanji

REF:


MSIG

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: FBMG105 A Yr Regn: Jan / 18  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha C.C. 155  
 Colour: Black A/C. Insured / Std / NI / NA  
 Sp. Reading T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MH3RG4710HK040809  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 100/80K17 R: 140/70K17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Road Winner  
 Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. mm L/Bal. mm  
 D.O.A. D.O.I. 14/5/18  
 Survey held at Equator Brokers  
 Des. of Damages (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction NO GIA. 25 lub bh + R14 # 03-79  
 Estimated repair range \$4,500 - \$5,300.

30/8/18 Submit PRS report.

Range + No. of days.  
 30/8/2018.

Date/Time. File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PRS

Lump Sum / I.B.I. (\$

120

10

130




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18014701/T1z4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-08-2018		
		Code : MSG		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLM 1727U	Veh. Inspected	FBM 6105A	
Policy No.	A28795104MCX	Coverage (\$)	0.00	
Claim No.	566670	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	14/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	28/07/2018	Inspection Date	14/08/2018	
Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		13 Aug 2018 16:10 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	MUHAMMAD ZAID BIN ROSLI, ID: S9641170G		
Vehicle Reg. No.:	FBM6105A	Date of Loss:	28/07/2018 23:00 - :59 [6 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566670	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLM1727U	Policy No. (Claimant):	
		Excess:	
Repairer:	Equator Brotherhood (KAKI BUKIT) 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2018]		
Driver/Custodian (Insured):	PEH SWEE YEO (), NRIC: S1205421A, Tel: +6597879918		
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE list, proceed to appoint LKK Auto Consultants. Contact Person: Wille / 6384 6939 / 9011 3391		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBM6105A		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YZF-R155		
Chassis No. :	MH3RG4710HK040809		
Propellant :	Petrol		
Engine No. :	G3J6E0078684		
Engine Capacity :	155 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	305 kg		
Unladen Weight :	137 kg		
Year Of Manufacture :	2017		
Original Registration Date :	06 Jan 2018		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$7,501.00		
COE Expiry Date :	05 Jan 2028		
Road Tax Expiry Date :	05 Jan 2019		
Inspection Due Date :	05 Jan 2021		
Intended Transfer Date :	21 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1170G
<b>Vehicle Details</b>	
Vehicle No.:	FBM6105A
Vehicle to be Exported:	No
Intended De-registration Date:	21 Aug 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R155
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	G3J6E0078684
Chassis No.:	MH3RG4710HK040809
Maximum Power Output:	-
Open Market Value:	\$2,925.00
Original Registration Date:	06 Jan 2018
First Registration Date:	06 Jan 2018
Transfer Count:	1
Actual ARF Paid:	\$439.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	05 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,501.00
COE Rebate Amount:	\$7,031.00
<b>Total Rebate Amount:</b>	<b>\$7,031.00</b>

The information contained herein is correct as at 21 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/07/2018 15:59
Date Of Accident	28/07/2018 23:10
Exact Location Of Accident	ALONG WOODLANDS AVE 3 TOWARDS CAUSEWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM6105A
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ZAID BIN ROSLI
NRIC No	S9641170G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91891944
Alternative Phone No	OFFICE-91891944
Vehicle Particulars	
Manufacturer	YAMAHA
Model	YZF-R155-155CC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D18MTMC01000252
Cover Note Number	08/01/2018 - 07/01/2019
Driver	
Name of Driver	MUHAMMAD ZAID BIN ROSLI
NRIC No	S9641170G
Date Of Birth	12/11/1996
Occupation	INDOOR
Date Of Driving Pass	02/10/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91891944
Fax Number	
Contact Number	OFFICE-91891944
EMail Address	NOEMAIL

Address	BLK 115 TECK WHYE LANE 05-702
Postcode	680115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM1727U
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PEH SWEE YEO
NRIC/Passport Number	S1205421A
Contact Number	97879918
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	




No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	MUHAMMAD ZAID BIN ROSLI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM6105A
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO THE POLICE REPORT T/20180730/7022

**Important:**

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

- |   |                                 |
|---|---------------------------------|
|   | - Reporting Only                |
|   | - Claim OD                      |
|   | - Claim TP                      |
| ✓ | - Claim OD/TP at other workshop |

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

*Zeid*

31 July 2018 15:45

Policyholder's signature  
Date & Time

Driver's Signature  
(if driver not the policyholder)  
Date & Time

*Kenneth*

Reporting Centre Personnel's Signature  
Name: Kenneth  
Nric/Fin No.

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Kenneth  
NRIC/FIN No:

## Sketch Plan Pg. 3



**SINGAPORE  
POLICE FORCE**



T/20180730/7022

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20180730/7022

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/07/2018 22:55			Vide Report No.:		Station Diary No.:
<b>Informant's Particulars</b>					
Name of Informant: MUHAMMAD ZAID BIN ROSLI			Address: APT BLK 115 TECK WHYE LANE #05-702 SINGAPORE 680115		
ID Type / ID No.: NRIC NO / S9641170G			Contact No.: Home/Office: Mobile: 91891944		
Nationality: SINGAPORE CITIZEN			Email: mzbr96@gmail.com		
Sex: Male	Age: 21	Date of Birth: 12/11/1996	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class:		Date of Expiry:

## General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/07/2018 23:10	Type of Location: T-Junction
Location:  WOODLANDS STREET 13				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM6105A	Motorcycle	YAMAHA	YZF-R155	Black		0
SLM1727U	Car	HONDA	Vezel	Gold	Slightly Damaged	1

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBM6105A	TENET SOMPO INSURANCE PTE. LTD.	D18MTMC0100025 2	08/01/2018	07/01/2019

## Sketch Plan Pg. 4



**SINGAPORE  
POLICE FORCE**



T/20180730/7022

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20180730/7022

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	MUHAMMAD ZAID BIN ROSLI	ID No.	S9641170G
Related Vehicle	FBM6105A (Motorcycle)	Contact No.	91891944
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Peh Swee Yeo	ID No.	S1205421A
Related Vehicle	SLM1727U (Car)	Contact No.	97879918
Hospital/Clinic	TOA PAYOH NORTH CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	30/07/2018	Date Discharge	30/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

## Brief Details.

I was travelling straight along the middle lane of woodlands avenue 3 towards causeway point, at the T-junction of Woodlands St 13, when a car opposite turned right from his give way line and collided into me. I sustained contusion on my shin, tigh and calf. I went to see a doctor after resting at home the whole day on Sunday, thinking that the pain would go away but subsequently got advised to see doctor if there were any serious injuries.



**SINGAPORE  
POLICE FORCE**



T/20180730/7022

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180730/7022

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
ONG YONG HOCK  
Contact No.: 65476436

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
30/07/2018 22:55

Classification Of Case:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2018		13 Aug 2018 16:10 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	<b>SKYWAY MOTOR PTE LTD</b> , Co. Reg. No.: 199904194N								
Main Claimant:	<b>MUHAMMAD ZAID BIN ROSLI</b> , ID: S9641170G								
Vehicle Reg. No.:	<b>FBM6105A</b>	Date of Loss:	28/07/2018 23:00 - :59 <b>[6 Months and 22 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 566670</b>	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018						
Vehicle Reg. No. (Insured):	<b>SLM1727U</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Equator Brotherhood (KAKI BUKIT)</b> 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Imm.Advice due 14/08/2018]</b>								
Driver/Custodian (Insured):	PEH SWEE YEO (), NRIC: S1205421A, Tel: +6597879918								
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE list, proceed to appoint LKK Auto Consultants. Contact Person: Wille / 6384 6939 / 9011 3391								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*FBM6105A (566670)

[SLM1727U]

TP

MUHAMMAD ZAID BIN ROSLI

Jul 28 2018 11:00PM

[SKYWAY MOTOR PTE LTD]

Equator Brotherhood

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)












































### Assessment Reports





No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page	<input checked="" type="checkbox"/>
1	10/08/18 14:46	<b>Accident Statement</b> From: SC - Reg. No: SLM1727U, Claimant: SKYWAY MOTOR PTE LTD	Load HTM	<input type="checkbox"/>
2	10/08/18 14:46	<b>Addendum Sheet</b> From: SC - Reg. No: SLM1727U, Claimant: SKYWAY MOTOR PTE LTD	Load TIF	<input type="checkbox"/>
3	10/08/18 14:46	<b>Accident Statement Addm. #1</b> From: SC - Reg. No: SLM1727U, Claimant: SKYWAY MOTOR PTE LTD	Load HTM	<input type="checkbox"/>

### Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	<input checked="" type="checkbox"/>
1	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	16/08/18 16:22	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/08/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	21/08/18 10:30	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	21/08/18 10:30	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	21/08/18 10:30	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
80	21/08/18 10:30	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	21/08/18 10:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/08/18 14:46	<b>FBM6105A GIA Rpt</b> From: SC - Reg. No: SLM1727U, Claimant: SKYWAY MOTOR PTE LTD	 Load PDF	
2	10/08/18 14:47	<b>PRI</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014701/T1Z4D3E2

Date: 31/08/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28795104MCX

Claimant Vehicle No : FBM6105A

Insured Vehicle No : SLM1727U

Date of Loss: 28/07/2018

Nature of Claim: TP

Claim No: 566670

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM6105A

Make &amp; Model: YAMAHA YZF-R155, 155cc

Engine No: G3J6E0078684

Reg. Date: 06/01/2018 (Man. Year: 2017)

Chassis No: MH3RG4710HK040809

Colour: Black

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 100/50 R17

Rear Tyre Size: 140/70 R17

Front Left Side: Road Winner 5 mm

Rear Left Side: Road Winner 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 13/08/2018

Date Inspected: 14/08/2018 Inspected At:

Equator Brotherhood (KAKI BUKIT)  
25 Kaki Bukit Road 4, #03 -79 Synergy @  
KB  
Singapore 417800

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$5,300.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 31 Aug 2018)	
<b>Parts:</b>	N/A	YAMAHA YZF-R155 155cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM6105A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >