

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18014704/T124302

Special Instruction:

Survivor:

Mehner

From (Person):

tau lich  
ehhia nyuk pui

ASSIGNMENT (Office)

of MSG

Date/Time:

11/8/18 @ 9:29 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81T 6609G

Insured:

SLR 4365J

at Workshop m/s

Fixmate Auto

Tel:

8263 2225

of

8 kaki Blk Ave 4 #02-37 premier

Policy No:

290060120MX

Claim No:

567079

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/08/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:01 am @ 14/8/18

Person Contacted:

Ah chui

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	81T 6609G - CCF/1AIG 12020476 / Cuz 1
	SLR 4365J - X.
	Dismantle: 15/8/2018

DUA: 20/10/2012

Tamplin

REF:

MS16

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SJT66096 Yr Regn: 2009, 201  
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: M. Fushio Lancer C.C. 1497  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 158209 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: SMYSRCCY2A44004B6  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60K16  
 R: 1  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front 6 mm Rear 6 mm  
 R/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 14/5/18-529  
 Survey held at Fixmate Auto  
 Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_  
 Estimated repair range \$4,000 - \$5,500.  
 Kahi buh? Ave 4 #02-37

30/8/18 Mlmif PRS Report  
 Range + No. of days.  
 30/8/2018

Date/Time. File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee

Transportation

120 S + RS SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Report Format : PRS

Lump Sum / I.B.I. (\$)

130



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18014704/T1z4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 14-08-2018		
		Code : MSG		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SLR 4365J	Veh. Inspected	SJT 6609G	
Policy No.	29006012QMX	Coverage (\$)	0.00	
Claim No.	567079	Excess (\$)	0.00	
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	14/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	11/08/2018	Inspection Date	14/08/2018	
Survey held at	FIXMATE AUTO-8 KAKI BKT AVE 4 #02-37			
Repairer	-			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		14 Aug 2018 09:29 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YEO KIM HAN JEREMY, ID: S8943666D		
Main Claimant:	SEOW POH LAI, ID: S1654956H		
Vehicle Reg. No.:	SJT6609G	Date of Loss:	11/08/2018 04:00 - :59 [105 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567079	Policy/Cover Note No.:	29006012QMX (Comprehensive) Coverage: 15/08/2017 - 14/08/2018
Vehicle Reg. No. (Insured):	SLR4365J	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Fixmate Auto Pte Ltd - Kaki Bukit (HQ) 8 KAKI BUKIT AVENUE 4, #02-37 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2018]		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK OI NOT REPORTED CONTACT: AH CHAI 8263 2225/9372 7000		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4956H
Vehicle Details	
Vehicle No.:	SJT6609G
Vehicle to be Exported:	No
Intended De-registration Date:	21 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	4A910126321
Chassis No.:	JMYSRCY2A9U004336
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,600.00
Original Registration Date:	26 Oct 2009
First Registration Date:	26 Oct 2009
Transfer Count:	0
Actual ARF Paid:	\$16,600.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2019
PARF Rebate Amount:	\$9,130.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,830.00
COE Rebate Amount:	\$2,121.00
<b>Total Rebate Amount:</b>	<b>\$11,251.00</b>

The information contained herein is correct as at 21 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2018 14:39
Date Of Accident	11/08/2018 04:30
Exact Location Of Accident	JALAN SRI PELANGI, TMN PELANGI JOHORS SHELL STATION
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT6609G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEOW POH LAI
NRIC No	S1654956H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98307386
Alternative Phone No	OTHERS-98307386

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M493548
Cover Note Number	

### Driver

Name of Driver	SEOW RUI WEN
NRIC No	S9539509J
Date Of Birth	01/11/1995
Occupation	INDOOR
Date Of Driving Pass	28/08/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98289018
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 738 PASIR RIS DRIVE 10 #10-23
Postcode	510738
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MERVIN GENDER: : MALE
Passenger 2	NAME: : ALOYSIUS GENDER: : MALE
Passenger 3	NAME: : ISAAC GENDER: : MALE
Passenger 4	NAME: : NICHOLAS GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR4365J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13/08/18

**IDAC KAKI BUKIT (VAC)**

Reporting Centre Roadblock Signpost  
Name: Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was paying for my petrol and I heard cracking sound and my friend sounded to honk. the driver then move the car forward and step out of the car to see what happen. I went to check on the car and my friends ~~was~~ alighted to also see what had happen. He was driving in and decided to use pump 13. So he went forward and reverse in to the ~~slot~~ slot for pump 13 but over reverse and bang into my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 13/08/18

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13/08/18

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4  
Reporting Centre Personnel's Signature  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: vackb@singnet.com.sg

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		14 Aug 2018 09:29 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured: <b>YEO KIM HAN JEREMY</b> , ID: S8943666D									
Main Claimant: <b>SEOW POH LAI</b> , ID: S1654956H									
Vehicle Reg. No.:	<b>SJT6609G</b>	Date of Loss:	11/08/2018 04:00 - :59 [105 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 567079</b>	Policy/Cover Note No.:	29006012QMX (Comprehensive) Coverage: 15/08/2017 - 14/08/2018						
Vehicle Reg. No. (Insured):	<b>SLR4365J</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Fixmate Auto Pte Ltd - Kaki Bukit (HQ)</b> 8 KAKI BUKIT AVENUE 4, #02-37 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Imm.Advice due 15/08/2018]								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK OI NOT REPORTED CONTACT: AH CHAI 8263 2225/9372 7000								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJT6609G (567079)**  
**[SLR4365J]**  
**TP**  
**SEOW POH LAI**  
**Aug 11 2018 4:00AM**  
**[YEO KIM HAN JEREMY]**  
**Fixmate Auto Pte Ltd - Kaki Bukit**


































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	24/08/18 08:55	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: SLR4365J, Claimant: YEO KIM HAN JEREMY</small>	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
22	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
23	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
24	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
25	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
26	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
27	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
28	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
29	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
30	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
31	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
32	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
33	16/08/18 15:44	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	16/08/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/08/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/08/18 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/18 16:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/08/18 16:47	SJT6609G TP E-FILE REPORT	 Load PDF	
2	13/08/18 16:47	PRI - CROSSBORDERS LLC	 Load PDF	
3	13/08/18 17:19	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014704/T1Z4D3E2

Date: 31/08/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29006012QMX

Claimant Vehicle No : SJT6609G

Insured Vehicle No : SLR4365J

Date of Loss: 11/08/2018

Nature of Claim: TP

Claim No: 567079

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJT6609G

Make &amp; Model: MITSUBISHI LANCER, 1.5 MIVEC (A)

Engine No: 4A910126321

Reg. Date: 26/10/2009 (Man. Year: 2009)

Chassis No: JMYSRCY2A9U004336

Colour: Red

Odometer: 158209 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/08/2018

Date Inspected: 14/08/2018 Inspected At:

Fixmate Auto Pte Ltd - Kaki Bukit (HQ)  
8 KAKI BUKIT AVENUE 4, #02-37  
PREMIER @ KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,500.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2018)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.5 MIVEC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT6609G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >