

7/03/2002

ASS. REC. BY:

REF:

CS/CTI18014722/T1td3

Special Instruction:

Surveyor:
menmen

Tuan Fieh

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CPI

Date/Time:

14/8/2018 @ 11:14am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 8350B

Insured:

GBC 2734M

at Workshop m/s

Falcon - Car Auto

Tel:

6779 5665

of

No. 8 penden loop (Blk K / Blk I)

Policy No:

DMCVSN1630041802

Claim No:

SNM18P03904C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/08/2018

CA / REV / REP. / REV 24 HRS

'up'

17/08/18 @ 3pm

H.O.D. Endorsement:

Date/Time:

207pm @ 14/8/18

Person Contacted:

Andy

Vehicle-IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBG 8350B - X

GBC 2734M - X

Vehicle not sent for repair. Pending liability.

Submit next report

(08/11/13) wef

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From: Date: 17/08/2018

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 8350B

at Workshop m/s Falcon Car Auto

of No. 8 penden loop (Blk K / Blk I)

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

3pm @ owner waiting

Make of Veh:

Andy @ 6779 5665

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBG 8350B Yr Regn: 2017, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 c.c. 1461

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 14248 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

USNY B AM 2040154756

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

Survey held at

Falcon Air Penden

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt/O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2018		14 Aug 2018 11:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	SCIMED (ASIA) PTE LTD		
Vehicle Reg. No.:	GBG8350B	Date of Loss:	01/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03904C02	Policy/Cover Note No.:	DMCVSN1630041802
Vehicle Reg. No. (Insured):	GBC2734M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Falcon-air Auto Services Pte Ltd (pandan Loop) (HQ) No. 8 Pandan Loop (Blk K / Blk 1), 128226 West Coast - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/08/2018]		
Adj Asg. Remarks:	EST \$1112.49, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

CHINA TA 3 ANSON RD, SPRINGLEAF				(S) PTE LTD SINGAPORE 079909		Ref : CS/CT118014722/T1td3 Date : 14-08-2018 Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM							
Insured		2734M		Veh. Inspected		GBG 8350B	
Policy No.		VSN1630041802		Coverage (\$)		0.00	
Claim No.		D03904C02		Excess (\$)		0.00	
Assignee		MEN (CHONG BOON		Assign Date		14/08/2018	
2. Vehicle Particulars & Condition							
Make				c.c		0	
Eng.				Year of Reg.			
Chassis				Colour			
Odds				Steering			
				Modification			
3. Conditions of Tyres							
		Make		Balance			
				mm			
				mm			
				mm			
				mm			
4. Description of Damages							
General Information							
18		Inspection Date		17/08/2018			
AIR AUTO SERVICES PTE LTD NDAN LOOP RE 128226							
5a. Remarks							
DUCTED ON A "WITHOUT PREJUDICE" BASIS. R INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							

Denise Tay (LKKAUTO)

From: ANDY <andy@falconair.com.sg>
Sent: Tuesday, 5 March 2019 12:18 PM
To: Denise Tay (LKKAUTO)
Subject: RE: GBG 8350B / CHINA TAI PING / DOA: 01/08/2018

Hi Denise

We haven't repair the vehicle yet.
Liability never advised by China

Regards
Andy

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, March 05, 2019 10:03 AM
To: andy@falconair.com.sg
Subject: RE: GBG 8350B / CHINA TAI PING / DOA: 01/08/2018

Dear Andy,

Can check for me this case? Any repair done? if yes forward me finalize please

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 12 February 2019 12:00 PM
To: 'andy@falconair.com.sg' <andy@falconair.com.sg>
Subject: RE: GBG 8350B / CHINA TAI PING / DOA: 01/08/2018

Dear Andy,

Can check for me this case? Any repair done? if yes forward me finalize please

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/08/2018 12:42
Date Of Accident	01/08/2018 12:45
Exact Location Of Accident	GHIM MOH RD FROM COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8350B
Insured/Policyholder	
Name Of Registered Owner	SCIMED (ASIA) PTE LTD
Co Reg No	199200104H
Email Address	JINGKANG@SCIMED.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96643940

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	509550541`3
Cover Note Number	

Driver

Name of Driver	LOH JING KANG
NRIC No	S9105911H
Date Of Birth	19/02/1991
Occupation	OUTDOOR
Date Of Driving Pass	21/09/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96643940
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 435 HOUGANG AVE 8 (530435)
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : COLLEAGUE
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLANS AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2734M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

GUMMOT RD FROM Commonwealth ave west.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:


[Handwritten signature]

Reporting Centre Personnel's Signature

Name: *B. K. Ng*

NRIC/FIN No.:





REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9105911H



Name

LOH JING KANG

罗敬康

Race

CHINESE

Date of birth

19-02-1991

Sex

M

Country of birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 21 Sep 2012

NP 428A




Licence No. S9105911H



3850365

NRIC No. S9105911H



Date of issue

03-03-2006

Address

APT BLK 435 HOUGANG AVENUE 8
#13-1679
SINGAPORE 530435



**SINGAPORE
POLICE FORCE**



T/20180801/2158

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20180801/2158

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/08/2018 21:04		Vide Report No.: D/20180801/0072		Station Diary No.: 166	
Informant's Particulars					
Name of Informant: LOH JING KANG			Address: APT BLK 435 HOUGANG AVENUE 8 #13-1679 SINGAPORE 530435		
ID Type / ID No.: NRIC NO / S9105911H			Contact No.: Home/Office: Mobile: 96643940		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 19/02/1991	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: SERVICE ENGINEER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/08/2018 12:45	Type of Location: Straight Road
Location: Along Road 1 GHIM MOH ROAD ALONG GHIM MOH ROAD				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC2734M	Lorry					0
GBG8350B	Van				Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20180801/2158

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20180801/2158

CONTINUATION OF REPORT

Brief Details.


On 01/08/2018 at about 1248hrs, I was stationary and outside the yellow box near to the traffic junction along Ghim Moh Road. When the traffic light turned green, the vehicle on my lane was still not moving. I then signal right and wanted to filter to the right lane. I did make a check and ensure that there was ample space and was clear for me to filter my lane.

As I was changing lane, I noticed that there was one lorry who refused to let me change the lane. After changing the lane and a distance away, the lorry was still stationary and keep honking.

Subsequently, as I wanted to make a left turn, the said lorry came from my right and he did not signal and cut in front of me. Due to his action, the side of the lorry swipe against my van.

We got down and a dispute broke out. Police were called in however no one was injured at that point of time.

There was some minor scratches on my van. There is in-built camera installed in my van.



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

SCIMED (ASIA) PTE LTD
NO 196, PANDAN LOOP #07-11, PANTECH IND
COMPLEX, SINGAPORE 128386

Attention : Motor Claim Department
Contact : 7793388 96643940

Estimate : ES003252

Date : 07/08/2018
Vehicle Num. : GBG8350B
Make/Model : NISSAN NV200
Chassis/Eng# :
Accident Date : 01/08/2018
Claim No. :
Reference : TP NTUC VS CHN
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS : FRONT BUMPER		536.10 <i>cut</i>
		Nett Total S\$:		536.10
		10.00% Discount S\$:		53.61
				482.49
		LABOUR : SPRAY PAINTING ON ACCIDENT DAMAGED AREAS TO REPAIR RH FRONT FENDER, RH APRON PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS		350.00 <i>280.</i>
				280.00 <i>200</i>
		Labour Total S\$:		630.00

E. & O.E.

Total S\$: 1,112.49

for FALCON AIR AUTO SERVICES PTE LTD



KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
3 days WP
Reamy before paint
sure@khanto.com
17/8/18 0 315pm

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



DATE: 12/11/18
TIME: 10:00 AM
LOCATION: 12/11/18
SUBJECT: 12/11/18
REFERENCE: 12/11/18
WORK: 12/11/18

STATION: 12/11/18
NO. 12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

STATION: 12/11/18
NO. 12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

12/11/18
12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

12/11/18
12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

12/11/18
12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

12/11/18
12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

12/11/18
12/11/18
12/11/18
12/11/18
12/11/18
12/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		14 Aug 2018 11:14 Edit Adj Rpt	S\$962.49 Edit Estimates	S\$962.49 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SCIMED (ASIA) PTE LTD								
Vehicle Reg. No.:	GBG8350B	Date of Loss:	01/08/2018 00:00 - :59 [9 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03904C02	Policy/Cover Note No.:	DMCVSN1630041802						
Vehicle Reg. No. (Insured):	GBC2734M	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Falcon-air Auto Services Pte Ltd (pandan Loop) (HQ) No. 8 Pandan Loop (Blk K / Blk 1), 128226 West Coast - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/08/2018]								
Adj Asg. Remarks:	EST \$1112.49, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG8350B (SNM18D03904C02)**
[GBC2734M]

TP

SCIMED (ASIA) PTE LTD

Aug 1 2018 12:00AM

[-]

Falcon-air Auto Services Pte Ltd (pandan Loop)

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
2	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
3	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
4	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
5	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
6	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
7	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
8	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
9	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
10	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
11	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
12	05/03/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page



No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/08/18 11:13	REPAIR EST		Load PDF	
2	14/08/18 11:13	TP GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014722/T1TD3E2

Date: 06/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1630041802

Claimant Vehicle
No: GBG8350BInsured Vehicle
No: GBC2734M

Date of Loss: 01/08/2018

Nature of Claim: TP

Claim
No: SNM18D03904C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8350B**

Make & Model: NISSAN NV200, 1.6 (A)

Reg. Date: 31/10/2017 (Man. Year: 2017)

Colour: Grey

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: K9KE628D368932

Chassis No: VSKYBAM20U0154756

Odometer: 19248 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	482.49	482.49	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	480.00	150.00	23.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,112.49	962.49	150.00	13.48
+ GST 7.00/7.00% (\$\$)	77.87	67.37	10.50	13.48
Nett Amount (\$\$)	1,190.36	1,029.86	160.50	13.48

INSPECTION

Date of Assignment: 14/08/2018

Date Inspected: 17/08/2018 Inspected At:

Falcon-air Auto Services Pte Ltd (pandan
Loop) (HQ)
No. 8 Pandan Loop (Blk K / Blk 1)
Singapore 128226

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 06 Mar 2019)
Parts:	N/A	NISSAN NV200 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBG8350B)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	536.10 FN	*536.10 FN
						F=Franchise part. N=NetItemDisc.
Sub Total (\$)					536.10	536.10
- Nett Item Discount on N Items 10.00/10.00% (\$)					53.61	53.61
Total Parts (\$)					482.49	482.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS	New	350.00	280.00
2	TO REPAIR RH FRONT FENDER, RH APRON PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS	New	280.00	200.00
Gross Labour Cost (S\$)			630.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >