

INS. CASE OWNER:

Huang Ng

CC 4, Asm 180 14726, N pa3

LKK:

IDAC:

62941

Surveyor:

N62

DOI:

ASSIGNMENT

14/8/18

Date / Time:

13/08/2018

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDS8596Y

Name of Insured:

TOL YOK LAN

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

10/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8MWRQV

Policy No.:

Make / Model:

Place of Accident:

846 348 YISHUN AVE 11 (C)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SY47466B



INSRS:

WSP:

Tel:

Liability:

RMKS:

kah maw



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SY47466B - X : SDS8596Y - X

14/8/18 OIR. Sent out 1st letter.

21/8/18 - Recd email from TP: TP owner
converted to CD claim23/8/18 - Email to AXA. TP had converted to CD
claim. LKK proceed to use ALE.

23/8/18 - File pass to Merit team to close up

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / OIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LCD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

16/8

Sent By:

Jm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(3

x

days)

Loss of Income (LOI):

S\$

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP (went to)

TP (went to)

CD claim

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 110k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 33Y 24665 Yr Regn: 22 MAY 2018

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.5 TURBO cc 1498

Colour: WHITE A/C: (Insured) / Std / NI / NA

Sp. Reading: 5,320 T/Radio: (Insured) / Std / NI / NA

Eng/No: _____

C/No: MRHFC1660TTC00037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / (STD) R/Rim or

Tyre Size: F: 215/50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 10/8/18 D.O.I. 14/8/18

Survey held at KAH MOTOR MANDAI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

Submit

PIP \$ 1233.35 (Peel \$ 1243.49 / 51%) - excluded check items \$ 272.00

AXA P/P

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / L.B.I: (\$ _____)

Vehicle No SSY2466B**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 11-Aug-18
1950

Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan

Blk 348 Yishun Ave 11 Car Park



A = SSY2466B

B = SDS8596X

Please continue to Annex E.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SJY2466B
 Chassis No : MRHFC1660JT000037
 Model : CIVIC 1.5 TURBO VTIS YM2018
 Owner's Name : HONG WEICHENG
 Ins Policy No. :
 Date of Accident : 10/8/2018

Document No. : SQT18003350 Page 1
 Date : 13. Aug 2018
 Customer No. : WZA006
 Svc Advisor : ANIKKA LAI SWEE KAM
 Engine No : L15B73621209
 Date | Time : 13. Aug 2018 8:09:49 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HONG WEI CHENG OWNER INSURER: AVIVA ACC DATE: 10/08/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA TP VEH: SDS8596Y						
	<p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>						
71101-TEA-T00ZZ	FACEFR.BUMPER X R	1	579.90	25	434.92	30.44	465.36
71103-TEA-T10	GARNISHR.FR.BUMPER SIDE ✓ SCR	1	13.80	25	10.35	0.72	11.07
71108-TEA-T10	GARNISHL.FR.BUMPER SIDE ?	1	13.80	25	10.35	0.72	11.07
71193-TEA-T01	SPACERR.FR.BUMPER SIDE ?	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE ?	1	10.40	25	7.80	0.55	8.35
71102-TBA-A00	GRILLEFR.BUMPER LOWER X 4 ✓	1	67.70	25	50.77	3.55	54.32
71130-TEA-T00	BEAM COMPFR.BUMPER ?	1	335.80	25	251.85	17.63	269.48
91505-TM8-003	CLIPBUMPER ✓ ALL	22	2.00	25	33.00	2.31	35.31
					Sum Item	806.84	56.47
							863.31
BOSUN	SUNDRIES X 10	1	100.00		100.00	7.00	107.00
BKBU01R	REMOVE & RENEW FR BUMPER.	1	1000.00	840 ✓	1000.00	70.00	1070.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	800.00	450 ✓	800.00	56.00	856.00
					Sum Labor	1900.00	133.00
							2,033.00

Survey By : NAZ LKK
 Date & Time : 14/8/18 11:20
 Excess : _____

Total Amount 2,706.84 189.47 2,896.31
Total (Inclusive of GST) 2,896.31

3 Days
 P/P
 AFTER REPAIR PHOTO




Service Request Details

Claim

S8M00RQV

Reference

None 

Loss Date

August 10, 2018

Request Date

August 13, 2018

Due Date

August 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

13082018 @ 2.44pm

Jack veh not in

14082018 @ 11am owner waiting

6A Menda Estate
Kah motor.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJY2466B

Make

TPVD HONDA

Model
CIVIL 1.5

Service Address

...

Primary Contact/Insured

TOH YOK LAN
BLK 276 YISHUN STREET 22, #12-254, 760276, Singapore

KOHSENGCHYE@HOTMAIL.COM

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
-

New Message



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

14 August, 2018

TOH YOK LAN
BLK 276 YISHUN STREET 22
#12-254
SINGAPORE 760276

Dear Sir,

OUR REF : CC4/ASM18014726/Npa3 / S8M00RQV
YOUR REF : SDS 8596Y
ACCIDENT INVOLVING SDS 8596Y & SJY 2466B ON 10/08/2018 ALONG/AT
BLK 348 YISHUN AVE 11 (CARPARK)

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

Hsiao Tong (LKKAuto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Tuesday, 21 August 2018 4:55 PM
To: Hsiao Tong (LKKAuto)
Cc: Anikka Lai; Vic (LKKAuto); Admin A
Subject: RE: Accident between SJY 2466 B AND your insured SDS 8596 Y *** LKK REF: CC4/ASM18014726/Npa3

Dear all,

Kindly take note that our client decided to claim under Own damage.

Thanks and Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

8 MANDAI ESTATE SINGAPORE 729905

TEL : +65 6514 5248 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Wednesday, August 15, 2018 9:35 AM
To: Jack Ng <jackng@honda.com.sg>
Cc: Anikka Lai <anikkalai@honda.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Accident between SJY 2466 B AND your insured SDS 8596 Y *** LKK REF: CC4/ASM18014726/Npa3

Without Prejudice

Hi Jack,

We refer to your below email,

Please be informed that our insured has yet lodge the accident report. Therefore, we are unable to advise liability at this moment.

We will follow up and get back to you asap.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>

Sent: Wednesday, 15 August 2018 9:31 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Anikka Lai <anikkalai@honda.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident between SJY 2466 B AND your insured SDS 8596 Y *** LKK REF: CC4/ASM18014726/Npa3

Good morning Hsiao Tong,

Kindly assist on this case liability states.

Thank you and have a nice day ahead.

Thanks and Best Regards,

Jack Ng

Hp: 8288 6309

Email: jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

8 MANDAI ESTATE SINGAPORE 729905

TEL : +65 6514 5248 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Sent: Tuesday, August 14, 2018 2:57 PM

To: Jack Ng <jackng@honda.com.sg>

Cc: Anikka Lai <anikkalai@honda.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto)

<vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident between SJY 2466 B AND your insured SDS 8596 Y *** LKK REF: CC4/ASM18014726/Npa3

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident and we are currently **pending verification for direct settlement**.

Please provide us evidence i.e. video and scene photo.

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>

Sent: Monday, 13 August, 2018 8:44 AM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor_survey@axa.com.sg>

Cc: Anikka Lai <anikkalai@honda.com.sg>

Subject: Accident between SJY 2466 B AND your insured SDS 8596 Y

Dear all,

Attached is our estimate and GIA report for your kind reference.

Kindly let us know who we look for to arrange surveyor to survey our client vehicle.

Thank you and have a nice days ahead.

Thanks and Best Regards,

Jack Ng


HP: 8288 6309

Kah Motor Co. Sdn. Bhd.


Website: www.honda.com.sg



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

<< <Third Party Converted to OD Claim> - S8M00RQV

Type

🔔 Question

Message

Hi, please be informed that third party had converted to OD claim. In view of this, we will proceed to close file and submit wp report to you good office. Thank you. Hsiao Tong - 23 Aug 2018

Reply

Service Request Details

Claim	S8M00RQV
Reference	CC4/A3M18014726/74px3u2
Loss Date	10 August 2018
Request Date	13 August 2018
Due Date	13 August 2019
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TPP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information	
Incident Vehicle Registration #	SJY2M68B
Make	TPWD HONDA
Model	CRV 1.5
Service Address	
...	
Primary Contact/Insured	
TOH YOK LAN BLK 276 YESHUN STREET 22, #12-25A, 760276, Singapore	
KOHSENGCHYE@HOTMAIL.COM	
Claim Handler	
NG Stacey 6568804351 stacey.ng@axa.com.sg	

Additional Instructions


Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKX SURVEY PHOTOS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TPP)	23 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Email from TP dkt210818.pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	23 August 2018
 TP ESTIMATE - MAIBREID.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 August 2018
 SJY 2466dB vs SDS 8596AY - TP VIDEO.mpg	Evidence	Video	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2018
 Lit to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2018
 GIA REPORT OF SJY2466dB (TP).pdf	Reports & Statement	GIA Report	KADRI Maateen	13 August 2018
 EMAIL.png	Letters and Correspondence	Workshop	KADRI Maateen	13 August 2018

Assessment Details

General & Workshop Details										Vehicle Condition			Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts				
Add		Approve		Decline		Suspend All																			
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	SIBC CUNT%	SALV AGE%	PART PROCENET	ACTION (PARTS)	REMOVE										
	1	1			FACER BUMPER			Repair	0	0	0	0	0	Deny											
	2	1			GARNISH FR BUMPER SIDE			Damaged	10.35		0		10.35	Approve											
	3	1			GARNISH LR BUMPER SIDE ("CHECK) (\$10.35)				0		0		0	Reviewing											
	4	1			SPACERR FR BUMPER SIDE ("CHECK) (\$7.80)				0		0		0	Reviewing											
	5	1			SPACER LR BUMPER SIDE ("CHECK) (\$7.80)				0		0		0	Reviewing											
	6	1			GRILLE FR BUMPER LOWER			Serviceable	0	0	0	0	0	Deny											
	7	1			BEAM COMP FR BUMPER ("CHECK) (\$351.85)				0		0		0	Reviewing											
	8	1			CLIP BUMPER			Necessary	33		0		33	Approve											
	9	1			SUNDRIES			Serviceable	0	0	0	0	0	Deny											
Labour																									
Add		Approve		Decline		Suspend All																			
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HLR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE																
	1		REMOVE & RENEW FR BUMPER	640	0	0	Approve																		
	2		SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	450	0	0	Approve																		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Cancel All

EDIT	SIR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR:3 DAYS	Approve			

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Radio	Parts & Labour	Miscellaneous	Summary's	Claim Amount
Claim Amount		\$1,333.36						\$1,333.36
CATEGORY		ESTIMATE	REVISED AMOUNT					
Spares Parts		\$43.35	\$43.35					
Labour		\$1,290.00	\$1,290.00					