

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB5039B

Ref. No

TAX/08/18/2041

Reg. Date

03/11/2017

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS4

Name of Driver

CHUA AH BENG

Type of Accident

SIDE SWIPE

Date / Time of Accident

08/08/2018 10:00:00 PM

Accident Reported Date / Time: 10/08/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024097469

Special Instruction to ARC, if any :

DROVE IN/SLU341M

Prepared Date

: 10/08/2018 12:48:56 PM



Section B - 10 De Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKB3FU203573575

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

0.00

Total Spray Painting Charges

Total Material Charges

936.00

0.00

Other Charges

6,552.01

6,552.01

TOTAL

700.00

0.00

9,033.01

0.00

Lum Sum Total

0.00

0.00

No. of Repair Days

Prepared / Adjusted Date

5.00 3.00

0.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 10/08/2018 01:49:24 PM

01/01/1900 12:00:00 AM

Remarks

Prepared Date : 10/08/2018 01:49:24 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

ΓAX/08/18/2041 Page: 2

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR RH PORTION	845.00	0.00		
Total Labour	845.00 500	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00 200	0.00
TO RESPRAY FRONT FENDER RH	378.00 200	0.00
TO RESPRAY RIM	180.00 . 100	0.00
Total Spray Painting & Panel Beating	936.00 500	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	8.0.00 50	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 × nn	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00 50	0.00
TO REMOVE AND REFIT TYRE	120.00 50	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00 \$ 50	0.00
TO REPLACE SUNDRY PARTS	100.00 x nn	0.00
TO WASH AND VACUUM	60.00 × 00	0.00
Total Other Costs	700.00	0.00

NA2 LKK 13/8/18 1000 AFTER REPAR PHOTO

LKK Auto Consultants hence notify

the Repairer of the following:

- · To recurvey beforelater apray painting
- To display demaged part(s) during recurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Milhout Projudice" bools
- No illegal modification(s) is allewed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No X R
52115470 50			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	No ?
53801470 80			FENDER SUB-ASSY, FR , RH	1	933.10	25.00	699.82	Replace	Replace	NOXR
53875470 70			LINER, FR FENDER, RH	1	198.40	25.00	148.80	Replace	Replace	No Jor
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No rec
			TYRE	1	126.74	0.00	126.74	Replace	Replace	No Xon
42611- 47450			WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace	No XR
81145476 91			UNIT, HEADLAMP , RH	1	2,558.90	10.00	2,303.01	Replace	Replace	No sca
81210470 20			LAMP ASSY, FOG, RH	1	910.20	10.00	819.18	Replace	Replace	No XSV
TOTAL MATERIALS								5,732.86	5,732.83	70301
	TOTAL MATERIALS(Discounted)							6,552.01	6,552.01	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price	ARC Check	Surveyor	LT Check
TOTAL SUPPLEMENTARY MATERIALS						(4)		Crieck	Check