

23/03/2002

ASS. REC. BY:

REF: CS/EGF/8014746/Klvb3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 14/6/18 @ 3:24pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: 8HD1059 Insured: GBD1496B

at Workshop m/s: premier taxi's Tel: 6544 6682

of 23 chengji south Ave 2 #01-02

Policy No: Claim No: GBD1496B/SL/p1

Sum Insured: Excess: 14/8/2018

Make of Veh: D.O.A. 17/07/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

Date/Time: 3:27pm @ 14/6/18 Person Contacted: wee dek H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	8HD1059 - CC3/AIG 15008797/Hljg 3.2 DOA: 23/5/2015
	GBD1496B - x
4/9/18	Email preli revised to Pei Li

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp G's Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 1059J Yr Regn: 29 Jan 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1800Colour: silver A/C: Insured / Std / NI / NASp. Reading: 214267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA 6M 4x4 MF5659.72

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 14/8/15 D.O.I. 3/9/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/9/18	Chassis P/P \$944.40 / 2 hrs (Red 380, 2990) Ergo

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 2

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

Transportation:

2) 7/9 - typistAdd Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

250

Report Format: TPLump Sum / I.B.I. (\$) 944.40



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GBD 1496B/SL/pl

Our ref: CS/EG118014746/K1vd3

Date : 4/9/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHD 1059J


We thank you for your instruction on 14/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/9/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,324.40
Revised Estimate Amount	: S\$944.40
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

KALVIN ANG

Automotive Assessor / Investigator

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 9:31 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); 'Yee Pei Li'
Cc: SUR
Subject: RE: GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018
Attachments: PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHD 1059J
Date of survey: 3/9/2018
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 14 August 2018 4:39 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018

Dear Pei Li,

Noted, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 14 August 2018 4:34 PM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM
Cc: sur@lkkauto.com
Subject: RE: GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018

Hi,

Enclosed OI & TP's SAS.

Rgds
Pei Li

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 14 August, 2018 3:33 PM
To: Survey Report (ERGO Insurance Pte. Ltd.); ASSIGNMENTS@LKKAUTO.COM
Cc: sur@lkkauto.com
Subject: RE: GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 14 August 2018 3:24 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 14 August 2018 3:24 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBD1496B / TP : SHD1059J/LKK / DOA : 17/07/2018
Attachments: SHD1059J - PRS NOTICE n SAS.pdf; SHD1059J - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 14.08.2018
Our Reference: GBD 1496B/SL/pl
Your Reference: SHD 1059J

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /
gary.shi@premiertaxi.com /
vincent.chua@premiertaxi.com

To: **PREMIER AUTOMOTIVE SERVICES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHD 1059J
Insured's Vehicle: GBD 1496B
Date Of Accident: 14.08.2018


We acknowledge receipt of your request for PRS on: 14.08.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	29 Jan 2016 / 09:52:07	Receipt No.:	AACCK001-AX239-160129-000015
Asset Type:	Vehicle	Transaction Amount:	\$68,670.00
Asset ID:	SHD1059J	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20160129095207939241		
Vehicle No.:	SHD1059J		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	29 Jan 2016		
Original Registration Date:	29 Jan 2016		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5659072		
Engine No.:	D4FDH314435		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,302.00		
Minimum PARF Benefit:	\$13,933.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	29 Jan 2016 09:52:07		
COE No.:	2016012901003610H		
COE Expiry Date:	28 Jan 2024		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,307.00		
Lifespan Expiry Date:	28 Jan 2024		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1059 J

1 pc	Wheel cover <i>brakes</i>	\$ 116.00
	Less 10%	\$ 11.60
		<u>\$ 104.40</u>
S/NETT		
1 set	rear n/s fender sticker <i>new</i>	\$ 60.00
	Sundry <i>new</i>	\$ 50.00 <i>20</i>
	Check alignment	\$ 80.00 <i>20</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 550.00 <i>400</i>
	To putty and spray painting on rear bumper, rear n/s fender	\$ 400.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00 <i>20</i>
		<u>\$ 1,324.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahri 11/11/18

3/9/18 11:10 hr

2 Repair Days

P/P

After Repair-photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair work commencing
- To display damaged parts for resurvey
- Parts prices are to be on "open market" basis
- Third party survey is to be on "open market" basis
- No illegal modification to be made
- Supplemental survey is to be on "open market" basis
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

P/P 944-40




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18014746/K1vd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 12-09-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 1496B	Veh. Inspected	SHD 1059J	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBD1496B/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAGM414MF5659072	Colour	SILVER	
Odometer	214267	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2018	Inspection Date	03/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1059J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-11.60	-11.60
			104.40	104.40
	SPECIAL NETT ITEMS			
1	SET REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			110.00	80.00
	LABOUR			
	CHECK ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME.		550.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR N/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			1,110.00	760.00
	GRAND TOTAL		1,324.40	944.40
RECOMMENDED COST OF REPAIRS				944.40

Report Ref No. CS/EGI18014746/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.