Surveyor NAZ | REF: AXA

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 80K

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 2 days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SLR 2423M Yr Regn: 4 AUG 2017

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: HONDA VEZEL HYBRID c.c 1,496

Colour BROWN A/C: **Insured / Std / NI / NA**

Sp.Reading 67,921 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: ~~DAA-RU3~~ RU3122790 1

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MICHELIN (F), DAVANTI (R)

Front		Rear	
R/Bal.	6 mm	R/Bal.	7 mm
L/Bal.	6 mm	L/Bal.	7 mm
D.O.A.	21/7/18	D.O.I.	14/8/18

Survey held at WORLD AUTO

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	AXA PIC

Date/Time, File Pass to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS.__SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)