COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref : 305199011

Date : 13-8-18

Time of Fax: ____

Via Fax : Encell
Your Insured: SLF 84481

Date of Acc

Attn: Motor Claims Department Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

Fauzy Bin Mokhtar

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

Lim Kwok Eng
 Larry Ng Nyuk Phin
 Lim Tien Siong
 Chiang Liat Choon
 Jumani Bin Masudin
 Tel: 6214 8316 or HP: 9824 0811
 Tel: 6214 8315 or HP: 9635 8546
 Tel: 6214 8314 or HP: 9296 6006
 Tel: 6214 8315 or HP: 9635 5305

Tel: 6214 8315 or HP: 9635 5305 Tel: 6214 8319 or HP: 8125 9176 Fax no. 6546 8156

PLS CALLED

Fauzy.

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President Crash Repairs & Claims Recovery

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

Date/Time^{320 Ubi} 13.36 page 201689 09:11 Page: 1


Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order: 3847100	JC NO.: 305199011
OMER			REGN NO.: SHC8729T	MILEAGE
S OMER NO.	COMFORT TRANSPORTATION PTE 7010045	LTD	MAKE: HYUNDA I	FUELF
FSS -	383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL I-40	DATE/TIME IN 1.08.2018 08:15
(R) (P)	65508755 (O)		YR OF MANU. 05.02.2015	TARGET DATE
UNT CAR	DNO		CHASSIS CODE KMHLB41UMFU064560	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 11.08.2018 NATURE: 3P 11.08.18/B

S/NO

LABOR CODE



of Service Advisor Signature/Date eturned to Service Reception upon collection		Name of Service Advisor Date To be kept by Security Guard		
: No.: SHC8729T	FZ AXA	Vehicle No.: SHC8729T		
vledgement Slip		Exit Pass		
SERVICE ADVISOR	*		CUSTOMER'S	SIGNATURE
CKED & PASSED OUT BY:				
				0
				5
		REAR	TE SE	

COMFORTDELGRO ENGINEERING

A member of COMFORIDELGRO

Name of Attending Staff/Guard

ComfortDelGro Engineering Pte Ltd

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline +65 6383 6280 Facsimile +65 6280 9755
Service Centres
205 Braddell Road Singapore 579701
45 Pandan Road Singapore 609286
7 Sungei Kadut Way Singapore 728791
24 Senoko Loop Singapore 758156

Signature of Attending Staff/Guard

CUSTOMER'S COP'

⊕ 6553 1111 **SPARH** ○ Aggigt Recovery · Towing · Accident



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

b Requisition		
Date: 11 108 2018 Time Received: 0845	3. Vehicle Type:	4. Type of Towing: Normal Tow
New SPARK Kakis	Private Taxi (CTPL/CCPL)	☐ King Dolly
Name of Customer: mo. Musa	Fleet	Flat Bed
Contact No. : 96857420	STK (Boon Lay)	Crane-up
Vehicle No. : SHC 8729T	5. Nature of Service:	6. Parts Replaced/Remarks:
	Jumpstart	
140	Recovery Change Tyre / Battery	
Email :		
Location: 698 Jurong West Central	1.5 - 0.000000000000000000000000000000000	le Tow - In Workshop: Smoky Exhaust
Preferred Workshop:		Overheating Steering Faulty
☐ Braddell ☐ Loyang	I andan	Brake Faulty Alternator Faulty
Sin Ming Sungei Kadut		Starting Problem Loss Power
Senoko Komoco (UBI / Leng Kee)	Oycle a Carriage (i b)	Accident Engine Stalled
Others:	Pipht Side damase	16 .
0. Odometer Reading :	11. Radio / CD Player	HONE
	ок	
Fuel Level : F 1/4 1/2 3/4 E	Faulty	
	☐ Not tested	
ob Attended		
2. Tow Truck / Recovery Van : VRS QA Q	GAO 🗆 TZ 🖃 YISHUN 🔲 OTI	HERS OF THE
Name of Driver : MUTU9AN	TOWING	
Vehicle No. : YP 8480 P	18	
2004		#: Cracked X: Dented /: Scatched Q: Missing
Time Dispatch : U845		7 . Scatched S. Missing
Time of Arrival		1000
Time Completed :		Signature of Customer
ash Invoice Details (if applicable)		
3. Cash Invoice No. :	y	
ustomer Acknowledgement		
. I have been advised to remove all valuable items in my vehicle, inc	cluding Global Positioning System (GPS), at	udio compact disk, thumbdrive, carpark coupor
cash cards, spectacles, pen, etc. I understand that any items left behind are at my own risk and SPA	ARK Car Care™ will not be held liable for s	uch losses.
Surcharge: Towing fee will be levied if the customer decides neither	er to tow nor proceed with the repairs in SI	PARK Car Care™.
1 0		
1/08/2018 1030	·)	~ X//-
Date Tim		Signature of Customer
4. WORKSHOP		1

Date & Time of Arrival

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 By the lodgement of this report to the insurers, you hereby consaforesaid. 	ent to the archiving of this report at the centre and to copies of the report being made available
196 The second cold the second	ACCIDENT STATEMENT
Date Of Report	11/08/2018 11:20
Date Of Accident	11/08/2018 08:15
Exact Location Of Accident	JURONG WEST CENTRAL 1 TWDS JLN BOON LAY
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC8729T
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
lf No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

YES

Insurance Company

MS FIRST CAPITAL INSURANCE LTD Name of Insurance Company THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

Fleet Policy

D-18088936MFSH Policy Number

Cover Note Number

Driver

MUSA B JANTAN Name of Driver NRIC No S0090184I Date Of Birth 05/01/1952 **OUTDOOR** Occupation

19/09/1978 Date Of Driving Pass 39 YEARS AND 10 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-96857420 Mobile Number

Fax Number

Contact Number

EMail Address MUSABJ_05@YAHOO.COM Address

BLK 136 TECK WHYE LANE

#02-297

Postcode

680136

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

: FEMALE

Passenger 2

NAME:

: -

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLF8448R

Vehicle Make/Model/Colour

HONDA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHEN JINPING

NRIC/Passport Number

S8772069A

Contact Number

Address

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

LH FRONT

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No .:

GIARMC SketchPlanForm V3

1

041

Sketch Plan Pg. 2



ON. 11 Ang 2010 @ 88.15 hr I VEH A
was driving along the above location.
going Smay at Suddenly UCH IS from my right
Signif Side dark into my lone and hit wet it
Right Side. WH B lane Duly Can got tun
Right - of the point of accident vet A
ferry 2 par both war on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIARMC SketchPlanForm_V3









