

ASS. REC. BY:

REF:

CS/MS/18014831/Urbn2

Special Instruction:

SURVEYOR

MARQUIS

ASSIGNMENT (Office)

From (Person):

Fievel Foo

of

MSH

Date/Time:

18082018 942am

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHE 3358P

Insured:

FBM 3699Y

at Workshop m/s

SM Automotiv

Tel:

of

Bk 1 Kaki Bukit Ave 6 #01-43

Policy No:

MSD / VNT / 17-374303

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13082018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

15082018 11am

Person Contacted:

Suky

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHE 3358P - NA/DAL18014724 / r3

DA 13082018

FBM 3699Y - x

16/8/18

Send preli revised na merimen

(08/11/13) waf

ASS REC BY: Mervin

REF:

MSIC/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TS / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGE3358Pat Workshop m/s: SM

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE3358P Yr Regn: 1 / 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAIMake: Mazda 6 c.c. 1998Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 48170 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: 3M66J107260221418

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 13/8/18 D.O.I. 15/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Acc O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
6/9/18	2/3 & 2200 confirmed with repairer (Ref 6906-30, 7512)

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

2) 7/9 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

Report Format: merimenLump Sum / I.B.I: (\$ 2200)

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018		15 Aug 2018 09:42 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	MUHAMMAD HISHAM BIN MAHAD, ID: S9715270E			[Created by insurer]
Main Claimant:	LIM TIONG BENG, ID: S1689033B			
Vehicle Reg. No.:	SGE3358P	Date of Loss:	13/08/2018 19:00 - :59 [30 Months and 15 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-374303 (Third Party Only) Coverage: 06/11/2017 - 05/11/2018	
Vehicle Reg. No. (Insured):	FBM3699Y	Policy No. (Claimant):		
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/08/2018]			
Adj Asg. Remarks:	OI not reported, SJE agree - LKK, Contact : Sukyi or Reena at 6747 9241			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 16 Aug 2018

Preliminary Advice

Insured Vehicle No	: FBM3699Y		
TP Vehicle No	: SGE3358P	Accident Date	: 13/08/2018
Make	: MAZDA 6	Assignment Date	: 15/08/2018
Date of Inspection	: 15/08/2018	Est. Duration of Repair	: 3.00
Inspection At	: SM AUTOMOTIVE - KAKI BUKIT (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,106.30
Revised Amount	:S\$	2,789.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,789.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9033B
Vehicle Details	
Vehicle No.:	SGE3358P
Vehicle to be Exported:	No
Intended De-registration Date:	15 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	PE20700859
Chassis No.:	JM6GJ1072G0221418
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,696.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$22,375.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2026
PARF Rebate Amount:	\$16,781.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$55,089.00
COE Rebate Amount:	\$40,924.00
Total Rebate Amount:	\$57,705.00

The information contained herein is correct as at 15 Aug 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9033B

Vehicle Details

Vehicle No.: SGE3358P
Vehicle to be Exported: No
Intended De-registration Date: 15 Aug 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: PE20700859
Chassis No.: JM6GJ1072G0221418
Maximum Power Output: 121.0 kW (162 bhp)
Open Market Value: \$21,696.00
Original Registration Date: 29 Jan 2016
First Registration Date: 29 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$22,375.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jan 2026
PARF Rebate Amount: \$16,781.00

Intended COE Rebate Details

COE Expiry Date: 28 Jan 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$55,089.00
COE Rebate Amount: \$40,924.00
Total Rebate Amount: \$57,705.00

The information contained herein is correct as at 15 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2018 14:36
Date Of Accident	13/08/2018 19:00
Exact Location Of Accident	JUNC OF ANG MO KIO AVE 5 & AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE3358P
Insured/Policyholder	
Name Of Registered Owner	LIM TIONG BENG
NRIC No	S1689033B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96317526
Alternative Phone No	OTHERS-96317526

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00445787
Cover Note Number	

Driver

Name of Driver	LIM TIONG BENG
NRIC No	S1689033B
Date Of Birth	07/07/1965
Occupation	INDOOR
Date Of Driving Pass	12/11/1991
Driving Experience	26 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96317526
Fax Number	
Contact Number	OTHERS-96317526
EMail Address	NOEMAIL

Address	BLK 129 SERANGOON NORTH AVE 1 #10-94
Postcode	550129
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG PING PING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM3699Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE SECOND RIGHT LANE OF A LANE ALONG ANGUS MC KD AVE 5, WHILE TRAVELLING, I CAME TO A STOP BEHIND VEHICLE AT THE JUNCTION WITH ANGUS MC KD AVE 10, DUE TO TRAFFIC RED LIGHT AHEAD. WHILE WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN, ONE MOTORCYCLE FBM 36994 CAME FROM MY REAR AND COLLIDED INTO THE REAR RIGHT PORTION OF MY STATIONARY STOP VEHICLE. AFTER THE ACCIDENT, WE BOTH STOP TO EXCHANGE PARTICULAR AND THE RIDER ALSO ADMITTED HIS FAULT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Police Officer's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

 14/08/18
 Reporting Centre Personnel's Signature
 Name
 NRIC/VIN No.

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

14/08/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 13/07/2018

Estimated repair cost for vehicle no: SGE3358P MAZDA 6 2.0 A 4DR '16

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Rear Boot Lid Emblem Logo	17	\$46.80	X
2	1	Rear Boot Lid Mazda 6 Logo	17	\$43.20	X
3	1	Rear Boot Lid Skyactiv Logo	17	\$71.10	X
4	1	Rear R/H Boot Lid Side Reflector	SCN	\$355.00	—
5	1	Rear R/H Boot Lid Side Reflector Top Moulding	SCN	\$143.30	—
6	1	Rear R/H Tail Lamp	320	\$726.40	—
7	2	Rear R/H Tail Lamp Clip	\$8.00 17	\$16.00	X
8	1	Rear Bumper 1172.80	2200/2	\$1,172.80	—
9	8	Rear Bumper Clip 45	\$6.50 22	\$52.00	—
10	1	Rear Bumper Reverse Sensor (Special Nett)	17	\$350.00	X
11	1	Rear R/H Bumper Side Retainer	17	\$39.00	X
12	1	Rear R/H Fender	17	\$1,255.00	X
13	1	Rear Exhaust	17	\$1,745.70	X
14	1	Rear Exhaust Chrome Pipe	17	\$220.00	X

20%

Subtotal: \$6,236.30

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Affected
Lbr
2200/2
3rd party repair
15/8/18

16/8/18

2442.50
202
1954
labour 830
2784
less 202
2227.20

Labour charges

To remove & refit cushion	\$280.00	60
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear exhaust	11 \$280.00	X
Tuff kote	11 \$150.00	X
To check wiring	\$60.00	20
Panel beating	\$1,000.00	300
Spray painting	\$1,000.00	400

Subtotal:- \$2,870.00

Total:- \$9,106.30

830

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014831/UVBN2

Date: 07/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/17-374303-CA	Claim No:	MSC/118-001100
Claimant Vehicle No :	SGE3358P	Insured Vehicle No :	FBM3699Y		
Date of Loss:	13/08/2018	Nature of Claim:	TP		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGE3358P	Engine No:	PE20700859
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1072G0221418
Reg. Date:	29/01/2016 (Man. Year: 2015)	Odometer:	48170 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,236.30	1,954.00	4,282.30	68.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	830.00	2,040.00	71.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,106.30	2,784.00	6,322.30	69.43
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	9,106.30	2,200.00	6,906.30	75.84

INSPECTION

Date of Assignment:	15/08/2018	
Date Inspected:	15/08/2018 Inspected At:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2018)
 Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGE3358P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID EMBLEM LOGO	Not Necessary	46.80 F	*- FL
2	1		*REAR BOOT LID MAZDA 6 LOGO	Not Necessary	43.20 F	*- FL
3	1		*REAR BOOT LID SKYACTIV LOGO	Not Necessary	71.10 F	*- FL
4	1		*REAR R/H BOOT LID SIDE REFLECTOR	Scratched	355.00 F	*355.00 FL
5	1		*REAR R/H BOOT LID SIDE REFLECTOR TOP MOULDING	Scratched	143.30 F	*143.30 FL
6	1		*REAR R/H TAIL LAMP	Broken	726.40 F	*726.40 FL
7	2		*REAR R/H TAIL LAMP CLIP	Not Necessary	16.00 F	*- FL
8	1		*REAR BUMPER	Deep Cut	1,172.80 F	*1,172.80 FL
9	1		*REAR BUMPER CLIP	Necessary	52.00 F	*45.00 FL
10	1		(8 Pcs) *REAR R/H BUMPER SIDE RETAINER	Not Necessary	39.00 F	*- FL
11	1		*REAR R/H FENDER	Repair	1,255.00 F	*- FL
12	1		*REAR EXHAUST	Not Necessary	1,745.70 F	*- FL
13	1		*REAR EXHAUST CHROME PIPE	Not Necessary	220.00 F	*- FL
14	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 6,236.30 2,442.50
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 488.50

Total Parts (\$\$) 6,236.30 1,954.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	280.00	60.00
2	TO REMOVE & REFIT REVERSES ENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR EXHAUST	New	280.00	-
4	TUFF KOTE	New	150.00	-
5	TO CHECK WIRING	New	60.00	20.00
6	PANEL BEATING	New	1,000.00	300.00
7	SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,870.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >