

22/03/2002

A.S. REC. BY:

REF: CS/msh18014833/Dsbez Special Instruction:

Survivor:

merimen

Bryan

ASSIGNMENT (Office)

From (Person):

Irene Tam

of

msh

Date/Time:

14/08/2018 4:25pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 1015R

Insured:

SKN 7862D

at Workshop m/s

Chunni Motor

Tel:

65425119

of

Sit 10 Amk Wd Park 2A #03-19

Policy No:

A80355660DMX

Claim No:

567179

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/08/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

15/08/2018 10:54am

Person Contacted:

Lynn

Vehicle: IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SHC 1015R - NS/INC17024066 / Klvbn2

DA: 16-12-2017

SKN 7862D - x

3/9/18

Send preli revised via merimen

# ASSIGNMENT

COR 2025 July


From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **BHC 1015R** Yr Regn: **July / 2017**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /  
 Truck / Trailer or  
 Make: **Toyota Prius** c.c. **1798**  
 Colour: **Blue** A/C: Insured / Std / NI / NA  
 Sp. Reading: **133364** T/Radio: Insured / Std / NI / NA  
 Eng/No: **2ZR8055899**  
 C/No: **5TDKB3FU803561236**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **Good** / Jammed / Leaked / Burnt or  
 Brake: **Good** / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **195/65 R15**  
 R: **— " —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Westlake**

Front	Rear
R/Bal. <b>S</b> mm	R/Bal. <b>S</b> mm
L/Bal. <b>S</b> mm	L/Bal. <b>S</b> mm
D.O.A. <b>12/08/2018</b>	D.O.I. <b>15/08/2018</b>
Survey held at <b>Churni AMC</b>	

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**N/S Front y 4/3 Body**  
 The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **13** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	<b>MSIG SKN 7862 D</b>

**25/09/18** **Ynaju** **2/3 13,000/- with 13 days**  
**25/09/18** **Confirmed 4/5 13,000/- @ 13 days with Bryan**  
**(6,364.18 Red - 33%)**

RECEIVED 27 SEP 2018

Date/Time, File Pass to?  
**27/09/18**  
 1) **Typist**  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: **13**  
 Resurvey No. of Trip: **2**

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

Survey Fee:	<b>200</b>
Transportation:	
Photos	
Others	<b>10</b>

Report Format :  
 Lump Sum / I.B.I: (\$ **13,000/- 4/5**)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018		14 Aug 2018 16:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY), ID: S8106111D, Tel: +6596233868</b>		<b>[Created by insurer]</b>
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R</b>		
Vehicle Reg. No.:	<b>SHC1015R</b>	Date of Loss:	12/08/2018 09:00 - :59 <b>[13 Months and 7 Days From LTA Reg Date (Man Yr)]</b>
Claim Type:	<b>TP / 567179</b>	Policy/Cover Note No.:	<b>A80355660QMX(COMP) (Comprehensive)</b> Coverage: 08/10/2017 - 08/04/2019
Vehicle Reg. No. (Insured):	<b>SKN7862D</b>	Policy No. (Claimant):	
		Excess:	<b>S\$500.00</b>
Repairer:	<b>Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162</b>		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]</b>		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2018]</b>		
Driver/Custodian (Insured):	<b>SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY) (37 / Female), NRIC: S8106111D, Tel: +6596233868</b>		
Adj Asg. Remarks:	<b>LIABILITY IN DISPUTE (PLS OUTSOURCE TO LKK AUTO ) Kindly arrange to survey at SOON HOCK MOTOR @ #01-05/06 AMK AUTOPOINT Please contact the workshop directly @ 6483 6016.</b>		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 03 Sep 2018
<b><u>Preliminary Advice</u></b>	

Insured Vehicle No	: SKN7862D	Accident Date	: 12/08/2018
TP Vehicle No	: SHC1015R	Assignment Date	: 14/08/2018
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 13.00
Date of Inspection	: 15/08/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,369.18
Revised Amount	:S\$	16,534.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	16,534.28
Lump Sum Repair	:S\$	
<b>Total Loss Consideration</b>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

MCD618103927 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 13/08/2018 10:49  
 SUBMITTED BY: Huang XiaoYan

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2018 10:49
Date Of Accident	12/08/2018 10:00
Exact Location Of Accident	SYED ALWI RD TWDS JLN BESAR
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1015R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHUA KEONG HIN
NRIC No	S1744531F
Date Of Birth	03/03/1966
Occupation	OUTDOOR
Date Of Driving Pass	15/02/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85553395
Fax Number	
Contact Number	
Email Address	CHUAKEONGHIN@YAHOO.COM.SG

Address BLK 651 PUNGGOL CENTRAL #10-306  
 Postcode 820651  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1

NAME: : -  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO ATTACHED / Type Of Accident : 3P OPEN DOOR

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKN7862D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.  
 Nature Of Damage LEFT REAR DOOR

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303921R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/8/18 at about 100thm while I Veh A was driving along the left lane, Veh B opened the Right Rear door and collided on the left portion of my moving vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303921R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**CHUNNI MOTOR WORK PTE LTD**

**REPAIR ESTIMATE**

VEHICLE NO : SHC 1015R

MAKE :

MODEL : TOYOTA PRIUS

LKK Auto Consultant DATE: 13.08.2018

the Repairer of the following

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TEL NO : 6542 5119

FAX NO : 6542 6039

MSIG

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>1st</i>		\$	950.50 ✓
LAMP ASSY, FOG, LH <i>broken</i>		\$	920.00 ✓
FRONT BUMPER COVER <i>broken</i>		\$	499.90 ✓
FRONT BUMPER CLIPS <i>Heu</i>		\$	22.00 ✓
FRONT BUMPER SIDE RETAINER, LH <i>SVC</i>		\$	77.00 X
BRACKET, FRONT BUMPER SIDE, LH <i>SVC</i>		\$	82.30 X
UNIT ASSY, HEADLAMP, LH (LED) <i>broken 1st</i>		\$	3,455.00 ✓
HEAD LAMP PANEL (LH) <i>1st</i>		\$	213.50 <i>2L</i>
TOP PANEL SIDE <i>2 1st</i>		\$	69.20 <i>2L</i>
BRACKET, HEADLAMP MOUNTING, LH <i>SVC</i>		\$	25.50 X
FENDER SUB-ASSY, FRONT LH <i>Dented</i>		\$	945.00 ✓
FRONT HOUSING ASSY <i>2 Dented</i>		\$	958.30 <i>2L</i>
FRONT FENDER SHIELD <i>SVC</i>		\$	196.60 X
FRONT FENDER SHIELD CLIP <i>SVC</i>		\$	3.80 X
FRONT FENDER HYBRID EMBLEM, LH <i>Heu</i>		\$	53.50 ✓
PANEL SUB-ASSY, REAR DOOR, LH <i>Dented</i>		\$	1,258.30 ✓
MIRROR ASSY, OUTER REAR VIEW, LH <i>broken</i>		\$	1,390.00 ✓
WIRING FRONT <i>2nd Choke housing</i>		\$	8,450.50 <i>2L</i>
SUB TOTAL			\$ 19,570.90
LESS 25%			\$ 4,892.73
DISCOUNTED TOTAL			\$ 14,678.18
FRONT DOOR COMFORT LOGO <i>Heu</i>			\$ 75.00 NETT ✓
REAR DOOR COMFORT & APPS STICKER <i>Heu</i>			\$ 80.00 NETT ✓
FRONT TYRE (LH) <i>SVC</i>			\$ 216.00 NETT X
			\$ 371.00
LABOUR CHARGE			
Panel Beating		\$	1,500.00 <i>800/-</i>
Spray Painting Charge		\$	1,800.00 <i>800/-</i>
Wiring Charge		\$	50.00 <i>30/-</i>
Tuff Kote		\$	100.00 <i>40/-</i>
Transfer of Door		\$	120.00 <i>60/-</i>
Remove/Refix Dashboard		\$	450.00 <i>150/-</i>
Remove/Refix Fuse Box		\$	180.00 <i>50/-</i>
FRT Wheel Alignment		\$	120.00 <i>60/-</i>
TOTAL LABOUR			\$ 4,320.00
ESTIMATE TOTAL			\$ 19,369.18

19195.70

14389.27

155.00

1990/-

15/08/2018 e 1345h

Not done

2/3mm

13 days

1990/-

LKK Auto

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

16534.27

1/5 13000/-

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2018		14 Aug 2018 16:25 <a href="#">Edit Adj Rpt</a>	<b>S\$13,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$13,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
















































  















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY)</b> , ID: S8106111D, Tel: +6596233868								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHC1015R</b>	Date of Loss:	12/08/2018 09:00 - :59 [13 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 567179</b>	Policy/Cover Note No.:	A80355660QMX(COMP) (Comprehensive) Coverage: 08/10/2017 - 08/04/2019						
Vehicle Reg. No. (Insured):	<b>SKN7862D</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Chunni Motor Work Pte Ltd (HQ)</b> Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... <b>[Final Rpt due 13/09/2018]</b>								
Driver/Custodian (Insured):	SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY) (37 / Female), NRIC: S8106111D, Tel: +6596233868								
Adj Asg. Remarks:	LIABILITY IN DISPUTE (PLS OUTSOURCE TO LKK AUTO ) Kindly arrange to survey at SOON HOCK MOTOR @ #01-05/06 AMK AUTOPOINT Please contact the workshop directly @ 6483 6016.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


## Claim Documents

**\*SHC1015R (567179)**  
**[SKN7862D]**  
**TP**  
**COMFORT TRANSPORTATION PTE LTD**  
**Aug 12 2018 9:00AM**  
**[SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY)]**  
**Chunni Motor Work Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	15/08/18 14:22	Video - Accident						Load AVI		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	14/08/18 13:55	Accident Statement From: SC - Reg. No: SKN7862D, Claimant: SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY)						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/09/18 15:15	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/09/18 15:51	Front View Right						Load JPG	<input checked="" type="checkbox"/>	
2	22/09/18 15:51	Front View Left						Load JPG	<input checked="" type="checkbox"/>	
3	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
4	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
5	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
6	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
7	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
8	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
9	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
10	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
11	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
12	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
13	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
14	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
15	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
16	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
17	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
18	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
19	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
20	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
21	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
22	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
23	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
24	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
25	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
26	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
27	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	
28	22/09/18 15:51	General View						Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
36	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
38	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
58	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
59	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
60	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
61	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
62	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
63	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
64	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
65	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
66	22/09/18 15:51	General View	 Load JPG	<input checked="" type="checkbox"/>
67	22/09/18 15:51	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
68	22/09/18 15:51	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
69	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
79	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	22/09/18 15:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
86	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
87	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
88	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
89	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
90	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
91	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
92	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
93	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
94	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
95	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
96	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
97	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
98	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
99	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
100	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
101	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
102	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
103	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
104	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
105	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
106	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
107	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
108	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
109	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
110	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
111	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
112	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
113	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
114	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
115	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
116	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
117	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
118	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
119	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
120	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
121	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
122	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
123	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
124	22/09/18 15:52	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/08/18 13:55	TPD SHC1015R GIA REPORT From: SC - Reg. No: SKN7862D, Claimant: SEOW FENG YANG CANDY (XIAO FENGYANG, CANDY)	 Load PDF	

Video			1 per page	<input type="checkbox"/>
No	Finalized On		Thumbnail	Print
2	14/08/18 14:12	MSIG Insurance (Singapore) Pte. Ltd. (HQ) TPD SHC1015R - ESTIMATE REPAIR	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014833/DSBE2

Date: 27/09/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80355660QMX(COMP)

Claimant Vehicle No : SHC1015R

Insured Vehicle No : SKN7862D

Date of Loss: 12/08/2018

Nature of Claim: TP

Claim No: 567179

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC1015R

Make &amp; Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS055899

Reg. Date: 05/07/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU803561236

Colour: Blue

Odometer: 133364 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,049.17	14,544.27	504.90	3.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,990.00	2,330.00	53.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,369.17</b>	<b>16,534.27</b>	<b>2,834.90</b>	<b>14.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,000.00</b>		
<b>(S\$)</b>	19,369.17	13,000.00	6,369.17	32.88
<b>+ GST 7.00/7.00% (S\$)</b>	1,355.84	910.00	445.84	32.88
<b>Nett Amount (S\$)</b>	<b>20,725.01</b>	<b>13,910.00</b>	<b>6,815.01</b>	<b>32.88</b>

## INSPECTION

Date of Assignment: 14/08/2018

Date Inspected: 15/08/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)  
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19  
AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 13.0 days



---

**Adjuster:** BRYAN TANI**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC1015R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	950.50 FL	*950.50 FL
2	1		*LAMP ASSY, FOG, LH	Broken	920.00 FL	*920.00 FL
3	1		*FRONT BUMPER COVER	Broken	499.90 FL	*499.90 FL
4	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*FRONT BUMPER SIDE RETAINER, LH	Serviceable	77.00 FL	*- FL
6	1		*BRACKET, FRONT BUMPER SIDE, LH	Serviceable	82.30 FL	*- FL
7	1		*UNIT ASSY, HEADLAMP, LH (LED)	Broken / Cut	3,455.00 FL	*3,455.00 FL
8	1		*HEAD LAMP PANEL (LH)	Bent	213.50 FL	*213.50 FL
9	1		*TOP PANEL SIDE	Bent	69.20 FL	*69.20 FL
10	1		*BRACKET, HEADLAMP MOUNTING, LH	Serviceable	25.50 FL	*- FL
11	1		*FENDER SUB-ASSY, FRONT LH	Dented	945.00 FL	*945.00 FL
12	1		*FRONT HOUSING ASSY	Dented	958.30 FL	*958.30 FL
13	1		*FRONT FENDER SHIELD	Serviceable	196.60 FL	*- FL
14	1		*FRONT FENDER SHIELD CLIP	Serviceable	3.80 FL	*- FL
15	1		*FRONT FENDER HYBRID EMBLEM, LH	Necessary	53.50 FL	*53.50 FL
16	1		*PANEL SUB-ASSY, REAR DOOR, LH	Dented	1,258.30 FL	*1,258.30 FL
17	1		*MIRROR ASSY, OUTER REAR VIEW, LH	Broken	1,390.00 FL	*1,390.00 FL
18	1		*WIRING FRONT	Housing Cracked	8,450.50 FL	*8,450.50 FL
19	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
20	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
21	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>19,941.90</b>	<b>19,340.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>4,892.73</b>	<b>4,796.43</b>
<b>Total Parts (S\$)</b>	<b>15,049.17</b>	<b>14,544.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,500.00	800.00
2	SPRAY PAINTING CHARGE	New	1,800.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TRANSFER OF DOOR	New	120.00	60.00
6	REMOVE / REFIX DASHBOARD	New	450.00	150.00
7	REMOVE / REFIX FUSE BOX	New	180.00	50.00
8	FRT WHEEL ALIGNMENT	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,320.00</b>	<b>1,990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >