

22/03/2002

ASS. REC. BY:

REF:

CS3/msh18014834/Tizubaz

Special Instruction:

Surveyor
Melvin

Taufik.

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSLH

Date/Time:

14082018 4:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 2681Z

Insured:

GBE 2496P

at Workshop m/s

AMA Autocare

Tel:

8778 2636

of

3b Tuh Guan Rd East #01-36

Policy No:

28626861MKC

Claim No:

667210

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04082018

CA / REV / REP. / REV 24 HRS 1WP

H.O.D. Endorsement:

Date/Time:

15082018 10:15am

Person Contacted:

Melvin

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKH 2681Z - X

GBE 2496P - X

15/8/18

Disassembled.

16/8/18

After repair.

Tanpin

REF:


MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

PRS

Veh No. SKH2681Z Yr Regn: 2009 / Aug
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Amore C.C. 1496
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 156930 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: GJ11307563
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15
 R: 7"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 15/8/18 @ 11am

Survey held at AMA Poh Guan

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$3,000 - \$4,000

1/9/18 submit PRS report

Johnnie Range + No. of repair.
 31/8/2018

Date/Time. File Pass to?

: Preli. Report
 : Final Report

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + PS \$

) Photos

) Other

)

TOTAL

120
10
130

Date/Time. File Return to?

2)

Add Fee: Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Report Format: PRS

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18014834/T1z4b	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-08-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBE 2496P	Veh. Inspected	SKH 2681Z
Policy No.	28626861MKC	Coverage (\$)	0.00
Claim No.	567210	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	14/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/08/2018	Inspection Date	15/08/2018
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		14 Aug 2018 16:28 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

<input type="button" value="Main"/>	<input type="button" value="Reference"/>	<input type="button" value="Claim Details"/>	<input type="button" value="Documents"/>	<input type="button" value="Show All"/>
-------------------------------------	--	--	--	---

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	S.S. KIM ENTERPRISES PTE LTD, Co. Reg. No.: 200105920F	
Main Claimant:	GLISSADE LEASING PTE LTD, Co. Reg. No.: 201708966M	
Vehicle Reg. No.:	SKH2681Z	Date of Loss: 04/08/2018 00:00 - :59 [107 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567210	Policy/Cover Note No.: 28626861MKC Coverage: 13/10/2017 - 12/10/2018
Vehicle Reg. No. (Insured):	GBE2496P	Policy No. (Claimant):
Repairer:	Ama Automotive Pte Ltd () 36 Toh Guan Road East #01-36, 608580 Jurong East - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2018]	
Adj Asg. Remarks:	OI NON REPORTING. LIABILITY NOT CLEAR. Contact: Mr Melvin - 8778 3636	

ASSOCIATED MAIL RECEIVED	
There are no mail for this case.	
<input type="button" value="View All"/>	<input type="button" value="Compose Case Mail"/>

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8966M
Vehicle Details	
Vehicle No.:	SKH2681Z
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A5209233
Chassis No.:	GJ11307563
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,534.00
Original Registration Date:	27 Aug 2009
First Registration Date:	27 Aug 2009
Transfer Count:	3
Actual ARF Paid:	\$17,534.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2019
PARF Rebate Amount:	\$9,643.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$1,509.00
Total Rebate Amount:	\$11,152.00

The information contained herein is correct as at 24 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/08/2018 15:06
Date Of Accident	04/08/2018 13:45
Exact Location Of Accident	ALONG PIE TWDS CHANGI (AFT TOH GUAN FLYOVER)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKH2681Z
Insured/Policyholder	
Name Of Registered Owner	GLISSADE LEASING PTE LTD
Co Reg No	201708966M
Email Address	REPORTING@AUTOINSURE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-31572626
Vehicle Particulars	
Manufacturer	HONDA
Model	AIRWAVE-1.5 M (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	100863558
Cover Note Number	
Driver	
Name of Driver	TEO GIM KIAT
NRIC No	S7011809B
Date Of Birth	10/04/1970
Occupation	OUTDOOR
Date Of Driving Pass	23/06/1988
Driving Experience	30 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87550100
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 105C EDGEFIELD PLAINS #03-65
Postcode	823105
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NPP
Police Station Address	ROAD: 461 TAMPINES ST 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2496P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180804/2080

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

2 of 3

Report No. T/20180804/2080

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date time and location, after exiting from Toh Guan Flyover and onto the filter lane, I was travelling on the middle lane when a traffic accident occurred in front of me. I then slowed down and suddenly, I felt a impact from my rear. I realized another vehicle (GBE2496P) had collided onto my rear. I was waiting for the other party to stop to alight and make a check however the said party subsequently drove off.

I wish to state that the whole incident was captured on my onboard CCTV and the impact cause the rear of my vehicle to be slightly dented.

Accident Sketch Plan



POLICE FORCE

T/20180804/2080

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

3 of 3


Report No. T/20180804/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 HO CHUN HAO, PATRICK	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 04/08/2018 15:34
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authentication Stamp NP168	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

T/20180204/2080

<p>Important: You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.</p>		- Reporting Only
		- Claim OD
		- Claim TP
		- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



 Policyholder's signature
 Date & Time




 Driver's Signature
 (if driver not the policyholder)
 Date & Time

 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.

Accident Sketch Plan Pg. 1



Land Transport Authority



This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	04/06/2018



Accident Sketch Plan Pg. 1



001101 01 05 0410 000
EAS 0510412 010

COVER NOTE

Cover Note No. 100563556		Date 20 Jul 2018	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder			
SCHEDULE			
Policyholder	Glissade Leasing Pte Ltd		
Age Condition	N/A	Registration No	SKR2661Z
Policy Type	THIRD PARTY COMMERCIAL MOTOR	Make/Model	Honda Airwave 1.5L VTEC
Effective Date	22 Jul 2018	CC/Tonnage	1,496.00
Expiry Date	21 Jul 2019	Engine No	L15A5209233
Hire Purchase Company	NA	Chassis No	GJ11307563
		Year of Registration	2009
<p>This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.</p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none"> 1 Use only for social, domestic and pleasure purposes and for the Policyholder's business. 2 Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p>			
<p>MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)</p>			
CERTIFICATE OF INSURANCE			
<p>We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)</p>			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.

Authorised Representative

054114

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		14 Aug 2018 16:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	S.S. KIM ENTERPRISES PTE LTD, Co. Reg. No.: 200105920F		
Main Claimant:	GLISSADE LEASING PTE LTD, Co. Reg. No.: 201708966M		
Vehicle Reg. No.:	SKH2681Z	Date of Loss:	04/08/2018 00:00 - :59 [107 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567210	Policy/Cover Note No.:	28626861MKC Coverage: 13/10/2017 - 12/10/2018
Vehicle Reg. No. (Insured):	GBE2496P	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Automotive Pte Ltd () 36 Toh Guan Road East #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 15/08/2018]		
Adj Asg. Remarks:	OI NON REPORTING. LIABILITY NOT CLEAR. Contact: Mr Melvin - 8778 3636		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKH2681Z (567210)**
[GBE2496P]
TP
GLISSADE LEASING PTE LTD
Aug 4 2018 12:00AM
[S.S. KIM ENTERPRISES PTE LTD]
Ama Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
2	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
3	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
4	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
5	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
6	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
7	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
8	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
9	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
10	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
11	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
12	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
13	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
14	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
15	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
16	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
17	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
18	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
19	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
20	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
21	16/08/18 15:40	General View		Load JPG	<input checked="" type="checkbox"/>			
22	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
23	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
24	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
25	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
26	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
27	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
28	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
29	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
30	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
31	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
32	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
33	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
34	16/08/18 15:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>			
35	24/08/18 10:02	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
36	24/08/18 10:02	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			
37	24/08/18 10:02	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/08/18 10:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	24/08/18 10:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	24/08/18 10:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	24/08/18 10:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/08/18 15:15	TP PRI NOTICE	 Load PDF	
2	14/08/18 15:16	TP PRI REQUEST EMAIL	 Load PDF	
3	14/08/18 15:16	TP REJECT SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014834/T1Z4BE2
Date: 04/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28626861MKC
Claimant Vehicle No : SKH2681Z	Insured Vehicle No :	GBE2496P
Date of Loss: 04/08/2018	Nature of Claim:	TP
		Claim No: 567210

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH2681Z	Engine No:	L15A5209233
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11307563
Reg. Date:	27/08/2009 (Man. Year: 2008)	Odometer:	156930 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/08/2018	Inspected At:	Ama Automotive Pte Ltd
Date Inspected:	15/08/2018		36 Toh Guan Road East #01-36
			Singapore 608580
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2018)	
Parts: M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKH2681Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >