

22/03/2012

ASS. REC. BY:

REF: CS/MSH18014535 / Ks bez Special Instruction:

\*SUMMARY:  
merimer

## ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSLH

Date/Time:

14082018 4:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 3913T

Insured:

SKL 3656U

at Workshop m/s

Trust Autoworks

Tel:

9108 2728

of

Bik 5035 AMK Ind Park 2 #01-345

Policy No:

A28626177QMY

Claim No:

567142

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

15082018 10:23am

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SJT 3913T - NA / LPC18014573 / h4

DIA: 09082018

SKL 3656U - X

13/09/18

@ 17:47 p.m. revised IA to Katherine Wong via merimer.

13/09/18

Anthony mention Owner's IC is correct. LTA Can't Search  
So registration date Can't reach.

ASS. REC. BY:

REF:

MSG/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJT 39237 Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or MPVMake: Honda Stream C.G. \_\_\_\_\_Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 195785 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RNG 1084360Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: Mic 205/85R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 8 mmL/Bal. 8 mm

D.O.A. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/8 File pass to Catherine, GIA &amp; Est not ready

Parts Price checked by Kenneth

13/09/18 Confirmed L/S \$1,900/- @ 5 days with Kenneth.

(\$1,981.28 Red - 51%)

RECEIVED 14 SEP 2018

Date/Time, File Pass to?

14/09/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$Survey Fee: 150Transportation: S + RS \$

Fees

Others

TOTAL

150
10
160

Report Format :

Lump Sum / I.B.I: (\$ 1,900/- L/S)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2018		14 Aug 2018 16:27 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YIAW KIN GIAP, ID: S25112701		
Main Claimant:	ONG SWEE KAR, ID: S2022503C		
Vehicle Reg. No.:	SJT3923T	Date of Loss:	09/08/2018 20:00 - :59 [106 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567142	Policy/Cover Note No.:	A28626177QMY (Comprehensive) Coverage: 30/07/2017 - 29/10/2018
Vehicle Reg. No. (Insured):	SKL3656U	Policy No. (Claimant):	
		Excess:	
Repairer:	Trust Autoworks - Ang Mo Kio (HQ) Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2, 569538 Ang Mo Kio - Tel: 91082728		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2018]		
Driver/Custodian (Insured):	CLARENCE YIAW JIN LIANG (), NRIC: S90504943, Tel: +6591294253		
Adj Asg. Remarks:	Liability 100%. TP agree with SJE - assign Kenneth Kong of LKK Auto Consultants Pte Ltd. Contact: Mr Anthony Cheong (9108 2728).		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 13 Sep 2018

**Preliminary Advice**

Insured Vehicle No	: SKL3656U	Accident Date	: 09/08/2018
TP Vehicle No	: SJT3923T	Assignment Date	: 14/08/2018
Make	: HONDA STREAM	Est. Duration of Repair	: 5 days
Date of Inspection	: 16/08/2018		
Inspection At	: Trust Autoworks - Ang Mo Kio (HQ) Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2 Singapore 569538		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,881.28
Revised Amount	:S\$	1,900.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,900.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/08/2018 15:48
Date Of Accident	09/08/2018 20:45
Exact Location Of Accident	MILLENIA WALK CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT3923T
-----------------------------	----------

### Insured/Policyholder

Name Of Registered Owner	ONG SWEE KAR
NRIC No	S2022503C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96980456
Alternative Phone No	Office-96980456

### Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05015528
Cover Note Number	-

### Driver

Name of Driver	TOH WEI JIE
NRIC No	S8417779B
Date Of Birth	03/06/1984
Occupation	OUTDOOR
Date Of Driving Pass	14/03/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97952338

Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	370 ALEXANDRA RD #02-16
Postcode	159953
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : UNKNOWN Gender: : Male
Passenger 2	Name: : UNKNOWN Gender: : Female
Passenger 3	Name: : UNKNOWN Gender: : Female
Passenger 4	Name: : UNKNOWN Gender: : Female

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL3656U
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CLARENCE YIAW JIN LIANG

NRIC/Passport Number

S9050494J

Contact Number

91294253

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 11.08.18  
11.00am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



A) SJT3923T

B) SKL3656U

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting the gantry, mine vehicle was stationary suddenly vehicle (B) came out from the left side parking lot and hit onto my left side portion

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

11-08-18  
11:00am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

11b

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/P 91082728

Fax : 64816131

Ong Swee Kar  
Blk 403 Bukit Batok West Ave 7  
#07-15 Singapore 850403

Vehicle No : SJT 3923 T  
Make : Honda Stream  
Year : 2009

*Not Authorized*  
*L1/L2 @ 1900h*  
*Penalty After 1900h*  
*5 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear n/s tail-lamp assy - reuse	858.30
1 pc	Rear n/s fender dent	
1 pc	Rear bumper deform	588.90
1 pc	Rear n/s bumper side retainer	new

Sum	\$485.10	X
2	\$925.60	✓
Sum	\$950.70	✓
1.1	\$65.20	✓
	\$2,426.60	
Less 20 %	\$485.32	
	\$1,941.28	

## S Nett

1 pc	Rear n/s fender glass sealant
10 pcs	Rear bumper clip

Sum	\$55.00	✓
2.50	\$25.00	✓
	\$80.00	

## Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,000.00	600
To putty & spray paint on accident affected portion.	\$600.00	400
Check/reconnect wiring.	\$40.00	150
To spray anti rust on accident affected portion.	\$120.00	300
Remove/refir rear n/s fender glass to facilitate repair	\$100.00	600
<b>Total</b>	<b>\$3,881.28</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Aug 2018		14 Aug 2018 16:27 <a href="#">Edit Adj Rpt</a>	<b>\$1,900.00</b> <a href="#">Edit Estimates</a>	<b>\$1,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	YIAW KIN GIAP, ID: S2511270I								
Main Claimant:	ONG SWEE KAR, ID: S2022503C								
Vehicle Reg. No.:	SJT3923T	Date of Loss:	09/08/2018 20:00 - :59						
Claim Type:	TP / 567142	Policy/Cover Note No.:	A28626177QMY (Comprehensive) Coverage: 30/07/2017 - 29/10/2018						
Vehicle Reg. No. (Insured):	SKL3656U	Policy No. (Claimant):							
		Excess:							
Repairer:	Trust Autoworks - Ang Mo Kio (HQ) Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2, 569538 Ang Mo Kio - Tel: 91082728								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/09/2018]								
Driver/Custodian (Insured):	CLARENCE YIAW JIN LIANG (), NRIC: S9050494J, Tel: +6591294253								
Adj Asg. Remarks:	Liability 100%. TP agree with SJE - assign Kenneth Kong of LKK Auto Consultants Pte Ltd. Contact: Mr Anthony Cheong (9108 2728).								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJT3923T (567142)  
[SKL3656U]  
TP  
ONG SWEE KAR  
Aug 9 2018 8:00PM  
[YIAW KIN GIAP]  
Trust Autoworks - Ang Mo Kio

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

**View** [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	14/08/18 10:51	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: SKL3656U, Claimant: YIAW KIN GIAP</small>		Load HTM	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>		Thumbnail	Print
1	13/09/18 17:47	<b>Adjuster Immediate Advice</b>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
<b>LKK Auto Consultants Pte Ltd (HQ)</b>					
1	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	13/09/18 13:26	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>
9	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	13/09/18 13:26	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>
11	13/09/18 13:26	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	13/09/18 13:27	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
13	13/09/18 13:27	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
14	13/09/18 13:27	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>
15	13/09/18 13:27	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b>					
1	14/08/18 10:51	<b>SJT3923T E-FILE REPORT</b> <small>From: SC - Reg. No: SKL3656U, Claimant: YIAW KIN GIAP</small>		Load PDF	
2	14/08/18 10:54	<b>TP agree SJE - assign LKK</b>		Load PDF	
3	14/08/18 10:55	<b>tp pri request email</b>		Load PDF	
4	14/08/18 10:55	<b>pri notice</b>		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> </div>			

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014835/KSBE2

Date: 14/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28626177QMY

Claimant Vehicle No: SJT3923T

Insured Vehicle No: SKL3656U

Date of Loss: 09/08/2018

Nature of Claim: TP

Claim No: 567142

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT3923T

Make &amp; Model: HONDA STREAM, 1.8 X (A)

Engine No: HIDDEN

Reg. Date: (Man. Year: )

Chassis No: RN61084360

Colour: Metallic Silver

Odometer: 195785 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Michelin 8 mm

Rear Left Side: Falken 7 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,021.28	1,274.92	746.36	36.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,105.00	755.00	40.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,881.28	2,379.92	1,501.36	38.68
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	3,881.28	1,900.00	1,981.28	51.05

INSPECTION

Date of Assignment: 14/08/2018

Date Inspected: 16/08/2018 Inspected At:

Trust Autoworks - Ang Mo Kio (HQ)  
Blk 5035, #01-345 Ang Mo Kio Industrial  
Pk 2  
Singapore 569538

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT3923T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S TAIL-LAMP ASSY	Serviceable	485.10 FL	*- FL
2	1		*REAR N/S FENDER	Bent	925.60 FL	*858.30 FL
3	1		*REAR BUMPER	MTG Cracked	950.70 FL	*588.90 FL
4	1		*REAR N/S BUMPER SIDE RETAINER	Distorted	65.20 FL	*65.20 FL
5	1		*REAR N/S FENDER GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
6	10		*REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,506.60</b>	<b>1,577.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>485.32</b>	<b>302.48</b>
<b>Total Parts (\$\$)</b>	<b>2,021.28</b>	<b>1,274.92</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	600.00	400.00
3	CHECK / RECONNECT WIRING	New	40.00	15.00
4	TO SPRAY ANTI-RUST ON ACCIDENT AFFECTED PORTION	New	120.00	30.00
5	REMOVE / REFIT REAR N/S FENDER GLASS TO FACILITATE REPAIR	New	100.00	60.00
Gross Labour Cost (S\$)			1,860.00	1,105.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >