

INSD33

INS. CASE OWNER:

valc | CC 4 <sup>ASm</sup> / AXA1801 4850, T1 y67LKK:  
IDAC:

Surveyor:

Tan Jiah.

DOI:

ASSIGNMENT

15/8/18

Date / Time:

15/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 32970

Name of Insured:

EWAN WENG MUN

Insured Tel No.:

HP:

96194071

Excess Sec II :\$5

D.O.A.:

14/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S8MD0044 / 63297

Policy No.:

VPA / P1970593

Make / Model:

TUMBUH

Place of Accident:

IMPT OF LKKA

If NO, Driver Name / Age:

Driver Tel No.:

(V/L-YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

VL 21732

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:sin  
shengINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

16/8/18

Jog

Smartclaim

ONE

HEAD TO REAR

18-3-19

2-4-19

SUR PHOTOS UPLOADED BY J  
IA UPLOADED  
449 W/OI (OVERSEAS) AGNED  
7 NAME NCA ISSUE

STAGE

DATE / PIC

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup):

Call OI:

27-8-19 JOY

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PTR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3-4-19

Confirm with:

SUJAN

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

\$54,173

Loss of Rental (LOR):

\$5

( days)

Loss of Use (LOU):

\$5

800 (510 x 8 days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

2.4x

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$54,975.72

Global Sum \$5:

4,975

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

4,975.72

Name 1:

SIN SHENG ENGINEERING SERVICES

Payee 2: (Strike if N.A.)

\$5

X

Name 2:

X

Payee 3: (Strike if N.A.)

\$5

X

Name 3:

X

COPY SENT  
8/10/18

(08/11/13) web

ASS. REC. BY: Tan M

REF: AXA

## ASSIGNMENT

6E - 2022 Sep

From: Date: 15/8/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: YL2173L

at Workshop m/s Sin Seng Engineering

of 3-tech park crescent

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: YL2173L

Yr Regn: 2002, Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi FE63

CC 3908

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 653498

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FE6391A 4544L

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00 R16

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austine

Front

Rear

R/Bal. 6 mm

R/Bal. 4/1 mm

L/Bal. 6 mm

L/Bal. 6/1 mm

D.O.A.

D.O.I. 15/8/18 @ 1390

Survey held at

Sin Seng

Des. of Damages: Frt / Rear / O/S / (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV 22K.

30-6-18 L/S \$3,900

R(\$4,205.79/52%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

: Site Insp (\$ )

☐

: Interview (\$ )

☐

: Tech. Invs (\$ )

☐

: Weekend (\$ )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18014850/jb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 15-08-2018	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLR 3297D	Veh. Inspected	YL 2173L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/08/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>3. General Information</b>				
Accident Date	14/08/2018	Inspection Date		
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002568

Date : 14/08/2018

Vehicle Num. : YL2173L

Make/Model : MITSUBISHI FE 639-2002

Chassis/Eng# : FE639EA43446/4D34J12368

Accident Date : 14/08/2018

Claim No. :

Reference : SLR3297D

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER		Mix X 534.05
2.	1	STEP GARNISH, LHS		X 175.20
3.	1	UPPER FENDER		cut 368.50
4.	1	DOOR GARNISH, LHS		Mix 215.20
5.	1	REAR MUDGUARD		de 295.40
6.	1	REAR LAMP, LHS		ad 275.50
7.	1	DOOR GARNISH, LHS		nv X 195.20

List TotalS\$ :

2,059.05

25.00% Discount S\$ :

514.76

1,544.29

NETT ITEMS :				
1.	1	STEP BRACKET		bt 250.00
2.	1	SIDE GUARD, LHS		Rw 280.00
3.	1	SLIDING DOOR, LH		bt 1,500.00
4.	1	SPRING LOCK, LH		bt 85.00
5.	1	T LOCK		bt 70.00
6.	1	REAR MUDGUARD, RR		de 350.00
7.	1	TAILGATE CONTROL BOX		mis 550.00
8.	1	TYRE		nv X 180.00
9.	1	STOP BRACKET		bt 70.00

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002568

Date : 14/08/2018

Vehicle Num. : YL2173L

Make/Model : MITSUBISHI FE 639-2002

Chassis/Eng# : FE639EA43446/4D34J12368

Accident Date : 14/08/2018

Claim No. :

Reference : SLR3297D

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
10.	1	TAILGATE MOTOR		1,200.00
		Nett Total S\$ :		4,535.00
		10.00% Discount S\$ :		453.50
				4,081.50
		LABOUR :		
		TO PANEL BEAT/REPAIR LH BODY		800 950.00
		TO REPAIR REAR ALUMINUM BOX		
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING		500 900.00
		TO CHECK/REPAIR TAILGATE SYSTEM		300 550.00
		TOWING CHARGES		? 80.00
		LOSS OF USE : 8 DAYS @ S 180/DAY		
		Labour Total S\$ :		2,480.00

Total S\$ : 8,105.79

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final 97495749  
- WP  
15/8/18 @ 180pm  
Resurvey after repair  
6 days  
sur@lkkauto.com

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002568

Date : 14/08/2018

Vehicle Num. : YL2173L

Make/Model : MITSUBISHI FE 639-2002

Chassis/Eng# : FE639EA43446/4D34J12368

Accident Date : 14/08/2018

Claim No. :

Reference : SLR3297D

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
<hr/>				
		LIST ITEMS :		
1.	1	FRONT BUMPER	X	534.05
2.	1	STEP GARNISH, LHS	X	175.20
3.	1	UPPER FENDER	cut X	368.50
4.	1	DOOR GARNISH, LHS	X	215.20
5.	1	REAR MUDGUARD	de	295.40
6.	1	REAR LAMP, LHS	am	275.50
7.	1	DOOR GARNISH, LHS	X	195.20
		List Total S\$ :		2,059.05
		25.00% Discount S\$ :		514.76
				<hr/> 1,544.29
		NETT ITEMS :		
1.	1	STEP BRACKET	H	250.00
2.	1	SIDE GUARD, LHS	R	280.00
3.	1	SLIDING DOOR, LH	bt	1,500.00
4.	1	SPRING LOCK, LH	bt	85.00
5.	1	T LOCK	bt	70.00
6.	1	REAR MUDGUARD, RR	de	350.00
7.	1	TAILGATE CONTROL BOX	mis	550.00
8.	1	TYRE	X	180.00
9.	1	STOP BRACKET	bt	70.00

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002568

Date : 14/08/2018

Vehicle Num. : YL2173L

Make/Model : MITSUBISHI FE 639-2002

Chassis/Eng# : FE639EA43446/4D34J12368

Accident Date : 14/08/2018

Claim No. :

Reference : SLR3297D

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
10.	1	TAILGATE MOTOR		× 1,200.00
		Nett Total S\$ :		4,535.00
		10.00% Discount S\$ :		453.50
				4,081.50
		LABOUR :		
		TO PANEL BEAT/REPAIR LH BODY	8 <sup>00</sup>	950.00
		TO REPAIR REAR ALUMINUM BOX		
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING	5 <sup>00</sup>	900.00
		TO CHECK/REPAIR TAILGATE SYSTEM	3 <sup>00</sup>	550.00
		TOWING CHARGES	?	80.00
		LOSS OF USE : 8 DAYS @ \$ 180/DAY		
		Labour Total S\$ :		2,480.00

Total S\$ : 8,105.79

SIN SHENG ENGINEERING SERVICES

Tan Jiah 9749 5749

- WP

15/8/18 @ 130pm

Resumy after repair

6 days

sur@lkhant.com

Lump Sum 23900



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1196N

### Vehicle Details

Vehicle No.:

YL2173L

Vehicle to be Exported:

No

Intended De-registration Date:

31 Dec 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

FE639E6SRDE

Primary Colour:

White

Manufacturing Year:

2002

Engine No.:

4D34J12368

Chassis No.:

FE639EA43446

Maximum Power Output:

-

Open Market Value:

\$22,127.00

Original Registration Date:

17 Sep 2002

First Registration Date:

17 Sep 2002

Transfer Count:

0

Actual ARF Paid:

\$1,107.00

### Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

### Intended COE Rebate Details

COE Expiry Date:

28 Feb 2022

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$40,549.00

COE Rebate Amount:

\$12,840.00

**Total Rebate Amount:**

**\$12,840.00**

The information contained herein is correct as at 14 Aug 2018

OK





## Service Request Details

Claim

S8M00RYX

Reference

None 

Loss Date

August 14, 2018

Request Date

August 14, 2018

Due Date

August 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

14/08/2018 @ 3.15pm  
Susan veh in.  
Sin Sheng

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

YL2173L

Make

TPVD MITSUBISHI

Model

CANTER-3.9 D FE639E6SRDE (M)

Service Address

---

...

Primary Contact/Insured

---

KWAN WENG MUN

40 HILLCREST ROAD, 288915, Singapore

S\_KWM@YAHOO.COM.SG

Claim Handler

---

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

INSD GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

---

[New Message](#)



## Re:MANDATE IA

Type

🔗 Question

Message

Hi Did you keep Insured updated on the matter. If yes, pls proceed as per IA-VO.

Reply

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/08/2018

### Survey Details:

Date of loss	14-Aug-18
Date of appointment	15-Aug-18
Date of survey	15-Aug-18
Location of survey	SIN SHENG ENGINEERING SERVICES

### Vehicle Details:

Claim Type:	Third party
Vehicle number	YL 2173L
Make and Model	MITSUBISHI FE639EA43446
Date of registration	17/9/2002
Excess	
Market Value	\$22,000
Part Rebate	\$12,840
Nett Loss	\$9,160

### Repair details:

Initial Estimate	\$ 8,105.79
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 3,292.05
Check items (estimate)	
Labour	\$ 1,600.00
<b>Total</b>	<b>\$ 4,892.05</b>
Lump Sum(if applicable)	\$ -
	\$ 3,900.00
Number of days for repair	6



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

**Remarks:**

*We have not authorized repairs. HEAD TO REAR ; OUR VEHICLE  
BEHIND ;BOLA 27*

**Mandate:**

Liability(TP)		100%
Proposed repair cost	\$	4,173.00
Loss of rental	\$	1,200.00
LTA search fees	\$	2.00
<b>Proposed Total</b>	<b>\$</b>	<b>5,375.00</b>

\$150 x 8 days

Your Insured's vehicle : SLR3297D

Our customer's vehicle : YL2173L

Date : 14/08/2018

## AXA INSURANCE PTE LTD

Dear Sirs,

**DATE OF ACCIDENT : 14 AUG 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION**

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. YL2173L.

Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services

Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129

Contact : Ms Susan / Ms Cheryl Yuan

Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below. Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

*NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.*

Your sincerely,

*Susan*

### Acknowledgement

This is to confirm that I <u>Tan Kah</u> (Full Name of Surveyor)	
of <u>Wick</u> (Surveyor's Company)	
have completed the pre-repair inspection on <u>15/8/18</u> (Date of Inspection)	
at <u>330</u> (Time of Inspection)	
<u>[Signature]</u>	<u>Susan</u>
Signature of Appointed Surveyor	Witnessed By:
Company Stamp	Date

### Waiver

We waive our rights to an inspection/survey of the above vehicle.	
Signature _____	
Name :	
Date :	



新盛机械工程服务

**SIN SHENG ENGINEERING SERVICES**

REGISTRATION NO : 312029/00D

No 3; Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

31-Aug-18

LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1, #02-25  
Paya Ubi Industrial Park  
Singapore 408933

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2018/0276

Your ref: S8M00RYX MC/VO

Attn: Ms Joy

Dear Sir,

**VEHICLE: YL2173L (DoA: 14/08/2018)**

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	4,173.00
Loss of Use: 8 days @ S\$ 180/day (including 2 day for PRI)	:	1440.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	2.00
Total	:	<b>5,615.00</b>

Thank You

Yours faithfully

**Susan Tan**  
**OPERATIONS EXECUTIVE**

Encl



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

27 AUGUST 2018

**KWAN WENG MUNG**  
40 HILLCREST ROAD  
SINGAPORE 288915

Dear Sir/Madam,

OUR REF : CC4/ASM18014850/T1jb3  
YOUR REF : SLR 3297D

**ACCIDENT INVOLVING SLR 3297D AND YL 2173L ALONG ALEXDRA ROAD ON 14.08.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SIN SHENG ENGINEERING SERVICES, acting on behalf of the owner of YL 2173L against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit Third Party vehicle from the rear. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Joy Irene  
Case Handler  
DID: 6841 2409  
FAX: 6741 4108  
Email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com)

c.c. AXA Insurance Singapore Pte Ltd (AXA)  
(Motor Claims Dept)

### AUTHORIZATION TO ACT

I, GOLDBELL LEASING PTE LTD ("The Third Party Claimant") of

NO 59, SENOKO ROAD, SINGAPORE 758123 (address),

being the owner of YL2173L (vehicle no.) hereby authorize

SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me

with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my

vehicle bearing registration no. YL2173L that was damaged pursuant to the accident

which occurred on 14/08/2018 along Alexandra Road

involving vehicle's YL2173L / SLR3297D ("the accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability in so far as the driver/owner/insurers of the other vehicle is concerned.

Dated this 23 day of AUG (month) 2018 (year)


Signed by "the Third Party claimant"



Signed by "the workshop"



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLR 3297D (Insd veh)	Model: MITSUBISHI CANTER FE83
	YL 2173L (TP veh)	
Date of Accident/ Time:	14/08/18 09:30	

Repair Estimate	: \$	8,673.20	
Final Repair Cost	: \$	3,900.00	
Loss of Use	: \$	800.00	8 days at \$ 100 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
Final Settlement Sum	GLOBAL SUM	: \$	4,975.00 ALL-IN

Payee Name: SIN SHENG ENGINEERING SERVICES

Is Third Party Workshop GIA Registered? [ ] YES [X] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:

#### NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: Date:	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: Date:
 Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date:	

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Tax Invoice : TI002568

Date : 31/08/2018

Vehicle Num. : YL2173L

Make/Model : MITSUBISHI FE 639-2002

Chassis/Eng# : FE639EA43446/4D34J12368

Accident Date : 14/08/2018

Claim No. : S8M00RYX MCVO

Reference : SLR3297D

Policy No. : 29004183

Amount S\$

ACCIDENT LUMP SUM REPAIR

3,900.00



SIN SHENG ENGINEERING SERVICES

M9-0010014-J

Total S\$ :	3,900.00
GST @ 7% S\$ :	273.00
Amount Due S\$ :	4,173.00

=====



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-124250  
Date of Request: 14/08/2018

Your Ref No: Online Purchase

Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129

Dear Sir/Madam,

YL2173L (DoA:14/08/2018)  
Owner : GBL

Enquiry Date 14/08/2018  
Enquiry By Wang Sye Yuen  
TP Vehicle No. SLR3297D  
Accident Date 14/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR 3297D (Insd veh)	Model:	MITSUBISHI FE63
	YL 2173L (TP veh)		
Date of Accident:	14/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		8,673.20
Final Repair Cost	:	\$		4,173.00
Loss of Use	:	\$		800.00
				8days at \$100.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,975.00

Is Third Party Workshop GIA Registered?	[ ] YES	[ X ] NO	(Kindly indicate below)
---	---------	----------	-------------------------

A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
-------------------------------------	---------------------------------

B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks	<div style="border-bottom: 1px solid black; height: 1.2em; margin-bottom: 2px;"></div> <div style="border-bottom: 1px solid black; height: 1.2em; margin-bottom: 2px;"></div>
---------	---

<b>Payment Instruction: Payee's Breakdown</b>			
1)	SIN SHENG ENGINEERING SERVICES	:	\$ 4,975.00

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

13/05/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014850/T1jb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:VALE OH

Date : 13-05-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLR 3297D	Veh. Inspected	YL 2173L
Policy No.	VPA/P1970593	Coverage (\$)	0.00
Claim No.	S8M00RYX	Excess (\$)	0.00
Assign From		Assign Date	15/08/2018

**2. Vehicle Particulars & Condition**

Make & Model	MITSUBISHI FE63	c.c	3908
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	FE639EA43446	Colour	WHITE
Odometer	653498	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	7.00 R16	AUSTONE	6 mm
L/H Front Tyre	7.00 R16	AUSTONE	6 mm
R/H Rear Tyre	7.00 R16 (D)	AUSTONE	6/6 mm
L/H Rear Tyre	7.00 R16 (D)	AUSTONE	6/6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	14/08/2018	Inspection Date	15/08/2018
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YL 2173L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	NOT NECESSARY	534.05	-
1	STEP GARNISH ,LHS (CONSISTENT)	NOT NECESSARY	175.20	-
1	UPPER FENDER (CONSISTENT)	CUT	368.50	368.50
1	DOOR GARNISH ,LHS (CONSISTENT)	NOT NECESSARY	215.20	-
1	REAR MUDGUARD (CONSISTENT)	DEFORMED	295.40	295.40
1	REAR LAMP ,LHS (CONSISTENT)	CRACKED	275.50	275.50
1	DOOR GARNISH ,LHS (CONSISTENT)	NOT NECESSARY	195.20	-
	LESS 25% DISCOUNT		-514.76	-234.85
			1,544.29	704.55
<b>NETT ITEMS</b>				
1	STEP BRACKET (N) (CONSISTENT)	BENT	250.00	250.00
1	SIDE GUARD ,LHS (N) (CONSISTENT)	TO REPAIR SEE LABOUR	280.00	-
1	SLIDING DOOR ,LH (N) (CONSISTENT)	BENT	1,500.00	1,500.00
1	SPRING LOCK ,LH (N) (CONSISTENT)	BENT	85.00	85.00
1	T LOCK (N) (CONSISTENT)	BENT	70.00	70.00
1	REAR MUDGUARD ,RR (N) (CONSISTENT)	DEFORMED	350.00	350.00
1	TAILGATE CONTROL BOX (N) (CONSISTENT)	MISSING	550.00	550.00
1	TYRE (N) (CONSISTENT)	NOT NECESSARY	180.00	-
1	STOP BRACKET (N) (CONSISTENT)	BENT	70.00	70.00
1	TAILGATE MOTOR (N) (CONSISTENT)	NOT NECESSARY	1,200.00	-
	LESS 10% DISCOUNT		-453.50	-287.50
			4,081.50	2,587.50
<b>LABOUR</b>				
	TO PANEL BEAT /REPAIR LH BODY.TO REPAIR REAR ALUMINIUM BOX.TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF SIDE GUARD ,LHS .		950.00	800.00
	SPRAY PAINTING.		900.00	500.00
	TO CHECK /REPAIR TAILGATE SYSTEM.		550.00	300.00

Report Ref No. CC4/ASM18014850/T1jb3q2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGES.	NOT NECESSARY	80.00	-
			2,480.00	1,600.00
GRAND TOTAL			8,105.79	4,892.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC4/ASM18014850/T1jb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim# SM000RYX

Reference CCA/ASM10014850/T1j0a2

Loss Date 14 August 2018

Report Date 14 Aug 2018 12:47:08 PM

Request Date 13 November 2018

Due Date

Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration # YL2173L

Make TPVO MITSUBISHI

Model CANTER-3.9 D FE639E65BDE (M)

Service Address

Primary Contact/Insured

KWAN WEING MUN

40 HILLCREST ROAD, 288915, Singapore

S\_KWM@YAHOO.COM.SG

Claim Handler

OH Vale

6568004897

vale.oh@axa.com.sg















Additional Instructions INSD QUA NOT REPORTED

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merlimen	
LKKInvoice3.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 LOO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 DS FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	13 May 2019
 MANDATE 1A - SUN SHENG.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2019
 GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2019
 SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 March 2019
 Non reporting letter.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	16 August 2018
 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	16 August 2018
 P1970593_C1_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	14 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 01970593_NB_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	14 August 2018
 TP FBI FROM WORKSHOP WITH GUA REPORT.mig	Letters and Correspondence	Workshop	DHAKAL Raghav	14 August 2018