

ASS. REC. BY:

REF:

cs/FCI/8014879/Nsd300

Special Instruction:

Surveyor:

Naz

aws

## ASSIGNMENT (Office)

From (Person):

Kerren Tan

of

FCI

Date/Time:

14/8/18 @ 6:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 80254

Insured:

SHC 2726R

at Workshop m/s

Bike production

Tel:

6392 2555

of

610 Springoon Road

Policy No:

Claim No:

D18005859 MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/07/2018

CA / REV / REP. / REV 24 HRS

(wp)

16/8/18

H.O.D. Endorsement:

Date/Time:

3:47pm @ 15/8/18

Person Contacted:

Wendy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

FBK 80254-x

SHC 2726R - NSI/NCI/001865/Fg

DOA: 27/01/2011

20/08/18

@ 09:09 a.m. revised PA to Karen via email.

to check with Marcus

(08/11/13) wef

ASS. REC. BY:

NAZ

REF:

FCI

## ASSIGNMENT

From:

Date:

16/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBK 80254

at Workshop m/s

Bike Production

of

G10 Serangoon Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

15K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1/2

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBK 80254

Yr Regn:

2 FEB 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA CB400X ABS c.c 399

Colour:

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

69,044

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH2NC4796 EK000385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/60 R17

R:

160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

—

mm

L/Bal.

—

mm

D.O.A.

31/7/18

D.O.I.

16/8/18

Survey held at

BIKE PRODUCTION

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/12/18

Submit Prel. report due to insured Consent to OD claim.

FCI L/S

Submit 2/5 \$10,600/- @ 5 days

(\$7,144.50 Red. 40%)

5/10/2018

RECEIVED 03 DEC 2018

Date/Time, File Pass to?

03/12/18

1)

Typ:st

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

7x11

105470

50

50

81

156

Report Format :

Lump Sum / I.B.I: (\$ 10,600/- 45)

**MOTOR SURVEY ASSIGNMENT**

|                           |                              |                                      |
|---------------------------|------------------------------|--------------------------------------|
| <b>Date</b>               | 02-08-2018                   | <b>Our Ref No.</b> D18005859MFSH     |
| <b>Accident Date</b>      | 31-07-2018                   | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHC2726R                     | <b>Third Party Vehicle.</b> FBK8025U |
| <b>Survey Location</b>    | 610 SERANGOON ROAD           |                                      |
| <b>Contact Person.</b>    | MR KWAN S.H                  |                                      |
| <b>Contact No.</b>        | 63922555/ 0                  | <b>Fax No.</b> 62975400              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:           |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD |                                      |
| <b>Contact Person</b>     | NA                           | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                           |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                         |                                |
|--------------------------|-------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | BIKE PRODUCTION PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | APAC LAW CORPORATION    | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | KARENT                  |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014879/Nsd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 15-08-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SHC 2726R       | Veh. Inspected | FBK 8025U  |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | D18005859MFSH   | Excess (\$)    | 0.00       |
| Assign From  | CWS (KAREN TAN) | Assign Date    | 15/08/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                   |                 |            |
|----------------|-------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 31/07/2018                                                        | Inspection Date | 16/08/2018 |
| Survey held at | BIKE PRODUCTION PTE LTD<br>610 SERANGOON ROAD<br>SINGAPORE 218216 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

|                               |                   |
|-------------------------------|-------------------|
| Vehicle Owner Particulars     |                   |
| Owner ID Type:                | Singapore NRIC    |
| Owner ID:                     | 5558J             |
| Vehicle Details               |                   |
| Vehicle No.:                  | FBK8025U          |
| Vehicle to be Exported:       | No                |
| Intended Deregistration Date: | 04 Oct 2018       |
| Vehicle Make:                 | HONDA             |
| Vehicle Model:                | CB400X ABS        |
| Primary Colour:               | Black             |
| Manufacturing Year:           | 2015              |
| Engine No.:                   | NC47E5000387      |
| Chassis No.:                  | JH2NC4796EK000385 |
| Maximum Power Output:         | -                 |
| Open Market Value:            | \$6,516.00        |
| Original Registration Date:   | 02 Feb 2016       |
| First Registration Date:      | 02 Feb 2016       |
| Transfer Count:               | 1                 |
| Actual ARF Paid:              | \$978.00          |
| Intended PARF Rebate Details  |                   |
| PARF Eligibility:             | No                |
| PARF Eligibility Expiry Date: | -                 |
| PARF Rebate Amount:           | \$0.00            |
| Intended COE Rebate Details   |                   |
| COE Expiry Date:              | 01 Feb 2026       |
| COE Category:                 | D - Motorcycle    |
| COE Period(Years):            | 10                |
| QP Paid:                      | \$6,512.00        |
| COE Rebate Amount:            | \$4,770.00        |
| Total Rebate Amount:          | \$4,770.00        |

The information contained herein is correct as at 04 Oct 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Sbk E <sbk5643e@yahoo.com>  
**Sent:** Saturday, 27 October 2018 9:34 AM  
**To:** Naz (LKKAuto)  
**Cc:** Shirley Hiew (LKK Auto)  
**Subject:** Re: FBK 8025U FINALIZATION

[Without Prejudice]

Dear Naz,

Good Day. The insured has decided to claim under his own insurance as there is a waiver on his excess. Thank you very much for your attention and sorry for the inconvenience caused.

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

---

On Fri, 10/26/18, Naz (LKKAuto) <Naz@lkkauto.com> wrote:

Subject: FBK 8025U FINALIZATION  
To: "Sbk E" <sbk5643e@yahoo.com>  
Cc: "Shirley Hiew (LKK Auto)" <ShirleyHiew@lkkauto.com>  
Date: Friday, October 26, 2018, 5:38 PM

Dear Mr Kwan

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS -  
\$12,220

LESS 10% -  
\$10,998

SPECIAL NETT -  
\$1,170

LABOUR -  
\$1,060

LESS  
LUMP SUM 20% - \$10,582

LUMP  
SUM TOTAL - \$10,600/ 5 REPAIR DAYS

Thank  
you.

Best Regards,

Naz |  
Technical Investigator

LKK Auto  
Consultants

Phone: 6841-2157 |  
Email: Naz@lkkauto.com |  
Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park,  
Ubi Avenue 1, #02-25 | S(408933)

From: Naz (LKKAuto)

Sent: Wednesday, 10 October 2018 11:59:14 AM

To: Sbk E

Cc: Shirley Hiew (LKK Auto)

Subject: Re: AFTER REPAIR PHOTOS - FBK8025U

Dear Mr Kwan ,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS  
- \$11,900  
LESS  
10% - \$10,710  
LABOUR  
- \$2,230  
LESS LUMP SUM 20% -  
\$10,352  
TOTAL -  
\$10,300/ 5 REPAIR DAYS

Thank  
you.

Best  
Regards,  
Naz |  
Technical Investigator  
LKK Auto  
Consultants  
Phone:  
6841-2157 | Email: Naz@lkkauto.com |  
Fax: 6256-4315  
Blk 51, Paya Ubi  
Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E  
<sbk5643e@yahoo.com>

Sent: Sunday, 9 September 2018 8:13 AM

To: Naz (LKKAuto)

Subject: RE: AFTER REPAIR PHOTOS - FBK8025U

Dear  
Naz,

Please finalise. Thanks.

Regards,



Kwan S. H.

Director

Bike Production Pte Ltd

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 20 August 2018 9:09 AM  
**To:** 'karentan@msfirstcapital.com.sg'; 'Claim Workflow System'  
**Cc:** 'SUR'; 'ASSIGNMENTS@LKKAUTO.COM'; 'Nivitha (LKK Auto)'  
**Subject:** RE: SURVEY ASSESSMENT - D18005859MFSH/1  
**Attachments:** FBK 8025U - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of FBK 8025U.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 15 August 2018 3:49 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** karentan@msfirstcapital.com.sg; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18005859MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Tuesday, 14 August 2018 6:56 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** karentan@msfirstcapital.com.sg; cwsmotorclaims@msfirstcapital.com.sg  
**Subject:** PRI: SURVEY ASSESSMENT - D18005859MFSH/1

Please find below link to download document  
[Jobsheet\\_D18005859MFSH\\_TPD1.pdf](#)

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005859MFSH

Date: 20 August 2018

Our Ref: CS/FCI18014879/Nsd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. FBK 8025U .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/08/2018 at the premises of M/s Bike Production Pte Ltd and have the following to report:-

|                          |                          |
|--------------------------|--------------------------|
| Workshop Estimate Amount | : S\$ <u>17,276.50</u> . |
| Revised Estimate Amount  | : S\$ <u>1,060.00</u> .  |
| "Check" Items Amount     | : S\$ <u>4,486.00</u> .  |
| Market Value             | : S\$ _____ .            |
| LTA Reimbursement Value  | : S\$ _____ .            |
| Nett Value               | : S\$ _____ .            |

**Description of Damage:**

The vehicle sustained damages at the front portion & o/s body.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 5 Days

Yours faithfully,  
Muhammad Nazril  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow the insurer to discontinue or terminate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available to the insurers.

### ACCIDENT STATEMENT

Date Of Report: 02/08/2018 14:00  
 Date Of Accident: 31/07/2018 20:00  
 Exact Location Of Accident: JURONG ISLAND HIGHWAY OUTSIDE A COMPANY (LINDE)  
 Country/State of Loss: SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number: FBK8025U  
 Insured/Policyholder:  
 Name Of Registered Owner: ABDUL RAHIM BIN ZAINAL ABIDIN  
 NRIC No: S8815558J  
 Email Address: RAHIMBZAINAL@GMAIL.COM  
 Mobile Phone No: (LOCAL) +65-83236917  
 Alternative Phone No: OFFICE-83236917

### Vehicle Particulars

Manufacturer: HONDA  
 Model: CB400X-39JCC

Exact Purpose for which vehicle was being used at time of accident:

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken:

Vehicle Category: MOTORCYCLE

### Insurance Company

Name of Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage: COMPREHENSIVE  
 Fleet Policy: NO  
 Policy Number: 2100452897-02  
 Cover Note Number:

### Driver

Name of Driver: ABDUL RAHIM BIN ZAINAL ABIDIN  
 NRIC No: S8815558J  
 Date Of Birth: 09/05/1988  
 Occupation: OUTDOOR  
 Date Of Driving Pass: 01/02/2016  
 Driving Experience: 2 YEARS AND 5 MONTHS  
 Gender: MALE  
 Mobile Number: (LOCAL) +65-83236917  
 Fax Number:  
 Contact Number: OFFICE-83236917  
 Email Address: RAHIMBZAINAL@GMAIL.COM



Address BLK 683B EDGEDALE PLAINS #02-689  
Postcode 822683  
Was driver an employee of the Insured's Company? NO  
If No, Relationship of the Driver with the Insured? OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type of Accident COLLISION - MAJOR/MINOR RD  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was anybody injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-8522999 - FAX NO: 68522239  
Was notice of Intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

**Details of Witness 1**

Name CHOON WEI  
Phone Number 92264670  
Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHC2726R  
Vehicle Make/Model/Colour COMFORT TAXI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver  
NRI /Passport Number  
Contact Number  
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name: ABDUL RAHIM BIN ZAINAL ABIDIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBK8025U

Worn seat belts worn?


Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

# Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/7/18 at about 2000hrs, I was riding home after work along Jong Island Highway towards the checkpoint of young island. I was riding on the most right lane which is the first lane. While I was riding, suddenly a taxi which was opposite of me turned right into a road that was heading to a company (Linc). I was unable to brake in time and collided to the left rear passenger door of the said taxi.

I flew about 1m to the front after colliding into the said taxi. A passerby approached me and assisted me up, which also told me that he was driving behind me and had captured the whole incident. After the passerby helped me up, Actos police came and Ambulance also came. I was then conveyed to the hospital by the ambulance to Ng Teng Fong General Hospital. I was then given 11 days of MC from 31/7/18 to 10/8/2018. I suffered injuries on my right shin and right wrist.

The said passerby then exchanged contact with me and subsequently sent me the video of the accident that happened with me and the taxi. I wish to add that I was driving below the speed limit.

## DECLARATION

I declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature

Date & Time: 3/8/18

18/8/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as in the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 2/8/18  
15:50Hrs

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:

## Honda CB400X

**SGD\$17000**

Reg : 01/06/2017

Type: **Sport Tourers****399cc****11661km**

Welcome trade in. Loan available. Ambra Enterprises is located at Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Posted on : 12/09/2018

PAID AD

DEALER AD

**COMPARE****DETAILS**

## Honda CB400X

**SGD\$11500**

Reg : 07/11/2013

Type: **Sport Tourers****399cc****35000km**

Very good condition. Regularly maintained. Used only for office commute in Singapore. Always parked in covered parking lot. Price is negotiable.

Posted on : 11/09/2018

PAID AD

DIRECT SELLER

**COMPARE****DETAILS**

## Honda CB400X

**SGD\$13800**

Reg : 30/01/2015

Type: **Sport Tourers****399cc**

-

Visit us at Ah Fook Motor. Well maintained condition. Trade in welcome / Loan available.

Posted on : 10/09/2018

PAID AD

DEALER AD

**COMPARE****DETAILS**

## Honda CB400X

**SGD\$16500**

Reg : 06/06/2014

Type: **Sport Tourers****399cc****70000km**

Well maintain. Trade in/Loan of vehicle available. Interested buyers are welcome to neg. Come visit Albert Motor Supply.

Posted on : 03/09/2018

PAID AD

DEALER AD

**COMPARE****DETAILS**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

|                               |                   |
|-------------------------------|-------------------|
| Vehicle Owner Particulars     |                   |
| Owner ID Type:                | Singapore NRIC    |
| Owner ID:                     | 5558J             |
| Vehicle Details               |                   |
| Vehicle No.:                  | FBK8025U          |
| Vehicle to be Exported:       | No                |
| Intended Deregistration Date: | 21 Sep 2018       |
| Vehicle Make:                 | HONDA             |
| Vehicle Model:                | CB400X ABS        |
| Primary Colour:               | Black             |
| Manufacturing Year:           | 2015              |
| Engine No.:                   | NC47E5000387      |
| Chassis No.:                  | JH2NC4796EK000385 |
| Maximum Power Output:         | -                 |
| Open Market Value:            | \$6,516.00        |
| Original Registration Date:   | 02 Feb 2016       |
| First Registration Date:      | 02 Feb 2016       |
| Transfer Count:               | 1                 |
| Actual ARF Paid:              | \$978.00          |
| Intended PARF Rebate Details  |                   |
| PARF Eligibility:             | No                |
| PARF Eligibility Expiry Date: | -                 |
| PARF Rebate Amount:           | \$0.00            |
| Intended COE Rebate Details   |                   |
| COE Expiry Date:              | 01 Feb 2026       |
| COE Category:                 | D - Motorcycle    |
| COE Period(Years):            | 10                |
| QP Paid:                      | \$6,512.00        |
| COE Rebate Amount:            | \$4,794.00        |
| Total Rebate Amount:          | \$4,794.00        |

The information contained herein is correct as at 21 Sep 2018

OK

**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 13 August 2018

**ASSESSMENT FOR REPAIR: HONDA CB400X ABS - FBK8025U**

Chassis No.: JH2NC4796EK000385

Engine No.: NC47E5000387

| Qty   | Description                          | Estimate               |
|-------|--------------------------------------|------------------------|
| 1 pc  | Front mudguard                       | \$235.00 ✓ CRA         |
| 1 pc  | Front wheel axle                     | \$95.00 ? ✓ Bt         |
| 2 pcs | Steering stem bearing @ \$45.00      | (270) \$80.00 ✓ n/c    |
| 1 pc  | Front brake disk                     | \$365.00 ✓ SCR         |
| 1 pc  | ABS disk                             | \$275.00 ? ✓ Bt        |
| 1 pc  | ABS sensor                           | \$175.00 ? X SVC       |
| 1 pc  | Front left fork assembly             | (800) \$1,105.00 ✓ BT  |
| 1 pc  | Front right fork assembly            | (800) \$1,105.00 ✓ BT  |
| 1 pc  | Steering head crown                  | \$430.00 ? X SVC       |
| 1 pc  | Steering stem underbracket           | \$480.00 ? ✓ Bt        |
| 1 pc  | Windshield                           | \$195.00 ✓ missing     |
| 2 pcs | Windshield support bracket @ \$75.00 | \$75 RH X SVC          |
| 1 pc  | Headlamp assembly                    | \$150.00 ✓ LH (BT)     |
| 1 pc  | Headlamp bracket                     | (240) \$480.00 ✓ SCR   |
| 1 pc  | Outer meter cover                    | \$275.00 ? ✓ CRA       |
| 1 pc  | Inner meter cover                    | \$245.00 ✓ SCR         |
| 1 pc  | Front beak cover                     | \$245.00 ? ✓ CRA       |
| 1 pc  | Left inner cover                     | \$255.00 ✓ BROKEN      |
| 1 pc  | Right inner cover                    | \$65.00 ? ✓ CRA        |
| 1 pc  | Upper crash bar right                | \$65.00 ? ✓ CRA        |
| 1 pc  | Upper crash bar left                 | \$180.00 ? ✓ Bt        |
| 1 pc  | Lower crash bar left                 | \$180.00 ✓ SCR         |
| 1 pc  | Lower crash bar right                | \$175.00 ? ✓ Def       |
| 1 pc  | Right engine cover                   | \$175.00 ? ✓ Def       |
| 1 pc  | Right engine cover gasket            | \$405.00 X SVC         |
| 1 pc  | Belly pan                            | \$65.00 X n/c          |
| 1 pc  | Belly pan aluminium cover            | \$285.00 ✓ SCR         |
| 1 pc  | Right handguard                      | \$275.00 ✓ SCR         |
| 1 pc  | Left handguard                       | \$125.00 ✓ SCR         |
| 1 pc  | Left view mirror                     | \$125.00 ✓ SCR         |
| 1 pc  | Right view mirror                    | \$140.00 ✓ SCR         |
| 1 pc  | handle bar                           | (150) \$140.00 ✓ SCR   |
| 1 pc  | Brake lever                          | \$195.00 ? ✓ Bt        |
| 1 pc  | Fuel tank assembly                   | (950) \$75.00 ✓ SCR    |
| 1 pc  | Horn                                 | \$980.00 X SVC ✓ Dt    |
| 1 pc  | Right body fairing                   | \$55.00 X SVC          |
| 1 pc  | Left body fairing                    | \$330.00 ? ✓ CRA       |
| 2 pcs | Honda wing decal @ \$45.00           | \$330.00 ? ✓ CRA       |
| 2 pcs | Mark X decal @ \$65.00               | \$90.00 ✓ n/c          |
| 1 pc  | Left body inner fairing              | \$130.00 ✓ n/c         |
| 1 pc  | Right body inner fairing             | \$195.00 ? ✓ CRA       |
| 1 pc  | Right body side fairing              | \$195.00 ? ✓ CRA       |
| 1 pc  | Radiator                             | \$305.00 ? ✓ CRA       |
| 1 pc  | Radiator fan motor                   | (450) \$650.00 ✓ DD    |
| 1 pc  | Radiator fan cover                   | (200) \$290.00 ? ✓ TAM |
|       |                                      | \$115.00 ? ✓ CRA       |

- 1 pc Rear right signal
- 1 pc Coolant
- 1 pc Right rear footrest
- 1 pc Right rear footrest holder
- 1 pc Front right footrest holder
- 1 pc Front right footrest
- 1 pc Exhaust assembly

Less discount 10%

**Special nett items**

- 1 pc Front sport rim
- 1 pc Front number plate
- 1 pc Rear top case
- 1 pc Rear box bracket
- 1 pc Front tyre

- 1) Towing charges
- 2) Replace, realign and adjust above damaged parts
- 3) Balancing front wheel rim
- 4) To remove/refit, replace (if damage) check and straighten front fork tubes
- 5) Reset meter
- 6) To knock, straighten chassis & body balancing
- 7) Spray painting

**Total Estimate**

9,895  
+ 1,485  
1,520  
11,900  
1,190  
10,710

\$105.00 XSV  
\$45.00 / nec  
\$95.00 / scr  
\$155.00 XSV Bt  
\$195.00 XSV Bt  
\$95.00 / scr  
\$1,880.00 / scr  
\$15,035.00  
\$1,503.50  
\$13,531.50

\$700.00 X nn Bt  
\$20.00 / missing  
\$450.00 / DD  
\$220.00 / DD ? XSV C  
\$175.00 X m

\$80.00 /

~~\$800.00~~ 400

~~\$150.00~~ 50

~~\$180.00~~ 100

~~\$120.00~~ 50

~~\$450.00~~ 180

~~\$400.00~~ 200

2,230

12,940

less 20% 2,588

\$17,276.50

Note: The above estimate is subjected to the prevailing GST of 7%

17,744.50



For Bike Production Pte Ltd

Total = 10,352

L/S = \$10,350

NA2 LKK  
16/8/18 1615  
L/S

5 days

AFTER REPAIR PHOTO

*[Signature]*  
20/8/18

**BIKE PRODUCTION PTE LTD**

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 25 August 2018

ASSESSMENT FOR REPAIR: HONDA CB400X ABS - FBK8025U

Chassis No.: JH2NC4796EK000385

Engine No.: NC47E5000387

| <u>Qty</u> | <u>Description</u>                   | <u>Estimate</u>  |
|------------|--------------------------------------|------------------|
| 1 pc       | Front bracket comp                   | \$80.00 ✓ BT A   |
| 1 pc       | Brake pedal                          | \$135.00 ✓ SCR A |
| 1 pc       | Right body side fairing              | \$305.00 ✓ CRA A |
|            |                                      | <hr/>            |
|            |                                      | \$520.00         |
|            | Less discount 10%                    | \$52.00          |
|            |                                      | <hr/>            |
|            |                                      | \$468.00         |
|            | <u>Special nett items</u>            |                  |
|            | <br><u>Total Additional Estimate</u> | <br><hr/>        |
|            |                                      | \$468.00         |

Note: The above estimate is subjected to the prevailing GST of 7%



9893

1485

520

# BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

TP

Date: 13 August 2018

## AGREEMENT FOR REPAIR: HONDA CB400X ABS - FBK8025U

Job No: JH2HC4796EK000385

Job No: NC471 5000387

| QTY | Description                          | Estimate             |
|-----|--------------------------------------|----------------------|
| 1   | Front mudguard                       | \$235.00 / CRA       |
| 1   | Front wheel axle                     | \$95.00 / BT         |
| 1   | Steering stem bearing @ \$45.00      | \$80.00 / CRA        |
| 1   | Front brake disk                     | \$305.00 / CRA       |
| 1   | ABS disk                             | \$275.00 / BT        |
| 1   | ABS sensor                           | \$175.00 / SVC       |
| 1   | Front left fork assembly             | \$1,105.00 / BT      |
| 1   | Front right fork assembly            | \$1,105.00 / BT      |
| 1   | Steering head crown                  | \$430.00 / 3X SVC    |
| 1   | Steering stem underbracket           | \$480.00 / BT        |
| 1   | Windshield                           | \$105.00 / CRA       |
| 1   | Windshield support bracket @ \$75.00 | \$150.00 / L.H. (BT) |
| 1   | Headlamp assembly                    | \$480.00 / SVC       |
| 1   | Headlamp bracket                     | \$275.00 / CRA       |
| 1   | Outer meter cover                    | \$245.00 / CRA       |
| 1   | Inner meter cover                    | \$245.00 / CRA       |
| 1   | Front peak cover                     | \$255.00 / CRA       |
| 1   | Left inner cover                     | \$65.00 / CRA        |
| 1   | Right inner cover                    | \$65.00 / CRA        |
| 1   | Upper crash bar right                | \$180.00 / BT        |
| 1   | Upper crash bar left                 | \$180.00 / SVC       |
| 1   | Lower crash bar left                 | \$175.00 / DEF       |
| 1   | Lower crash bar right                | \$175.00 / DEF       |
| 1   | Right engine cover                   | \$405.00 / SVC       |
| 1   | Right engine cover gasket            | \$65.00 / CRA        |
| 1   | Belly pan                            | \$285.00 / SVC       |
| 1   | Belly pan aluminium cover            | \$275.00 / SVC       |
| 1   | Right handguard                      | \$125.00 / SVC       |
| 1   | Left handguard                       | \$125.00 / SVC       |
| 1   | Left view mirror                     | \$140.00 / SVC       |
| 1   | Right view mirror                    | \$140.00 / SVC       |
| 1   | Handle bar                           | \$195.00 / BT        |
| 1   | Brake lever                          | \$75.00 / SVC        |
| 1   | Fuel tank assembly                   | \$980.00 / BT        |
| 1   | Horn                                 | \$55.00 / SVC        |
| 1   | Right body fairing                   | \$330.00 / CRA       |
| 1   | Left body fairing                    | \$330.00 / CRA       |
| 1   | Honda wing decal @ \$45.00           | \$90.00 / CRA        |
| 1   | Mark X decal @ \$65.00               | \$130.00 / CRA       |
| 1   | Left body inner fairing              | \$195.00 / CRA       |
| 1   | Right body inner fairing             | \$195.00 / CRA       |
| 1   | Right body side fairing              | \$305.00 / CRA       |
| 1   | Radiator                             | \$650.00 / BT        |
| 1   | Radiator fan motor                   | \$290.00 / BT        |
| 1   | Radiator fan cover                   | \$115.00 / CRA       |

1 pc Fear right signal  
 1 pc Coolant  
 1 pc Right rear footrest  
 1 pc Right rear footrest holder  
 1 pc Front right footrest holder  
 1 pc Front right footrest  
 1 pc Exhaust assembly

Less discount 10%

Special nett items

1 pc Front sport rim  
 1 pc Front number plate  
 1 pc Rear top case  
 1 pc Rear box bracket  
 1 pc Front tyre

1) Towing charges  
 2) Replace, realign and adjust above  
 damaged parts  
 3) Balancing front wheel rim  
 4) To remove/refit, replace (if damage) check and  
 straighten front fork tubes  
 5) Reset meter  
 6) To knock, straighten chassis & body  
 balancing  
 7) Spray painting

Total Estimate

\$105.00  
 \$15.00  
 \$15.00  
 \$15.00  
 \$15.00  
 \$15.00  
 \$15.00  
 \$18.00  
 \$15.00  
 \$15.00  
 \$15.00

\$70.00  
 \$20.00  
 \$40.00  
 \$20.00  
 \$15.00

\$40.00

\$840.00

\$450.00

\$150.00

\$140.00

\$40.00

\$400.00

\$1,726.50

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

NA2 LKK

16/8/18 1615

L/S

5 days

AFTER REPAIR PHOTO

98804220





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                  |                                                                   |         |                             |                                                                                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|---------|-----------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                     |                                                                   |         | Ref : CS/FCI18014879/Nsd3e2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                              |                                                                   |         | Date : 10-12-2018           |  |
|                                                                                                                                                                                    |                                                                   |         | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                  |                                                                   |         |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                       | SHC 2726R                                                         |         | Veh. Inspected              | FBK 8025U                                                                           |
| Policy No.                                                                                                                                                                         |                                                                   |         | Coverage (\$)               | 0.00                                                                                |
| Claim No.                                                                                                                                                                          | D18005859MFSH                                                     |         | Excess (\$)                 | 0.00                                                                                |
| Assign From                                                                                                                                                                        | KAREN TAN                                                         |         | Assign Date                 | 14/08/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                      |                                                                   |         |                             |                                                                                     |
| Make & Model                                                                                                                                                                       | HONDA CB400X ABS                                                  |         | c.c                         | 399                                                                                 |
| Engine No.                                                                                                                                                                         | HIDDEN                                                            |         | Year of Reg.                | 2016                                                                                |
| Chassis No.                                                                                                                                                                        | JH2NC4796EK000385                                                 |         | Colour                      | BLACK                                                                               |
| Odometer                                                                                                                                                                           | 69044                                                             |         | Steering                    | JAMMED                                                                              |
| Brakes                                                                                                                                                                             | IN ORDER                                                          |         | Modification                | STANDARD ALLOY RIM                                                                  |
| General                                                                                                                                                                            | FAIR                                                              |         |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                      |                                                                   |         |                             |                                                                                     |
|                                                                                                                                                                                    | Size                                                              | Make    | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                     | 120/60 R17                                                        | PIRELLI | 5 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                     |                                                                   |         | mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                      | 160/60 R17                                                        | PIRELLI | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                      |                                                                   |         | mm                          |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                   |                                                                   |         |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                                                           |                                                                   |         |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                      |                                                                   |         |                             |                                                                                     |
| Accident Date                                                                                                                                                                      | 31/07/2018                                                        |         | Inspection Date             | 16/08/2018                                                                          |
| Survey held at                                                                                                                                                                     | BIKE PRODUCTION PTE LTD<br>610 SERANGOON ROAD<br>SINGAPORE 218216 |         |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                 |                                                                   |         |                             |                                                                                     |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                   |         |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                 |                                                                   |         |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                |                                                                   |         | <b>5 Working Days</b>       |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 8025U

| Qty | Description of Parts                | Condition                     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|-------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                               |                           |                   |
| 1   | FRONT MUDGUARD                      | CRACKED                       | 235.00                    | 235.00            |
| 1   | FRONT WHEEL AXLE                    | BENT                          | 95.00                     | 95.00             |
| 2   | STEERING STEM BEARING @\$40.00      | NECESSARY                     | 80.00                     | 80.00             |
| 1   | FRONT BRAKE DISK                    | SCRATCHED                     | 305.00                    | 270.00            |
| 1   | ABS DISK                            | BENT                          | 275.00                    | 275.00            |
| 1   | ABS SENSOR                          | SERVICEABLE                   | 175.00                    | -                 |
| 1   | FRONT LEFT FORK ASSEMBLY            | BENT                          | 1,105.00                  | 800.00            |
| 1   | FRONT RIGHT FORK ASSEMBLY           | BENT                          | 1,105.00                  | 800.00            |
| 1   | STEERING HEAD CROWN                 | SERVICEABLE                   | 430.00                    | -                 |
| 1   | STEERING STEM UNDERBRACKET          | BENT                          | 480.00                    | 480.00            |
| 1   | WINDSHIELD                          | MISSING                       | 195.00                    | 195.00            |
| 2   | WINDSHIELD SUPPORT BRACKET @\$75.00 | N/S BENT / O/S<br>SERVICEABLE | 150.00                    | 75.00             |
| 1   | HEADLAMP ASSEMBLY                   | SCRATCHED                     | 480.00                    | 480.00            |
| 1   | HEADLAMP BRACKET                    | CRACKED                       | 275.00                    | 240.00            |
| 1   | OUTER METER COVER                   | SCRATCHED                     | 245.00                    | 245.00            |
| 1   | INNER METER COVER                   | CRACKED                       | 245.00                    | 245.00            |
| 1   | FRONT BEAK COVER                    | BROKEN                        | 255.00                    | 255.00            |
| 1   | LEFT INNER COVER                    | CRACKED                       | 65.00                     | 65.00             |
| 1   | RIGHT INNER COVER                   | CRACKED                       | 65.00                     | 65.00             |
| 1   | UPPER CRASH BAR RIGHT               | BENT                          | 180.00                    | 180.00            |
| 1   | UPPER CRASH BAR LEFT                | SCRATCHED                     | 180.00                    | 180.00            |
| 1   | LOWER CRASH BAR LEFT                | DEFORMED                      | 175.00                    | 175.00            |
| 1   | LOWER CRASH BAR RIGHT               | DEFORMED                      | 175.00                    | 175.00            |
| 1   | RIGHT ENGINE COVER                  | SERVICEABLE                   | 405.00                    | -                 |
| 1   | RIGHT ENGINE COVER GASKET           | NOT NECESSARY                 | 65.00                     | -                 |
| 1   | BELLY PAN                           | SCRATCHED                     | 285.00                    | 285.00            |
| 1   | BELLY PAN ALUMINIUM COVER           | SCRATCHED                     | 275.00                    | 275.00            |
| 1   | RIGHT HANDGUARD                     | SCRATCHED                     | 125.00                    | 125.00            |
| 1   | LEFT HANDGUARD                      | SCRATCHED                     | 125.00                    | 125.00            |
| 1   | LEFT VIEW MIRROR                    | SCRATCHED                     | 140.00                    | 140.00            |

Report Ref No. CS/FCI18014879/Nsd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                 | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|-------------|---------------------------|-------------------|
| 1   | RIGHT VIEW MIRROR                    | SCRATCHED   | 140.00                    | 140.00            |
| 1   | HANDLE BAR                           | BENT        | 195.00                    | 150.00            |
| 1   | BRAKE LEVER                          | SCRATCHED   | 75.00                     | 75.00             |
| 1   | FUEL TANK ASSEMBLY                   | DENTED      | 980.00                    | 950.00            |
| 1   | HORN                                 | SERVICEABLE | 55.00                     | -                 |
| 1   | RIGHT BODY FAIRING                   | CRACKED     | 330.00                    | 330.00            |
| 1   | LEFT BODY FAIRING                    | CRACKED     | 330.00                    | 330.00            |
| 2   | HONDA WING DECAL @\$45.00            | NECESSARY   | 90.00                     | 90.00             |
| 2   | MARK X DECAL @\$65.00                | NECESSARY   | 130.00                    | 130.00            |
| 1   | LEFT BODY INNER FAIRING              | CRACKED     | 195.00                    | 195.00            |
| 1   | RIGHT BODY INNER FAIRING             | CRACKED     | 195.00                    | 195.00            |
| 1   | RIGHT BODY SIDE FAIRING              | CRACKED     | 305.00                    | 305.00            |
| 1   | RADIATOR                             | DENTED      | 650.00                    | 450.00            |
| 1   | RADIATOR FAN MOTOR                   | JAMMED      | 290.00                    | 200.00            |
| 1   | RADIATOR FAN COVER                   | CRACKED     | 115.00                    | 115.00            |
| 1   | REAR RIGHT SIGNAL                    | SERVICEABLE | 105.00                    | -                 |
| 1   | COOLANT                              | NECESSARY   | 45.00                     | 45.00             |
| 1   | RIGHT REAR FOOTREST                  | SCRATCHED   | 95.00                     | 95.00             |
| 1   | RIGHT REAR FOOTREST HOLDER           | BENT        | 155.00                    | 155.00            |
| 1   | FRONT RIGHT FOOTREST HOLDER          | BENT        | 195.00                    | 195.00            |
| 1   | FRONT RIGHT FOOTREST                 | SCRATCHED   | 95.00                     | 95.00             |
| 1   | EXHAUST ASSEMBLY                     | SCRATCHED   | 1,880.00                  | 900.00            |
| 1   | FRONT BRACKET COMP (ADDITIONAL)      | BENT        | 80.00                     | 80.00             |
| 1   | BRAKE PEDAL (ADDITIONAL)             | SCRATCHED   | 135.00                    | 135.00            |
| 1   | RIGHT BODY SIDE FAIRING (ADDITIONAL) | CRACKED     | 305.00                    | 305.00            |
|     | LESS 10% DISCOUNT                    |             | -1,555.50                 | -1,222.00         |
|     |                                      |             | 13,999.50                 | 10,998.00         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>     |             |                           |                   |
| 1   | FRONT SPORT RIM (SN)                 | BENT        | 700.00                    | 700.00            |
| 1   | FRONT NUMBER PLATE (SN)              | MISSING     | 20.00                     | 20.00             |
| 1   | REAR TOP CASE (SN)                   | DENTED      | 450.00                    | 450.00            |
| 1   | REAR BOX BRACKET (SN)                | SERVICEABLE | 220.00                    | -                 |

Report Ref No. CS/FCI18014879/Nsd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | FRONT TYRE (SN)                                                               | NOT NECESSARY | 175.00                    | -                 |
|                                                                             |                                                                               |               | 1,565.00                  | 1,170.00          |
|                                                                             | <b>LABOUR</b>                                                                 |               |                           |                   |
|                                                                             | TOWING CHARGES.                                                               |               | 80.00                     | 80.00             |
|                                                                             | REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS.                              |               | 800.00                    | 400.00            |
|                                                                             | BALANCING FRONT WHEEL RIM.                                                    |               | 150.00                    | 50.00             |
|                                                                             | TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES. |               | 180.00                    | 100.00            |
|                                                                             | RESET METER.                                                                  |               | 120.00                    | 50.00             |
|                                                                             | TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.                                |               | 450.00                    | 180.00            |
|                                                                             | SPRAY PAINTING.                                                               |               | 400.00                    | 200.00            |
|                                                                             |                                                                               |               | 2,180.00                  | 1,060.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                               |               | <b>17,744.50</b>          | <b>13,228.00</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                               |               |                           | <b>10,600.00</b>  |

Report Ref No. CS/FCI18014879/Nsd3e2

**MUHAMMAD NAZRIL BIN ABDULLAH**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.