

ASS. REC. BY

REP: cs/CTI18014910/TITd3<sup>92</sup>

Special Instruction:

Survivor  
mevimeh

Tau hich

ASSIGNMENT (Office)

From (Person):

Chong Ban Sen

of

CTI

Date/Time

15/8/18 @ 4:13pm

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBD1450H

Insured:

YP3004P

at Workshop in/s

HKL Lim Team

Tel:

62756656/62756666/62727292

or

B 1k 1008 #01-24 Blok Merah Lane 3 #

Policy No:

DMCVSN3033341800

Claim No:

SNM1800395302

Sum Insured:

Excess:

Make of Veh:

D.O.A

07/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

16/8/18 @

Person Contacted:

Mr. Lim

Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>Submit Total loss uneconomeal .</u>
	<u>MV: \$300 LTA: 30 NV: 770</u>


Tanphi

REF:

CTI

ASSIGNMENT

Front Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 9800  
 IDAC Accident Rpt. Consistent? Yes or No  
 GIA / PR Seen. Consistent? Yes or No  
 Est. Repairs. days Res: Yes or No  
 Lum Sum. % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: FBZ1450H Vc Regn: 2008 Nov  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha FZ150 cc: 150  
 Colour: Black AAC: Insured / Std / NI / NA  
 Sp. Reading: 19140 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: PMYK 602508002547  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modf:  N / S/Rim / STD A/Rim or  
 Tyre Size: F: 80/90R17  
 R: 90/80R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Maxxis  
 Front Rear  
 R/Bal: 5 mm R/Bal: 5 mm  
 L/Bal: mm L/Bal: mm  
 D.O.A. D.O.I. 16/8/18 @ 0245 pm  
 Survey held at: HKL LIM  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision  
 : 5063C

Date / Time | Action / Instruction

RECEIVED 13 SEP 2018.

Date/Time, File Pass to?  
 Date/Time, File Return to?

: Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp. (\$)  
 Interview (\$)  
 Tech Invs (\$)  
 Wash-cy (\$)

Survey Fee: 220  
 Transportation: \_\_\_\_\_  
 S-R: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL

Report Format: TP-Tu  
 Lump Sum / I.B.L: (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Aug 2018		15 Aug 2018 16:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MOHAMED AYOUBKHAN		
Vehicle Reg. No.:	FBD1450H	Date of Loss:	07/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03953C02	Policy/Cover Note No.:	DMCVSN3033341800
Vehicle Reg. No. (Insured):	YP3004P	Policy No. (Claimant):	
		Excess:	\$50.00
Repairer:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/08/2018]		
Adj Asg. Remarks:	EST \$1040, ASSIGN HENRY NG AS SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Lucas Lee

---

**From:** HKL Lim Team Motorsport <hkllimteam@gmail.com>  
**Sent:** Wednesday, 15 August, 2018 2:14 PM  
**To:** Claims Dept of CTI  
**Subject:** FBD1450H / YP3004P on 07/08/2018 Arrange Surveyor  
**Attachments:** FBD1450H 10.jpg; FBD1450H 1.jpg; FBD1450H 5.jpg; FBD1450H 3.jpg; FBD1450H 4.jpg; FBD1450H 2.jpg; FBD1450H 6.jpg; FBD1450H 7.jpg; FBD1450H 8.jpg; FBD1450H 9.jpg

Hi,

Do arrange surveyor for this case.

--  
Thank You.

Best Regards

**James Lim ( Keong )**

Tel:+65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722

Tel:+65 6275-6656, 6275-6566 Fax: 6272-9291

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014910/T1td3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 16-08-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3004P	Veh. Inspected	FBD 1450H
Policy No.	DMCVSN3033341800	Coverage (\$)	0.00
Claim No.	SNM18D03953C02	Excess (\$)	0.00
Assign From	MERIMEN (CHING BOON SEN)	Assign Date	16/08/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	07/08/2018	Inspection Date	16/08/2018
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/08/2018 11:07
Date Of Accident	07/08/2018 15:30
Exact Location Of Accident	AYE 3KM-EXIT 20 TOWARDS LOWER DELTA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBD1450H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMED AYIOUBKHAN
NRIC No	S9675063C
Email Address	AYIOUBKHAN27@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81615664
Alternative Phone No	OTHERS-81615664

### Vehicle Particulars

Manufacturer	YAMAHA
Model	FZ150I-150CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/17-364930-CA
Cover Note Number	

### Driver

Name of Driver	MOHAMED AYIOUBKHAN
NRIC No	S9675063C
Date Of Birth	10/01/1996
Occupation	INDOOR
Date Of Driving Pass	07/04/2015
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81615664
Fax Number	
Contact Number	OTHERS-81615664
E-Mail Address	AYIOUBKHAN27@HOTMAIL.COM

Address	BLK 909 JURONG WEST STREET 91 #02-251
Postcode	640909
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MARISH B CHEONG JIA LIN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 JURONG WEST AVENUE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO: 67912972
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180808/2133

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3004P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name MOHAMED AYOUBKHAN

Approximate Age

Injuries Sustain SERIOUS INJURY

Injured person in which vehicle? FBD1450H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name MARISH B CHEONG JIA LIN

Approximate Age

Injuries Sustain SERIOUS INJURY

Injured person in which vehicle? FBD1450H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:


10/6/2018  
14:15:18

SM 00000000000000000000

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

JOYDI WATSON

Accident Sketch Plan

SKETCH PLAN



A) FBD 1450H  
B) YP 3004 P.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*PLS REFER TO POLICE REPORT  
7/20180008/2133*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
Policyholder's Signature  
Date & Time:  
10/08/2018  
14:15 HRS

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*[Signature]* 14/08/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180808/2133

1 of 4

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

Report No: T/20180808/2133

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/08/2018 17:57	Vide Report No.: A/20180807/0114	Station Diary No.: 234
--	-------------------------------------	---------------------------

Informant's Particulars			
Name of Informant: MOHAMED AYOUBKHAN		Address: APT BLK 918 HOUGANG AVENUE 9 #07-36 SINGAPORE 530918	
ID Type / ID No.: NRIC NO / S9675063C		Contact No.: Home/Office: Mobile: 81615664	
Nationality: INDIAN		Email:	
Sex: Male	Age: 22	Date of Birth: 10/01/1996	Type of Informant: Rider
Race: Indian		Language: English	Institution / School Name:
Occupation: SCDF NSF		Driving Licence Information: Class: 2B	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/08/2018 15:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH EXPRESSWAY LOWER DELTA ROAD AYE 3KM - exit 20 towards lower delta road.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passen.
FBD1450H	Motorcycle	YAMAHA	FZ150I	Black	Seriously Damaged	1
YP3004P	Lorry				No Damage	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBD1450H	MSIG INSURANCE (SINGAPORE) PTE. LTD.	MSDTMT17364930	18/05/2018	11/11/2018

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180808/2133

2 of 4

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

Report No. T/20180808/2133

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	MOHAMED AYIOUBKHAN	ID No.	S9675063C
Related Vehicle	FBD1450H (Motorcycle)	Contact No.	81615664
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
Passenger			
Name	MARISH B CHEONG JIA LIN	ID No.	S9603893C
Related Vehicle	FBD1450H (Motorcycle)	Contact No.	91689286
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious

**Brief Details.**

On 07/08/2018, at around 1530hrs, I was riding my vehicle bearing the registration plate number FBD1450H along lane 2 of 2 AYE heading towards CTE. Somewhere along the road, I exit AYE via exit 20 into Lower Delta Rd and a vehicle bearing the registration plate number YP3004P was driving on lane 1 of 2 AYE in front of me. I did not see any signal on the other vehicle as such I decided to drove forward and came up to its left side. Subsequently, the other vehicle started to filter into my lane whereas I starting moving left and eventually colliding onto the kerb on my left and fell onto the ground.

The other vehicle stopped and the driver exited his vehicle and made a check on me and my passenger. The other driver was not injured. I suffer abrasions on my limbs and my chest. While my passenger suffers abrasions on her left arm, hip, knee, feet, right arm, deep cuts on her right elbow and fracture on her left wrist. The police vide A/20180807/0114 and ambulance then arrived and we were conveyed to Singapore General Hospital for treatment. My passenger and I received a 10-days MC and a 4-days MC respectively.

I am lodging this report for insurances purposes. I wish to state that my vehicle does not have any dash cam. Furthermore, my passenger's silver colored 64GB Iphone 6S+ was shattered during the accident.

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20180808/2133

3 of 4

Report No: T/20180808/2133

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

CONTINUATION OF REPORT

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20180808/2133

Police Station Of Origin:  
Nanyang N.P.C  
2 Jurong West Avenue 5 SINGAPORE  
649482  
Tel No: 1800-7929999

4 of 4  
Report No. T/20180808/2133

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/  
KWONG ZHENG JIE

Signature Of Informant:


Signature Of Interpreter:  
Not applicable

Date/Time:  
08/08/2018 17:57

Officer In Charge Of Case:  
TP / GIT /  
Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN  
Contact No: 65476185

Classification Of Case:

Authentication Stamp  
No 188



Signature:

Singapore Police Force

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5063C
Vehicle Details	
Vehicle No.:	FBD1450H
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	YAMAHA
Vehicle Model:	FZ150I
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	G372EE002547
Chassis No.:	PMYKKG025080002547
Maximum Power Output:	-
Open Market Value:	\$2,390.00
Original Registration Date:	12 Nov 2008
First Registration Date:	12 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$359.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2018
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,289.00
COE Rebate Amount:	\$30.00
<b>Total Rebate Amount:</b>	<b>\$30.00</b>

The information contained herein is correct as at 17 Aug 2018

OK



# HKL LIM TEAM MOTORSPORT

Blk 100B #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291  
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FBD1450H

1 TOWING		\$40.00 ✓
2 TOTAL LOSS	<i>Estimated repair cost.</i>	\$1,000.00 ✓
TOTAL		\$1,040.00

*Tanpha 97495749  
WP  
16/8/18 @ 1245pm  
serv @ hklauto.com*

*[Signature]  
17/8/18*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



Business Reg No : 53240921c  
H/P No : 9222 8511

Received From : AKL Lim.  
Vehicle No : FBD 1450  
From : TP power.  
Handphone No : \_\_\_\_\_  
Amount : \$40-/-

**OFFICIAL RECEIPT**

No: 1650

Date: 14/8/18

Issued By

NOTE : Vehicle is transported at owner's risk. The company accepts no responsibility for damages or other misdemeanor to your vehicle whilst being transported.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Aug 2018		15 Aug 2018 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

- Main
Reference
Claim Details
Documents
Show All

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	MOHAMED AYOUBKHAN, ID: S9675063C		
Main Claimant:	MOHAMED AYOUBKHAN		
Vehicle Reg. No.:	FBD1450H	Date of Loss:	07/08/2018 00:00 - :59 [116 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03953C02	Policy/Cover Note No.:	DMCVSN3033341800
Vehicle Reg. No. (Insured):	YP3004P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3, 159722 Bukit Merah - Tel: 62756656/62756566/62727292		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/08/2018]		
Adj Asg. Remarks:	EST \$1040, ASSIGN HENRY NG AS SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBD1450H (SNM18D03953C02)**  
**[YP3004P]**  
**TP**  
**MOHAMED AYOUBKHAN**  
**Aug 7 2018 12:00AM**  
**[MOHAMED AYOUBKHAN]**  
**Hkl Lim Team Motorsport**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>		<a href="#">Compose New Letter</a>		<b>View</b>	<a href="#">View in Browser</a>	
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
2	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
3	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
4	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
5	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
6	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
7	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
8	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
9	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
10	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
11	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
12	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
13	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
14	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
15	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
16	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
17	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
18	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
19	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
20	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
21	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
22	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
23	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
24	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
25	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
26	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
27	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
28	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
29	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
30	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
31	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
32	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
33	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
34	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
35	12/09/18 17:49	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
37	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
38	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
39	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
40	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
41	12/09/18 17:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/08/18 16:12	<b>EMAIL FM HKL</b>	Load PDF	
2	15/08/18 16:12	<b>REPAIR EST</b>	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 10:34	<b>LTA REBATE</b>	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST




There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014910/T1TD3S2

Date: 14/09/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3033341800

Claimant Vehicle No: FBD1450H Insured Vehicle No: YP3004P

Date of Loss: 07/08/2018 Nature of Claim: TP Claim No: SNM18D03953C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FBD1450H**

Make & Model: YAMAHA FZ150I, 150cc Engine No: G372EE002547

Reg. Date: 12/11/2008 (Man. Year: 2008) Chassis No: PMYKG025080002547

Colour: Black Odometer: 19140 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 80/90R17 Rear Tyre Size: 90/80R17

Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/08/2018

Date Inspected: 16/08/2018 Inspected At: Hkl Lim Team Motorsport (HQ)  
BLK 1008 #01-24 BUKIT MERAH LANE 3  
Singapore 159722

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$800.00
OMV :	\$2,390.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$1,289.00
COE Rebate (2) :	\$30.00
Total Rebate (1) + (2) = :	\$30.00

The total amount incurred will be Market Value \$800.00 minus Total Rebate \$30.00 = \$770.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 Sep 2018)

**Parts:** N/A YAMAHA FZ150I 150cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBD1450H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >