



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/12/2018

Survey Details:

| | |
|---------------------|-----------------------------------|
| Date of loss | 10-Aug-18 |
| Date of appointment | 16-Aug-18 |
| Date of survey | 16-Aug-18 |
| Location of survey | COMFORTDELGRO ENGINEERING PTE LTD |

Vehicle Details:

| | |
|----------------------|-----------------------------|
| Claim Type: | Third party |
| Vehicle number | SHB 3833M |
| Make and Model | MERCEDES BENZ E220 CDI (E5) |
| Date of registration | 31/8/2012 |
| Excess | |
| Market Value | \$0 |
| Parf Rebate | \$0 |
| Nett Loss | \$0 |

Repair details:

| | | |
|------------------|----|----------|
| Initial Estimate | \$ | 3,808.00 |
|------------------|----|----------|

Proposed/Revised repair cost:

| | | |
|--------------------------------|-----------|---------------|
| Parts | | |
| Check items (estimate) | \$ | - |
| Labour | \$ | 300.00 |
| Total | \$ | 300.00 |
| Lump Sum(if applicable) | \$ | - |

| | |
|---------------------------|---|
| Number of days for repair | 2 |
|---------------------------|---|



Remarks:

Third party video shows that there is a jerk on third party vehicle.

Mandate:

| Liability(TP) | | % |
|-----------------------|----|-------------|
| Proposed repair cost | \$ | |
| Loss of use | \$ | no. of days |
| Loss of rental | \$ | no. of days |
| Loss of income | \$ | no. of days |
| LTA search fees | \$ | |
| Others | \$ | |
| Proposed Total | | |