

(08/11/13) wef

ASS. REC. BY: MW 45

REF:

CS/7P18014939/4rd3n2**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLF 46877at Workshop m/s 3m

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 68

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: 1 Consistent?: Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LIA 51478

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLF 46877 Yr Regn: 10, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or LA /Make: Volkswagen Golf A7.c 1395Colour: black A/C: Insured / Std / NI / NASp. Reading: 35848 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVWZZZAUZFV 357879Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/8/18 D.O.I. 16/8/18

Survey held at \_\_\_\_\_

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear 15.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

F7A 7400 Ind. rep 9800C/S 4300Red: \$5769.55, 51K

RECEIVED 03 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: TP - IndependentLump Sum / L.B.I. (\$ 4300.00 )1703050+506880468

Ref. No : CS/TP18014939/Ucd3n2	Res. Date: 21/8/18	Date Received:
Ver No : 52746877	SP:	WKSP: Ben
C/No :		
<b>Action/Instruction:</b>		
1.File	2.Submit Photo? YES / NO	
3.Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By:

MSME18105185 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 14/08/2018 17:48  
SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

## ACCIDENT STATEMENT

Date Of Report 14/08/2018 17:48  
Date Of Accident 14/08/2018 08:00  
Exact Location Of Accident YISHUN AVE 1 FILTERING TO LENTOR AVE  
Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SLF4687T  
Insured/Policyholder  
Name Of Registered Owner YONG CHAN HOU  
NRIC No S7938625A  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-96991786  
Alternative Phone No OFFICE-96991786

## Vehicle Particulars

Manufacturer VOLKSWAGEN  
Model GOLF

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number GA282269  
Cover Note Number

## Driver

Name of Driver YONG CHAN HOU  
NRIC No S7938625A  
Date Of Birth 07/12/1979  
Occupation INDOOR  
Date Of Driving Pass 28/02/2000  
Driving Experience 18 YEARS AND 5 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-96991786  
Fax Number  
Contact Number OFFICE-96991786  
Email Address NOEMAIL

1YISHUN STB1  
#B-02 S(267996)

Address 1 YISHUN ST 51 #03-02  
 Postcode 767996  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : NIGEL  
 GENDER: : MALE

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

AS VEHICLE A WAS TRAVELLING ALONG YISHUN AVE 1 ABOUT TO FILTER LEFT INTO LENTOR AVE, SUDDENLY VEHICLE B COLLIDED ONTO MY REAR PORTION. WHEN I GOT OUT OF MY CAR, I NOTICED IT'S A 3 VEHICLE CHAIN COLLISION.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLV4766P  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SGV6453M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


## Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) Any insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8625A
<b>Vehicle Details</b>	
Vehicle No.:	SLF4687T
Vehicle to be Exported:	No
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CXS259217
Chassis No.:	WVWZZZAUZFW357879
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,642.00
Original Registration Date:	27 Oct 2015
First Registration Date:	27 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$13,699.00 <i>449</i>
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2025
PARF Rebate Amount:	\$10,274.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$41,204.00
<b>Total Rebate Amount:</b>	<b>\$51,478.00</b>

The information contained herein is correct as at 17 Aug 2018

OK





**WIDE RANGE OF PRE-OWNED  
TOYOTA AND OTHER MAKES  
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2016 Mini Cooper Clubman 1.5A At Only \$107,800 Nego.



1 Owner Only With Full Agent  
Service And Warranty, Spacious  
5 Door Mini  
Car Lingual StarAd

ABWIN



Browse by Category ▼

« Back ( 1 2 3 ) Next »

Sort b

48 vehicles

Volkswagen Golf

Advanc

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection

Volkswagen Golf

Any

Any

2015

Any



**Volkswagen Golf 1.4A TSI**

**\$60,500**

**\$8,780 /yr**

**25-Mar-2015**

**1,395 cc**

**28**

\$10K Drive Away, 10% Down Payment Only. Under Utilized German Hatchback With Genuinely Low Mileage Of 28k Km ( Maintained At VW Agent Since Day 1. We Provide 6 Months Warranty For Ge...

Lowest Mileage 28K, Full Agent Maintained, 1 Owner, Almost Brand New Condition!  
Tradeit.Com Pte Ltd

Posted: 17-Aug-2018 Tags: 2015 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf 1.4A TSI**

**\$60,000**

**\$8,710 /yr**

**02-Jan-2015**

**1,395 cc**

**35**

VW Authorised Agent Serviced. Under Warranty Till End 2019 Accident-free Lady Driver Single Owner Schedule A Test D By Appointment Only.

Carro

Posted: 16-Aug-2018 Tags: 2015 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf 1.2A TSI**

**\$62,800**

**\$8,380 /yr**

**19-Aug-2015**

**1,197 cc**

**45**

Graded A by **STA**

1 Year Comprehensive Warranty Inclusive! \$4K Down Payment! STA Certified Accident Free Quality Pre-Owned With Low Service History For Peace Of Mind. 100% Loan Approval With Our ...

Cosmo Automobiles

Posted: 16-Aug-2018 Tags: 2015 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen



**Volkswagen Golf 1.4A TSI**

**\$72,888**

**\$9,740 /yr**

**21-Aug-2015**

**1,395 cc**

**60**

Like New White Beauty. 1 Careful Family Man Owner. Original And Zero Modification. Multitude Of Safety Features Such Disc Brakes At Front And Rear, Electronic Stabilization,...

Posted: 16-Aug-2018 Tags: 2015 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf, Used Volkswagen

Compare

Car Selling

Car Ownership





# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
 (Unit C) #01-28-53/55 Singapore 417883  
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg  
 Co. Reg. No.: 200704951N  
 GST Reg. No.: 200704951N

SLF 46F7T

2ps	Rear bumper	20/02	1207.23	/
	Rear bumper side holder n/s	bul	42.80	/
	Rear bumper reinforcement	bul	748.02	/
	Rear bumper retainer	cu	115.32	/
	Rear bumper sensors @ 185.00	n/s shub	370.00	1pc
	Rear bumper clips	cu	39.00	/
	Rear end panel	n	590.53	x
	Tailgate weatherstrips	n	274.35	x
	Tail lamp n/s	cu	392.30	/
			3779.55	2729.67

S. Not f

1ps	Rear bumper lower carbon fibre	cu	1800.00	1100
	Rear bumper sticker	n	200.00	x
	Rear exhaust gassy sport	bul	1880.00	2 LR 200
	Rear exhaust tail carbon	cu	450.00	350

To check wiring	80.00	- 20
To dismantle & replacing pdc sensor	80.00	- 50
To dismantle & refix seat cushion upholstery	120.00	- 80
To spray rust proofing	80.00	x
labour for panel beating & replacing parts	800.00	400
To putty & spray painting	800.00	600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

TOTAL \$10069.55



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18014939/Urd3n2

BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)SINGAPORE  
417883

Date : 07-09-2018



ON BEHALF OF YONG CHAN HOU

Code : TP149

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLF 4687T
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	16/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF A7 (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WVWZZZAUZFW357879	Colour	BLACK
Odometer	35848	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 ZR18	MICHELIN	6 mm
L/H Front Tyre	225/40 ZR18	MICHELIN	6 mm
R/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm
L/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	14/08/2018	Inspection Date	16/08/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4687T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED / DEFORMED	1,207.23	1,207.23
1	REAR BUMPER SIDE HOLDER N/S	BENT	42.80	42.80
1	REAR BUMPER REINFORCEMENT	BENT	748.02	748.02
1	REAR BUMPER RETAINER	CRACKED	115.32	115.32
2	REAR BUMPER SENSORS @\$185.00	N/S SHORTED	370.00	185.00
1	REAR BUMPER CLIPS	NECESSARY	39.00	39.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	590.53	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	274.35	-
1	TAILLAMP N/S	CRACKED	392.30	392.30
	LESS 5% DISCOUNT		-	-136.48
			3,779.55	2,593.19
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER LOWER CARBON FIBRE (SN)	CRACKED	1,800.00	1,100.00
1	SET REAR BUMPER STICKER (SN)	NOT NECESSARY	200.00	-
1	REAR EXHAUST ASSY SPORT (LOCAL REPAIR)(SN)	BENT	1,880.00	200.00
1	REAR EXHAUST TAIL CARBON (SN)	CUT	450.00	350.00
			4,330.00	1,650.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
	-		-	-
	-		-	-
	-		-	-
			1,960.00	1,150.00
<b>GRAND TOTAL</b>			<b>10,069.55</b>	<b>5,393.19</b>

Report Ref No. CS/TP18014939/Urd3n2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,300.00</b>
---	--	--	-----------------

Report Ref No. CS/TP18014939/Urd3n2

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.