

INSURANCE

INS. CASE OWNER:

LAUTHA

CC 3 / III 1801 4945, 41639

LKC

IDAC

Surveyor:

MARCUS

DOI:

25/08/18

Date / Time:

16/8/18

Registered in Merit:

16/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 4693X

Claim No.:

MCA180179

Name of Insured:

LUMFOURDEURU KET + CAR DR

Policy No.:

M46080Y

Insured Tel No.:

HP:

Make / Model:

KEMMUT

Excess Sec II : \$5

D.O.A.:

13/8/18

Place of Accident:

UPP KEMMUTUW KO

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

400 GUY PHOON

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SLC98153



INSRS:
WSP:
Tel:
Liability:
RMKS:

cac
Fulco



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

11/8/18

vic

20/08/18

25/08/18

30/08/18

31/08/18

05/09/18

24/10/18

21/11/18

20/11/18

SLC98153 - M/11/18/15/45/14/19

SLU 4693X - X

1st REPORTED. OLD REPAIR-ENDED TP.

1st CHECK IT CAN DO CONTRIBUTION

ON LIABILITY TO TP CROOKED STOP

1st REPORTED TO SCENE PHOTO

1st REPORTED TO 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

1st REPORTED 100%.

STAGE	DATE / PIC
Non-Reporting 1st (1st):	
Non-Reporting 1st (2nd):	
Non-Reporting 1st (Final):	
Notification 1st (if non-pickup):	
Call OI:	
After call 1st to OI:	
Documentation Check List:	Handler Typist
Notification 1st (if non-pickup):	
After call 1st to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LT / GLA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time: 19/12/18 Sent By: OMS. BY IN. ALL DOCS IN ORDER.

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: PIP	\$5 4,370.00	4 days) Reduction:	18
FINAL SETTLEMENT	Date/Time: 14/12/18	Confirm with: MRS LEE	Email: Call:
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost: (W/GH)	\$5 5,103.90		
Loss of Rental (LOR):	\$5 - (days)		
Loss of Use (LOU):	\$5 210.00 x 4 days)		
Loss of Income (LOI):	\$5 - (5 x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>			
GIATA Search	\$5 7.45		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost:	\$5 -		
Total:	\$5 5,361.35	Global Sum \$5:	-
FINAL PAYMENT	Date/Time:	Confirm with:	Email: Call:
Payee 1:	\$5 5,361.35	Name 1:	CYCUS 4 CHARGES FULCO MOTOR DAMAGE
Payee 2: (Strike if N.A.)	\$5 -	Name 2:	
Payee 3: (Strike if N.A.)	\$5 -	Name 3:	

COPY SENT 11/11/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$350.00

ASSIGNMENT

From Date 23082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLC 9815Z

at Workshop name:

Cycle & Carriage

at

No-330 Ubi Rd 3

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh.

Mars

(Policy Condition)

130pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDV / Accident Report

Consistent? : Yes or No

GVA / PR Seen

Consistent? : Yes or No

Est. Repairs

4

days

Res:

Yes or No

Lum Sum:

-

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted:

Veh No:

SLC 9815Z

Vr Regn

5 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make

KIA forte

K3

15-9/

Colour

S.hv

A/C

Insured / Std / NI / NA

Sp. Reading

34375

T/Radio: Insured / Std / NI / NA

Eng/No:

KNAFX411M95579476

C/No

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

nexen

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/8/18

D.O.I

23/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

P/R \$4,770.00

Crew: \$4,235.00 / 101.7

Date/Time: File Pass to?

☐

Preli. Report

Date/Time: File Return to?

☐

Final Report

Date/Time: File Return to?

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Instruction

1. S - P.C. 18

1. Photo

1. Other

Report Format :

Lump Sum / LB. 15

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Workshop (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18014945/hb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 16-08-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 4693X	Veh. Inspected	SLC 9815Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/08/2018	Inspection Date		
Survey held at	CYCLE & CARRIAGE FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING) Blk 152 Rivervale Crescent 07-106 Singapore 540152	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen) Reg No/Reg Date SLC9B15Z*KC17R(/ 31/05/2016 Date In/Mileage 15/08/2018/ 0 Chassis No KNAFX411MG5579476 Engine No G4FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK
Contact No Mobile: 98633469	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / Marsler	63253
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	REVERSE SENSOR SET		280.00		
M SUNDRY	C & C LOGO		50.00		
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS		80.00		
S MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS		600.00		
S MIPNT88088	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS		600.00		
S MIPNT88088	TO REPLACE REAR BUMPER, REAR BEAM, REAR BOOT, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS		2400.00		
S MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL		200.00		
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS		1680.00		
M KS 86611 A7 000	COVER - REAR BUMPER	1.00	768.00	0.00	768.00
P KS 86695 A7 000	COVER - REAR BUMPER,	1.00	234.00	0.00	234.00
M KS 92405 A7 000	LHR REFLECTOR REFLEX	1.00	114.00	0.00	114.00
M KS 86613 A7 000	LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
M KS 86614 A7 000	RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
P KS 06032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00
P KS 86631 A7 000	BEAM-RR BUMPER	1.00	365.00	0.00	365.00
M KS 86636 A7 000	BRACKET - REAR BEAM	2.00	5.00	0.00	10.00
M KS 86635 A7 000	BRACKET - REAR BEAM	1.00	5.00	0.00	5.00
M KS 86641 A7 000	LH STAY - REAR BUMPER	1.00	75.00	0.00	75.00
M KS 86642 A7 000	RH STAY - REAR BUMPER	1.00	75.00	0.00	75.00
M KS 69200 A7 070	PANEL ASSY - TRUNK L	1.00	1491.00	0.00	1491.00
P KS 86310 A7 050	KIA LOGO ASSY	1.00	37.00	0.00	37.00

Confirm & accepted by

confirm & 4770

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67481000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING Blk 152 Rivervale Crescent 07-106 Singapore 540152	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen Reg No/Reg Date SLC9B15Z*KC1/ 31/05/2016 Date In/Mileage 15/08/2018/ 0 Chassis No KNAFX411MG5579476 Engine No G4FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 455 / WK
Contact No Mobile: 98633469	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / MarsLer	63253

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P WFFORTE FORTE EMBLEM	1.00	40.00	0.00	40.00
P WFEMBLEMK3 EMBLEM K3	1.00	15.00	0.00	15.00
Z NOTES ACCIDENT ON 13/08/2018 ALONG JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SLU4693X TP INS : 1.1.1				
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To Resurvey before/after spray painting • To Resurvey damaged part(s) during resurvey • Parts prices are subject to confirmation • The estimate survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div>				

Estimate

Not Authorised

h/ker

Tel: 62563561

To be paid before pa. rdy.

23/8/18

4 day.

Confirm & accepted by

\$ 4770

Parts	3,315.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,840.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	9,205.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen Reg No/Reg Date SLC9815Z*KC17R(/ 31/05/2016 Date In/Mileage 15/08/2018/ 0 Chassis No KNAFX411MG5579476 Engine No 64FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	17/09/2018/ 11:45	DS	323 / ChrisBulaclac	63253

Description of Goods/Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 REVERSE SENSOR SET				280.00
M SUNDRY C & C LOGO				50.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				300.00
S MIPNT88088 TO REPLACE REAR BUMPER, REAR BEAM, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				1200.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1260.00
X KS 86611 A7 000 COVER - REAR BUMPER	1.00	768.00	0.00	768.00
X KS 86695 A7 000 COVER - REAR BUMPER,	1.00	234.00	0.00	234.00
X KS 86613 A7 000 LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
X KS 86614 A7 000 RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
X KS 06032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00
X KS 86641 A7 000 LH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
X KS 86310 A7 050 KIA LOGO ASSY	1.00	37.00	0.00	37.00
X WFFORTE FORTE EMBLEM	1.00	40.00	0.00	40.00
X WFEMBLEMK3 EMBLEM K3	1.00	15.00	0.00	15.00
X KS 86631 A7 000 BEAM-RR BUMPER	1.00	365.00	0.00	365.00
Z NOTES ACCIDENT ON 13/08/2018 ALONG JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 OWNER CLAIMING THIRD PARTY LOSS OF USE 04DAYS x S\$80.00 = S\$320.00 TP # SLU4693X TP INS : I.I.I				

Confirm & accepted by

Finalization 17/09

Authorized signatory and company stamp

Parts	1,620.00
Labour	0.00
Standard Menu	0.00
Specialist Job	3,100.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	4,770.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING B1k 152 Rivervale Crescent 07-106 Singapore 540152	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen Reg No/Reg Date SLC9815Z*KC17R(/ 31/05/2016 Date In/Mileage 15/08/2018/ 0 Chassis No KNAFX411MG5579476 Engine No G4FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK
Contact No Mobile: 98633469	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / MarsLer	63253
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	REVERSE SENSOR SET				280.00
M SUNDRY	C & C LOGO				50.00
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088	TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS				600.00
S MIPNT88088	TO REPLACE REAR BUMPER, REAR BEAM, REAR BOOT, ETC -REPAIR REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				2400.00
S MIPNT88088	TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1680.00
M KS 86611 A7 000	COVER - REAR BUMPER	1.00	768.00	0.00	768.00
P KS 86695 A7 000	COVER - REAR BUMPER,	1.00	234.00	0.00	234.00
M KS 92405 A7 000	LHR REFLECTOR REFLEX	1.00	114.00	0.00	114.00
M KS 86613 A7 000	LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
M KS 86614 A7 000	RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
P KS 06032 50 037A	CLIP - BUMPER	10.00	2.00	0.00	20.00
P KS 86631 A7 000	BEAM-RR BUMPER	1.00	365.00	0.00	365.00
M KS 86636 A7 000	BRACKET - REAR BEAM	2.00	5.00	0.00	10.00
M KS 86635 A7 000	BRACKET - REAR BEAM	1.00	5.00	0.00	5.00
M KS 86641 A7 000	LH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
M KS 86642 A7 000	RH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
M KS 69200 A7 070	PANEL ASSY - TRUNK L	1.00	1491.00	0.00	1491.00
P KS 86310 A7 050	KIA LOGO ASSY	1.00	37.00	0.00	37.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHIAN TIAN MING (ZHONG ZHENMING Blk 152 Rivervale Crescent 07-106 Singapore 540152	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen Reg No/Reg Date SLC9815Z*KC1/ 31/05/2016 Date In/Mileage 15/08/2018/ 0 Chassis No KNAFX411MG5579476 Engine No G4FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK
Contact No Mobile: 98633469	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	16/08/2018/ 08:19	DS	218 / MarsLer	63253

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P. WFFORTE FORTE EMBLEM <i>see</i>	1.00	40.00	0.00	40.00 ✓
P. WFEMBLEMK3 EMBLEM K3 <i>see</i>	1.00	15.00	0.00	15.00 ✓
Z. NOTES ACCIDENT ON 13/08/2018 ALONG JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SLU4693X TP INS : I.I.I				
<div style="border: 1px solid black; padding: 10px; margin: 10px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No (illegal modification) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				

Estimate

Not Authorised
h/klr

Tel: 62563561

Take photo before parting.

23/8/18

4 day.

Confirm & accepted by

Parts	3,315.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,840.00
Others (Lub, etc)	0.00
Sundry	50.00
Total (w/o GST)	9,205.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6873I

Vehicle Details

Vehicle No.:	SLC9815Z
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A EX
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	G4FGFH609713
Chassis No.:	KNAFX411MG5579476
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$14,104.00
Original Registration Date:	31 May 2016
First Registration Date:	31 May 2016
Transfer Count:	0
Actual ARF Paid:	\$14,104.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2026
PARF Rebate Amount:	\$10,578.00

Intended COE Rebate Details

COE Expiry Date:	30 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$36,516.00
Total Rebate Amount:	\$47,094.00

The information contained herein is correct as at 23 Aug 2018

OK

Print Received Message

This mail is associated with :


*SLC9815Z (MCA180179)
[SLU4693X]
TP
CHIAN TIAN MING
Aug 13 2018 8:00AM
[COMFORTDELGRO RENT-A-CAR PTE. LTD]
Cycle & Carriage Fulco Motor Dealer Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/11/2018 10:20 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5351.35) - SLC9815Z - Claim Handler: Lalitha Krishnan

Approved:5351.35.



FOR LAC USE ONLY



FOR C&C USE ONLY



949 4284A



FOR C&C USE ONLY



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00006647 (Comprehensive - Classic Plan)

Car plate number: SLC9815Z

Your name (As the policyholder): Chian Tian Ming

Coverage start date: 31/05/2018

Coverage end date: 30/05/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank Singapore

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 15/05/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2018-00006647

About this policy

Premium paid : S\$749.13 Coverage start date : 31/05/2018
(Inclusive of GST) Coverage end date : 30/05/2019
Who is insured to drive: : You and any Authorised Driver
Policy Type : CLASSIC

About you (As the policyholder)

Your name : Chian Tian Ming
Address : 152 Rivervale Crescent 07-106 Rivervale Green Singapore 540152
Email : chiantm8@gmail.com
NRIC/FIN : 57216873I Date of birth : 23/05/1972
Marital status : Married Gender : Male
Current no claims discount : 50% Mobile Number : 98633469
Years of driving experience : Three or more Certificate of merit : Yes

About your car

Car make and model : KIA FORTE K3 1.5
Year of first registration : 2016
Car plate number : SLC9815Z
Issued on: : 15/05/2018

A. Bhatia

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions
and exclusions of this policy.

Please immediately inform us at +65-6620-8888
or email us to contact.ag@fwd.com if any details in
this Car Insurance Summary need to be changed.



**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

REPAIRER CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - EUNOS LINK SERVICE CENTRE

MOTOR VEHICLE CLAIM DISCHARGE VOUCHER

ATTN: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET # 04/ # 05
IOB BUILDING
Singapore 049711

OWNER : CHIAN TIAN MING

VEHICLE NO : SLC9815Z

VEHICLE MODEL : KIA/K3

THIRD PARTY# SLU4693X

ACCIDENT DATE : 13/08/2018

WIP NO : 63253

I/WE CERTIFY THAT THE VEHICLE HAS BEEN FULLY REPAIRED TO MY ENTIRE SATISFACTION AND THE PAYMENT OF REPAIRER'S CHARGES ARE CLAIMABLE UNDER THE POLICY WILL BE DEEMED IN FULL AND THE FINAL SETTLEMENT OF MY CLAIMS.



OWNER/INSURED SIGNATURE

DATE : _____

TIME : _____

Mars Ler

From: Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Sent: Monday, 3 September, 2018 5:30 PM
To: Mars Ler
Cc: Chris Bulaclac; Admin A; Vic (LKKAUTO)
Subject: RE: Accident On 13/08/2018 Involving Our Insured SLC9815Z And Your Insured SLU4693X
***LKK REF:CC3/III18014945/hb3

WITHOUT PREJUDICE

Dear Mars Ler,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK  *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Mars Ler [mailto:mars.ler@ccfulco.com.sg]
Sent: Monday, 3 September, 2018 4:33 PM
To: Vic (LKKAUTO)
Cc: Chris Bulaclac
Subject: RE: Accident On 13/08/2018 Involving Our Insured SLC9815Z And Your Insured SLU4693X ***LKK
REF:CC3/III18014945/hb3

Dear Vic,



CYCLE & CARRIAGE

Our Ref : SLC9815Z
Your Ref : SLU4693X

October 18, 2018

AR. REGISTERED

INDIA INTERNATIONAL INSURANCE SINGAPORE
64 CECIL STREET # 04-05 IOU BUILDING
SINGAPORE 049711

Attention: Motor Claims,

Dear Sir/Madam,

Repair Services Rendered to Vehicle Reg. No.SLC9815Z – Accident on 13/08/2018
ALONG JUNCTION UPPER SERANGOON ROAD & HOUGANG AVENUE 4.

We are pleased to enclose our invoice number 77404311 dated 15/10/2018 amounting as follows:

Cost of Repair	S\$5103.90
Loss of USE 04 days x S\$80/DAY	S\$ 320.00
LTA Search Fee	S\$ 7.45

Grand Total	S\$5431.35
--------------------	-------------------

In addition, attached are the supporting documents of repair services rendered to the abovementioned vehicle.

Please acknowledge receipt of the same.

Thank you.

Yours sincerely

Cycle & Carriage –Fulco Motor Dealer Pte Ltd
Eunos Service Centre

Encs.

LETTER OF AUTHORITY

ACCIDENT INVOLVING SLC9815Z AND SLU4693X ON 13/8/2018
Own Vehicle's Number Other Vehicle's Number Date Of Accident

Along JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4
Accident Location

BY THE LETTER OF AUTHORITY, I/We CHIAN TIAN MING S7216873I
Name of Policy Holder & NRIC/Passport/Fin #

Of BLK 152 RIVERVALE CRESCENT #07-108 SINGAPORE S40152
Address of Policy Holder

Owner of Vehicle Registration Number SLC9815Z hereby authorize **Cycle & Carriage-Fulco Motor**
Own Vehicle Number

Dealer Pte Ltd. to act for me with respect to my claim for repair cost and Car Rental and/or Loss of Use ("claim")

for my vehicle SLC9815Z that was damaged.
Own Vehicle Number

I further Authorized **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** To settle my above mentioned claim in a manner that they deem fit and **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** Is further Authorize to Signed on my behalf & receive payment further to settlement cheque/s of my claim with payment being made in favour of **Cycle & Carriage-Fulco Motor Dealer Pte Ltd** I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis in so far as the driver/owner/insurers of the vehicle/s is concerned.

Dated this 13 AUGUST (Month) 2018 (Year)


CHIAN TIAN MING

Signed By Claimant/Policy Holder


Signed by " The Workshop"



EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCA180179
Claimant Ref: SLC9815Z

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
We/I, _____ ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 5,103.90 (repair cost), S\$ 240.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLC9815Z that was damaged pursuant to the accident which occurred on 13/08/2018 (date) at UPPER SERANGOON ROAD (location) involving vehicle no. SLU4693X (insured vehicle). This is pursuant to the inspection conducted on 23/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHIAN TIAN MING ("the third party claimant") of vehicle no. SLC9815Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLC9815Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,351.35 to CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

Dated this 11 day of December 20 18

CLAIMANT:

Signature: _____
Signed by "the workshop" (with chop)
Name: CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
NRIC: 199707303Z
Address: 330 UBI ROAD 3 SINGAPORE 408650
Nationality: _____
Occupation: _____

WITNESS:

Signature: _____
Signed by appointed Surveyor
Name: LKK AUTO CONSULTANTS PTE LTD
NRIC: 199607198R
Address: 51 UBI AVENUE 1 #01-25
PAYA UBI INDUSTRIAL PARK (S) 408933
Nationality: _____
Occupation: _____



EXPRESS SETTLEMENT

DISCHARGE VOUCHER **III – Direct Settlement (PODS)**

India Ref:
Claimant Ref :

We/I, CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$_____ (repair cost), S\$_____ (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLC9815Z that was damaged pursuant to the accident which occurred on 13/08/2018 (date) at JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 (location) involving vehicle no. SLJ4693X (Insured vehicle). This is pursuant to the inspection conducted on 23/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHIAN TIAN MING ("the third party claimant") of vehicle no. SLC9815Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLC9815Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$_____ to CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD.

Dated this _____ day of SEPTEMBER, 20 18.

CLAIMANT:

Signature: _____

Signed by "the workshop"
(with chop)

Name: _____

LER YEONG CHERNG

Address: _____

330 UBI ROAD 3 SINGAPORE 408650

WITNESS:

Signature: _____

Signed by appointed Surveyor

Name: _____

Address: _____



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

TAX INVOICE

Co Reg No : 199707303Z

GST Reg No : 19-9707303-Z

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name /Mr Chian Tian Ming (Zhong Zhen Reg No/Reg Date SLC9815Z*KC17R(/ 31/05/2016 Date In/Mileage 15/08/2018/ 35152 Chassis/Package KNAFX411MG5579476 /T3 Engine No G4FGFH609713 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
F0000036	Credit	15/10/2018/ 09:12	D5	323 / ChrisBulaclac	63253	77404311

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 REVERSE SENSOR SET				280.00
M SUNDRY C & C LOGO				50.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				300.00
S MIPNT88088 TO REPLACE REAR BUMPER,REAR BEAM,ETC -REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				1200.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				1260.00
X KS 86611 A7 000 COVER - REAR BUMPER	1.00	768.00	0.00	768.00
X KS 86695 A7 000 COVER - REAR BUMPER,	1.00	234.00	0.00	234.00
X KS 86613 A7 000 LH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
X KS 86614 A7 000 RH SIDE BRACKET ASSY	1.00	33.00	0.00	33.00
X KS 0G032 50 037A CLIP - BUMPER	10.00	2.00	0.00	20.00
X KS 86641 A7 000 LH STAY - REAR BUMPE	1.00	75.00	0.00	75.00
X KS 86310 A7 050 KIA LOGO ASSY	1.00	37.00	0.00	37.00
X WFFORTE FORTE EMBLEM	1.00	40.00	0.00	40.00
X WFEMBLEMK3 EMBLEM K3	1.00	15.00	0.00	15.00
X KS 86631 A7 000 BEAM-RR BUMPER	1.00	365.00	0.00	365.00
Z NOTES ACCIDENT ON 13/08/2018 ALONG JUNC B/W UPP SERANGOON RD & HOUGANG AVE 4 OWNER CLAIMING THIRD PARTY LOSS OF USE 04DAYS x \$80.00 = S\$320.00 TP # SLU4693X TP INS : I.I.I				F.O.C.

Parts	1,620.00	Nett	4,770.00
Labour	0.00	7% GST on	333.90
Standard Menu	0.00		
Specialist Job	3,100.00	Total Payable	5,103.90
Others(Lub,etc)	0.00	Paid	0.00
Sundry	50.00	Total Due	5,103.90
Total(w/o GST)	4,770.00	Balance B/FWD	20,474.56
		Total Payable or C/FWD	25,578.46

Any dispute to the invoice must be made within 3 days.
 Cheques should be crossed and made payable to CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - (SERVICE)
 This is a computer generated document, no signature is required.

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time : 16 Aug 2018 / 08:13:15

Receipt Date/Time : 16 Aug 2018 / 08:13:15

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180816-000112

Previous Receipt No.:

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLU4693X As at 13 Aug 2018/08:10:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SLU4693X Enquiry Fee 20180816081159319323	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx5046 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018 Edit Reg		23 Aug 2018 00:00 Edit Adj Rpt	S\$4,770.00 Edit Estimates	S\$4,770.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORTDELGRO RENT-A-CAR PTE. LTD. Co. Reg. No.: -								
Main Claimant:	CHIAN TIAN MING , ID: S72168731								
Vehicle Reg. No.:	SLC9815Z	Date of Loss:	13/08/2018 08:00 - :59 [26 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCA180179	Policy/Cover Note No.:	M495128/01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLU4693X	Policy No. (Claimant):	PNPV2018-00006647						
		Excess:							
Repairer:	Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (26/11/2018): Alert - Adj Mandate Approved (S\$5351.35) - SLC9815Z - Claim Handler: Lalitha Kri... III_SG (31/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SLC9815Z - Claim Handler: Lalitha Krishn... III_SG (20/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SLC9815Z - Claim Handler: Lalitha Krishn... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC9815Z (MCA180179)
 [SLU4693X]
 TP
 CHIAN TIAN MING
 Aug 13 2018 8:00AM
 [COMFORTDELGRO RENT-A-CAR PTE. LTD]
 Cycle & Carriage Fulco Motor Dealer Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/11/18 19:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 19:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
18	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
19	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
20	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
21	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
22	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
23	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
24	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
25	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
26	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
27	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
28	21/11/18 19:16	General View		Load JPG	<input checked="" type="checkbox"/>
29	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	21/11/18 19:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 16:46	TP EST & GIA REPORT	Load PDF	
2	23/08/18 15:00	TP SCENE PHOTOS	Load PDF	
3	27/08/18 19:28	TP ESTIMATE- MARKED	Load PDF	
4	21/11/18 11:48	WORKSHOP INVOICE	Load PDF	
5	21/11/18 11:48	LTA SEARCH	Load PDF	
6	24/12/18 10:18	AUTHORISATION TO ACT FORM	Load PDF	
7	24/12/18 10:18	DISCHARGE VOUCHER	Load PDF	
8	24/12/18 10:18	LOD	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/08/18 08:54	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18014945/UHB3Q2

Date: 24/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M495128/01

Claimant Vehicle
No : SLC9815Z

Insured Vehicle No : SLU4693X

Date of Loss: 13/08/2018

Nature of Claim: TP

Claim No: MCA180179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC9815Z

Make & Model: KIA FORTE K3, 1.6 (A)

Engine No: G4FGFH609713

Reg. Date: 31/05/2016 (Man. Year: 2016)

Chassis No: KNAFX411MG5579476

Colour: Silver

Odometer: 34375 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,645.00	1,950.00	1,695.00	46.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,560.00	2,820.00	2,740.00	49.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,205.00	4,770.00	4,435.00	48.18
+ GST 7.00/7.00% (S\$)	644.35	333.90	310.45	48.18
Nett Amount (S\$)	9,849.35	5,103.90	4,745.45	48.18
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,351.35		

INSPECTION

Date of Assignment: 23/08/2018

Date Inspected: 23/08/2018 Inspected At:

Cycle & Carriage Fulco Motor Dealer Pte
Ltd (HQ)
330 Ubi Road 3
Singapore 408650

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: 143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9815Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*280.00 FS
2	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
3	1		*COVER-REAR BUMPER	Dented	768.00 FS	*768.00 FS
4	1		*COVER-REAR BUMPER	Deformed / Cut	234.00 FS	*234.00 FS
5	1		*LHR REFLECTOR REFLEX	Not Necessary	114.00 FS	*- FS
6	1		*LH SIDE BRACKET ASSY	Necessary	33.00 FS	*33.00 FS
7	1		*RH SIDE BRACKET ASSY	Necessary	33.00 FS	*33.00 FS
8	10		*CLIP-BUMPER	Necessary	20.00 FS	*20.00 FS
9	1		*BEAM-RR BUMPER	Cracked	365.00 FS	*365.00 FS
10	2		*BRACKET-REAR BEAM	Not Necessary	10.00 FS	*- FS
11	1		*BRACKET-REAR BEAM	Not Necessary	5.00 FS	*- FS
12	1		*LH STAY -REAR BUMPER	Bent	75.00 FS	*75.00 FS
13	1		*RH STAY -REAR BUMPER	Not Necessary	75.00 FS	*- FS
14	1		*PANEL ASSY -TRUNK L	Repair	1,491.00 FS	*- FS
15	1		*KIA LOGO ASSY	Necessary	37.00 FS	*37.00 FS
16	1		*FORTE EMBLEM	Necessary	40.00 FS	*40.00 FS
17	1		*EMBLEM K3	Necessary	15.00 FS	*15.00 FS
Total Parts (S\$)					3,645.00	1,950.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	80.00	80.00
2	TO REMOVE & RE-INSTALL TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	600.00	300.00
3	TO TRANSFER REAR BOOT COMPONENT & MECHANISM PARTS	New	600.00	0.00
4	TO REPLACE REAR BUMPER ,REAR BEAM ,REAR BOOT ,ETC -REPAIR REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	2,400.00	1,200.00
5	TO APPLY SEALANT KIT ON NEW PANEL	New	200.00	0.00
6	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,680.00	1,260.00
Gross Labour Cost (S\$)			5,560.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >