

ASS. REC. BY:

REF: CS3/MSG18014950/424d307

Special Instruction:

Survivor:

Maimen

From (Person):

Marcus

Jasmine Tok

ASSIGNMENT (Office)

of MSG

Date/Time: 16/8/18 @ 10:19 am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 6922 H

Insured:

Yp 2074T

at Workshop m/s

Motor Intel

Tel:

6281 0087

of

13 Kaki Bkt Rd 4 #01-20

Policy No:

B287212S1MKC

Claim No:

567279

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/8/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

2:22pm @ 16/8/18

Person Contacted:

Tinnie

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKZ 6922 H - CS/FCI 1700 2843 / Ugh 3m2 DoA: 11/2/17
	Yp 2074T - CS3/MSG1 700 3018 / Ggh 3m2 DoA: 16/2/17
17/8/18	Dismantled.
24/8/18	After Repair

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MSCH  
**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 6922H

at Workshop m/s 1 wheel motor

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKZ 6922H Yr Regn: 11 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Honda verel c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: SP/PR T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R411109078

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/8/18 D.O.I. 16/8/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 Sep.  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No report @ 5.30pm  
park & found.

4500 - 6500

28/8/18 submit PRS Report.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

1)

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: 120

Transportation: 10

Photos

Others

TOTAL

130

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2018		16 Aug 2018 10:19 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LIM TRADERS PTE LTD, Co. Reg. No.: 200305123D			
Main Claimant:	CHEW ENG PENG, ID: S2187033A			
Vehicle Reg. No.:	SKZ6922H	Date of Loss:	13/08/2018 12:00 - :59 [30 Months and 15 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 567279	Policy/Cover Note No.:	B28721251MKC (Comprehensive) Coverage: 08/04/2018 - 07/04/2019	
Vehicle Reg. No. (Insured):	YP2074T	Policy No. (Claimant):		
		Excess:		
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/08/2018]			
Driver/Custodian (Insured):	WU DEJUN (), NRIC: G2439030L, Tel: +6585878118			
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP reject SJE , please assign Lkk to survey. Liability : 100% Contact : Mtr Wilson @ 8838 3318			

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS ▢

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18014950/Uz4d3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-08-2018



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YP 2074T	Veh. Inspected	SKZ 6922H
Policy No.	B28721251MKC	Coverage (\$)	0.00
Claim No.	567279	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	16/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	13/08/2018	Inspection Date	16/08/2018
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/08/2018 17:01
Date Of Accident	13/08/2018 12:30
Exact Location Of Accident	CP OF BLK 205 BEDOK CENTRAL LOT 35
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ6922H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEW ENG PENG
NRIC No	S2187033A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90281879
Alternative Phone No	OTHERS-90281879

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088387941-01
Cover Note Number	

### Driver

Name of Driver	CHEW ENG PENG
NRIC No	S2187033A
Date Of Birth	16/01/1964
Occupation	INDOOR
Date Of Driving Pass	14/01/1983
Driving Experience	35 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90281879
Fax Number	
Contact Number	OTHERS-90281879
Email Address	NOEMAIL

Address	BLK 152 #13-07 YUNG HO ROAD
Postcode	610152
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP2074T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/08/18 @ 1030 hrs, I had parked my vehicle car plate no. SKZ 6922H at lot 35 carpark of BIK 205 Bedok Central. At 1645 hrs, I went to collect my vehicle and discovered that my ~~car~~ vehicle's right front portion was badly damaged. When I checked my car video camera, I saw this truck vehicle no. YP2074T, which was initially parked on my ~~right~~ right parking lot, had collided into my vehicle when the driver drove out from the parking lot, swinging left colliding into my vehicle's right portion. Thus, I have encountered a hit and run incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4

Reporting Centre  
Name: Singapore 415933  
Tel: 67416697  
NRIC/FIN No.: Fax: 67492305  
Email: vackb@singnet.com.sg

> **Back to OneMotoring**

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7033A
<b>Vehicle Details</b>	
Vehicle No.:	SKZ6922H
Vehicle to be Exported:	No
Intended De-registration Date:	16 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4029082
Chassis No.:	RU11109078
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,940.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$8,940.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2026
PARF Rebate Amount:	\$6,705.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,399.00
COE Rebate Amount:	\$41,266.00
<b>Total Rebate Amount:</b>	<b>\$47,971.00</b>

The information contained herein is correct as at 16 Aug 2018

OK



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2018		16 Aug 2018 10:19 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LIM TRADERS PTE LTD, Co. Reg. No.: 200305123D	
Main Claimant:	CHEW ENG PENG, ID: S2187033A	
Vehicle Reg. No.:	SKZ6922H	Date of Loss: 13/08/2018 12:00 - :59 [30 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567279	Policy/Cover Note No.: B28721251MKC (Comprehensive) Coverage: 08/04/2018 - 07/04/2019
Vehicle Reg. No. (Insured):	YP2074T	Policy No. (Claimant):
		Excess:
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 17/08/2018]	
Driver/Custodian (Insured):	WU DEJUN (), NRIC: G2439030L, Tel: +6585878118	
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP reject SJE , please assign Lkk to survey. Liability : 100% Contact : Mtr Wilson @ 8838 3318	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		



















































  



















































ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

**\*SKZ6922H (567279)**  
**[YP2074T]**  
**TP**  
**CHEW ENG PENG**  
**Aug 13 2018 12:00PM**  
**[LIM TRADERS PTE LTD]**  
**Motor Intel Automo Pte Ltd - Kaki Bukit**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports								1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	15/08/18 15:17	Accident Statement From:SC - Reg. No: YP2074T, Claimant: LIM TRADERS PTE LTD		Load HTM						
Photos/Images								3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/08/18 18:09	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
2	16/08/18 18:10	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
13	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
14	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
15	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
16	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
17	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
18	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
19	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
20	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
21	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
22	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
23	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
24	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
25	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
26	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
27	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
28	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
29	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
30	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
31	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
32	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					
33	16/08/18 18:10	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/08/18 18:10	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	18/08/18 13:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	25/08/18 20:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	28/08/18 11:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
134	28/08/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
135	28/08/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
136	28/08/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
137	28/08/18 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/08/18 15:17	<b>E-FILE REPORT (SKZ6922H)</b> From: SC - Reg. No: YP2074T, Claimant: LIM TRADERS PTE LTD		Load PDF	
2	15/08/18 15:18	<b>TP PRI &amp; ACCDT REPORT</b>		Load PDF	
3	15/08/18 15:33	<b>TP REJECTION REPLY &amp; WE NOMINATED LKK TO BE SJE</b>		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18014950/UZ4D3E2

Date: 29/08/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28721251MKC

Claimant Vehicle No : SKZ6922H

Insured Vehicle No : YP2074T

Date of Loss: 13/08/2018

Nature of Claim: TP

Claim No: 567279

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ6922H

Make &amp; Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4029082

Reg. Date: 29/01/2016 (Man. Year: 2015)

Chassis No: RU11109078

Colour: White

Odometer: 88182 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 16/08/2018

Date Inspected: 16/08/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)  
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre  
Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$6,500.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ6922H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >