

Police Report



SINGAPORE
POLICE FORCE



T/20170714/2060

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

4 of 4

Report No: T/20170714/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report

G /
Sgt CHOO YOU CHENG, EUGENE

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time
14/07/2017 12 52

Officer In Charge Of Case:

TP / CIT /
Sgt MARIAH BINTE ZAKARIA
Contact No: 65476433

Classification Of Case:

Authentication Stamp
AP 115



SINGAPORE POLICE FORCE



T/20170714/2042

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20170714/2042

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2017 12:04		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: Yee See Niap			Address: 110 JURONG EAST ST 13 HDB JURONG EAST SINGAPORE 600110		
ID Type / ID No.: NRIC NO / S2011736B			Contact No.: Home/Office: Mobile: 84012852		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 09/03/1952	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/07/2017 09:20	Type of Location:
Location: PAN ISLAND EXPRESSWAY towards airport before toa payoh and Thomson exit				
Weather:		Road Surface: Certified True Copy	Road Speed Limit:	
Traffic Flow:		Traffic Control pursuant to Sec. 78 of the Evidence Act, Cap 97.		Traffic Volume:
Type of Collision:		Anyone conveyed by ambulance: No		

Siti Rohayah Kasmani (M)
Traffic Police
Date: 14 AUG 2017

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDK3330Y	Car				Seriously Damaged	0
SH6201E	taxi				Seriously Damaged	1
SLH8174U	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20170714/2042

2 of 3

Report No. T/20170714/2042

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Brief Details.

As above mention date time and location,

I was at the location mentioned. I was driving slowly it was drizzling then the front car brake and I didn't notice that the car braked and I hit onto the rear of the car in front.

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

.....
Siti Rohaiyah Kasmani (MX)
Traffic Police

Date :

14 AUG 2017



**SINGAPORE
POLICE FORCE**



T/20170714/2042

3 of 3

Report No. T/20170714/2042

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD ALFIE AASRIQ BIN MOHAMMED
IRWAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Certified True Copy
pursuant to Sec. 78 of the
Evidence Act, Cap 97.

Date/Time:
14/07/2017 12:04


Siti Rohalyah Kasmani (MX)
Traffic Police
Date :

Classification Of Case: 14 AUG 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/07/2017 15:00
Date Of Accident	14/07/2017 09:20
Exact Location Of Accident	PIE(AIRPORT) B4 THOMSON EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6201E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	
Driver	
Name of Driver	YEE SEE NIAP
NRIC No	S2011736B
Address	110 #10-298 JURONG EAST STREET 13

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	2

Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20170714/2042

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES

arks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDK3330Y

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLH8174U

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Injured person in which vehicle?


SDK3330Y

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

COMFORT TRANSPORTS PTE LTD
CO REG NO 194302418



S R Moorthy
CSO

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

PREPARED BY: B. P. THOMSON ESQ

A) SH6201E
B) SDK3330Y
C) SLH 81744

CONFIRMED

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 14/7/17 at about 0915hrs while I was
A was driving straight ahead, collided on
the rear of Veh B when it stopped
suddenly - when I came out to check
it was realized that Veh C was also
involved in the chain collision.

Refer Police Report - T/20170714/2042

Declaration

We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION LTD LTD
CO REG NO 129503210

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

SR Mool...
GSO
14/7/17



**SINGAPORE
POLICE FORCE**



T/20170714/2042

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20170714/2042

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2017 12:04		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: Yee See Nlap			Address: 110 JURONG EAST ST 13 HDB JURONG EAST SINGAPORE 600110		
ID Type / ID No.: NRIC NO / S2011736B			Contact No.: Home/Office: Mobile: 84012852		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 09/03/1952	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 14/07/2017 09:20	Type of Location:
Location: PAN ISLAND EXPRESSWAY towards airport before toa payoh and Thomson exit				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SDK3330Y	Car				Seriously Damaged	0
SH6201E	taxi				Seriously Damaged	1
SLH8174U	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20170714/2042

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20170714/2042

CONTINUATION OF REPORT

Brief Details.

As above mention date time and location,

I was at the location mentioned. I was driving slowly it was drizzling then the front car brake and I didn't notice that the car braked and I hit onto the rear of the car in front.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20170714/2042

3 of 3

Report No. T/20170714/2042

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD ALFIE AASRIQ BIN MOHAMMED
IRWAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
14/07/2017 12:04

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6258
www.police.gov.sg

Our Ref : TP/IP/36697/2017
Date : 19 July, 2017

Tan Kong Beng
Block 507 Jelapang Road
11-14
Singapore 670507

Dear Sir/Madam


**ACCIDENT INVOLVING SLH8174U, SDK3330Y AND SH6201E ON 14.7.2017 AT 0940 HRS,
ALONG PAN ISLAND EXPRESSWAY**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver/rider of motor taxi SH6201E has committed an offence of Careless driving under Rule 29 Road Traffic Rules. Action has been initiated against the driver/rider for the said offence.

3. If you have any queries, please contact the Investigation Officer, Mohamed Yazid at telephone number 6547 2075.

Yours faithfully


Zainuddin M Saleh, SSI(2)
For Head Investigation
Traffic Police
Singapore Police Force



**SINGAPORE
POLICE FORCE**

TRAFFIC POLICE
10 UBI AVE 3
SINGAPORE 408865
Tel : 65476244/43
Fax : 65474749

Your Ref: MKR/109/7431/2017/as

Our Ref: TP/IP/36699/2017(TP101121/SR)

Date : 14/08/2017

ROY & PARTNERS
101 CECIL STREET #11-09
TONG ENG BUILDING
SINGAPORE 069533

15 AUG 2017

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NOS: SH6201E, SLH8174U AND SDK3330Y ON 14/07/2017.

I refer to your application dated 02/08/2017. I wish to draw to your attention to the item(s) marked "X" hereunder:-

- ☐ Please be informed that Traffic Police will not investigating into the accident as it is a non-injury case which did not fall within the various categories of exception. You may wish to know that this is pursuant to the Non-injury Accident Reporting Scheme which was implemented on 1 May 1999.
- ☐ This case is still under investigation by IO _____. Tel no: _____.
- ☐ No action is being taken against anyone in this case. This does not preclude further prosecution should new evidence emerge later. Our findings do not affect insurance and civil claims.
- ☒ **Action is being taken against the driver of vehicle no: SH6201E for Careless Driving.**
- ☐ The driver of vehicle no: _____ has accepted the offer of composition on _____ for Careless Driving.
- ☐ The driver of vehicle no: _____ has been given a warning for Inconsiderate Driving.
- ☐ The driver of vehicle no: _____ has pleaded guilty in Court no: 24 on _____ for Careless Driving.
- ☒ **A copy of Police Report T/20170714/2042 is attached as requested.**
- ☐ Please be informed that there is no record of this incident/accident in this case.
- ☐ There is no Police Report for vehicle no: _____.
- ☐ The Sketch Plan will be sent later.
- ☐ The Coroner's Inquiry was held on _____ in Court no: 22 C.I. No: _____.

Yours Faithfully


SITI ROHAYAH KASMANI
for HEAD INVESTIGATION
TRAFFIC POLICE

*Delete where inapplicable

A FORCE FOR THE NATION

NP 510



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-110240
Date of Request: 28/07/2017

Your Ref No: MKR/109/7431/2017/MT

ROY & PARTNERS
101 Cecil Street #11-09
Tong Eng Building
Singapore 069533

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 14/07/2017
Place of Accident: PIE TOWARDS CHANGI AIRPORT
Client Vehicle No: SDK3330Y

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-110245
Date of Request: 28/07/2017

Your Ref No: MKR/109/7431/2017/MT

ROY & PARTNERS
101 Cecil Street #11-09
Tong Eng Building
Singapore 069533

Dear Sir/Madam,

Date of Accident: 14/07/2017
Vehicle No: SDK3330Y
of Accident: PIE TWDS CHANGI AIRPORT B4 THOMSON EXIT
Involving Vehicle No: SH6201E

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SH6201E	PIE TWDS CHANGI AIRPORT B4 THOMSON EXIT	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

☒ GIRO ☐ Cash ☐ Cheque



**SINGAPORE
POLICE FORCE**

PAYMENT

TAX INVOICE

Invoice No: SPF2017073101020593
Date/Time: 31/07/2017 11:01:35

Application Paid Via: Master
GST Reference No: MG-8400000-5

Transaction Ref No: TP000101121

Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1 Police Document	Search Fee	0050000001725289	14.00	0.00	1	14.00

Total (S\$) 14.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION

**SINGAPORE
POLICE FORCE****PAYMENT****TAX INVOICE**

Invoice No: SPF2017081001022642
Date/Time: 10/08/2017 12:23:34

Application Paid Via: Master
GST Reference No: MG-8400000-5

Transaction Ref No: TP000101121

Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1 Police Document	Document Fee	0050000001728495	16.00	0.00	1	16.00
Total (S\$)						16.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TAN KONG BENG
BLK 507 JELAPANG ROAD #11-14
SINGAPORE 670507

Contact : 98778860

TAX INVOICE

Date : 07/06/2018
Date in : 14/07/2017
Vehicle Num. : SDK3330Y
Make/Model : NISSAN SUNNY 1.6EXM-2005
Chassis/Eng# : JN1CFAN16Z0515099/QG16388946
Accident Date : 14/07/2017
Claim No : CLM14123
Reference : JULY-29/2017
Policy No. : 5009621484-11 (14/10/2017)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0241-18-N51 DATED 07/05/2018
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
20,600.00

E. & O.E.	Sub S\$:	20,600.00
	Add GST (7 %) S\$:	1,442.00
	Total Amount S\$:	22,042.00



for N-51 AUTOMOTIVE PTE LTD



bizSAFE₃



TOWING.COM SERVICES

Workshop : Blk 520 Jelapang Road #01-281 Singapore 670520
Please Call : 9797 5797 Fax : 6996 5797

CASH / INVOICE

No: 20091

Date: 14/7/17

M/s: Cash
Thomas Henry Capet

Place from: Autohub #01-17

Place to: SPK 53304

Breakdown Vehicle No.: Nura Sunay

Vehicle Model:

Remarks:

Tel:

Pager:

H/P:

Wrecker Vehicle No: 60905

Time:

Memb. No:

\$: 50

24 Hours - 365 days Accident / Emergency Towing Services

Issued by: [Signature]

Received's Signature:

Note

Conditions on the use of our towing trucks, truck cranes, etc. Towing of vehicles is at customer's risks. We will NOT be responsible for any consequences which may arise due to breakage or other unforeseen circumstances









PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0241-18-N51

07 May 2018

Tan Kong Beng
Blk 507 Jelapang Road #11-14
Singapore 670507

INVOICE No. 0241-18-N51

Vehicle No. SDK3330Y

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,276.00
Total amount payable		<u>\$1,276.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0241-18-N51

07 May 2018

ACCIDENT VEHICLE SURVEY REPORT

Tan Kong Beng
Blk 507 Jelapang Road #11-14
Singapore 670507

VEHICLE INFORMATION:

Vehicle Reg No.:	SDK3330Y	Odometer:	184021km
Make & Model:	Nissan Sunny 1.6 EXM	Colour:	Gold
Chassis number:	JN1BAAG16Z0515099	Date of accident:	14/07/2017
Year of Regn.:	15/10/2005	Date inspected:	17/07/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	05/08/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Yokohama	5mm/Yokohama	185/65R15
Rear:	5mm/Yokohama	5mm/Yokohama	185/65R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
AIRCON CONDENSER	1	bent	534.20	534.20	X NN
CENTER EXHAUST SILENCER PIPE	1	bent	471.90	✓ 471.90	BT ✓
FRONT BONNET	1	buckled	891.20	891.20	R X
FRONT BUMPER	1	squashed	370.60	✓ 370.60	DD ✓
FRONT BUMPER BEAM	1	bent	156.60	156.60	R X
FRONT BUMPER CHROME MOULDING	1	deformed	168.60	70.00 168.60	DD ✓
FRONT BUMPER FOGLAMP COVER L/R	2	warped	240.00	240.00	SVC
FRONT BUMPER FOGLAMP L/R	2	fractured	558.00	558.00	SVC X
FRONT BUMPER REINFORCEMENT	1	bent	316.10	316.10	SVC X
FRONT BUMPER REINFORCEMENT BRACKET L/R	2	bent	183.40	✓ 183.40	BT ✓
FRONT BUMPER SIDE RETAINER L/R	2	necessary	183.40	40.80 183.40	NEC ✓
FRONT GRILLE	1	fractured	236.20	✓ 236.20	BR ✓
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	35.20	✓ 35.20	NEC ✓
FRONT HORN 'HI'	1	distortion	98.50	98.50	NN X
FRONT HORN 'LOW'	1	distortion	98.50	98.50	NNX
FRONT SUPPORT PANEL	1	bent	540.40	540.40	R X
FRONT SUPPORT PANEL BRACKET L/R	2	bent	62.40	62.40	NNX
REAR AXLE CARRIAGE	1	distorted	963.60	963.60	NNX
REAR BOOTLID	1	buckled	655.00	✓ 655.00	DB ✓
REAR BOOTLID LOWER CHROME MOULDING	1	fractured	167.60	✓ 167.60	CUT ✓
REAR BOOTLID MECHANISM LOCK STRIKER	1	bent	51.90	✓ 51.90	BT ✓
REAR BUMPER	1	squashed	433.50	✓ 433.50	CRU ✓
REAR BUMPER BRACKET L/R	2	bent	183.40	✓ 183.40	BT ✓
REAR BUMPER CHROME MOULDING	1	deformed	168.60	✓ 168.60	CUT ✓
REAR BUMPER INNER SPONGE	1	deformed	133.80	✓ 133.80	CUT ✓
REAR BUMPER SIDE RETAINER L/R	2	necessary	70.40	44.00 70.40	NEC ✓
REAR END PANEL	1	buckled	376.20	✓ 376.20	BUC ✓
REAR EXHAUST ALUMINIUM HEAT SHIELD	1	deformed	142.10	✓ 142.10	DB ✓
REAR FENDER L/R L-R, R-BAC	12	buckled	1,789.60	848.60 1,789.60	X D
REAR FENDER MUDFLAP L/R	2	deformed	142.40	142.40	NN X
REAR SHOCK ABSORBER L/R	2	R-bent	216.00	108.00	NN X
REAR SPARE TYRE PANEL	1	buckled	848.60	771.50 848.60	BUC ✓
REAR SPARE TYRE RETAINER LOCK	1	bent	87.90	67.50 87.90	BT ✓
REAR TAILLAMP INNER PANEL L/R	2	buckled	311.20	311.20	DD ✓
REAR WHEEL BEARING L/R	2	R-dislodged	291.80	286.40 145.90	DL ✓
REAR WINDSCREEN MOULDING	1	necessary	130.10	130.10	✓ D

Subtotal before discount S\$ 12,308.90 S\$ 12,055.00 5256.00

Percentage discount 30% and 30%

S\$ 3,692.67 S\$ 3,616.50 1576.80

Sub-total 1 S\$ 8,616.23 S\$ 8,438.50 3679.20

CENTER EXHAUST GASKET	1	necessary	15.00	✓15.00 NEC ✓
CENTER EXHAUST RUBBER MOUNTING	1	distorted	25.60	✓25.60 DIS ✓
FRONT BONNET MECHANISM LOCK	1	bent	49.40	49.40 R X
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	deformed	20.00	20.00 NNX
FRONT BONNET WEATHERSTRIP	1	deformed	18.10	18.10 NNX
PETROL TANK	1	distorted	577.50	577.50 NNX
RADIATOR (MANUAL)	1	bent	585.70	585.70 XNN Δ
REAR ABS SENSOR L/R	2	R-shortcd	647.40	243.10 323.70 CUT ✓
REAR BOOTLID 'EX-SALOON' EMBLEM	1	necessary	54.00	✓54.00 NEC ✓
REAR BOOTLID 'LOGO' EMBLEM	1	necessary	38.80	✓38.80 NEC ✓
REAR BOOTLID 'SUNNY' EMBLEM	1	necessary	62.40	✓62.40 NEC ✓
REAR BOOTLID HINGES L/R	2	bent	147.20	147.20 BTX R
REAR BOOTLID MECHANISM LOCK	1	bent	43.30	✓43.30 BT ✓
REAR BOOTLID RUBBER GUIDE STOPPER L/R	2	deformed	21.60	21.60 NNX
REAR BOOTLID UPHOLSTERY TRIM GARNISH	1	deformed	188.30	188.30 NNX
REAR BOOTLID UPPER CHROME MOULDING	1	fractured	369.10	✓369.10 CRA ✓
REAR BOOTLID WEATHERSTRIP	1	deformed	59.90	✓59.90 CUT ✓
REAR BUMPER END SEAL COVER L/R	2	reuse	50.60	-0.00-
REAR CHASSIS END SUB FRAME L/R	2	R-bent	795.80	397.90 R X
REAR END PANEL INNER TOP GARNISH	1	fractured	69.60	✓69.60 CUT ✓
REAR END PANEL INNER UPHOLSTERY TRIM GARNISH	1	deformed	144.50	✓144.50 DIS ✓
REAR EXHAUST GASKET	1	necessary	34.70	✓34.70 NEC ✓
REAR EXHAUST RUBBER MOUNTING	3	distorted	32.40	✓32.40 DIS ✓
REAR EXHAUST SILENCER BOX	1	bent	468.70	Δ 468.70 BTX R
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	466.60	466.60 ✓ Δ
REAR FENDER LH AIR VENT	1	warped	50.30	-50.30 NNX
REAR FLOOR PANEL	1	buckled	832.70	782.00 832.70 BUG ✓
REAR SPARE TYRE INNER TOP BOARD COVER	1	deformed	203.30	131.20 203.30 DIS ✓
REAR SPARE TYRE INNER TOP CARPET	1	reuse	452.30	-0.00 X
REAR SPARE TYRE SIDE EXTENSION PANEL L/R	2	buckled	250.60	250.60 BUC ✓ Δ
REAR TAILLAMP BACK RUBBER SEAL L/R	2	necessary	44.60	✓44.60 NEC ✓
REAR TAILLAMP L/R	2	fractured	566.40	✓566.40 BR ✓
REAR TAILLAMP LOWER BRACKET L/R	2	bent	54.00	✓54.00 BT ✓

Subtotal before discount S\$ 7,440.40 S\$ 6,215.90 3825.00
Percentage discount 10% and 10% S\$ 744.04 S\$ 621.59 382.50

		Sub-total 2	S\$ 6,696.36	S\$ 5,594.31 3442.50
FRONT BONNET INSULATOR MAT CLIPS - SET	1	necessary	50.00	50.00 NNX
FRONT BUMPER CLIPS - SET	1	necessary	30.00	✓30.00 NEC ✓
FRONT GRILLE CLIPS - SET	1	necessary	30.00	15.60 30.00 NEC ✓
FRONT NUMBER PLATE	1	bent	25.00	✓25.00 BT ✓
REAR BOOTLID UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	50.00	30 50.00 NEC ✓ Δ
REAR BOOTLID UPPER CHROME MOULDING CLIPS - SET	1	necessary	30.00	✓30.00 NEC ✓
REAR BUMPER END SEAL COVER CLIPS L/R - SET	2	necessary	60.00	✓60.00 NEC ✓
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	200.00 350.00 CUT ✓
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	✓30.00 NEC ✓

390.60

REAR END PANEL INNER UPHOLSTERY TRIM

GARNISH CLIPS - SET

1	necessary	30.00	✓30.00	NECV
---	-----------	-------	--------	------

REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET

2	necessary	80.00	60.00	80.00	NECV
---	-----------	-------	-------	-------	------

REAR FLOOR PANEL INSULATION

1	necessary	600.00	120.00	600.00	NECV
---	-----------	--------	--------	--------	------

REAR SPARE TYRE

1	reusc	280.00	0.00		
---	-------	--------	------	--	--

REAR SPARE TYRE PANEL INSULATION

1	necessary	400.00	115.00	400.00	NECV
---	-----------	--------	--------	--------	------

REAR TAILLAMP CLIPS L/R - SET

2	necessary	60.00	44.00	60.00	NECV
---	-----------	-------	-------	-------	------

REAR WINDSCREEN SEALANT

1	necessary	100.00	50.00	100.00	NECV
---	-----------	--------	-------	--------	------

Subtotal before discount		SS 2,205.00	SS 1,925.00	759.60
--------------------------	--	-------------	-------------	--------

Sub-total 3		SS 2,205.00	SS 1,925.00	759.60
-------------	--	-------------	-------------	--------

Parts-total		SS 17,517.59	SS 15,957.81	4202.10
-------------	--	--------------	--------------	---------

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

180.00	150.00	100.00	✓
--------	--------	--------	---

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

200.00	140.00	100.00	✓
--------	--------	--------	---

To remove and refit rear windscreen(to FR)

150.00	120.00	✓	Δ
--------	--------	---	---

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

500.00	350.00	X	Δ
--------	--------	---	---

To road test driving, check and resetting wheel alignments system.

180.00	180.00	60.00	✓
--------	--------	-------	---

To remove, change petrol tank.

120.00	80.00	NNX	
--------	-------	-----	--

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00	120.00	80.00	✓
--------	--------	-------	---

To send vehicle for cleaning, shampoo, upholstery and cushion seat.

200.00	150.00	NNX	
--------	--------	-----	--

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

2,000.00	1,600.00	1,000.00	✓
----------	----------	----------	---

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

1,200.00	1,000.00	400.00	✓
----------	----------	--------	---

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

200.00	140.00	100.00	✓
--------	--------	--------	---

To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.

5,500.00	3,740.00	2,500.00	✓
----------	----------	----------	---

To mount vehicle on to Car 'O' Liner.

400.00	400.00	250.00	✓
--------	--------	--------	---

To apply anti-rust chemical on repaired and replaced panel.

120.00	120.00	100.00	Δ
--------	--------	--------	---

Labour Total		SS 11,090.00	SS 8,290.00	4,620.00
--------------	--	--------------	-------------	----------

Parts & Labour Total		SS 28,607.59	SS 24,247.81	8822.10
----------------------	--	--------------	--------------	---------

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 20,600.00
and the recommended number of working days for the repairs is within 24 day(s).

45 7,000/2

Repair days 44 16

B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

TGL m
8/8/18