




Report No: 0241-18-N51

07 May 2018

ACCIDENT VEHICLE SURVEY REPORT

Tan Kong Beng
Blk 507 Jelapang Road #11-14
Singapore 670507

VEHICLE INFORMATION:

Vehicle Reg No.:	SDK3330Y	Odometer:	184021km
Make & Model:	Nissan Sunny 1.6 EXM	Colour:	Gold
Chassis number:	JN1BAAG16Z0515099	Date of accident:	14/07/2017
Year of Regn.:	15/10/2005	Date inspected:	17/07/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	05/08/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.







