

ASS. REC. BY:

REF

CS3/CT18014979/Gzad3d2

Special Instruction:

Surveyor

From (Person):

Chang Boon Sen

ASSIGNMENT (Office)

of

CTI

Date/Time: 16/8/18 @ 3.57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 8834X

Insured:

SLU 4971T

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 kaki 8kt Ave 2 # 01-17/18

Policy No:

5093013949-01

Claim No:

SNM18D03967C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/08/18

17/8/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

5.30pm @ 17/8/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SLR 8834X - NA/INC 18014867/r3

DOA: 14/8/18

SLU 4971T - NA/INC 18014867/r3

DOA: 14/8/18

20/8/18

Disassembled.

(28/11/13) wef

ASS. REC. BY:

REF:

CTI

C6287m ✓

ASSIGNMENT

From:

Date:

17/8/18

Estimated Cost:

On ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLR 8834X

at Workshop m/s

N-SI Automotive

of

2 kuki Bkt Ave 2 #01-17/18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 8834X

Yr Regn:

30 Aug 2017

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour:

black

A/C:

Insured / Std / NI / NA

Sp. Reading

76124

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU31246740

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

N

BS / ☒ DUNLOP / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17-08-18

Survey held at

w/s

5:40pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

21/8/18

submit PRS report

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Report Format:

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2018		16 Aug 2018 15:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JEYALATHA BALASINGAM, ID: S1500032E		
Main Claimant:	DARWIN AUTOMOBILE PTE LTD, Co. Reg. No.: 201612871M		
Vehicle Reg. No.:	SLR8834X	Date of Loss:	14/08/2018 21:00 - :59
Claim Type:	TP / SNM18D03967C02	Policy/Cover Note No.:	DMPCSN3003011800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU4971T	Policy No. (Claimant):	5093013949-01
		Excess:	S\$0.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/08/2018]		
Driver/Custodian (Insured):	VIVECK BALASINGAM (27 / Male), NRIC: S9104401C, Tel: +6585884591		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18014979/Gz4d3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-08-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLU 4971T	Veh. Inspected	SLR 8834X
Policy No.	DMPCSN3003011800	Coverage (\$)	0.00
Claim No.	SNM18D03967C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/08/2018	Inspection Date	17/08/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2018 16:31
Date Of Accident	14/08/2018 21:15
Exact Location Of Accident	HOUGANG AVE 1 INFRT OF BLK 137 LOR AH SOO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8834X
Insured/Policyholder	
Name Of Registered Owner	DARWIN AUTOMOBILE PTE LTD
Co Reg No	201612871M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-83802233
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	CHAUFFEUR
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5093013949-01
Cover Note Number	

Driver

Name of Driver	TANG VINCENT
NRIC No	S8128172F
Date Of Birth	07/09/1981
Occupation	OUTDOOR
Date Of Driving Pass	03/11/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93466118
Fax Number	
Contact Number	
EMail Address	VINCENTTANG108@GMAIL.COM

Address	BLK 4 BEACH RD #05-4959
Postcode	190004
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JOO CHIAT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: 267 ONAN ROAD , POSTCODE: 424773 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3459999 - FAX NO: 64474181
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20180815/2096

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU4971T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VIVECK BALASINGAM
NRIC/Passport Number	S9104401C
Contact Number	85884591
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TANG VINCENT

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SLR8834X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Report Centre Personnel's Signature
Name:
NRIC/EPF No.:

Accident Sketch Plan

SKETCH PLAN



(A) SLR 8834 X.
(B) SLH 4971 T.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/08/18 at @ 3:15 hrs, after dropping off my passenger, I exit the carpark of BLK 137 LOR AH Soo. After passing the carpark barrier, there was a bend. After turning the bend, I saw a car (SLH 4971 T) approaching my direction in my lane. On seeing these, I stopped my vehicle. The said vehicle then kept to the left and drove past me. While driving past me, the said vehicle collided onto the right side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRP/IN No:

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180815/2096

2 of 3

Police Station Of Origin:
Joo Chiat NPP
267 Onan Road SINGAPORE 424773
Tel No 1800-3459999

Report No T/20180815/2096

CONTINUATION OF REPORT

Driver		ID No.	
Name	TANG VINCENT	S8128172F	
Related Vehicle	SLR8834X (Car)	Contact No.	93466118
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	15/08/2018	Date Discharge	15/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver		ID No.	
Name	Viveck balasingam	S9104401C	
Related Vehicle	NIL	Contact No.	85884591
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/8/2018 at around 2130hrs, as I was dropping off a passenger, I was turning out of the carpark turning to road 135 Hougang ave 1. As it was a two way road, when I was about to make a full turn out to the main road to hougang ave 1, I saw a opposite car coming towards me without his headlight on. I quickly stop to let him go pass me, as he was more into the first lane, he turn slightly back into the second lane before going pass my car, but he did not managed to turn enough and hit onto my car head light and the side of my driver door. we then exchange particulars and I told him that we will solve the problem by insurance.

Driver particulars
Viveck Balasingam
S9104401C
08/02/1991
85884591

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	2871M

Vehicle Details

Vehicle No.:	SLR8834X
Vehicle to be Exported:	No
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5946758
Chassis No.:	RU31246740
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,446.00
Original Registration Date:	30 Aug 2017
First Registration Date:	30 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,001.00
COE Rebate Amount:	\$42,865.00
Total Rebate Amount:	\$46,615.00

The information contained herein is correct as at 20 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2018		16 Aug 2018 15:57 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JEYALATHA BALASINGAM, ID: S1500032E								
Main Claimant:	DARWIN AUTOMOBILE PTE LTD, Co. Reg. No.: 201612871M								
Vehicle Reg. No.:	SLR8834X	Date of Loss:	14/08/2018 21:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03967C02	Policy/Cover Note No.:	DMPCSN3003011800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLU4971T	Policy No. (Claimant):	5093013949-01						
		Excess:	\$0.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/08/2018]								
Driver/Custodian (Insured):	VIVECK BALASINGAM (27 / Male), NRIC: S9104401C, Tel: +6585884591								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR8834X (SNM18D03967C02)
[SLU4971T]

TP

DARWIN AUTOMOBILE PTE LTD

Aug 14 2018 9:00PM

[JEYALATHA BALASINGAM]

N-51 Automotive Pte Ltd

View View in Browser

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

1 per page 1 ☒

Assessment Reports			Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)	1	Load HTM
1	15/08/18 16:58	Accident Statement		

3 per page 3 ☒

Photos/Images			Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)		
1	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
3	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
4	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
5	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
6	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
7	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
8	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
9	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
10	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
11	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
12	15/08/18 16:51	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
13	15/08/18 16:52	Police Report [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
14	15/08/18 16:52	Police Report [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
15	15/08/18 16:52	Police Report [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>

1 per page 1 ☒

Documentation			Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		
1	16/08/18 15:57	PRS WITH TP GIA	1 Load PDF	
2	16/08/18 15:57	OI GIA	1 Load PDF	

National Assessment Centre Services (Ubi)			Thumbnail	Print
No	Finalized On			
1	15/08/18 16:52	Accident Sketch Plan [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 16:52	Accident Sketch Plan [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
3	15/08/18 16:52	Individual Statement [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>

LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
No	Relabel/Reorder			
1	21/08/18 14:14	LKKPhotosIn6-1.pdf	1 Load PDF	
2	21/08/18 14:14	LKKPhotosIn6-2.pdf	1 Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/08/18 16:58	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
			3 per page	<input checked="" type="checkbox"/>
Photos/Images			Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)		
1	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	15/08/18 16:51	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	15/08/18 16:52	Police Report	 Load JPG	<input checked="" type="checkbox"/>
14	15/08/18 16:52	Police Report	 Load JPG	<input checked="" type="checkbox"/>
15	15/08/18 16:52	Police Report	 Load JPG	<input checked="" type="checkbox"/>
			1 per page	<input checked="" type="checkbox"/>
Documentation			Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)		
1	15/08/18 16:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	15/08/18 16:52	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	15/08/18 16:52	Individual Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Reset Save Print
DOCUMENTS CHECKLIST There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118014979/GZ4D3E2
Date: 23/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3003011800
Claimant Vehicle No: SLR8834X Insured Vehicle No: SLU4971T
Date of Loss: 14/08/2018 Nature of Claim: TP Claim No: SNM18D03967C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8834X Engine No: LEB5946758
Make & Model: HONDA VEZEL, 1.5 (A) Chassis No: RU31246740
Reg. Date: 30/08/2017 (Man. Year: 2017) Odometer: 76124 km
Colour: Black
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/08/2018
Date Inspected: 17/08/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR8834X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >