

22/03/2001

ASS. REC. BY:

REF: C93/SPF/18015023/Grd3²

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Frankie

of

SPF

Date/Time:

17/8/18

Estimated Cost:

Bill to:

OD / ~~FD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GU 4394T

Insured:

GZ 3371P

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 Kelci Bldg Ave 2 #01-1718

Policy No:

Claim No:

AEMD 1105 / 009 / 2018 / 098

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

3:31pm @ 17/8/18

Person Contacted:

Melody

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

GU 4394T - NA/INC/18014849 / 13

DOA: 14/8/18

GZ 3371P - NA/INC/18014849 / 13

DOA: 14/8/18

Submit LIS \$1700 @ 3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE POLICE FORCE		Ref : CS3/SPF18015023/Grd3	
?? POLICE DIVISIONSINGAPORE 		Date : 17-08-2018	
		Code : SPF1	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GZ 3371P	Veh. Inspected	GU 4394T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/098	Excess (\$)	0.00
Assign From	FRANKIE	Assign Date	17/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/08/2018	Inspection Date	17/08/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			



SINGAPORE POLICE FORCE

Your Ref : AKN-atv-INS-N63-GU4394T-2018

Our Ref : AEMD/105/009/2018/098

Date : 16 Aug 2018

107675

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Tel: 64784840
Fax: 64784848

VISION LAW LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Via Fax only: 65356802

Dear Sir/Madam,

RTA ON 14 AUGUST 2018 INVOLVING GOVT VEH GZ3371P AND YOUR CLIENT'S VEH GU4394T

We refer to your Notification To Conduct Pre-Repair Survey dated 15 Aug 2018 via fax.

- 2 Please be informed that arrangement will be made with Govt Appointed Appraiser, M/s LKK Auto Consultants Pte Ltd for the Pre-Repair Inspection of your client's vehicle.
- 3 Appreciate for the details of your client's vehicle for the same.
- 4 Thank you.

Yours faithfully,

Frankie Thay
Safe Driving Manager
for ASST DIRECTOR

A FORCE FOR THE NATION

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Company Registration No. 200721148H

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-N63-GU4394T-2018 - please reply to: annatan@visionlawllc.com
YOUR REF: GZ 3371 P

16 August 2018

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Avenue 1
#02-25 Paya Ubi Industrial Park
Singapore 408933

BY FAX 6256-4315 & EMAIL:
assignments@lkkauto.com

Dear Sirs

DATE OF ACCIDENT: 14 AUGUST 2018

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We are instructed by **N-51 AUTOMOTIVE PTE LTD** to notify you of a road traffic accident on **14 AUGUST 2018** at about **1400HOURS ALONG GANGSA ROAD** involving our client's vehicle **GU 4394 T** and **GZ 3371 P** driven by you / your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

A copy of the letter dated 16 August 2018 from SPF is enclosed for your attention.

Yours faithfully

(Head Office)
Enc



Form 1

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2018 12:39
Date Of Accident	14/08/2018 14:00
Exact Location Of Accident	GANGSA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU4394T
Insured/Policyholder	
Name Of Registered Owner	BEST QUALITY FURNITURE
Co Reg No	46858100J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92768799

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	PARKED VEH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5098056275
Cover Note Number	

Driver

Name of Driver	LEE CHIN POH
NRIC No	S1395457G
Date Of Birth	23/12/1959
Occupation	INDOOR
Date Of Driving Pass	07/11/1977
Driving Experience	40 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92768799
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 117 PENDING ROAD #03-228
Postcode	670117
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ3371P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/con be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

REPORT NO:
T/2018 0917/2112
BUKIT PANGKAL NRE

VEHICLE A - GU 4394 T (STATIONARY PARKED)
VEHICLE B - G2 3571 P (POLICE VEHICLE)

THE UNIVERSITY OF CHICAGO PRESS



Driver's Signature
(If driver is not the policyholder)
Date & Time

2/ym 15/08/18
Report of Police Personnel's Signature
12/18
12/18/18

Police Report



**SINGAPORE
POLICE FORCE**



T/20180814/2112

Police Station Of Origin:
Bukit Panjang N.P.C.
1 Segar Road #01-05 SINGAPORE 877738
Tel. No: 1800-8926999

Page 1 of 3
Report No.: T/20180814/2112

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/08/2018 16:10	Video Report No.: J/20180814/0112	Station Diary No.: 107
--	--------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LEE CHIN POH		Address: APT BLK 117 PENDING ROAD #03-228 SINGAPORE 870117	
ID Type / ID No.: NRIC NO / S13954570		Contact No: Home/Office: Mobile: 92768799	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 58	Date of Birth: 23/12/1959	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Lorry driver		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 14/08/2018 14:00	Type of Location: Car Park
Location: Along Road 1 GANGSA ROAD			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GU4394T	Lorry	NISSAN		Silver	Slightly Damaged	0
GZ3371P	Truck				Slightly Damaged	0

Accident Photo



SINGAPORE
POLICE FORCE



T/20180814/2112

2 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20180814/2112

CONTINUATION OF REPORT

Brief Details.

On 14/06/2018 at about 1330hr I parked my vehicle GU4394T at blk 106 Gangsa road open space car park lot 269 everything intact situation normal. I proceed home. On 14/08/2018 at about 1424hrs. my neighbor informed me that there were police vehicle around my vehicle. I proceed down to make a check and I was informed by police officer that one of the police vehicle bearing GZ3371P had reversed and collided onto my vehicle front left portion.


Traffic police came down to scene to managed the situation. I was then advised to lodge a police report regarding the incident. My vehicle suffered damage on the front left portion, left headlight dented and scratch, left front rearview mirror broken, bumper bracket broken, cover set for the front portion mirror also dented.

That's all

Police Report



SINGAPORE
POLICE FORCE



T/20180814/2112

Police Station Of Origin
Bukit Panjang N.P.C.
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 3

Report No: T/20180814/2112

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
J /
Sgt 2 NUR HIDAYAH BINTE MOHAMED
SHARIFF

Signature Of Interpreter
Not applicable

Officer In Charge Of Case
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No: 65476151

Authentication Stamp
NF105

Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:
14/08/2018 15:10

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8100J
Vehicle Details	
Vehicle No.:	GU4394T
Vehicle to be Exported:	No
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2001
Engine No.:	QD32147119
Chassis No.:	JN1SF4F23Z0843811
Maximum Power Output:	-
Open Market Value:	\$20,792.00
Original Registration Date:	17 Mar 2001
First Registration Date:	17 Mar 2001
Transfer Count:	1
Actual ARF Paid:	\$1,040.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$31,369.00
COE Rebate Amount:	\$8,051.00
Total Rebate Amount:	\$8,051.00

The information contained herein is correct as at 20 Aug 2018

OK

VAN / LORRY (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	Cut		
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp	CRA		
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish	Cut		
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber	Cut		
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay	BR		
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		panel beating : 200			
		spray paint : 300			
		wiring : 30			
		remove & refit windscreen : 120			

No of Items:

Assessor:

10%: 1520.37
270.37 20%: 1700

Original Copy



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18015023/Grd3s2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE Date: 03-09-2018

FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD

POLICE ACADEMY SINGAPORE 298333

ATTN: FRANKIE

Code: SPF



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GZ 3371P	Veh. Inspected	GU 4394T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/098	Excess (\$)	0.00
Assign From	FRANKIE	Assign Date	17/08/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	3153
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JN1SF4F23Z0843811	Colour	SILVER
Odometer	287365 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MAXXIS	5 mm
L/H Front Tyre	195 R15	MAXXIS	5 mm
R/H Rear Tyre	155 R12	MAXXIS	5 mm
L/H Rear Tyre	155 R12	MAXXIS	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/08/2018	Inspect Date / Time	17/08/2018 (05:45 PM)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. GU 4394T

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT BUMPER	CUT	663.60
1	FRT LH SIDE LAMP	CRACKED	156.80
1	WIPER PANEL GARNISH	CUT	390.70
1	FRT WINDSCREEN RUBBER	CUT	108.70
1	FRT WING MIRROR STAY	BROKEN	185.30
1	FRT LH DOOR (NPA)	TO REPAIR SEE LABOUR	-
1	FRT STEP PANEL TOP GARNISH	CUT	184.20
	LESS 10% DISCOUNT		-168.93
			1,520.37
	<u>LABOUR</u>		
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT LH DOOR.		200.00
	SPRAY PAINT.		300.00
	WIRING.		30.00
	REMOVE & REFIT WINDSCREEN.		120.00
			650.00
	GRAND TOTAL		2,170.37

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	1,700.00
---	-----------------

Report Ref No. CS3/SPF18015023/Grd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.