

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18015025/G240302

Special Instruction:

Surveyor: GIO
munim

ASSIGNMENT (Office)

From (Person): Christina Wong

of MS16

Date/Time: 16/8/18 @ 4:03pm

Estimated Cost:

Bill to:

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW 5221C

Insured: XD 2967S

at Workshop m/s Kent Auto

Tel: 9487 2487

of 2 Kaki Bkt Ave 2 # 01-21

Policy No: B 277 831407MV

Claim No: 56 7417

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/08/2018

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 12:24pm @ 17/8/18

Person Contacted: Cecilia

Vehicle IN OUT

Date/Time	Action/Instruction (x) Estimate
	SDW 5221C - x
	XD 2967S - CC-21/III/1-7017854/71hb3 DoA: 15/9/17

(08/1/13) wef

ASS. REC. BY:

PPS
Ked.

REF:

MSIG

B 4332M ✓

ASSIGNMENT

(-2019)

From: _____ Date: 17/8/18

Veh No: SDW 5221C Yr Regn: 24 Apr 2009

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OP / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SDW 5221C

Make: Toyota Altis c.c 1598

at Workshop m/s Kent Auto

Colour: Gold A/C: Insured / Std / NI / NA

of 2 Kelai Bkt Ave 2 # 01-21

Sp. Reading: 231070 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: MR 0532EE 106143837

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

3pm

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIE / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: \$14K

Front R/Bal. 6 mm Rear R/Bal. 6 mm

IDAC Accident Rpt: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

D.O.A. D.O.I. 17-08-18

Est. Repairs: _____ days Res.: Yes or No

Survey held at W/S 5:10pm

Lum Sum: _____ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

CA / REV / REP. / 24 HRS (up)

n/s rear

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$ 2000 - \$ 3000
21/8/18	submit PPS report

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Survey Fee: 120

Transportation: _____

Photos: _____

Others: 10

TOTAL: 130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		16 Aug 2018 16:03 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>
------	-----------	---------------	-----------	---

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH RESOURCES PTE LTD, Co. Reg. No.: 0		
Main Claimant:	KENT AUTO SERVICES, Co. Reg. No.: 52974332M		
Vehicle Reg. No.:	SDW5221C	Date of Loss:	10/08/2018 12:00 - :59 [111 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567417	Policy/Cover Note No.:	B27783140TMV (Third Party Only) Coverage: 26/11/2017 - 25/11/2018
Vehicle Reg. No. (Insured):	XD2967S	Policy No. (Claimant):	
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/08/2018]		
Driver/Custodian (Insured):	LEE AH TEE (), NRIC: S1384137C, Tel: +6591397101		
Adj Asg. Remarks:	Liability unclear, TP disagree with our SJE List. To appoint case to LKK - Marcus / Kenneth for all SAMWOH cases. Contact Person: Kent Tan / 9754 7573		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015025/Gz4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 17-08-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XD 2967S	Veh. Inspected	SDW 5221C
Policy No.	B27783140TMV	Coverage (\$)	0.00
Claim No.	567417	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	17/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/08/2018	Inspection Date	17/08/2018
Survey held at	KENT AUTO SERVICES 2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Surior copy.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/08/2018 10:44
Date Of Accident	10/08/2018 13:20
Exact Location Of Accident	JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW5221C
Insured/Policyholder	
Name Of Registered Owner	KENT AUTO SERVICES
Co Reg No	52974332M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67412539

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5083187969-01
Cover Note Number	

Driver

Name of Driver	KANG HONG SENG
NRIC No	S2204702G
Date Of Birth	16/06/1961
Occupation	OUTDOOR
Date Of Driving Pass	29/03/1983
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96920890
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 2 KAKI BUKIT AVENUE 2 #01-21 KAKI BUKIT AUTOHUB
 Postcode 417921
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4

Passenger 1
 NAME: : -
 GENDER: : MALE
 Passenger 2
 NAME: : -
 GENDER: : FEMALE
 Passenger 3
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20180811/20299

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD2967S
 Vehicle Make/Model/Colour
 Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE AH TEE
NRIC/Passport Number	S1384137C
Contact Number	91397101
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre for
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN

Refer attached sketch plan (SPW 5524C)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As Per Police Report

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Reporting Centre Personnel's Signature


Name:

NRIC/PR No.:

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

SGH





Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	KANG HONG SENG		ID No. S2204702G
Related Vehicle	SDW5221C (Car)		Contact No. 96920890
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE AH TEE		ID No. S1384137C
Related Vehicle	XD2967S (TRUCK)		Contact No. 91397101
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

11/08/2018 @1320HRS (JALAN BUKIT MERAH, INFRONT SINGAPORE GENERAL HOSPITAL, NEAR TO SINGAPORE HEART CENTRE)

I WAS DRIVING ALONG JALAN BUKIT MERAH, INFRONT SINGAPORE GENERAL HOSPITAL, NEAR TO SINGAPORE HEART CENTRE. I WAS USING A RENTED CAR FROM KENT AUTO SERVICES, WHEN I HAD A INCIDENT ON 11/08/2018. THE ROAD SURFACE WAS DRY AND THE TRAFFIC FLOW WAS MODERATE. I WAS SEND MY PASSENGER TO SINGAPORE GENERAL HOSPITAL, I WAS TRAVELLING ON THE MIDDLE LANE OUT OF 3 LANES. WHEN I WAS ENTER THE BEND AND I SAW THERE WAS A TRUCK IN THE MIDDLE LANE IN A STATIONARY POSITION, THERE A MAN ON THE EXTREME LEFT LANE MOVING THE BARRER. THERE WAS NO ONE CONTROLLING THE TRAFFIC AND NO SIGN OF SLOWING DOWN, I FILTER TO THE EXTREME RIGHT LANE AND PROCEEDED FORWARD. AS I WAS DRIVING PASS THE TRUCK, SUDDENLY THERE WAS A LOUD BANG ON MY VEHICLE AND I ALMOST LOST CONTROL OF THE VEHICLE. I SAW THE TRUCK COLLIDED ONTO MY VEHICLE AND STILL WAS REVERSING AND STOP IN THE MIDDLE OF THE ROAD AGAIN.

THERE WAS NO INDICATION OR ANYONE SLOWING DOWN THE TRAFFIC BEFORE THE TRUCK STARTED TO REVERSED, I FELT THEY COULD HAVE INFORM ALL THE DRIVER TO SLOW DOWN BEFORE THEY WANTED TO REVERSED THEIR VEHICLE. WHEN THE INCIDENT HAPPENED I QUICKLY STOP MY VEHICLE AND TOOK A PHOTO OF THE INCIDENT SIGHT, I CHECKED THERE WAS NO ONE INJURED FROM THE ACCIDENT. I QUICKLY WHEN TO THE DRIVER AND ASKED HIM, "HOW ARE WE GOING TO SETTLE IT, PRIVATE SETTLEMENT OR LODGE A POLICE REPORT?". THE DRIVER INFORM ME, TO CONTACT HIS GROUND OFFICER INCHARGE. AFTER



**SINGAPORE
POLICE FORCE**



T/20180811/2029

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180811/2029

CONTINUATION OF REPORT

GETTING THE NUMBER I SEND MY PESSINGER TO THE HOSPITAL FOR THEIR APPOINTMENT.
WHEN I CALLED GROUND OFFICER IN CHARGE, THEY AGREE TO DO PRIVATE SETTLEMENT.
LATER ON AROUND NIGHT TIME, MY RENTAL COMPANY CALLED MY AND INFORM TO LODGE A
POLICE REPORT AS THEY REFUSED TO SETTLE IT PRIVATELY.

THAT'S ALL



Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
KEE CHUAN JIA MARCUS

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt IRMAN BIN MOHAMAD SAID
Contact No.: 65476365

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
11/08/2018 10:11

Classification Of Case:



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4332M
Vehicle Details	
Vehicle No.:	SDW5221C
Vehicle to be Exported:	No
Intended De-registration Date:	20 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	3ZZ4882339
Chassis No.:	MR053ZEE106143837
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,990.00
Original Registration Date:	24 Apr 2009
First Registration Date:	24 Apr 2009
Transfer Count:	1
Actual ARF Paid:	\$16,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2019
PARF Rebate Amount:	\$8,495.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$478.00
Total Rebate Amount:	\$8,973.00

The information contained herein is correct as at 20 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018		16 Aug 2018 16:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	SAMWOH RESOURCES PTE LTD, Co. Reg. No.: 0		
Main Claimant:	KENT AUTO SERVICES, Co. Reg. No.: 52974332M		
Vehicle Reg. No.:	SDW5221C	Date of Loss:	10/08/2018 12:00 - :59 [111 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 567417	Policy/Cover Note No.:	B27783140TMV (Third Party Only) Coverage: 26/11/2017 - 25/11/2018
Vehicle Reg. No. (Insured):	XD2967S	Policy No. (Claimant):	
		Excess:	
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 17/08/2018]		
Driver/Custodian (Insured):	LEE AH TEE (), NRIC: S1384137C, Tel: +6591397101		
Adj Asg. Remarks:	Liability unclear. TP disagree with our SJE List. To appoint case to LKK - Marcus / Kenneth for all SAMWOH cases. Contact Person: Kent Tan / 9754 7573		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SDW5221C (567417)**
[XD2967S]
TP
KENT AUTO SERVICES
Aug 10 2018 12:00PM
[SAMWOH RESOURCES PTE LTD]
Kent Auto Services - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser
Assessment Reports			1 per page <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	15/08/18 18:01	Accident Statement <small>From: SC - Reg. No: XD2967S, Claimant: SAMWOH RESOURCES PTE LTD</small>	Load HTM
Photos/Images			3 per page <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
2	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
3	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
4	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
5	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
6	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
7	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
8	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
9	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
10	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
11	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
12	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
13	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
14	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
15	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
16	21/08/18 14:03	General View	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	15/08/18 18:01	SDW5221C GIA Rpt <small>From: SC - Reg. No: XD2967S, Claimant: SAMWOH RESOURCES PTE LTD</small>	Load PDF
2	15/08/18 18:09	PRI and TP SJE list	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015025/GZ4D3E2
Date: 23/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27783140TMV
Claimant Vehicle No : SDW5221C	Insured Vehicle No :	XD2967S
Date of Loss: 10/08/2018	Nature of Claim:	TP
		Claim No: 567417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW5221C	Engine No:	3ZZ4882339
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106143837
Reg. Date:	24/04/2009 (Man. Year: 2009)	Odometer:	231070 km
Colour:	Gold		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/08/2018	
Date Inspected:	17/08/2018	Inspected At: Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW5221C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >