

11/03/2002

ASS. REC. BY:

REF: CS/CT#18015027/Krd3

Special Instruction:

Surveyor
menhen

Kenneth

ASSIGNMENT (Office)

From (Person):

Jumyn Ty

of

CTI

Date/Time:

16/8/18 @ 2.46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 2447L

Insured:

GBD 5500X

at Workshop m/s

Kong Auto

Tel:

6556 0103

of

160 An Ming Drive # 02-16

Policy No:

DMCVSN 3116 301701

Claim No:

8 NM18P03972C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

3.02pm @ 17/8/18

Person Contacted:

May

Vehicle IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	SMC 2447L-X
	GBD 5500 X-CS/CT#18013998/Krd3
	D.O.A. 30/7/2018
	\$4085.20 @ 4 days
	(Red: \$ 6210.80, 60%)

REF: CTE

ASSIGNMENT

From: Date: 10/09/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8MC 2447L
at Workshop n/s: Kang Auto
of 160 Sin Ming Drive #02-16

Insured

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

After 10am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 8MC 2447L Yr Regn: 06 18

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Hyundai i30 C.C. 1353

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 2786 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 7MA143813 VJJ 033067

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front	Rear
R/Bal. 9 mm	R/Bal. 9 mm
L/Bal. 9 mm	L/Bal. 9 mm
D.O.A. 15/8/18	D.O.I. 10/9/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19 File pass to

RECEIVED 10/10/2018

Date/Time, File Pass to?

1) tripit

Date/Time, File Return to?

2)

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format: 1P

Lump Sum / I.B.I: (\$ 4085.20)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2018		16 Aug 2018 14:46 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	FAN YONG KENG		
Vehicle Reg. No.:	SMC2447L	Date of Loss:	15/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03972C02	Policy/Cover Note No.:	DMCVSN3116301701
Vehicle Reg. No. (Insured):	GBD5500X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kang Auto Engineering Pte Ltd () 160 Sin Ming Drive, #02-16, Sin Ming AutoCity, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/08/2018]		
Adj Asg. Remarks:	EST \$9663.60, ASSIGN KENNETH KONG AS SJE,		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18015027/Krd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 17-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 5500X	Veh. Inspected	SMC 2447L
Policy No.	DMCVSN3116301701	Coverage (\$)	0.00
Claim No.	SNM18D03972C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	17/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/08/2018	Inspection Date	10/09/2018
Survey held at	KANG AUTO ENGINEERING PTE LTD 160 SIN MING DRIVE #02-16 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2018 17:58
Date Of Accident	15/08/2018 12:40
Exact Location Of Accident	CHOA CHU KANG RD TWDS BUKIT BATOK RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC2447L
Insured/Policyholder	
Name Of Registered Owner	FAN YONG KENG
NRIC No	S7616975F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96238598
Alternative Phone No	OFFICE-96238598

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30-1.4 GLS 5DR DCT TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0
Cover Note Number	CN895425

Driver

Name of Driver	FAN YONG KENG
NRIC No	S7616975F
Date Of Birth	07/06/1976
Occupation	INDOOR
Date Of Driving Pass	14/11/1995
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96238598
Fax Number	
Contact Number	OFFICE-96238598
Email Address	NOEMAIL

Address	16 CHOA CHU KANG GROVE #16-42
Postcode	688210
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH CLIENT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD5500X
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 15.8.18, WHILE I AM WAITING FOR TRAFFIC TO TURN GREEN.

A LORRY GBD5500X SUDDENLY BANGS ME FROM THE BACK...

NOBODY WAS INJURY.

* Repair other workshop *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:







Agent Code: 08260

Policy No. (if any):

New Business

SmartDrive Quote Ref:

MOTOR COVER NOTENo. **CN895425**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby **HELD COVERED** under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	FAN YONG KENG
MAKE AND DESCRIPTION OF VEHICLE	HYUNDAI I30 1.4 TURBO GLS 5D DCT TURBO
VEHICLE REGISTRATION NO.	SMC2447L
YEAR OF MANUFACTURE	2018
ENGINE NO.	G4LDJD051157
CHASSIS NO.	TMAH3813VJJ033067
ENGINE CAPACITY/TONNAGE	1353
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	MAYBANK
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 28/06/2018 TO: 27/06/2019
EXCESS (S\$)	AS PER POLICY
AXA PREMIUM WORKSHOP?	NO

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD

Issued by HOCK MOH NELSON on 28/06/2018 2:44pm
 TEO


 Authorised Signature

Note : This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged:
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY**For Individual Customers:**

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



REVISE

M/S FAN YONG KENG
16 CHOACHU KANG GROVE
#16-42
SINGAPORE 688210

POLICY NO : THIRD PARTY CLAIMS

OUR REF : TP18/08/1117

VEHICLE NO : SMC2447L

MAKE/MODEL : HYUN. I30 (500)

DATE OF ACCIDENT : 15.08.18

Chassis - TMA113813VJ1033087

1	PC	TAILGATE GLASS	S\$	795.00	X
1	PC	TAILGATE → 2360.00	R	3898.50	✓
1	PC	TAILGATE INNER BOARD	R	856.00	X
1	PC	TAILGATE LOCK	R	520.00	X
1	PC	TAILGATE HINGES	R	120.00	X
1	PC	TAILGATE HANDLE	R	312.00	X
1	PC	TAILGATE EMBLEM	R	68.00	—
1	PC	TAILGATE 'I30' BADGE	R	38.00	—
1	PC	TAILGATE '1.4t' BADGE	R	30.00	—
2	PCS	TAILGATE REFLECTORS	242.50 EA	R 485.00	X
1	PC	REAR BUMPER → 1008.00	R	1428.00	✓
1	SET	REAR BUMPER SIDE RETAINER	R	22.00	X
1	PC	REAR REINFORCEMENT	R	335.00	X
1	PC	REAR BUMPER SPONGE	R	210.00	X
1	PC	REAR BUMPER CLIPS	R	40.00	✓

6047.50
20% 1209.50
4838.10

S\$ 9,157.50
LESS 20% 1,831.50
7,326.00

5302.50
1100.50
4402

- 1 PC TAILGATE GLASS GUM
- 4 PCS REVERSE SENSOR

S\$ R 50.00 S'NETT 500
R 450.00 X

TO CHECK WIRING SYSTEM
TO REMOVE & REFIT TAILGATE GLASS
TO TRANSFER TAILGATE MECHANISM NEW TAILGATE
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANELS
TO PUTTY AND SPRAY PAINT CHARGES
LABOUR CHARGES

50.00 20k
160.00 120k
180.00 80k 1230
80.00 30k
1,200.00 480k
800.00 50k
S\$ 10,296.00

SGD TEN THOUSAND TWO HUNDRED AND NINETY SIX ONLY.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

Not Notarised
1.13.1
Remy Bepain
84085.20
6568
Edm

Specialised In :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD



Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg

REVISE

M/S FAN YONG KENG
16 CHOACHU KANG GROVE
#16-42
SINGAPORE 688210

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/08/1117
VEHICLE NO : SMC2447L
MAKE/MODEL : HYUN. I30
DATE OF ACCIDENT : 15.08.18

- | | | |
|---|-----|---------------------------|
| 1 | PC | TAILGATE GLASS |
| 1 | PC | TAILGATE 2360 |
| 1 | PC | TAILGATE INNER BOARD |
| 1 | PC | TAILGATE LOCK |
| 1 | PC | TAILGATE HINGES |
| 1 | PC | TAILGATE HANDLE |
| 1 | PC | TAILGATE EMBLEM |
| 1 | PC | TAILGATE 'i30' BADGE |
| 1 | PC | TAILGATE '1.4t' BADGE |
| 2 | PCS | TAILGATE REFLECTORS |
| 1 | PC | REAR BUMPER 1068 |
| 1 | SET | REAR BUMPER SIDE RETAINER |
| 1 | PC | REAR REINFORCEMENT |
| 1 | PC | REAR BUMPER SPONGE |
| 1 | PC | REAR BUMPER CLIPS |

S\$	SVC	795.00	✓
	R	3898.50	✓
	SM	856.00	X
	R	520.00	X
	R	120.00	✓
	SM	312.00	X
	SM	68.00	—
	SM	38.00	—
	SM	30.00	—
242.50	EA	SM 485.00	X
		BR 1428.00	✓
		SM 22.00	X
		R 335.00	✓
	SVC	210.00	✓
	SM	40.00	✓
S\$		9,157.50	
LESS 20%		1,831.50	
		7,326.00	

- | | | |
|---|-----|--------------------|
| 1 | PC | TAILGATE GLASS GUM |
| 4 | PCS | REVERSE SENSOR |

S\$	SM	50.00	S'NETT
	SVC	450.00	✓

TO CHECK WIRING SYSTEM
TO REMOVE & REFIT TAILGATE GLASS
TO TRANSFER TAILGATE MECHANISM NEW TAILGATE
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANELS
TO PUTTY AND SPRAY PAINT CHARGES
LABOUR CHARGES

	50.00	200
	160.00	1200
	180.00	800
	80.00	300
	1,200.00	4800
	800.00	500
S\$	10,296.00	

SGD TEN THOUSAND TWO HUNDRED AND NINETY SIX ONLY.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

Not Authorised
1.12.1
Resuming Bepain

4 days

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909.
Motor Claims Dept

Date :15/8/2018

Your Insured: GBD5500X
Our Insured : SMC2447L
OUR REF: TP18/08/1117

Notice to conduct Pre-Repair Inspection within 2 working days pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Case.

We act for Mr. Fan Yong Keng , the owner of motor vehicle **SMC2447L** who has appointed us **Kang Auto Engineering Pte Ltd** to act on his behalf to claim against your insured's vehicle. GBD5500X in regards to the road traffic accident on 15.08.2018 along Chua Chu Kang Road Towards Bukit Batok Road.

Please be informed that the said motor vehicle can be inspected at :

Kang Auto Engineering Pte Ltd
Sin Ming AutoCity
160 Sin Ming Drive, #02-16
Singapore 575722
Tel: 6556 0103 fax: 6556 1015
Contact : Kenny/May

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding and intervening Saturday, Sunday or Public holiday, the said workshop will commerce repairs thereafter without further reference to you.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015027/KRD3N2

Date: 17/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3116301701
Claimant Vehicle No :	SMC2447L	Insured Vehicle No :	GBD5500X
Date of Loss:	15/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03972C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2447L	Engine No:	G4LDJD051157
Make & Model:	HYUNDAI I30, 1.4 GLS 5DR DCT TURBO (A)	Chassis No:	TMAH3813VJJ033067
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	2784 km
Colour:	Metallic Grey		
Engine Capacity:	1353 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,826.00	2,875.20	4,950.80	63.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,210.00	1,260.00	51.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	10,296.00	4,085.20	6,210.80	60.32

INSPECTION

Date of Assignment:	16/08/2018	
Date Inspected:	10/09/2018	Inspected At: Kang Auto Engineering Pte Ltd 160 Sin Ming Drive, #02-16, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts:	144	HYUNDAI I30 1.4 GLS 5DR DCT TURBO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC2447L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS	Serviceable	795.00 FL	*- FL
2	1		*TAILGATE	Bent	3,898.50 FL	*2,360.00 FL
3	1		*TAILGATE INNER BOARD	Serviceable	856.00 FL	*- FL
4	1		*TAILGATE LOCK	Repair	520.00 FL	*- FL
5	1		*TAILGATE HINGES	Repair	120.00 FL	*- FL
6	1		*TAILGATE HANDLE	Serviceable	312.00 FL	*- FL
7	1		*TAILGATE EMBLEM	Necessary	68.00 FL	*68.00 FL
8	1		*TAILGATE I30 BADGE	Necessary	38.00 FL	*38.00 FL
9	1		*TAILGATE 1.4T BADGE	Necessary	30.00 FL	*30.00 FL
10	2		*TAILGATE REFLECTORS	Serviceable	485.00 FL	*- FL
11	1		*REAR BUMPER	Buckled	1,428.00 FL	*1,008.00 FL
12	1		*SET REAR BUMPER SIDE RETAINER	Serviceable	22.00 FL	*- FL
13	1		*REAR REINFORCEMENT	Repair	335.00 FL	*- FL
14	1		*REAR BUMPER SPONGE	Serviceable	210.00 FL	*- FL
15	1		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
16	1		*TAILGATE GLASS GUM	Necessary	50.00 FS	*40.00 FS
17	4		*REVERSE SENSOR	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,657.50	3,584.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,831.50	708.80
Total Parts (\$\$)	7,826.00	2,875.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIT TAILGATE GLASS	New	160.00	120.00
3	TO TRANSFER TAILGATE MECHANISM NEW TAILGATE	New	180.00	60.00
4	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANELS	New	80.00	30.00
5	TO PUTTY AND SPRAY PAINT CHARGES	New	1,200.00	480.00
6	LABOUR CHARGES	New	800.00	500.00
Gross Labour Cost (\$\$)			2,470.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >