

INSURANCE

INS. CASE OWNER:

EC

CC4/AXA1801

5082, R2 p339

LKK:

IDAC:

Surveyor:

Kusni

DOI:

ASSIGNMENT

12/8/18

Date / Time:

12/8/18

Registered in Merimen:

12/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 98659

Name of Insured:

TRANS-AB SERVICES P/L

Insured Tel No.:

HP:

Excess Sec II :SS

\$5000

D.O.A:

4/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SOH KAH HWEE

Driver Tel No.:

(V/L) YES / NO

Claim No.:

CU474740

Policy No.:

VR/P1680570

Make / Model:

RENAULT

Place of Accident:

NEPPOAT BUNLEARD SHIP RD
TWO 73 TAXI QUE

OI GIA REPORT YES / NO

TP GIA REPORT YES / NO

Insured Liability:

% Final ? Yes / No

SH 75935



INSRS:
WSP:
Tel:
Liability:
RMKS:

LOGE
m



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SH 75935-4

SHB 98659-4

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mutate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

12/11/18

* TO get under-then TP.

✓ TP under

old envelope to car

24/11/18

DV sent

2/1/19

Far to shupet to lora

RECEIVED 03 JAN 2019

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 15

If NO B 28; Ass. Lia :

Repair Cost:

SS

1658.50

Loss of Rental (LOR):

SS

64.20

(4 days)

X#16780

Loss of Use (LOU):

SS

(5 days)

Loss of Income (LOI):

SS

20.00

(5 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Towel Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

2529.70

Global Sum SS:

2520.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2520.00

Name 1:

CompuBelgn Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA18015082/R1pb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 20-08-2018		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 9865G	Veh. Inspected	SH 7593S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/08/2018	Inspection Date	17/08/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Team:	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO:	305199918
CUSTOMER	COMFORT TRANSPORTATION PTE LTD		REGN NO:	SH 7593S	MILEAGE
MS	7010045		MAKE	MERCEDES BENZ	FUEL
CUSTOMER NO:	383 SIN MING DRIVE		MODEL	E220CDI(E5)	DATE/TIME IN
RESS	Singapore SINGAPORE 575717		YR OF MANU	06.06.2013	TARGET DATE
(R)	65508755	(C)	CHASSIS CODE	WDD2120022A757452	COMPLETION DATE/TIME
(P)					
COUNT CARD NO:					

JOB DESCRIPTION

Accident Date: 14.08.2018
NATURE: 3P 14.08.18

S/NO	LABOR CODE	DESCRIPTION
		

BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR _____ CUSTOMER'S SIGNATURE _____

Wedgeament Slip

Vehicle No.: SH 7593S

LIMITS

Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 7593S

Name of Service Advisor

Date

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

Our Job Ref No. : 305199918

Date : 20/08/18

FINALIZATION FORM

To : LKK

Fax :

Attn : RASUL

Vehicle Reg No. : SH 7593S

Date of Accident : 14-Aug-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA --- **TRANSCAB**
SHB9865G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,550.00

Final Lumpsum Repair cost \$1,550.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : RASUL

Date : 21/8/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: **URGENT! - 3P (Mr Soh - HP : 90909357) REQUESTS MUTUAL SETTLEMENT.**

$$\mathbb{I}^{\sqrt{R}}$$

DATE 14/8/2018

1550

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt			\$ 1,890.50
	Bumper Bracket, Frt/LH			\$ 95.00
	Bumper Inner Clip, Frt			\$ 22.00
	Daylight Chrome Cover (LH)			\$ 78.00
	SUB TOTAL		1912.50	\$ 2,085.50
	LESS 20%		20%	\$ 417.10
	DISCOUNTED TOTAL		1530	\$ 1,668.40
	Labour Charge			
	Panel Beating		380	\$ 400.00
	Spray Painting Charge			\$ 250.00
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 2,318.40
	Paid HP 90010068			1530 380 1910 20% 1528 417 1550
	<div style="border: 1px solid black; padding: 5px;"> <p>Let Assured Insurers hence notify the Repairs of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Part prices are subject to confirmation Third party survey is on a "Without Prejudice" basis Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company <p>Acknowledged by Resurvey after repair</p> <p>Signature: _____</p> <p>Date: _____</p> </div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

$$\underline{\underline{\Sigma}}^{\sqrt{R}}$$

DATE 14/8/2018

MAKE :

MODEL : MERCEDES

1550

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt			\$ 1,890.50
	Bumper Bracket, Frt/LH			\$ 95.00
	Bumper Inner Clip, Frt			\$ 22.00
	Daylight Chrome Cover (LH)			\$ 78.00
	SUB TOTAL			\$ 2,085.50
	LESS 20%			\$ 417.10
	DISCOUNTED TOTAL			\$ 1,668.40
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 250.00
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 2,318.40
	<p><i>Paul</i> <i>Hp 90010068</i></p> <div style="border: 1px solid black; padding: 5px;"> <p><i>2 days</i> <i>45</i> <i>7/08/18 @ 15:20</i></p> <p>Let Appraisants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To resurvey damaged part(s) during resurvey • Part prices are subject to confirmation • Third party survey on a "Without Prejudice" basis • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p><i>Resurvey after repair</i></p> <p>Signature: _____ Date: _____</p> </div>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Hsiao Tong (LKKAUTO)

From: Catherine Koh Mui Gek <catherinekoh@cdge.com.sg>
Sent: Monday, 12 November 2018 4:37 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]
Attachments: SH7593S doa 14.8.18.mov

Dear Hsiao Tong

Attached as requested. Kindly settle our PD claim as per BOLA S15.

Thank you.

Best Regards
Catherine Koh
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148733 | Fax : 62141843

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Monday, 5 November 2018 12:37:44 PM
To: William Tan Thoo Seng; Catherine Koh Mui Gek
Subject: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]

Your ref: **T 0818/ SH 7593S/ WT(st)** **Without Prejudice**
Our ref: CC4/AXA18015082/R1pb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018

We refer to the above matter.

Please be informed that both parties had given a conflict of version. Our insured driver reported that he was driving straight along Airport Boulevard slip road towards T3 taxi queue. Suddenly he felt an impact. Your client had grazed onto his taxi. Attached is a copy of our insured accident report for your easy reference.

Circumstances of Accident

On 14.08.2018 at about 00015hours, I was travelling straight along Airport Boulevard slip road towards T3 taxi queue. Sudd felt an impact. Vehicle B (SH7593S) slightly glazed onto my taxi's right rear portion.


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH7593S
Vehicle Make/Model/Colour COMFORT TAXI
Details Of Properties
Vehicle Category TAXI
Name of Driver YEO
NRIC/Passport Number

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GIA Report

We would like to request a copy of video footage as stated in your client GIA report for our reference.

Appreciate an early reply.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Print Sent Message

This mail is associated with :

***SH7593S (C0474230)**
[SHB9865G]
TP
COMFORT TRANSPORTATION PTE LTD
Aug 14 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 04/12/2018 15:48 PM.
To kianchuan.chan@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Mandate IA> C0474230/ P1680520

Hi KC,

We refer to the above matter.

Liability: 100%. We have uploaded a copy of third party video footage in Merimen. The video shows that our insured driver had encroached into third party lane and resulted the accident. We are of the view that liability is not in our driver favour.

We seek your mandate up to \$2,529.70(all-in). Mandate IA had been uploaded in Merimen.

Kindly let us have your comments/ approval/ instruction.

Hsiao Tong



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 04/12/2018

Survey Details:

Date of loss	14-Aug-18
Date of appointment	17-Aug-18
Date of survey	17-Aug-18
Location of survey	FORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SH 7593S
Make and Model	MERCEDES BENZ E220 CDI (E5)
Date of registration	6/6/2013
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 2,318.40
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,530.00
Check items (estimate)	
Labour	\$ 380.00
Total	\$ 1,910.00
Lump Sum(if applicable)	\$ 1,550.00

Number of days for repair	2
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	1,658.50
Loss of use		NIL
Loss of rental	\$	671.20 (4days x \$167.80)
Loss of income	\$	200.00 (4days x \$50.00)
LTA search fees		NIL
Others		NIL
Proposed Total	\$	2,529.70

Print Received Message

This mail is associated with :

***SH7593S (C0474230)**

[SHB9865G]

TP

COMFORT TRANSPORTATION PTE LTD

Aug 14 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

ComfortDelGro Engineering Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 20/12/2018 14:40 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2529.70) - SH7593S - Claim Handler: Chan Kian Chuan

Approved:2529.70.

Hsiao Tong (LKKAUTO)

From: William Tan Thoo Seng <williamtan@cdge.com.sg>
Sent: Thursday, 20 December 2018 3:08 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]

Without Prejudice.

Dear Hsiao Tong

We accept your global offer at \$2,520.00. Kindly forward your D.V.

Thank you.

Best Regards

William Tan

Claims Department | ComfortDelgro Engineering Pte Ltd

Off : 62148737 | Fax : 62141843

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Thursday, 20 December 2018 2:59:46 PM
To: Catherine Koh Mui Gek; William Tan Thoo Seng
Subject: RE: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We propose settlement at a global sum of \$2,520.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Koh Mui Gek <catherinekoh@cdge.com.sg>
Sent: Monday, 12 November 2018 4:37 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Re: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]

Dear Hsiao Tong

Attached as requested. Kindly settle our PD claim as per BOLA S15.

Thank you.

Best Regards

Catherine Koh

Claims Department | ComfortDelgro Engineering Pte Ltd

Off : 62148733 | Fax : 62141843

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Sent: Monday, 5 November 2018 12:37:44 PM

To: William Tan Thoo Seng; Catherine Koh Mui Gek

Subject: Your ref: T 0818/ SH 7593S/ WT(st) *Our ref: CC4/AXA18015082/R1pb3 [ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018]

Your ref: **T 0818/ SH 7593S/ WT(st)**
Our ref: CC4/AXA18015082/R1pb3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SHB 9865G(AXA) & SH 7593S ON 14/08/2018

We refer to the above matter.

Please be informed that both parties had given a conflict of version. Our insured driver reported that he was driving straight along Airport Boulevard slip road towards T3 taxi queue. Suddenly he felt an impact. Your client had grazed onto his taxi. Attached is a copy of our insured accident report for your easy reference.

Circumstances of Accident

On 14.08.2018 at about 00015hours, I was travelling straight along Airport Boulevard slip road towards T3 taxi queue. Suddenly I felt an impact. Vehicle B (SH7593S) slightly grazed onto my taxi's right rear portion.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH7593S


Vehicle Make/Model/Colour COMFORT TAXI

Details Of Properties

Vehicle Category TAXI

Name of Driver YEO

NRIC/Passport Number

SKETCH PLAN**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

pls see attach GIA Report

We would like to request a copy of video footage as stated in your client GIA report for our reference.

Appreciate an early reply.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

Our Ref : T 0818/ SH 7593S /WT(st)

Your Ref :

Date : 21-Aug-18

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6333 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198602499

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
330 Ubi Road 3
Singapore 408549

Senoko
24 Senoko Loop
Singapore 759156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
Yishun Industrial Park A
Singapore 766732

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 7593S YOUR INSURED SHB9865G
AND OTHER _____ ON 14.08.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : SH 7593S which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SHB9865G we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,658.50
2	<u>5</u> days Loss of Rental @ \$ 167.80 per day	\$ 839.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fee	\$ -
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
Sub Total :		\$ 2,497.50

HIRER'S CLAIM

7	<u>5</u> days Loss of Income @ \$ 80.00 per days	\$ 400.00
Total Claims:		\$ 2,897.50

We enclose herewith the following documents to support the claims: -

- Original repair bill and photocopies of photographs 8 pcs
- LTA search slip/s of : SHB9865G
- GIA / Police report/s of : SH 7593S
- Letter of authority from owner / hirer / operator
 - () Photocopy/s of Accident Scene Photo/s () Traffic Compound () PIR
 - () Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 5 November 2018 11:44 AM
To: claims@transcab.com.sg
Cc: 'carrisalee@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHB 9865G AND SH 7593S ALONG/AT AIRPORT BOULEVARD SLIP ROAD TWDS T3 TAXI QUE ON 14/08/2018

05 NOV 2018

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA18015082/R1pb3

YOUR REF : P1680520 (SHB 9865G)

ACCIDENT INVOLVING SHB 9865G AND SH 7593S ALONG/AT AIRPORT BOULEVARD SLIP ROAD TWDS T3 TAXI QUE ON 14/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from COMFORTDELGRO ENGINEERING PTE LTD acting on behalf of the owner of SH 7593S against your motor insurance policy.

Both parties involved have given conflict of version. Based on the circumstances of accident and both parties damage profile, there is no conclusive evidence to substantiate either's parties version. Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

We also wish to advise that there is an excess of S\$5,000/- is attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- 1) Any settlement equal to or above the excess, you shall be liable to make the payment of \$5000/-; or
- 2) Any settlement below the excess, you shall be liable for the amount settled.

We shall keep you informed of the third party claim settlement and thereafter kindly let us have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by us for the above subject matter, we expressly reserve all our rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

As Insurers, we shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)

- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg / chewht@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

[NAF / PAF]

ACCIDENT INVOLVING
ALONGMERCEDES E220 SH7593S , SHB9865G
AIRPORT BLVD TWDS TAXI Q 1 AND 3

ON 14-Aug-18 00:15

I / We

LEE BAN HIN (LI WANXI... (Hirer) NRIC No.: S7102919J

and/or

YEO NGEE HIANG (Relief) NRIC No.: S1441635H

Taxi Number

SH7593S

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

14-Aug-2018

Name of Hirer

LEE BAN HIN (LI WANXING)

Hirer NRIC

S7102919J

Signature :

Address

149 BEDOK RESERVOIR ROAD #10-1...
470149

Contact No.

98732335

Name of Relief

YEO NGEE HIANG

Relief NRIC

S1441635H

Signature :

Address

105 BEDOK RESERVOIR ROAD 07-398
470105

Contact No.

92722311



redefining / insurance

CLAIM REF : C0474230
INSURED : TRANS-CAB SERVICES PTE LTD

DISCHARGE VOUCHER

We, **ComfortDelgro Engineering Pte Ltd** confirm that by letter of authorisation dated 14/08/2018, we are authorised to and do hereby give this discharge for ourselves and on behalf of Comfort Transportation Pte Ltd and the Hirer, Lee Ban Hin (Li WanXing) of vehicle no. SH 7593S.

Now we **ComfortDelgro Engineering Pte Ltd** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars **Two Thousand Five Hundred Twentyv only (S\$2,520.00)** in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. (SHB 9865G) arising out of an accident with (SH 7593S) on 14/08/2018.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SHB 9865G arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **ComfortDelgro Engineering Pte Ltd** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SHB 9865G.

Dated this 21 day of December 2018

Signed by _____
(AUTHORISED SIGNATORY)

Company Stamp _____

Witness : _____

Name : _____

I/C No : _____

Address : _____

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

*The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document*

Our Ref: CT18080396

Date: 21 August 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 14/08/2018 @ 00:15 hrs
ALONG AIRPORT BLVD TWDS TAXI Q 1 AND 3
INVOLVING SHB9865G

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH7593S** (the "Taxi"). The Taxi was hired to **LEE BAN HIN (LI WANXING) IC NO S7102919J** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$167.80** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018		17 Aug 2018 14:10 Edit Adj Rpt	S\$1,550.00 Edit Estimates	S\$1,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: TRANS-CAB SERVICES PTE LTD , ID: -									
Main Claimant: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Vehicle Reg. No.:	SH7593S	Date of Loss:	14/08/2018 00:00 - :59 [62 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0474230	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHB9865G	Policy No. (Claimant):	MCOM0015						
		Excess:	S\$5,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chan Kian Chuan - 6880 4269]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (20/12/2018): Alert - Adj Mandate Approved (S\$2529.70) - SH7593S - Claim Handler: Chan Kian Ch... AXA_SG (17/08/2018): New TP Assignment - C0474230/P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SH7593S (C0474230)
[SHB9865G]
TP
COMFORT TRANSPORTATION PTE LTD
Aug 14 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video																		1 per page		<input checked="" type="checkbox"/>
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	04/12/18 15:22		SH7593S doa 14.8.18 - TP VIDEO															Load MOV		
Letters/Correspondences																		1 per page		<input checked="" type="checkbox"/>
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Photos/Images																		3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	05/11/18 11:37		Odometer Reading															Load JPG <input checked="" type="checkbox"/>		
2	05/11/18 11:37		Chassis Number															Load JPG <input checked="" type="checkbox"/>		
3	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
4	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
5	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
6	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
7	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
8	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
9	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
10	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
11	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
12	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
13	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
14	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
15	05/11/18 11:37		General View															Load JPG <input checked="" type="checkbox"/>		
16	05/11/18 11:38		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
17	05/11/18 11:38		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
18	05/11/18 11:38		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
Documentation																		1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	20/08/18 19:15		TP ESTIMATE- MARKED															Load PDF		
2	04/12/18 15:40		LKK Survey Photos															Load PDF		
3	04/12/18 15:40		LKK Resurvey Photos															Load PDF		
4	04/12/18 15:41		Rental Rate & Mileage															Load PDF		
5	20/12/18 11:45		Mandate IA dd 041218															Load PDF		
6	08/01/19 10:15		WORKSHOP INVOICE															Load PDF		
7	08/01/19 10:15		AUTHORISATION TO ACT FORM															Load PDF		
8	08/01/19 10:15		DISCHARGE VOUCHER															Load PDF		
9	08/01/19 10:15		RENTAL RECEIPT															Load PDF		
10	08/01/19 10:15		RENTAL MILEAGE															Load PDF		
11	08/01/19 10:15		LOD															Load PDF		
12	08/01/19 10:15		LETTER TO OI															Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LXX Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB9865G (Insd veh)	Model:	MERCEDES-BENZ E220 2.0
	SH7593S (TP veh)		(A)
Date of Accident:	14/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		2,480.69
Final Repair Cost	:	\$		1,658.50
Loss of Token Sum	:	\$		200.00
Rental (if any)	:	\$		4.00 days at \$50.00 per day
LTA / GIA Search Fee	:	\$		671.20
Others:	:	\$		4 days
	:	\$		0.00
	:	\$		0.00
Final Settlement Sum (Global Sum)	:	\$		2,520.00

Is Third Party Workshop GIA Registered? ☒ [X] YES ☐ [] NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 2,520.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

08 Jan

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18015082/R1PB3Q2

Date: 08/01/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SH7593S

Insured Vehicle No :

SHB9865G

Date of Loss: 14/08/2018

Nature of Claim:

TP

Claim No: C0474230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH7593S**

Make & Model: MERCEDES-BENZ E220, 2.0 (A)

Engine No: 65192431243790

Reg. Date: 06/06/2013 (Man. Year: 2013)

Chassis No: WDD2120022A757452

Colour: White

Odometer: 567417 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,668.40	1,530.00	138.40	8.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	380.00	270.00	41.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,318.40	1,910.00	408.40	17.62
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	2,318.40	1,550.00	768.40	33.14
+ GST 7.00/7.00% (S\$)	162.29	108.50	53.79	33.14
Nett Amount (S\$)	2,480.69	1,658.50	822.19	33.14
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$167.80/day) (S\$)		671.20		
Nett Liability (S\$)		2,529.70		
Global Sum Settlement (S\$)		2,520.00		

INSPECTION

Date of Assignment: 17/08/2018

Date Inspected: 17/08/2018 Inspected At:

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18015082/R1PB3Q2

Date: 08/01/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No: P1680520

Claimant Vehicle
No: SH7593S

Insured Vehicle No: SHB9865G

Date of Loss: 14/08/2018

Nature of Claim:

TP

Claim No: C0474230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH7593S

Make & Model: MERCEDES-BENZ E220, 2.0 (A)

Engine No: 65192431243790

Reg. Date: 06/06/2013 (Man. Year: 2013)

Chassis No: WDD2120022A757452

Colour: White

Odometer: 567417 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,668.40	1,530.00	138.40	8.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	380.00	270.00	41.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,318.40	1,910.00	408.40	17.62
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	2,318.40	1,550.00	768.40	33.14
+ GST 7.00/7.00% (S\$)	162.29	108.50	53.79	33.14
Nett Amount (S\$)	2,480.69	1,658.50	822.19	33.14
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$167.80/day) (S\$)		671.20		
Nett Liability (S\$)		2,529.70		
Global Sum Settlement (S\$)		2,520.00		

INSPECTION

Date of Assignment: 17/08/2018

Date Inspected: 17/08/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts: 143	MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH7593S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASSY ,FRT (CONSISTENT)	Scratched	1,890.50 FL	*1,890.50 FL
2	1		*BUMPER BRACKET ,FRT/LH (CONSISTENT)	Serviceable	95.00 FL	*- FL
3	1		*BUMPER INNER CLIP ,FRT (CONSISTENT)	Necessary	22.00 FL	*22.00 FL
4	1		*DAYLIGHT CHROME COVER (LH) (CONSISTENT)	Serviceable	78.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,085.50	1,912.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	417.10	382.50
Total Parts (\$\$)	1,668.40	1,530.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	180.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
Gross Labour Cost (S\$)			650.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >