Surveyor Tanpin | REF: ASM(AXA) | 15096 / 71443 - W.

ASSIGNMENT

OPC

From: | Date: 08.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 8832G

at Workshop m/s Cycle & Carriage

of 209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Coco

(Policy Condition) 10am - 1pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9476.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: - days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: | Person Contacted: | Vehicle: IN / OUT

Veh No: SL Q8832G. Yr Regn: 2017 July.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Attrage. c.c 1193

Colour White A/C: Insured / Std / Ni / NA

Sp.Reading 14682 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MMBSTA13AH4005605

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Maxxis

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. D.O.I. 8/10/18 @ 1.15pm

Survey held at C&C Pandan Gdns

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Invs ($) ☐ : Weekend ($)

Survey Fee:

Transportation: S + RS S

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)