

3/03/2018

ASS. REC. BY:

REF:

CS/SMD18015097/Urbn

Special Instruction:

WVeyor

ASSIGNMENT (Office)

From (Person):

Melvin Ye

of

SMD

Date/Time:

2008/01/18

5:50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBT 564ST

Insured:

SLD 9405T

at Workshop m/s:

Fastech

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 # 01-45

Policy No:

Claim No:

CMTD1803582

Sum Insured:

Excess:

Make of Veh:

D.O.A.

1808/01/18

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBT 564ST - x
	SLD 9405T - CS / m3618015015445 / R24413
	Def: 1803/18
29/8/18	Informed Melvin pending workshop est by email
30/8/18	Email preli revised to Melvin

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 56 487at Workshop m/s fl.

of _____

Insured: SLD 94057

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2604C

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF 56 487 Yr Regn: 12/16Type: M.Car / M.Cycle / Bus Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CMMake: Nissan NV200 c.c. 1461Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 65682 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM2020133385Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 175/70214

R: _____

BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/8/18

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 20/8/18

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8/18 continue 2/5 86500 with Adv. (Red 9438-20, 599)

RECEIVED 30 AUG 2018

Date/Time, File Pass to?

☐

Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 30/8 - typistDays Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S * RS * SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 6500/-)

450



Auto
Consultants
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: CMTD1803582

Our ref: CS/SMO18015097/Uvb

DATE: 30/8/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. GBF 5648T


We thank for your instruction on 20/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/8/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$15,938.20
Revised Estimate Amount	:S\$6,500.00 (LUMP SUM)
"Check" Items Amount	:S\$
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 30 August 2018 9:10 AM
To: 'melvin.ye@sompo.com.sg'
Cc: SUR
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T
Attachments: GBF 5648T PRELI ADVISED.pdf

Dear Melvin,

Re-forward.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 30 August 2018 9:09 AM
To: 'melvin.ye@sompo.com.sg' <melvin.ye@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Dear Melvin,

Enclosed preliminary revised of vehicle GBF 5648T
Date of survey: 20/8/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 29 August 2018 2:06 PM
To: 'melvin.ye@sompo.com.sg' <melvin.ye@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Dear Melvin,

Please be informed that we have inspected the vehicle GBF 5648T on 20/8/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]

Sent: Wednesday, 29 August, 2018 11:23 AM

To: 'assignments' <assignments@lkkauto.com>

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Hi

Please refer to the email as below.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]

Sent: Monday, August 20, 2018 5:50 PM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Our Claim Reference: CMTD1803582

Your Reference: GBF5648T

Hi Nancy,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK to conduct the survey on a without Prejudice and without any admission of liability basis.

Aside to LKK,

Please make arrangement to conduct the survey for SKQ5990P on a without Prejudice and without any admission of liability basis.

Please submit with your report to my colleague, Ms Agnes Chan.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 20 August, 2018 5:33 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582

Your Reference: GBF5648T

Dear Melvin

Please arrange LKK Auto Consultants to survey the car.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, August 20, 2018 5:23 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582
Your Reference: GBF5648T

Without Prejudice

Date: 20th August 2018

Attention:
M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING GBF5648T & SLD9405T ON 18.08.2018

We refer to your Notice of Accident dated 20/08/2018.

Please be informed that Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Melvin Ye
Claims Division
D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Monday, 20 August, 2018 3:02 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Hi Sir

My client claiming your insured SLD 9405T.

Please kindly arrange PRS for GBF 5648T.

Date of accident 18.08.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are required to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 29 August 2018 2:06 PM
To: 'melvin.ye@sompo.com.sg'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Dear Melvin,

Please be informed that we have inspected the vehicle GBF 5648T on 20/8/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Wednesday, 29 August, 2018 11:23 AM
To: 'assignments' <assignments@lkkauto.com>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Hi

Please refer to the email as below.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, August 20, 2018 5:50 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Our Claim Reference: CMTD1803582
Your Reference: GBF5648T

Hi Nancy,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK to conduct the survey on a without Prejudice and without any admission of liability basis.

Aside to LKK,

Please make arrangement to conduct the survey for SKQ5990P on a without Prejudice and without any admission of liability basis.

Please submit with your report to my colleague, Ms Agnes Chan.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 20 August, 2018 5:33 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582

Your Reference: GBF5648T

Dear Melvin

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, August 20, 2018 5:23 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582
Your Reference: GBF5648T

Without Prejudice

Date: 20th August 2018

Attention:
M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING GBF5648T & SLD9405T ON 18.08.2018

We refer to your Notice of Accident dated 20/08/2018.

Please be informed that Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	

3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 20 August, 2018 3:02 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Hi Sir

My client claiming your insured SLD 9405T.

Please kindly arrange PRS for GBF 5648T.

Date of accident 18.08.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

Catherine Chong (LKK Auto)

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Wednesday, 29 August, 2018 11:23 AM
To: 'assignments'
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Hi

Please refer to the email as below.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, August 20, 2018 5:50 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Without Prejudice

Our Claim Reference: CMTD1803582
Your Reference: GBF5648T

Hi Nancy,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK to conduct the survey on a without Prejudice and without any admission of liability basis.

Aside to LKK,

Please make arrangement to conduct the survey for SKQ5990P on a without Prejudice and without any admission of liability basis.

Please submit with your report to my colleague, Ms Agnes Chan.

Thank you.

Best Regards
Melvin Ye
Claims Division



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 20 August, 2018 5:33 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582

Your Reference: GBF5648T

Dear Melvin

Please arrange LKK Auto Consultants to survey the car.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]

Sent: Monday, August 20, 2018 5:23 PM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Our Reference: CMTD1803582

Your Reference: GBF5648T

Without Prejudice

Date: 20th August 2018

Attention:
M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING GBF5648T & SLD9405T ON 18.08.2018

We refer to your Notice of Accident dated 20/08/2018.

Please be informed that Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Melvin Ye
Claims Division
D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Monday, 20 August, 2018 3:02 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF 5648T

Hi Sir

My client claiming your insured SLD 9405T.

Please kindly arrange PRS for GBF 5648T.

Date of accident 18.08.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2604C
Vehicle Details	
Vehicle No.:	GBF5648T
Vehicle to be Exported:	No
Intended De-registration Date:	21 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	K9KC400D055989
Chassis No.:	VSKYBAM20Z0133385
Maximum Power Output:	-
Open Market Value:	\$20,261.00
Original Registration Date:	16 Dec 2016
First Registration Date:	16 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$1,014.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,473.00
COE Rebate Amount:	\$28,665.00
Total Rebate Amount:	\$28,665.00

The information contained herein is correct as at 21 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 15:21
Date Of Accident	18/08/2018 15:45
Exact Location Of Accident	BKE EXIT DAIRY FARM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF5648T
Insured/Policyholder	
Name Of Registered Owner	ENG SOON HENG TRADING PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63650025

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0102781-VCV
Cover Note Number	

Driver

Name of Driver	LEE LAI HENG
NRIC No	S7907740B
Date Of Birth	17/03/1979
Occupation	OUTDOOR
Date Of Driving Pass	08/10/2013
Driving Experience	4 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90689794
Fax Number	
Contact Number	
Email Address	GERALD@ESH.COM.SG

Address	BLK 104 GANGSA RD #07-59
Postcode	670104
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD9405T
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	ANG KIN MENG
NRIC/Passport Number	S1150858H
Contact Number	92958426
Address	NA
	NA
Postcode	NA
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBD3211T
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HE XIAN ZHUANG
NRIC/Passport Number	S8017119F
Contact Number	98247552
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LEE LAI HENG
Approximate Age	
Injuries Sustain	WHOLE BODY
Injured person in which vehicle?	GBF5648T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 104 GANGSA RD #07-59
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Common Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report T/20180220/2057

Insurance Co: _____
 Vehicle No: _____ Date of Accident: _____
☐ Reporting Only
☐ Own Damage Claim
☒ Third Party Claim

@ Fastech

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 4

Report No. T/20180820/2057

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2018 12:45		Vide Report No.:		Station Diary No.: 56
Informant's Particulars				
Name of Informant: LEE LAI HENG		Address: APT BLK 104 GANGSA ROAD #07-59 SINGAPORE 670104		
ID Type / ID No.: NRIC NO / S7907740B		Contact No.: Home/Office: Mobile: 90689794		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 39	Date of Birth: 17/03/1979	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: MANAGER		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/08/2018 15:45	Type of Location: Slip Road
Location: Junction of Road 1 and Road 2 BUKIT TIMAH EXPRESSWAY DAIRY FARM ROAD slip road to Dairy Farm Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD3211T	Van	TOYOTA	HIACE	White	Seriously Damaged	0
GBF5648T	Van	NISSAN	NV200	Grey	Seriously Damaged	0
SLD9405T	Car	MITSUBISHI	LANCER	Silver	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 4

Report No. T/20180820/2057

CONTINUATION OF REPORT

Driver			
Name	HE XIAN ZHUANG		ID No. S8017119F
Related Vehicle	GBD3211T (Van)		Contact No. 98247552
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE LAI HENG		ID No. S7907740B
Related Vehicle	GBF5648T (Van)		Contact No. 90689792
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	20/08/2018	Date Discharge	20/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	ANG KIN MENG		ID No. S1150858H
Related Vehicle	SLD9405T (Car)		Contact No. 92958426
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/08/2018 at about 1545hrs, I was driving my company's van Reg no: GBF5648T Nissan Grey in colour along BKE towards Woodlands. Upon reaching the Dairy Farm Road Exit, I exited from the expressway and was on slip road turning into Dairy Farm Road. As there were cars along Dairy Farm Road, I stopped my van behind the give way line to wait for the road to be clear before I enter Dairy Farm Road. Suddenly, I felt an impact on the rear of my vehicle. I then went out of the car to check and discovered that there are two more vehicles involved in the accident. The car Reg no: SLD9405T that hit me have been hit by the van behind it thus causing the car to move and hit the rear of my van. None of the drivers complain of any injury at that time.

My van rear bumper and the two rear doors were badly dented. The car behind me had its front bumper and rear bumper badly damaged and dented and also leakage can be seen coming out from the vehicle.



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 4

Report No. T/20180820/2057

CONTINUATION OF REPORT

The last vehicle front bumper were also damaged and dented.

After taking pictures of the vehicles and exchanging particulars, we all left the accident area. On 19/08/2018, I wake up from sleep and starts feeling pain on the rear of my neck and the back of my body. On 20/08/2018 the pain still have not subside thus I decided to go to the clinic for treatment. I was then given 5 days medical leave.



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

4 of 4

Report No. T/20180820/2057

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sr Staff Sgt MUHAMAD FAISAL BIN MOHD
SALEH

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
20/08/2018 12:45

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No.: 65476436

Classification Of Case:

Authentication Stamp
NP168

Date of Accident : 18/8/18 Accident Time: 1545hrs (24-HR-Format)
 Accident Place : BKE Exit Dairy Farm Rd.
 Vehicle No. (Car Plate No.) : GBF 5648T Make/Model: NV 200 Nissan
 Insurance Company : Great Eastern Policy No: 2017-V0102781-VCV
 Owner or Company Name / IC No. : Eng Soon Heng Trading Pte Ltd.
 Owner or Company Contact No. : 6365 0025 Owner's Hp 98005916 Company Tel
 DRIVER'S Name / IC No. : Lee Lai Heng S7907740B
 DRIVER'S Date Of Birth : 17/3/79 DRIVER'S License Pass Date 2/10/2018
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
 DRIVER'S Address : BLK 104 Gangsa Rd #07-59S (670104)
 DRIVER'S Contact No. / Alt No. : 1) 90689774 2) _____
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : atwyn_troy78@yahoo.com.sg
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 01
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): _____

Other Party Driver's Particular (if any)

Vehicle No: <u>SLD 9405T (30mpo)</u>	Vehicle No: <u>ABD 3211T</u>
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

VERA: GBF5648T

veh B: 5LD 9405T

Verh C : ABD, 3011T



Dairy farm record.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report 7/20/2020/2057.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

1 of 4

Report No. T/20180820/2057

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2018 12:45		Vide Report No.:		Station Diary No.: 56	
Informant's Particulars					
Name of Informant: LEE LAI HENG			Address: APT BLK 104 GANGSA ROAD #07-59 SINGAPORE 670104		
ID Type / ID No.: NRIC NO / S7907740B			Contact No.: Home/Office: Mobile: 90689794		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 17/03/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/08/2018 15:45	Type of Location: Slip Road
Location: Junction of Road 1 and Road 2 BUKIT TIMAH EXPRESSWAY DAIRY FARM ROAD slip road to Dairy Farm Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD3211T	Van	TOYOTA	HIACE	White	Seriously Damaged	0
GBF5648T	Van	NISSAN	NV200	Grey	Seriously Damaged	0
SLD9405T	Car	MITSUBISHI	LANCER	Silver	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

CONTINUATION OF REPORT

Driver			
Name	HE XIAN ZHUANG		ID No. S8017119F
Related Vehicle	GBD3211T (Van)		Contact No. 98247552
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE LAI HENG		ID No. S7907740B
Related Vehicle	GBF5648T (Van)		Contact No. 90689792
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	20/08/2018	Date Discharge	20/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	ANG KIN MENG		ID No. S1150858H
Related Vehicle	SLD9405T (Car)		Contact No. 92958426
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/08/2018 at about 1545hrs, I was driving my company's van Reg no: GBF5648T Nissan Grey in colour along BKE towards Woodlands. Upon reaching the Dairy Farm Road Exit, I exited from the expressway and was on slip road turning into Dairy Farm Road. As there were cars along Dairy Farm Road, I stopped my van behind the give way line to wait for the road to be clear before I enter Dairy Farm Road. Suddenly, I felt an impact on the rear of my vehicle. I then went out of the car to check and discovered that there are two more vehicles involved in the accident. The car Reg no: SLD9405T that hit me have been hit by the van behind it thus causing the car to move and hit the rear of my van. None of the drivers complain of any injury at that time.

My van rear bumper and the two rear doors were badly dented. The car behind me had its front bumper and rear bumper badly damaged and dented and also leakage can be seen coming out from the vehicle.



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 4

Report No. T/20180820/2057

CONTINUATION OF REPORT

The last vehicle front bumper were also damaged and dented.

After taking pictures of the vehicles and exchanging particulars, we all left the accident area. On 19/08/2018, I wake up from sleep and starts feeling pain on the rear of my neck and the back of my body. On 20/08/2018 the pain still have not subside thus I decided to go to the clinic for treatment. I was then given 5 days medical leave.



**SINGAPORE
POLICE FORCE**



T/20180820/2057

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

4 of 4

Report No. T/20180820/2057



CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sr Staff Sgt MUHAMAD FAISAL BIN MOHD SALEH
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436

Signature Of Informant: 
Date/Time: 20/08/2018 12:45
Classification Of Case: 

Authentication Stamp
NP168



FASTECH AUTO PTE LTD
1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

Not Authorised
N/A
4/5 \$6500
5 dy.

VEHICLE NO:GBF 5648T

QTY	PARTICULAR (NETT ITEM)		
1 PCS	REAR BACK DOOR N/S	1285.40	Body 20 \$1,610.10 ✓
1 PCS	REAR BACK DOOR 'NV200' EMBLEM	118	re \$205.30 ✓
1 PCS	REAR BACK DOOR REAR LOGO N/S	48.50	re \$66.80 ✓
1 PCS	REAR BACK DOOR OUTER HANDLE N/S		11 \$168.50 X
1 PCS	REAR BACK DOOR LOWER LOCK N/S	166.50	twi/gm \$299.30 ✓
1 PCS	REAR BACK DOOR INNER TRIM N/S	295.30	To 1 \$625.10 ✓
1 SET	REAR BACK DOOR INNER TRIM CLIPS N/S		re \$25.00 ✓
1 PCS	REAR BACK DOOR O/S	1285.40	Body 20 \$1,615.10 ✓
1 PCS	REAR BACK DOOR 'Dci' EMBLEM O/S	725	re \$66.80 ✓
1 PCS	REAR BACK DOOR LOWER LOCK O/S	166.50	twi/gm \$299.30 ✓
1 PCS	REAR BACK DOOR INNER RUBBER O/S	188.20	To 1 \$288.50 ✓
1 PCS	REAR BACK DOOR INNER TRIM O/S	295.30	To 1 \$605.10 ✓
1 SET	REAR BACK DOOR INNER TRIM CLIPS O/S		re \$30.00 ✓
1 PCS	REAR BUMPER	645.02	20/2e \$822.30 ✓
2 PCS	REAR BUMPER REFLECTORS @\$60.00		11 \$120.00 X
1 PCS	REAR BUMPER SPONGE	105	To 1 \$288.00 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @\$95.00		3e \$190.00 ✓
2 PCS	TAILLAMPS @\$480		11 \$960.00 X
1 PCS	REAR END PANEL		Body 20 \$665.20 ✓
1 PCS	REAR END PANEL TOP GARNISH		twi \$311.30 ✓
1 PCS	REAR END PANEL WEATHERSTRIP	248.20	twi \$366.50 ✓
1 PCS	REAR FLOOR PANEL		re \$1,420.00 X
			\$11,048.20

S.NETT

1 PCS	REAR BACK DOOR GLASS SEALANT N/S	re \$50.00 40
1 PCS	70 KM/H' STICKER	re \$20.00 10
1 PCS	REAR BACK DOOR GLASS SEALANT O/S	re \$50.00 40
1 PCS	6 PAX' STICKER	re \$20.00 10
1 SET	REAR BUMPER REVERSE SENSOR	5 holder \$280.00 200
1 SET	REAR BUMPER CLIPS	re \$30.00 ✓
1 SET	REAR FLOOR PANEL INSULATOR	11 \$180.00 X

LABOUR CHARGES:

TO CHECK WIRING	\$80.00 20
TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00 50
TO DISMENTLE & REFIX BOTH BACK DOOR GLASS	\$300.00 200
TO DISMENTLE & REFIX BOTH BACK DOOR MECHANISM	\$200.00 120

6135.62
5522.05

TO DISMENTLE & REFIX REAR EXHAUST

TO CONDUCT CHASSIS ALIGNMENT

TO SPRAY RUST PROOFING

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED

& REPLACING PARTS

TO PUTTY & SPRAY PAINTING

TOTAL

11	\$100.00	✓
11	\$380.00	✓
	\$120.00	100
	\$1,500.00	900
	\$1,500.00	900
	\$15,938.20	

\$142.05

- Let Auto Consultants hence notify the Repairer of the following:
- To resurvey vehicle after spray painting
 - To inspect damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - The repair survey is on a "Without Prejudice" basis
 - The repair modification(s) is allowed
 - The damaged part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18015097/Uvbn2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 07-09-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLD 9405T	Veh. Inspected	GBF 5648T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803582	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200 (M)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VSKYBAM20Z0133385	Colour	GREY
Odometer	65682	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	GOODYEAR	6 mm
L/H Front Tyre	175/70 R14	GOODYEAR	6 mm
R/H Rear Tyre	175/70 R14	GOODYEAR	6 mm
L/H Rear Tyre	175/70 R14	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/08/2018	Inspection Date	20/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5648T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BACK DOOR N/S	BADLY DENTED	1,610.10	1,285.40
1	REAR BACK DOOR "NV200" EMBLEM	NECESSARY	205.30	118.00
1	REAR BACK DOOR REAR LOGO N/S	NECESSARY	66.80	48.50
1	REAR BACK DOOR OUTER HANDLE N/S	NOT NECESSARY	168.50	-
1	REAR BACK DOOR LOWER LOCK N/S	TWISTED / JAMMED	299.30	166.50
1	REAR BACK DOOR INNER TRIM N/S	TORN	625.10	295.30
1	SET REAR BACK DOOR INNER TRIM CLIPS N/S	NECESSARY	25.00	25.00
1	REAR BACK DOOR O/S	BADLY DENTED	1,615.10	1,285.40
1	REAR BACK DOOR "DCI" EMBLEM O/S	NECESSARY	66.80	66.80
1	REAR BACK DOOR LOWER LOCK O/S	TWISTED / JAMMED	299.30	166.50
1	REAR BACK DOOR INNER RUBBER O/S	TORN	288.50	188.20
1	REAR BACK DOOR INNER TRIM O/S	TORN	605.10	295.30
1	SET REAR BACK DOOR INNER TRIM CLIPS O/S	NECESSARY	30.00	30.00
1	REAR BUMPER	DENTED / DEFORMED	822.30	645.02
2	REAR BUMPER REFLECTORS @\$60.00	NOT NECESSARY	120.00	-
1	REAR BUMPER SPONGE	TORN	288.00	105.00
2	REAR BUMPER SIDE HOLDERS @\$95.00	BENT	190.00	190.00
2	TAILLAMPS @\$480.00	NOT NECESSARY	960.00	-
1	REAR END PANEL	BADLY DENTED	665.20	665.20
1	REAR END PANEL TOP GARNISH	TWISTED	311.30	311.30
1	REAR END PANEL WEATHERSTRIP	TWISTED	366.50	248.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,420.00	-
	LESS 10% DISCOUNT		-	-613.56
			11,048.20	5,522.06
<u>SPECIAL NETT ITEMS</u>				
1	REAR BACK DOOR GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR BACK DOOR GLASS SEALANT O/S (SN)	NECESSARY	50.00	40.00
1	6 PAX STICKER (SN)	NECESSARY	20.00	10.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS/SMO18015097/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
			630.00	330.00
	LABOUR			
	TO CHECK WIRING.		80.00	20.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMENTLE & REFIX BOTH BACK DOOR GLASS.		300.00	200.00
	TO DISMENTLE & REFIX BOTH BACK DOOR MECHANISM.		200.00	120.00
	TO DISMENTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING.		120.00	100.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,500.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			4,260.00	2,290.00
GRAND TOTAL			15,938.20	8,142.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CS/SMO18015097/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.