



Your Ref: MCT16120443

Date: 13<sup>th</sup> September 2018

Our Ref: CS1/III18015103/Brbs2

**M/s India International Insurance Pte Ltd**

64 Cecil Street  
#05-02 IOB Building  
Singapore 049711  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SKA 2464X  
INSURED VEHICLE: SH 6611E  
ACCIDENT DATE: 10/12/2016**

We thank you for your instruction on 20/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKA 2464X from M/s CL Appraiser Pte Ltd.
- b) Final Repair Bill of SKA 2464X from M/s Torque 5 Pte Ltd.
- c) Singapore Accident Statement of Vehicles SKA 2464X and SH 6611E.
- d) Colour damaged vehicle photographs of SKA 2464X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKA 2464X
Make & Model	: Volkswagen Scirocco
Year of Registration	: 2011
Chassis Number	: WVWZZZ13ZBV021874
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.