

ASW REC. BY:

REF: CS3 / ASM18015108 / GZ4657 Special Instruction:

Surveyor:

From (Person):

Gulo Gulo
Cynthia Loh

ASSIGNMENT (Office)

of ASM

Date/Time: 20082018 3:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 8503C

Insured:

SLF 8448R

at Workshop m/s

Twincor Automotive

Tel:

68420051

of

2 Kaki Bukit Ave 2 #01-17

Policy No:

Claim No:

S8M0032LN

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

21-082018

H.O.D. Endorsement:

Date/Time: 20082018 5:06pm

Person Contacted:

Elynn

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SJH 8503C - CS/Smo17000211 / mldh3n2	DA: 07012017
	SLF 8448R - C4 / ASM18014763 / K1463	DA: 11082018
24/8/18	TS mantled.	

(08/11/13) wef

ASS. REC. BY:

REF: ASM(AXA)

674461

ASSIGNMENT

(-2028)

From: Date: 21/8/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJH 8503C
at Workshop m/s Twincar Automotive
of 2 kaki Bkt Ave 2 #01-17 118

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$60k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJH 8503C Yr Regn: 27 Aug 2008

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit lancia 1.6 c.c 1584

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 107737 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSNCS3A.84006033

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 21-08-18

Survey held at w/s 4:45pm

Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / UIC / Rooftop orThe ☒ UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/8/18 Inhibit PRS Report.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS, ☐ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/ASM18015108/Gz4b

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 20-08-2018



Code : ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLF 8448R	Veh. Inspected	SJH 8503C
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00SLN	Excess (\$)	0.00
Assign From	SMART CLAIM (CYNTHIA LOH)	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/08/2018	Inspection Date	21/08/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Service Request Details

Claim

S8M00SLN

Reference

None 

Loss Date

August 19, 2018

Request Date

August 20, 2018

Due Date

August 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SJH8503C

Make

TPVD TBC

Model
TBC

Service Address

...

Primary Contact/Insured

SENTOSA BUILDING CONSTRUCTION PTE LTD
37 LORONG 23 GEYLANG #03-02, YU LI INDUSTRIAL BUILDING, 388371, Singapore
84159990
MEEYEE@INSMART.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
INSD GIA NOT REPORTED

[Messages](#) [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

New Message

Vehicle No.	SJH 8503C		Model / Make	Mit. Lancer
Date of Accident	19/08/18			
Time of Accident	1745 HRS			
Location of Accident	Stadium Walks in front of Singapore Indoor Stadium			
Exact purpose use during accident	Private Used			
Name of Owner	Mu Jinduo			
Telephone No.	H/P : 8323 8870	Home :	Office :	
NRIC	S 8376744H			
Address	Blks 115B Yishun Ring Road #15-821 (S) 762115			
Claim type	OD	THIRD PARTY	REPORTING ONLY	
Insurance Company	Aviva			
Type of Coverage	Comprehensive	Third Party	Third Party / Fire / Theft	
Policy No.	10811551			
Name of Driver	As Above If No,			
NRIC	Any Passengers : N.A.			
Date of birth	10/09/1983			
Occupation	Outdoor	/	Indoor	
Driving License Pass Date	29/07/2008			
Gender	Male	/	Female	
Contact No.	H/P :	Home :	Office :	
Address				
Driver have any own vehicle	No,	If yes, Reg No.		
Relationship	Employee,	If no, state <i>Owner</i>		
Weather condition	Clear	Raining	Other	
Road Surface	Dry	Wet	Other	
Any Injuries	No,	If Yes, Who?		
Name And Contact No.	Mu Jinduo (H/P: 8323 8870)			
Name And Contact No.				
Police Report	No,	If Yes, Where?		
Vehicle B No.	SLF 8448 R		Any Passengers :	03
Name of Driver	Chen Jiaoping		Contact No. :	
Vehicle C No.			Any Passengers :	
Vehicle D No.			Any Passengers :	
Vehicle E no.			Any Passengers :	
Vehicle F No.			Any Passengers :	
Vehicle G No.			Any Passengers :	
Witness Name	N.A.		Witness Contact :	
Accident Portion	Right and left side and undercarriage			
Camera Recorder	Yes No			
Email Address	jinduo2400@gmail.com			
PARTICULAR WORKSHOP	Tuescar			
CONTACT NO.	6842 0051 / 6744 0510			
CONTACT PERSON	Huixian			
FAX NO	6741 0510			

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/08/18 at @ 1745 hrs, I was travelling in my vehicle (SJH 8503C) along Stadium Walk ~~from~~ opposite of Singapore Indoor Stadium on the left lane travelling straight. Suddenly, a vehicle (SLF 8448R) exit from Singapore Indoor Stadium carpark did not stop at the stop line to give way. As a result, the said vehicle collided onto the right rear side of my vehicle. The impact caused my vehicle to spin and the left side of my vehicle collided onto the railing on the left.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6744H
Vehicle Details	
Vehicle No.:	SJH8503C
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4G18JS4583
Chassis No.:	JMYSNCS3A8U006033
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$10,236.00
Original Registration Date:	27 Aug 2008
First Registration Date:	27 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$10,236.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2018
PARF Rebate Amount:	\$5,118.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$10.00
Total Rebate Amount:	\$5,128.00

The information contained herein is correct as at 23 Aug 2018

OK


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18015108/Gz4bs2	
8 SHENTON WAY #24-01		Date: 29-08-2018	
AXA TOWERSINGAPORE 068811			
ATTN: CYNTHIA LOH		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLF 8448R	Veh. Inspected	SJH 8503C
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00SLN	Excess (\$)	0.00
Assign From	SMART CLAIM (CYNTHIA LOH)	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER 1.6	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JMYSNCS3A8U006033	Colour	GREY
Odometer	107737 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60R15	FALKEN	5 mm
L/H Front Tyre	195/60R15	FALKEN	5 mm
R/H Rear Tyre	195/60R15	FALKEN	5 mm
L/H Rear Tyre	195/60R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.			
5. General Information			
Accident Date	19/08/2018	Inspect Date / Time	21/08/2018 (04:45 PM)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18015108/Gz4bs2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	S8M00SLN			
Reference				
CS3/ASM18015108/Gz4bs2	Loss Date			
August 19, 2018	Request Date			
August 20, 2018	Due Date			
August 20, 2019	Vendor Name			
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss			
Third Party Vehicle Damage	Services			
Pending verification - Direct Settlement				
Additional Instructions				
INSD GIA NOT REPORTED				
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Claim Handler				
LOH Cynthia				
6568804843				
cynthia.loh@axa.com.sg				
Messages	Invoices	History	Documents	
Assessment	Metrics	Notes		

Actions

Next Step

Finish the work

Complete Work

More

Document Type

Document SubType

Upload Documents

Vehicle Information	
Incident Vehicle Registration #	SJH8503C
Make	Service Address
TPVD TBC	Model
TBC	Primary Contact/Insured
SENTOSA BUILDING CONSTRUCTION PTE LTD	
37 LORONG 23 GEYLANG #03-02, YU LI INDUSTRIAL BUILDING, 388371, Singapore	
84159990	
MEEYEE@INSMART.SG	



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Vehicle & Driver Details					
Vehicle Registration#	SJH8503C	Purchase Date	mm/dd/yyyy		
Registration State	SINGAPORE	Registration Date *	08/27/2008		
Mileage	107737	Age of Vehicle	9		
Driver Details					
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2008		Driver Name	MU IENDUC	
Make	TPVD TBC	MITSUBISHI	Date of Birth		mm/dd/yyyy
Model	TBC	LANCER 1.6 M	Age	0	
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No	JMYSNCS3A8U006033		Driving Experience	0	
Engine No	4G18J54583		Driver License #		
Engine Capacity	1584 cc				

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	08/21/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	195/60R15	Rear Tyre Size	195/60R15
Front left side	FALKEN 5mm	Rear left side	FALKEN 5mm
Front right side	FALKEN 5mm	Rear right side	FALKEN 5mm