ASS. REC. B	Y: Marcw	E CS EGII8		rd3eBpecial Instru	ection:	
From (Perso Estimated Co	n): Yee fei si	of	Bill to:	. Date/Tii	me: 20/8/18/8/11/2)San
To Inspect V	/STTP RES / OD RES / I	SKX36-	CS 41	Insured: 1	01950X 54 7617	
of Policy No: Sum Insured		thoz Gr pine st	Claim No:Excess:		0x/RH/p/	
Make of Veh (Client's Recor	/ REP. / REV 24 HRS	lwp,		D.O.A	14/08/2018 1188 after 9-300	am
Date/Time: Date/Time	Action/Instruction (Vehicle II		
	SKX 3647-X 101950 X-X		ę			_
241818	Revol thou em	ar				

ASS. REC. BY: Marns REF: FGI	
	SSIGNMENT
From: . Date: 21/08 2018	Veh No: Sk X S647 Yr Regn: 1/1 15
Estimated Cost:	Type: M.Car./ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (v9 /
To Inspect Vehicle No: 3K× 364T	Make: NISSAN QAShqai c.c 1987
at Workshop m/s Ethoz Group	Colour 5/00/C A/C: Insured / Std / NI / NA
of 22 tempines 8+.92	Sp.Reading 67/80 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: SJNFBAJILU 1521002
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh: Mr · Nq	Modi: Nil /(S/Rim / STD A/Rim or
	Tyre Size: F: 275/45-tn/9
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Nexen
Bal. or Market Value:	Front Rear
IDAG Accident Rport: Consistent? : Yes or No	R/Bal. A mm R/Bal. mm
GIAPR Seen: Consistent? : Yes or No	L/Bal. P, mm L/Bal. P, mm
Est. Repairs:	D.O.A. 14/8/18 D.O.I. 2//8/16
Lum Sum: /3 / % 3 Val.: Yes or No	Survey held at
1-VI	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS WP LTH STORY Vehicle: IN / OU	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time Action / Instruction/	
Ill Colfind find by	4 4634.54 will AH lea
10/0	
Red:\$2968.19, 397.	
RECEIVED	2 8 AUG 2018
NE SELVED	2 0 700 200
	2
·	
Date/Time, File Pass to?	D
. I Tell: Keport	Days Of Repair: 4
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 250
A.J. C.	Transportation: Site Insp (\$)_s+RS,SI
Add Fe	
Report Format: 1P	
Lump, Sum / I.B.I: (\$ 4634.54)	: Weekend (\$)
	TOTAL 29V

(08/11/13) wef



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation	Internationale Des Experts En Autor	mobile				
ER	GO INSURANCE F	PTE LTD	Ref : CS/EGI18015	120/Urd3				
#04	EMASEK BOULEV -01 SUNTEC TOW GAPORE 038985		Date : 20-08-2018 Code : EGI					
1.	DET TO STATE	Policy Par	ticulars :- THIRD PARTY CLA	IM				
	Insured Veh.	YP 1950X	Veh. Inspected	SKX 364T				
	Policy No.		Coverage (\$)	0.00				
	Claim No.	YP1950X/RH/pl	Excess (\$)	0.00				
	Assign From	YEE PEI LI	Assign Date	20/08/2018				
2.		Vehic	cle Particulars & Condition					
	Make & Model		c.c	0				
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	:-	Steering					
	Brakes		Modification					
	General							
3.			Conditions of Tyres					
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
	L/H Rear Tyre			mm				
4.		VelD	escription of Damages					
5.	Engine No	HEDEN	General Information					
	Accident Date	14/08/2018	Inspection Date	21/08/2018				
	Survey held at	ETHOZ GROUP LTD		@100075077 11 2 0				
		22 TAMPINES STREET SINGAPORE 528876	T 92					
ia.	DELICIES		Remarks					
	A)THE INSPECTIO	N WAS CONDUCTED O	N A"WITHOUT PREJUDICE" BAS	IS.				
	IRJIN ACCORDANC	E TO YOUR INSTRUCT	IONS, WE HAVE NOT AUTHORIS	ED REPAIRS.				

Nivitha (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Monday, 20 August 2018 11:25 AM

To:

'admin-d@lkkauto.com'

Subject:

OI: YP1950X / TP: SKX364T/LKK / DOA: 14/08/2018

Attachments:

YP1950X - SAS.pdf; SKX364T - SAS.pdf; SKX364T - estimate.pdf; SKX364T - PRS

FORM.pdf

Dear Catherine.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANCY PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from ETHOZ GROUP LTD.

ADDRESS

: 22 TAMPINES ST 92

SINGAPORE 528876

PERSON TO CONTACT

NG BOON KAI @ 6654 7617

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Regards, Yee Pei Li (Ms) Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985 DID.: +65 6829 9194 Tel.: +65 6829 9199 Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Date:	20.08.2018		Sent via Fax	
Our Reference:	YP 1950X/RH/pl	_		
	SKX 364T	-	or	
Your Reference:	3KX 3041	_	Email	
То:	ETHOZ GROUP LTD	_		onKai.Ng@ethozgroup.com
Pre-Repair Su	rvey (PRS) Acknowledgement			
Vehicle For Insp	ection: SKX 364T			
Insured's Vehicle	YP 1950X			
Date Of Acciden	t: 14.08.2018	_		
We acknowledge	e receipt of your request for PRS on:	20.08.2018	_	
In compliance w	rith "State Courts Practice Directions An	nendment No.1 o	f 2016", do select an a	ssessor from
the list below ar	nd indicate your selection in the box ma	rked *.	* 4	K Ado
AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants I	Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants P	te Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services	
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd	
		1		
Your reque	est for inspection does not have your client's est for inspection does not have your client's wledge your interest for direct settlement, will d's driver has not reported the accident to under the work of the write to confirm our agreement of the accident to be agreed. OFFICER-	GIA report, kindly to e will assess & reve s todate. ent to have a d	orward a copy. rt soon upon receipt of es	stimate.
4				
Prepared by:	b.A.	Pei Li	6829 9194	claims@ergo.com.sg
Signature:	10			FAX: 6829 9247
Assessor use only: Assignment Date: Assignment Time: Remarks:				
			wledgement & Stamp. tion is on a without admi	



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: YP1950X/RH/pL Our Ref: CS/EGI18015120/Urd3

The Motor Claims Department ERGO Insurance Pte Ltd

Without Prejudice

nearside

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKX 364T .

We thank you for the instruction on 20/08/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on $\underline{21/08/2018}$ at the premises of M/s $\underline{ETHOZ\ GROUP\ LTD}$ and have the following to report:-

Workshop Estimate Amount	: S\$ 7,602.73
Revised Estimate Amount	: S\$ 3,179.24
"Check" Items Amount	: <u>S</u> \$ 1,455.30
Market Value	: <u>S</u> \$
LTA Reimbursement Value	: <u>S</u> \$
Nett Value	: <u>S</u> \$

Description of Damage: The vehicle sustained damages at the n/s front portion.

at the n/s front portion.

rear

offside

front

Comments/ Present Status:

Yours faithfully

MARCUS CHUA Automotive Assessor

Damages Consistent.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report

14/08/2018 17:37

Date Of Accident

14/08/2018 11:40

Exact Location Of Accident

BLK 1001 EUNOS AVE 8 CARPARK

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKX364T

Insured/Policyholder

Name Of Registered Owner

LOW KUM HENG

NRIC No

S1303395A

Email Address

KHLOW2000@YAHOO.COM

Mobile Phone No

(LOCAL) +65-96773357

Alternative Phone No

OFFICE-96773357

Vehicle Particulars

Manufacturer

NISSAN

Model

QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

If No, Please state action to be taken

NO

for repair to your vehicle?

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

GA288256/1

Cover Note Number

25/11/2017-24/11/2018

Driver

Name of Driver

LOW KUM HENG

Data Of Birth

NRIC No

S1303395A

Date Of Birth

30/04/1958

Occupation

OUTDOOR

Date Of Driving Pass

.......

Driving Experience

21/07/1983

Driving Experience

35 YEARS AND 0 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96773357

Fax Number

Contact Number

OFFICE-96773357

EMail Address

KHLOW2000@YAHOO.COM

Address

BLK 11 FLORA ROAD #02-01 SINGAPORE 509732

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

÷

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP1950X

Vehicle Make/Model/Colour

MITSUBISHI

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

RAJENDRAN VIGNESH

NRIC/Passport Number

037368407 94650294

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Saho

NRIC/FIN No.:

GIARMC SketchPlanForm V3

)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked stationary at the carpark
lot just outside Block 1001, thit 01-16 Euros
Ave 8. All of 9 suddents and lovery reversed into
the agacent carpark but and but the left side
of my car.
I approached the other driver and we exchanged
partalan.
I even called his boss and he mentioned to punde
insurance dain.
You had been advised by workshop that in the event that you wish to claim Reporting Only
against your own policy (OD claim), there is a Fourteen (14) days clause Claim OD
whereby the claim must be made within the stipulated timeframe from the day of occurance.
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

7/1/-1

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: This

NRIC/FIN No.:

u-
@ethozgroup.com
from
uto.
90
aim with
aim with
aim with ms@ergo.com.sg
ms@ergo.com.sg
aim with ms@ergo.com.sg
ms@ergo.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	3395A
Vehicle No.:	SKX364T
Vehicle to be Exported:	No
ntended De-registration Date:	23 Aug 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	MR20382535W
Chassis No.:	SJNFBAJ11U1521002
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,333.00
Original Registration Date:	25 Nov 2015
First Registration Date:	25 Nov 2015
Fransfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$19,333.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2025
PARF Rebate Amount: ntended COE Rebate Details	\$14,499.00
COE Expiry Date:	24 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$44,316.00
Total Rebate Amount:	\$58,815.00

The information contained herein is correct as at 23 Aug 2018

OK

SGCARMART.COM

New Cars

Used Cars


Sell My Car

Directory

Products

Insurance

Article



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Advertiser Login

Make

Ways of Selling

Maserati GTS.



Rare.

Direct Owner StarAd

ABWIN

Browse by Category

Post an Ad

« Back (1 2 3) Next »

Sort b

Advant

44 vehicles

Nissan Qashqai

Model

Price

Depreciation

Reg Date

Eng Cap

____Mile

Search Selection

Nissan Qashqai

Any

Any

2015

Any

Nissan Qashqai 1.2A DIG-T

\$72,900

\$9,310 /yr

30-Sep-2015

1,197 cc

50

Look No Further, Superbly Low Mileage. Best Value For Your Money. Direct Owner's Silver, Sept 2015, Nissan Qashqai 1. With Black Leather Upholstery. Selling Due To Upgrading To...

Posted: 23-Aug-2018 Tags: 2015 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai, Used Nissan



Nissan Qashqai 2.0A Premium

\$78,800

\$9,710 /yr

23-Sep-2015

1,997 cc

40

1 Owner, 5 Years Warranty By Agent Tan Chong, Just Serviced In August 2018, Depreciation Comparable With 1.2L Vers (142bhp), More Accessories (Panaromic Roof, Keyless Entry, Dr...

Posted: 21-Aug-2018 Tags: 2015 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium \$71,500

\$9,890 /yr

25-May-2015

1,197 cc

54

Elegant Brown SUV, Serviced By Agent, With Navigation System And Reverse Camera, Low Mileage Done, Low, One Owr Cost, Very Well Maintained, Drive Away With Minimum Down Payment...

Prime Motor & Leasing

Posted: 21-Aug-2018 Tags: 2015 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai, Used Nissan



Nissan Qashqai 1.2A DIG-T Premium

\$74,800

\$9,260 /yr

29-Dec-2015

1,197 cc

46

Flexible Repayment In House Financing!5 Years Warranty By Tan Chong Motor. Unlimited Mileage!Stylish Crossover Equi Fuel Efficient 1.2L Engine And Mated To A CVT Gearbox!Spacio...

Quality Motor Trading Enterprise

Posted: 21-Aug-2018 Tags: 2015 Nissan Qashqai, Nissan Qashqai, Nissan, Qashqai, Used Nissan

Car Buying

Car Selling

Car Ownership



Compare



PLEASE ARRANGE TO SURVEY VEHICLE AT 22 TAMPINES ST 92 (S 528876)

Ng Boon Kai

CLAIM DEPARTMENT

DID: 6654 7617

FAX:

Date

18/08/2018

To

ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

LOW KUM HENG

AXA INSURANCE PTE LTD

Certificate No

GA288256/1

Accident Date

14/08/2018

Vehicle No

SKX-364-T

Make & Model

NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

SURVEYOR APP. REPAIRER AMT (\$) QTY DESCRIPTION **Nett Item** 961.40 1 BONNET 185.50 1 BONNET INSULATION 44.00 10 BONNET INSULATION CLIPS M 1 498.30 FRONT GRILLE 1 FRONT GRILLE LOGO 11 73.60 498.30 1 FRONT BUMPER 44.00 10 FRONT BUMPER CLIPS 14 32.50 1 FRONT BUMPER SIDE RETAINER RH 32.50 1 FRONT BUMPER SIDE RETAINER LH

PAGE:



Date

18/08/2018

To

ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

LOW KUM HENG

AXA INSURANCE PTE LTD

Certificate No

GA288256/1

Accident Date

: 14/08/2018

Vehicle No

SKX-364-T

Make & Model

NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

QTY	DESCRIPTION		REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT HEADLAMP LH holde	CV	1,617.00	A .
1	FORNT FENDER LH 70/ Kuc		622.70	_
1	FRONT FENDER INNER SHIELD LH 11		97.50	X
10	FRONT FENDER INNER SHIELD CLIPS 12	u	44.00	
1	FRONT FENDER WHEEL ARCH GARNISH L	H Toin	483.00	
	Sub Total	(10%)	5234.30	
Speci	al Nett Item			
1	FRONT NUMBER PLATE & HOLDER		1 1 35.00	X

3760.6 102 3384:54

PAGE:



Date

18/08/2018

To

ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn

Motor Claim Department

FAX:

Owner

LOW KUM HENG

AXA INSURANCE PTE LTD

Certificate No

GA288256/1

Accident Date

14/08/2018

Vehicle No

SKX-364-T

Make & Model

NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

ESTIMATED REPAIR COST DETAILS

Excess

0.00

Add Excess : 0.00

QTY DESCRIPTION			The state of the s	REPAIRER AMT (\$)	SURVEYOR APP.
Sub Total				35.00	
Labour & Misc					
LABOUR TO FACILIAT	E REPAIR			800.00	400
LABOUR TO SPRAY PAINT AFFECTED AREAS		900.00	800		
TO CHECK AND RECO	NNECT ALL N	ECCESSARY V	WIRINGS	30.00	20
TO RUST PROOF AFFE	CTED AREA			80.00	30
Sub Total				1810.00	

Remarks:

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

SUB TOTALs prices are sub/2602:073 rmation

GST 7.0 % Third party survey is on a "Without Prejudice" basis

TOTAL Supplementary items 1340 resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Principal's name:

Surveyor's name:

LOW KUM HENG

Survey Date & Time:

PAGE:

3

ETHOŻ

Date

27/08/2018

To

ERGO INSURANCE PTE. LTD.

Attn

Motor Claim Department

FAX:

Owner

LOW KUM HENG

Insured By

AXA INSURANCE PTE LTD

Certificate No

GA288256/1

Accident Date : 14/08/2018

Vehicle No

SKX-364-T

Make & Model :

NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2V

FINAL ESTIMATED REPAIR COST DETAILSExcess

0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$SURVEYOR AMT (\$	
Nett 1	tem_		
1	BONNET	961.40	961.40
1	BONNET INSULATION	185.50	0.00
10	BONNET INSULATION CLIPS	44.00	0.00
1	FRONT GRILLE	498.30	0.00
1	FRONT GRILLE LOGO	73.60	0.00
1	FRONT BUMPER	498.30	0.00
10	FRONT BUMPER CLIPS	44.00	0.00
1	FRONT BUMPER SIDE RETAINER RH	32.50	0.00
1	FRONT BUMPER SIDE RETAINER LH	32.50	32.50
1	FRONT HEADLAMP LH	1617.00	1617.00
1	FORNT FENDER LH	622.70	622.70
1	FRONT FENDER INNER SHIELD LH	97.50	0.00
10	FRONT FENDER INNER SHIELD CLIPS	44.00	44.00
1	FRONT FENDER WHEEL ARCH GARNISH	483.00	483.00
	P=井3760.60-10%= 井3384.54	Appir days: Ox.	

PAGE:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile	,
---	---

ERGO INSURANCE PTE LTD

Ref: CS/EGI18015120/Urd3e2

5 TEMASEK BOULEVARD

Date : 29-08-2018



#04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date: 29-08-2018			
JING	VL OVE 030303		Code: EGI			
1.		Policy Particulars	:- THIRD PARTY CLAIN			
	Insured Veh.	YP 1950X	Veh. Inspected	SKX 364T		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	YP1950X/RH/pI	Excess (\$)	0.00		
	Assign From	YEE PEI LI	Assign Date	20/08/2018		
2.		Vehicle Part	iculars & Condition	化 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
	Make & Model	NISSAN QASHQAI (A)	c.c	1997		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	SJNFBAJ11U1521002	Colour	BLACK		
	Odometer	67190	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Condi	tions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	225/45Z R19	NEXEN	8 mm		
	L/H Front Tyre	225/45Z R19	NEXEN	8 mm		
	R/H Rear Tyre	225/45Z R19	NEXEN	8 mm		
	L/H Rear Tyre	225/45Z R19	NEXEN	8 mm		
4.		Descript	ion of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/08/2018	Inspection Date	21/08/2018		
	Survey held at	ETHOZ GROUP LTD				
		22 TAMPINES STREET 92 SINGAPORE 528876				
5a.			Remarks			
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A"WI CE TO YOUR INSTRUCTIONS, \	THOUT PREJUDICE" BASIS WE HAVE NOT AUTHORISE	S. ED REPAIRS.		
5b.		Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 364T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (N)	DENTED / BENT	961.40	961.40
1	BONNET INSULATION (N)	NOT NECESSARY	185.50	_
10	BONNET INSULATION CLIPS (N)	NOT NECESSARY	44.00	-
1	FRONT GRILLE (N)	NOT NECESSARY	498.30	-
1	FRONT GRILLE LOGO (N)	NOT NECESSARY	73.60	-
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	498.30	-
10	FRONT BUMPER CLIPS (N)	NOT NECESSARY	44.00	-
1	FRONT BUMPER SIDE RETAINER RH (N)	NOT NECESSARY	32.50	-
1	FRONT BUMPER SIDE RETAINER LH (N)	BENT	32.50	32.50
1	FRONT HEADLAMP LH (N)	HOLDER CRACKED	1,617.00	1,617.00
1	FRONT FENDER LH (N)	DENTED / BUCKLED	622.70	622.70
1	FRONT FENDER INNER SHIELD LH (N)	NOT NECESSARY	97.50	-
10	FRONT FENDER INNER SHIELD CLIPS (N)	NECESSARY	44.00	44.00
1	FRONT FENDER WHEEL ARCH GARNISH LH (N)	TORN	483.00	483.00
	LESS 10% DISCOUNT		-	-376.06
			5,234.30	3,384.54
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE & HOLDER (SN)	NOT NECESSARY	35.00	-
			35.00	-
	LABOUR			
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	400.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS.		900.00	800.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	20.00
	TO RUST PROOF AFFECTED AREA.		80.00	30.00
			1,810.00	1,250.00
	GRAND TOTAL		7,079.30	4,634.54

Report Ref No. CS/EGI18015120/Urd3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 4,634.54

Report Ref No. CS/EGI18015120/Urd3e2

CHUA KANG SENG
Licensed Appraiser