

ASS. R.P.C. BY:

REF

CS/MSG18015122/Gtd32

Special Instruction:

Mr/Ms/Mr/Ms
Number

Gua Ching

ASSIGNMENT (Office)

From (Person)

Kwok Woon Choo

of

MSIG

Date/Time

20/8/18 @ 10:27am

Estimated Cost:

Bill to

OD

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKL 4270S

Insured:

at Workshop m/s

Cycle & Carriage Kia
209 Punden Gardens

Tel:

9144 9137 / 9121 9978

Policy No:

28630077Mcy

Claim No:

531258

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

19/09/2017

CA / REV

REP. / REV 24 HRS

R.O.D. Enforcement:

Date/Time:

12:51pm @ 20/8/18

Person Contacted:

Andre

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction

(✓) Estimate

SKL 4270S - CS/MSG17019071 / Affn 2 DOA: 4/9/2017

1/2/19

Revert via menimen.

1/2/19

authorise repair by Jason Sim

7/2/19 @ 8:49am

Email cycle & carriage authorise repair. excess \$600/-

Part by part \$5099/- (Red. 6531, 56%)

(9/11/13) waf

ASS. REC. BY:

REF: MS19

C1137M

ASSIGNMENT

From: Date: 27/8/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 4270S

at Workshop m/s

of 9 tanjong rhu road # 03-04

Insured: 65684501

Policy No: 91865200 CoCo

Claims No: 9181 9978 Edwin

Sum Insured: Excess: \$600.00

(Client's Record) * Have 2 OD estimate - 1st est.

Make of Veh: is 3k & 2nd Est is 11k. Pls check damages because accident happened on 19/11/2017.

(Policy Condition) Reena @ 9727 4877

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$80k 2pm

ID/C Accident Rpt: Consistent? : Yes or No

MIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKL 4270S Yr Regn: 08 Nov 2013

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Sorento 2.2 cc 2199

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 56187 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAKU 814 SE 547 8811

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 27-08-18

Survey held at n/s 2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

: Prel. Report

1) 1518 Typist

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I (\$) 5099

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

200

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2017		20 Aug 2018 10:27 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ISIN INTERNATIONAL PTE LTD, Co. Reg. No.: 199101137M		
Vehicle Reg. No.:	SKL4270S	Date of Loss:	19/09/2017 00:00 - :59 [46 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 531258	Policy/Cover Note No.:	28630077MCY (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
		Excess:	S\$600.00
Repairer:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/08/2018]		
Driver/Custodian:	VEENA CHOUDHARY (44 / Female), NRIC: S73759251, Tel: +6597274877		
Adj Asg. Remarks:	Pls get Surveyor to call Mr Prakash Kejriwal @ 97319366. TO REVERT - WE HAVE 2 OD ESTIMATE FR C&C KIA. 1ST ESTIMATE IS 3K & 2ND ESTIAMTE ID \$11K. PLEASE CHECK THE DAMAGED BECAUSE THE ACCIDENT HAPPENED ON 19.09.2017 - 1 YR AGO.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18015122/Gtd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-08-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKL 4270S
Policy No.	28630077MCY	Coverage (\$)	0.00
Claim No.	531258	Excess (\$)	0.00
Assign From	MERIMEN (KWOK WOON CHOO)	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/09/2017	Inspection Date	27/08/2018
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 01 Feb 2019

Preliminary Advice

Vehicle No	: SKL4270S	Accident Date	: 19/09/2017
Make	: KIA SORENTO	Policy No.	: 28630077MCY
Assignment Date	: 20/08/2018	Excess	: S\$600.00
Date of Inspection	: 27/08/2018	Est. Duration of Repair	: 3.00
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,715.00
Revised Amount	:S\$	2,803.00
Check Items (Estimated)	:S\$	5,080.00
Total	:S\$	7,883.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	67,027.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,973.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 7 February 2019 8:49 AM
To: Edwin Abcede Caina; Andre Chow En De
Cc: Coco Lu Ting; Loi Ai Ting; Don Bong Kiong Hua; SUR
Subject: SKL 4270S / MSIG / OD
Attachments: ESTIMATE.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKL 4270S (Excess \$600/-)**. As attached **above the estimate to be used.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKL4270S (531258)**

OD

Sep 19 2017 12:00AM

[ISIN INTERNATIONAL PTE LTD]

Cycle & Carriage KIA Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 01/02/2019 18:22 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7883.00) - SKL4270S - Claim Handler: Kwok Woon Choo

Approved:7883.00.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 19/09/2017 15:33
 Date Of Accident 19/09/2017 06:55
 Exact Location Of Accident TANJONG RHU ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKL4270S
 Insured/Policyholder
 Name Of Registered Owner ISIN INTERNATIONAL PTE LTD.
 Co Reg No 199101137M
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-63482118
 Vehicle Particulars
 Manufacturer KIA
 Model SORENTO-2.2 (A)
 Exact Purpose for which vehicle was being used at time of accident DROPPING DAUGHTER TO SCHOOL
 Are you claiming under your own insurance policy for repair to your vehicle? YES
 If No, Please state action to be taken
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number
 Cover Note Number
 Driver
 Name of Driver VEENA CHOUDHARY
 NRIC No S7375925J
 Date Of Birth 24/01/1973
 Occupation OUTDOOR
 Date Of Driving Pass 13/12/2006
 Driving Experience 10 YEARS AND 9 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-87274877
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address 9 TANJONG RHU ROAD #05-04
Postcode 436894
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGB1171P
Vehicle Make/Model/Colour TOYOTA COROLLA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver KU BOON CHYE
NRIC/Passport Number S6838964C
Contact Number 97322277
Address
Postcode
Insurance Company Name
Nature Of Damage DENT ON THE LEFT SIDE
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Vineet Kumar


Driver's Signature
(If driver is not the policyholder)
Date & Time:



tzh

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was leaving to drop my daughter to school around 6:58 am in the morning. I had to turn towards right on the Tanjong Rhu Road from my The Waterside road. First lane was blocked by Big Bus and the second lane was empty. I was on the yellow box to turn right and this car came from the right and we barged each other.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Edm





MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 10 Robinson Road, #04-01, Singapore 068912
 Tel: 65-6733 8888 Fax: 65-6733 8889
 E-mail: msig@msig.com.sg

Certificate of Insurance

[illegible]

MOTORMAX PLUS COMMERCIAL
CONSTRUCTION

Form 10-8-1

100

Certificate No.

Case No. 24,200-1-73

1. Index Mark and Registration Number of Vehicle

Example
V71104ET0011 14033

2. Name of Policyholder

Trans International Co. Inc.

Effective Date of the Commencement of Insurance for the purposes of the Act
02/12/2017

Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to vote

Barakat, K. (1992). *Ventre d'écriture*.

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

* Provided that the person driving is permitted in accordance with the Licensing or otherwise to lawfully possess or drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation that forbids them from driving the Motor Vehicle.

Limitations on use

The only for social domestic and pleasure purposes under the Police and Security Regulations.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MGIC AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. For any reason the Policy is terminated during its currency, this Certificate must be returned to the insurer within 10 days of the termination. Only the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle Third-Party Risk and Compensation Act (Cap. 165).

I/WE HEREBY CERTIFY that the Policy is being filed in accordance with the provisions of the Motor Vehicle Third-Party Liability and Compensation Act (Chapter 183) and Part 1 of the Road Transport Act. This Policy is being submitted to the Act as required in substitution for a:

MSIO Insurance (Singapore) Pte. Ltd.
Approved Insurers

[Handwritten signature]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1137M
Vehicle Details	
Vehicle No.:	SKL4270S
Vehicle to be Exported:	No
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	SORENTO 2.2(A) SUNROOF DIESEL
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	D4HBDH092974
Chassis No.:	KNAKU814SE5478811
Maximum Power Output:	145.0 kW (194 bhp)
Open Market Value:	\$31,410.00
Original Registration Date:	08 Nov 2013
First Registration Date:	08 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$35,974.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2023
PARF Rebate Amount:	\$26,980.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,100.00
COE Rebate Amount:	\$40,047.00
Total Rebate Amount:	\$67,027.00

The information contained herein is correct as at 28 Aug 2018

OK



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Isin International Pte Ltd	Cust No/Name LCV00327/Isin International Pte Ltd
143 Cecil Street	Reg No/Reg Date SKL42705 / 08/11/201
#14-00 Gb Building	Date In/Mileage / 0
Singapore 069542	Chassis No KNAKUB14SE5478811
Contact No Mobile: 81833815RAMESH	Engine No 04HBDH092974
	Make/Model KIA/SORENTO 2.2 A DIESEL
	Colour/Trim K3R / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	18/06/2018/ 20:06	QUE	261 / Edwin Caina	15317
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000				550	2200.00
RENEW & RE-ALIGN FRT DAMAGED PORTION:					
RENEW FRT BUMPER & FRT SUPPORT PNL					
REPAIR FRT FENDER RH					
E PNT98000				350	840.00
RESPRAY FRT BUMPER & FRT FENDER RH					
A 25000001				100.00	
REMOVE & REFIT AC COND & RADIATOR				NN X	
A 25000001				80.00	
TOP UP AIRCON GAS				X	
A 54900099				30.00	
CHECK WIRING & ADJUST HEADLAMP AIM				X	
A 10028901				200.00	
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				X	
USING HI-SCAN PRO TEST				NN X	
M SUNDRY				80.00	
SUPPLY FRT NUMBER PLATE WITH CASING				X	
E PNT88000				100.00	
RENEW FRT PARKING SENSOR					
M SUNDRY				30.00	
Sundries					
M LAMP ASSY-HEAD,RH		1.00	2516.00	00.00	2516.00
M COVER-FR BUMPER,LWR		1.00	709.00	00.00	709.00
M MESH-FRONT BUMPER,CTR		1.00	45.00	00.00	45.00
M CAP-FRONT HOOK		1.00	13.00	00.00	13.00
M COVER-FR BUMPER UPR		1.00	709.00	00.00	709.00
M MOULDING-FRT BPR LICENSE PLATE		1.00	26.00	00.00	26.00
M GRILLE ASSY-RADIATOR		1.00	334.00	00.00	334.00
M MOULDING-FRONT BUMPER A/INTAKE		1.00	27.00	00.00	27.00
M ABSORBER-FRONT BUMPER ENERGY		1.00	122.00	00.00	122.00
M STIFFENER ASSY-FR BUMPER LWR		1.00	64.00	00.00	64.00
M STIFFNER-FR BUMPER UPR		1.00	166.00	00.00	166.00
M BRACKET-FR BUMPER SIDE,RH		1.00	13.00	00.00	13.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after repair work has commenced. We would advise you. Please be informed that a



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Isin International Pte Ltd	Cust No/Name LCV00327/Isin International Pte Ltd
143 Cecil Street	Reg No/Reg Date SKL42705 / 08/11/201
#14-00 Gb Building	Date In/Mileage / 0
Singapore 069542	Chassis No KNAKUB14SE5478811
Contact No Mobile: 81833815RAMESH	Engine No D4HBDH092974
	Make/Model KIA/SORENTO 2.2 A DIESEL
	Colour/Trim K3R / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	18/06/2018/ 20:06	QUE	261 / Edwin Caina	15317
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-FRONT FOG,RH	✓ SC	1.00	177.00	00.00	209 177.00
M GRILLE-FRONT FOG,RH	✓ SC	1.00	24.00	00.00	✓ 24.00
M WIRING ASSY-FR BUMPER	✓ NN	1.00	377.00	00.00	✓ 377.00
M ULTRASONIC SENSOR ASSY-BWS	✓ DM	1.00	171.00	00.00	266 171.00
M COVER-TELESCOPE,RH	✓ MS	1.00	37.00	00.00	✓ 37.00
M TELESCOPE UNTT ASSY-HEAD LAMP	✓ CFA	1.00	245.00	00.00	✓ 245.00
M RAIL ASSY-FR BUMPER	✓ VT	1.00	520.00	00.00	✓ 520.00
M CARRIER ASSY-FRONT END MODULE	✓ NN	1.00	760.00	00.00	✓ 760.00

Estimate

3 Days.

before part photos

Not Authorized.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett 10,715.00
 7% GST on 10715.00 750.05
Total Payable 11,465.05

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered. Should this occur, we would advise you. Please be informed that a

SUPPLEMENTARY

INSURANCE CO : MSIG INSURANCE (S'PORE) PTE LTD

REGISTRATION NO : SKL4270S

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>PARTS</u>					
1	SENSOR & UNIT ASSY-ACTIVE HOOD <i>✓ nke.</i>	1.00	951.00	0.00	951.00
2	ULTRASONIC SENSOR ASSY-BWS <i>X Repeat</i>	1.00	266.00	0.00	266.00
Total					1,217.00
7 % GST					85.19
Grand Total					<u>1,302.19</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ISIN INTERNATIONAL PTE LTD	Cust No/Name LCV00327/Isin International Pte Ltd
143 Cecil Street	Reg No/Reg Date SKL42705 / 08/11/201
#14-00 Gb Building	Date In/Mileage / 0
Singapore 069542	Chassis No KNAKUB14SE5478811
Contact No 97344559ANIL	Engine No D4HBDH092974
	Make/Model KIA/SORENTO 2.2 A DIESEL
	Colour/Trim K3R / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV00327	CRDVCH	25/07/2018/ 17:08	QUE	261 / Edwin Caine	32743		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550.00
RENEW & RE-ALIGN FRT DAMAGED PORTION:							
RENEW FRT BUMPER							
E PNT98000							350.00
RESPRAY FRT BUMPER							
M	COVER-FR BUMPER UPR	= CRD		1.00	743.00	00.00	743.00
M	COVER-FR BUMPER, LWR	= Cnt		1.00	709.00	00.00	709.00
M	CAP-FRONT HOOK	= Cnt		1.00	13.00	00.00	13.00
M	RESERVOIR & PUMP ASSY-WASHER	? Cnt		1.00	577.00	00.00	577.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts (during resurvey)
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Excess \$ 600
Not Authorised.
before paint photos.
27/8/18
Gue Qiang - 8288 0282
3 Days.

Confirm & accepted by

	Nett	2,942.00
7% GST on	2942.00	205.94
Total Payable		3,147.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Guo Qiang-LKK
Company : MSIG
DOA : 19/09/2017
CSE : Edwin
Date of Survey : -

VEHICLE NO : SKL4270S
MODEL : KIA/ SORENTO 2.2 A DIESEL
WIP : 48996

Material	:	\$	3,839.00
Labour	:	\$	1,260.00
Sub-Total	:	\$	5,099.00
Less Excess	:	\$	600.00
Total	:	\$	4,499.00
GST 7%	:	\$	314.93
Grand Total	:	\$	4,813.93
Finalise By/Date	:	JoJo dtd 06/08/2019	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + Days () Weekends
+ Days () Public Holiday
+ Survey -
TOTAL DAYS REPAIR TOOK = 3

☐ TP Claim

☐ Claim GIA / LTA fee

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

Car No: SKL42708 WIP 48996

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	HEADLAMP WASHEN COVER RH MUX	? /Supp	2/26/08/19 2/26/08/19		
2	HEADLAMP WASHEN RH CCA	? /Supp			
3	FAST BUMPER PROTECTOR CCA	? /Supp			
4	FAST WIRING AU	? /Supp			
5	FAST BUMPER RAIN F M	? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

DATE	TAKEN BY
29-4	2/26/08/19
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CELLETE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO B4 SUSP & U/C REMOVE	

Model: SORENTO

Surveyor: GUO - LKK



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MSIG INSURANCE (S'PORE) PTE LTD	Cust No/Name /Isin International Pte Ltd
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SKL4270S / 08/11/2013
16 RAFFLES QUAY #24-01	Date In/Mileage 24/04/2019/ 65016
HONG LEONG BUILDING	Chassis/Package KNAKU8145E5478811
SINGAPORE 048581	Engine No D4HBDH092974
Contact No 66431303	Make/Model KIA/SORENTO 2.2 A DIESEL
24/04/	Colour/Trim K3R / VA

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LA000006	Credit	05/08/2019/ 17:38	BLE	881 / Jojo Cheng	48996

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER				✓ 550.00
E PNT98000 RESPRAY FRONT BUMPER				✓ 350.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
E PNT88000 RENEW FRONT PARKING SENSOR				✓ 100.00
M SUNDRY SUNDRIES				30.00
X EXC EXCESS				-600.00
X COVER-FR BUMPER,LWR	1.00	709.00	00.00	✓ 709.00
X CAP-FRONT HOOK	1.00	13.00	00.00	✓ 13.00
X COVER-FR BUMPER UPR	1.00	* 743.00	00.00	✓ 743.00
X ABSORBER-FRONT BUMPER ENERGY	1.00	122.00	00.00	✓ 122.00
X LAMP ASSY-FRONT FOG,RH	1.00	* 209.00	00.00	209.00
X GRILLE-FRONT FOG,RH	1.00	24.00	00.00	✓ 24.00
X COVER-TELESCOPE,RH	1.00	37.00	00.00	✓ 37.00
X TELESCOPE UNTT ASSY-HEAD LAMP,	1.00	245.00	00.00	✓ 245.00
X RAIL ASSY-FR BUMPER	1.00	520.00	00.00	✓ 520.00
X SENSOR & UNIT ASSY-ACTIVE HOOD -supp P / MCL.	1.00	951.00	00.00	951.00
X ULTRASONIC SENSOR ASSY-BWS -supp	1.00	266.00	00.00	266.00
Z TEXT MSIG OD CLAIM DOA: 19/09/2017 SURVEYOR: QUOQIANG LKK				
* Price Change				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	3,839.00	Nett	4,499.00
Labour	1,230.00	7% GST on	314.93
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	-570.00		
Total(w/o GST)	4,499.00	Total Payable	4,813.93

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2017		20 Aug 2018 10:27 Edit Adj Rpt	\$55,099.00 Edit Estimates	\$55,099.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ISIN INTERNATIONAL PTE LTD, Co. Reg. No.: 199101137M								
Vehicle Reg. No.:	SKL4270S	Date of Loss:	19/09/2017 00:00 - :59 [46 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 531258	Policy/Cover Note No.:	28630077MCY (Comprehensive) Coverage: 01/01/2017 - 31/12/2017						
		Excess:	\$600.00						
Repairer:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/09/2018]								
Driver/Custodian:	VEENA CHOUDHARY (44 / Female) , NRIC: S7375925J, Tel: +6597274877 Email: NOEMAIL								
Adj Asg. Remarks:	Pls get Surveyor to call Mr Prakash Kejriwal @ 97319366. TO REVERT - WE HAVE 2 OD ESTIMATE FR C&C KIA. 1ST ESTIMATE IS 3K & 2ND ESTIMATE IS \$11K. PLEASE CHECK THE DAMAGED BECAUSE THE ACCIDENT HAPPENED ON 19.09.2017 - 1 YR AGO.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (14/08/2019): Alert - Adj Mandate Approved (\$5099.00) - SKL4270S - Claim Handler: Kwok Woon C... - MSIG_SG (01/02/2019): Alert - Adj Mandate Approved (\$7883.00) - SKL4270S - Claim Handler: Kwok Woon C...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL4270S (531258)
OD
Sep 19 2017 12:00AM
[ISIN INTERNATIONAL PTE LTD]
Cycle & Carriage KIA Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		v	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)					Thumbnail	Print	
1	19/09/17 16:23	Accident Statement					Load HTM		
2	05/12/17 17:35	Addendum Sheet					Load JPG	☒	
3	05/12/17 17:36	Accident Statement Addm. #1					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	01/02/19 10:07	Adjuster Immediate Advice					Load HTM		
2	08/08/19 17:47	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		v	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)					Thumbnail	Print	
1	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
2	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
3	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
4	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
5	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
6	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
7	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
8	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
9	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
10	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
11	19/09/17 16:22	Accident Photo [Linked Accident Report Documents]					Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	01/02/19 10:08	General View					Load JPG	☒	
2	01/02/19 10:08	General View					Load JPG	☒	
3	01/02/19 10:08	General View					Load JPG	☒	
4	01/02/19 10:08	General View					Load JPG	☒	
5	01/02/19 10:08	General View					Load JPG	☒	
6	01/02/19 10:08	General View					Load JPG	☒	
7	01/02/19 10:08	General View					Load JPG	☒	
8	01/02/19 10:08	General View					Load JPG	☒	
9	01/02/19 10:08	General View					Load JPG	☒	
10	01/02/19 10:08	General View					Load JPG	☒	
11	01/02/19 10:08	General View					Load JPG	☒	
12	01/02/19 10:08	General View					Load JPG	☒	
13	01/02/19 10:08	General View					Load JPG	☒	
14	01/02/19 10:08	General View					Load JPG	☒	
15	01/02/19 10:08	General View					Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
16	01/02/19 10:08	General View		☒
17	01/02/19 10:08	General View		☒
18	01/02/19 10:08	General View		☒
19	01/02/19 10:08	General View		☒
20	01/02/19 10:08	General View		☒
21	01/02/19 10:08	General View		☒
22	01/02/19 10:08	General View		☒
23	01/02/19 10:08	General View		☒
24	01/02/19 10:08	General View		☒
25	01/02/19 10:08	General View		☒
26	08/08/19 11:03	Dismantled Parts		☒
27	08/08/19 11:03	Dismantled Parts		☒
28	08/08/19 11:03	Dismantled Parts		☒
29	08/08/19 11:03	Dismantled Parts		☒
30	08/08/19 11:03	Dismantled Parts		☒
31	08/08/19 11:03	Dismantled Parts		☒
32	08/08/19 11:03	Dismantled Parts		☒
33	08/08/19 11:03	Dismantled Parts		☒
34	08/08/19 11:03	Dismantled Parts		☒
35	08/08/19 11:03	Dismantled Parts		☒
36	08/08/19 11:03	Dismantled Parts		☒
37	08/08/19 11:03	Dismantled Parts		☒
38	08/08/19 11:03	Dismantled Parts		☒
39	08/08/19 11:03	Dismantled Parts		☒
40	08/08/19 11:03	Dismantled Parts		☒
41	08/08/19 11:03	Dismantled Parts		☒
42	08/08/19 11:03	Reinspection Photo		☒
43	08/08/19 11:03	Reinspection Photo		☒
44	08/08/19 11:03	Reinspection Photo		☒
45	08/08/19 11:03	Reinspection Photo		☒
46	08/08/19 11:03	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/08/18 13:40	OD ESTIMATE AT 3K		☐
2	16/08/18 13:50	OD ESTIMATE + GIA REPORT + DRIVER NRIC + DL + CI.		☐
3	16/08/18 13:52	E-MAIL FR WORKSHOP DD 8.8.18		☐
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	19/09/17 16:21	Sketch Plan [Linked Accident Report Documents]		☒
2	19/09/17 16:21	Sketch Plan #2 [Linked Accident Report Documents]		☒
3	19/09/17 16:22	Sketch Plan #3 [Linked Accident Report Documents]		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	20/08/18 10:23	Email - Outsource case as per Woon Choo's instruction		☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 10:01	ESTIMATE		☐
2	10/04/19 09:02	EMAIL AUTHORISE		☐
3	08/08/19 17:35	SUPPLEMENTARY		☒
4	08/08/19 17:38	ESTIMATE		☐

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	19/09/17 16:23	Accident Statement	 Load HTM	☐
2	05/12/17 17:36	Accident Statement Addm. #1	 Load HTM	☐
3	20/06/18 10:20	Addendum Sheet	 Load JPG	☒
4	20/06/18 10:22	Accident Statement Addm. #2	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	19/09/17 16:22	Accident Photo	 Load JPG	☒
2	19/09/17 16:22	Accident Photo	 Load JPG	☒
3	19/09/17 16:22	Accident Photo	 Load JPG	☒
4	19/09/17 16:22	Accident Photo	 Load JPG	☒
5	19/09/17 16:22	Accident Photo	 Load JPG	☒
6	19/09/17 16:22	Accident Photo	 Load JPG	☒
7	19/09/17 16:22	Accident Photo	 Load JPG	☒
8	19/09/17 16:22	Accident Photo	 Load JPG	☒
9	19/09/17 16:22	Accident Photo	 Load JPG	☒
10	19/09/17 16:22	Accident Photo	 Load JPG	☒
11	19/09/17 16:22	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	19/09/17 16:21	Sketch Plan	 Load JPG	☒
2	19/09/17 16:21	Sketch Plan #2	 Load JPG	☒
3	19/09/17 16:22	Sketch Plan #3	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18015122/GTD3E2

Date: 16/08/2019

REFERENCE

Insured/Claimant: ISIN INTERNATIONAL PTE LTD

Policy No: 28630077MCY

Date of Loss: 19/09/2017

Nature of Claim: OD

Claim No: 531258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL4270S

Make & Model: KIA SORENTO, 2.2 (A)

Reg. Date: 08/11/2013 (Man. Year: 2013)

Colour: Red

Engine Capacity: 2199 cc

Market Value/New Car Price: S\$80,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: D4HBDH092974

Chassis No: KNAKU814SE5478811

Odometer: 56187 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Tyre Size: 235/55 R19

Rear Left Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,543.00	3,869.00	4,674.00	54.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,230.00	2,320.00	65.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,093.00	5,099.00	6,994.00	57.84
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	11,493.00	4,499.00	6,994.00	60.85
+ GST 7.00/7.00% (S\$)	804.51	314.93	489.58	60.85
Nett Amount (S\$)	12,297.51	4,813.93	7,483.58	60.85

INSPECTION

Date of Assignment: 20/08/2018

Date Inspected: 27/08/2018 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan
Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2019)
Parts: M1-SUV	KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKL4270S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS
2	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
3	1		*LAMP ASSY-HEAD, RH	Not Necessary	2,516.00 FS	*- FS
4	1		*COVER-FR BUMPER, LWR	Cut	709.00 FS	*709.00 FS
5	1		*MESH-FRONT BUMPER, CTR	Not Necessary	45.00 FS	*- FS
6	1		*CAP-FRONT HOOK	Cut	13.00 FS	*13.00 FS
7	1		*MOULDING-FRT BPR LICENSE PLATE	Not Necessary	26.00 FS	*- FS
8	1		*GRILLE ASSY-RADIATOR	Not Necessary	334.00 FS	*- FS
9	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	27.00 FS	*- FS
10	1		*ABSORBER-FRONT BUMPER ENERGY	Cracked	122.00 FS	*122.00 FS
11	1		*STIFFENER ASSY-FR BUMPER LWR	Not Necessary	64.00 FS	*- FS
12	1		*STIFFENER-FR BUMPER UPR	Not Necessary	166.00 FS	*- FS
13	1		*BRACKET-FR BUMPER SIDE, RH	Not Necessary	13.00 FS	*- FS
14	1		*LAMP ASSY-FRONT FOG, RH	Scratched	209.00 FS	*209.00 FS
15	1		*GRILLE-FRONT FOG, RH	Scratched	24.00 FS	*24.00 FS
16	1		*WIRING ASSY-FR BUMPER	Not Necessary	377.00 FS	*- FS
17	1		*ULTRASONIC SENSOR ASSY-BWS	Damaged	266.00 FS	*266.00 FS
18	1		*COVER-TELESCOPE, RH	Missing	37.00 FS	*37.00 FS
19	1		*TELESCOPE UNIT ASSY-HEAD LAMP,	Cracked	245.00 FS	*245.00 FS
20	1		*RAIL ASSY-FR BUMPER	Bent	520.00 FS	*520.00 FS
21	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	760.00 FS	*- FS
22	1		*SENSOR & UNIT ASSY-ACTIVE HOOD	Necessary	951.00 FS	*951.00 FS
23	1		*ULTRASONIC SENSOR ASSY-BWS	Repeated	266.00 FS	*- FS
24	1		*COVER-FR BUMPER UPR	Cracked	743.00 FS	*743.00 FS
Total Parts (S\$)					8,543.00	3,869.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW & RE-ALIGN FRT DAMAGED PORTION : RENEW FRT BUMPER & FRT SUPPORT PNL. REPAIR FRT FENDER RH	New	2,200.00	550.00
2	RESPRAY FRT BUMPER & FRT FENDER RH	New	840.00	350.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AIRCON GAS	New	80.00	0.00
5	CHECK WIRING & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
7	RENEW FRT PARKING SENSOR	New	100.00	100.00
Gross Labour Cost (S\$)			3,550.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >