

23/03/2003

ASS. REC. BY:

REF:

08/MSG18015126/71240302

Special Instruction:

Surveyor
Munirah

Tau Fieh

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time:

17/8/18 @ 3:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 2908B

Insured:

FZ 466G

at Workshop m/s

MS Car Auto

Tel:

62851838

of

8 Keiki Blvd Ave 4 # 01-07 Premier

Policy No:

MSD/VMT/18-379129-CA

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/08/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:29pm @ 20/8/18

Person Contacted:

Adele

Vehicle

IN/OUT

Date/Time

Action/Instruction

(4)

Estimate

FBM 2908B - X

FZ 466G - X

23/8/18

@ 2:37pm

Surveyor

Adele said no est provided. they use their indendante

Signature

TupfM

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: _____

Yes or No

Lum Sum: _____

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

FBM 2908B

Tr Regn: _____

2017 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Yamaha Super T150 c.c.

150

Colour: _____

Black

A/C: _____

Insured / Std / NI / NA

Sp Reading: _____

T/Radio

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MH3460740H 0057649

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

80/80R17

R: _____

120/80R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. _____

5 mm

R/Bal. _____

5 mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

21/8/18 @ 5pm

Survey held at _____

MS Auto

Des. of Damages: _____

Frnt

Rear

U/S

U/C

Rooftop

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$3,800 - \$5,000

[Signature] 6/9/2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Site Insp: _____

Interview: _____

Tech. Invs: _____

Weekend: _____

TOTAL

Report Format: _____

PRS

Lump Sum / L.B.I: (\$)

120

10

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015126/T1z4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-08-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FZ 466G	Veh. Inspected	FBM 2908B	
Policy No.	MSD/MT/18-379129-CA	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/08/2018	Inspection Date	21/08/2018	
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2018		17 Aug 2018 15:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	OW KOK WHYE, ID: S1534636A		
Main Claimant:	LEE KHEK SIONG, ID: S7187815E		
Vehicle Reg. No.:	FBM2908B	Date of Loss:	13/08/2018 00:00 - :59 [11 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/18-379129-CA Coverage: 22/03/2018 - 21/03/2019
Vehicle Reg. No. (Insured):	FZ466G	Policy No. (Claimant):	
		Excess:	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/08/2018]		
Adj Asg. Remarks:	OI non reporting. Liability not clear. TP reject SJE - assign LKK Auto Consultants Pte Ltd contact: Mr Desmond (9425 4442)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7815E
Vehicle Details	
Vehicle No.:	FBM2908B
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	G3E6E0295750
Chassis No.:	MH3UG0740H0057649
Maximum Power Output:	-
Open Market Value:	\$2,073.00
Original Registration Date:	12 Sep 2017
First Registration Date:	12 Sep 2017
Transfer Count:	1
Actual ARF Paid:	\$311.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,402.00
COE Rebate Amount:	\$4,884.00
Total Rebate Amount:	\$4,884.00

The information contained herein is correct as at 27 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/08/2018 15:06
Date Of Accident	13/08/2018 14:30
Exact Location Of Accident	UPPER CHANGI RD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM2908B
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	LEE KHEK SIONG
NRIC No	S7187815E
Email Address	MINCHAU1992KV@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90080802
Alternative Phone No	OTHERS-90080802

Vehicle Particulars

Manufacturer	YAMAHA
Model	SNIPER T150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTMC01001624
Cover Note Number	N.A

Driver

Name of Driver	LEE KHEK SIONG
NRIC No	S7187815E
Date Of Birth	23/02/1971
Occupation	INDOOR
Date Of Driving Pass	28/06/2012
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90080802
Fax Number	
Contact Number	OTHERS-90080802
EMail Address	MINCHAU1992KV@GMAIL.COM

Address	ASTON MANSIONS, 3 LORONG 42 GEYLANG #07-09
Postcode	398026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFFIC POLICE DIVISION HQ
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report Ref: T/20180813/7023 lodged at Traffic Police Division HQ. On the stated date and time, I was travelling on my designated lane along Upper Changi Road North towards Loyang. The traffic light was red, hence I waited at the stop line. When the lights turned green, I moved off from my lane. Shortly after suddenly I felt a huge impact hitting me on my right side causing me to fall to the left. I fell to the floor to realise that another vehicle from Upper Changi Road East has beat the red light and collided into me. That is all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FZ466G
Vehicle Make/Model/Colour	HYOSUNG COMET 125 / YEL
Details Of Properties	NIL
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN RIDER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name LEE KHEK SIONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBM2908B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180813/7023

1 of 3

Report No. T/20180813/7023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
13/08/2018 19:42

Vide Report No.:

Station Diary No.:

Informant's Particulars

Name of Informant:
LEE KHEK SIONG

Address:
3 LORONG 42 GEYLANG #07-09 SINGAPORE 398026

ID Type / ID No.:
NRIC NO / S7187815E

Contact No.:
Home/Office: Mobile: 90080802

Nationality:
MALAYSIAN

Email:
asiong2908@gmail.com

Sex: Male Age: 47 Date of Birth: 21/02/1971

Type of Informant:
Rider

Race:
Chinese

Language:
English

Institution / School Name:

Occupation:
Building construction engineer

Driving Licence Information:
Class: 2B,2A,3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury
Attended by Police

Drink
Drive:
No

Date/Time of
Accident:
13/08/2018 14:30

Type of Location:
Straight Road

Location:

UPPER CHANGI ROAD NORTH

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
Dual Carriage Way

Traffic Control:
Traffic Light - Working

Traffic Volume:
Moderate

Type of Collision:
Between Moving Vehicles - Head To Side

Anyone conveyed by
ambulance:
Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBM2908B	Motorcycle	YAMAHA	SNIPER T150	Black	Slightly Damaged	1
FZ466G	Motorcycle	HONDA	SUPER 4	Yellow	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM2908B	TENET SOMPO INSURANCE PTE. LTD.	D17MTMC0100162 4	12/09/2017	11/09/2018

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180813/7023

2 of 3

Report No. T/20180813/7023

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	LEE KHEK SIONG	ID No.	S7187815E
Related Vehicle	FBM2908B (Motorcycle)	Contact No.	90080802
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	13/08/2018	Date Discharge	13/08/2018
No. of Days granted Medical Leave	18	Degree of Injury	Serious

Brief Details.

On the stated date and time, I was travelling on my designated lane along upp changi road north towards loyang. The traffic light was red hence i waited at the stop line. When the lights turned green i moved off from my lane. Shortly after suddenly i felt a huge impact hitting me on my right side causing me to fall to the left. I fell to the floor to realised that another vehicle from upp changi road east has beat the red light and collided into me. That is all.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180813/7023

3 of 3

Report No. T/20180813/7023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MOHAMMED FADZLY BIN ABDUL AZIZ
Contact No.: 65476365

Authentication Stamp
NP108

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
13/08/2018 19:42

Classification Of Case:






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2018		17 Aug 2018 15:45 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: OW KOK WHYE , ID: S1534636A									
Main Claimant: LEE KHEK SIONG , ID: S7187815E									
Vehicle Reg. No.: FBM2908B		Date of Loss: 13/08/2018 00:00 - :59 [11 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MSC/V/18-001110		Policy/Cover Note No.: MSD/VMT/18-379129-CA Coverage: 22/03/2018 - 21/03/2019							
Vehicle Reg. No. (Insured): FZ466G		Policy No. (Claimant):							
		Excess:							
Repairer: Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 18/08/2018]									
Adj Asg. Remarks: OI non reporting. Liability not clear. TP reject SJE - assign LKK Auto Consultants Pte Ltd contact: Mr Desmond (9425 4442)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBM2908B (MSC/V/18-001110)**
[FZ466G]
TP
LEE KHEK SIONG
Aug 13 2018 12:00AM
[OW KOK WHYE]
Ms Car Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
60	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
61	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
72	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
79	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
80	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
81	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
82	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
83	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
84	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
86	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>
87	24/08/18 15:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
89	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
90	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
91	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
92	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
93	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
94	24/08/18 15:41	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/08/18 14:51	pri notice		Load PDF	
2	17/08/18 14:52	TP PRI REQUEST EMAIL		Load PDF	
3	17/08/18 14:53	TP REJECT SJE - ASSIGN LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015126/T1Z4D3E2

Date: 07/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-379129-CA
Claimant Vehicle No :	FBM2908B	Insured Vehicle No :	FZ466G
Date of Loss:	13/08/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-001110

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM2908B		
Make & Model:	YAMAHA SNIPER T150, 150cc	Engine No:	G3E6E0295750
Reg. Date:	12/09/2017 (Man. Year: 2017)	Chassis No:	MH3UG0740H0057649
Colour:	Black	Odometer:	0 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/80 R17	Rear Tyre Size:	120/70 R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/08/2018	
Date Inspected:	21/08/2018 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Sep 2018)

Parts: N/A YAMAHA SNIPER T150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBM2908B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >