

Kenage 1
Photo

ASS. REC. BY:

REF: CS3/MSG18015137/NZ40302

Special Instruction:

Surveyor
-menmen

Naz

ASSIGNMENT (Office)

From (Person):

Katherine Wang

of

MSG

Date/Time:

17/8/18 @ 3:43pm

Estimated Cost:

Bill to:

OD / TP / DWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBA 7543A

Insured:

SLV 4563H

at Workshop n/s:

Brother's Motor

Tel:

9643 2540

of

Bk 1016, Yishun Ind. Park A # 01-218

Policy No:

MSD/vpcp/18-000001

Claim No:

566091

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/07/2018

CA / REV / REP. / REV 24 HRS

(cup)

H.O.D. Endorsement:

Date/Time:

12:31pm @ 20/8/18

Person Contacted:

Mr. Tat

Vehicle:

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBA 7543A - N/A / INC 09017604 / SI
	Slv 4563H - X

DoA: 18/8/2019

Surveys N/A

REF:

MS167

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 12.5K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBA7543A Yr Regn: 3 AUG 200

Type: M. Car (M. Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CB400 c.c. 399

Colour: - BLUE A/C: Insured / Std / Nil / N

Sp. Reading: 14,1, 628 T/Radio: Insured / Std / Nil / N

Eng/No: _____

C/No: JH2NC39946M200238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In O/S / Jammed / Leaked / Burnt or

Brake: In O/S / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 130/60 R17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZLER

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. mm L/Bal. mm

D.O.A. 31/7/2018 D.O.I. 20/8/18

Survey held at BROTHERS MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or FRT O/S

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	Repair range \$2K - \$4K
	Net Value 85K
26/9/18	submit PRV report

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 120

Transportation: _____

Add Fee: : Site Insp (\$ _____)) 5 + RS 51

: Interview (\$ _____)) Photos

: Tech. Invs (\$ _____)) Others 10

: Weekend (\$ _____))

TOTAL

130

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rat	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018		17 Aug 2018 15:43 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H		
Main Claimant:	NURHAYATI BINTE KAMARUDIN, ID: S84289801		
Vehicle Reg. No.:	FBA7543A	Date of Loss:	31/07/2018 18:00 - :59 [143 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 566091	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	SLV4563H	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Brothers Motor (HQ) BLK 1016 YISHUN INDUSTRIAL PARK A #01-218, 768758 Yishun - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/08/2018]		
Driver/Custodian (Insured):	PAUL LIEW YONG-JIA (), NRIC: S74972171, Tel: +6596800198		
Adj Asg. Remarks:	Liability 100%, SJE disagree - assign LKK, Contact : Mr Tat at 9643 2540		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18015137/Nz4d3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 20-08-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLV 4563H	Veh. Inspected	FBA 7543A
Policy No.	MSD/VPCP/18-000001	Coverage (\$)	0.00
Claim No.	566091	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/07/2018	Inspection Date	20/08/2018
Survey held at	BROTHER MOTORS BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2018 13:05
Date Of Accident	31/07/2018 18:30
Exact Location Of Accident	KALLANG PAYA LEBAR EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBA7543A
Insured/Policyholder	
Name Of Registered Owner	NURHAYATI BINTE KAMARUDIN
NRIC No	S8428980I
Email Address	NURHAYATI.KAMARUDIN@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92318124
Alternative Phone No	OTHERS-92318124

Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5098137784
Cover Note Number	21/02/18 - 02/02/19

Driver

Name of Driver	NURHAYATI BINTE KAMARUDIN
NRIC No	S8428980I
Date Of Birth	25/09/1984
Occupation	INDOOR
Date Of Driving Pass	24/11/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92318124
Fax Number	
Contact Number	OTHERS-92318124
EMail Address	NURHAYATI.KAMARUDIN@YAHOO.COM.SG

Address	BLK 274D PUNGGOL PLACE #12-838
Postcode	824274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	SHELTERED
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV4563H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PAUL LIEW YONG-JIA
NRIC/Passport Number	S7497217I
Contact Number	96800198
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NURHAYATI BINTE KAMARUDIN
Approximate Age	33
Injuries Sustain	
Injured person in which vehicle?	FBA7543A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 274D PUNGGOL PLACE #12-838
Postcode	824274

Sketch Plan

SKETCH PLAN

VEHICLE NO.: F6A7543A
INSURER : NTFC
DATE & TIME: 31/7/18 18:30

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ii. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time: 14/08/18

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


**SINGAPORE
POLICE FORCE**


T/20180801/7011

1 of 3

Police Station Of Origin
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408855
Tel No: 65470000

Report No: T/20180801/7011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 01/08/2018 16:36		Vide Report No. G/20180731/0175	Station Diary No.
Informant's Particulars			
Name of Informant: NURHAYATI BINTE KAMARUDIN		Address: APT BLK 274D PUNGGOL PLACE #12-838 SINGAPORE 824274	
ID Type / ID No. NRIC NO / S8428980I		Contact No. Home/Office:	Mobile: 92318124
Nationality SINGAPORE CITIZEN		Email nurhayati.kamarudin@yahoo.com.sg	
Sex: Female	Age: 33	Date of Birth: 25/09/1984	Type of Informant: Rider
Race: Malay		Language: English	Institution / School Name
Occupation: OPERATION TECHNICIAN		Driving Licence Information: Class: 2B,2A,3	Date of Expiry

General Information of the Accident

Type of Accident	Injury Attended by Police	Drink Drive No	Date/Time of Accident: 31/07/2018 18:30	Type of Location: Tunnel
Location: KALLANG PAYA LEBAR EXPRESSWAY				
Weather: Sheltered		Road Surface Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA7543A	Motorcycle	HONDA	CB400	Grey		0
SLV4563H	Car	BLUECAR	BLUESG rental car	White	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBA7543A	NTUC Income Insurance Co-Operative Limited	5098137784	21/02/2018	02/02/2019



**SINGAPORE
POLICE FORCE**



T/20180801/7011

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No: T/20180801/7011

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	NURHAYATI BINTE KAMARUDIN	ID No.	S8428980I
Related Vehicle	FBA7543A (Motorcycle)	Contact No.	92318124
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	31/07/2018	Date Discharge	01/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	PAUL LIEW YONG-JIA	ID No.	S7497217I
Related Vehicle	SLV4563H (Car)	Contact No.	96800198
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

Accident inside KPE tunnel towards TPE, exactly after ECP entrance into KPE & before PIE (Tuas/Changi) exit. Car switch lane from 3rd lane to 2nd lane, and subsequently 1st lane without exercising due care and proper check. Motorcyclist was on 1st lane at the point of accident. Car swipe motorcycle, motorcyclist fell on right side upon impact. No video/pictures attached



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180801/7011

3 of 3

Report No: T/20180801/7011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
IRMAN BIN MOHAMAD SAID
Contact No : 65476365

Authentication Stamp
NP168

Signature Of Informant

The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
01/08/2018 16:36

Classification Of Case

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2018		17 Aug 2018 15:43 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BLUECAR EAST ASIA PTE LTD , Co. Reg. No.: 201617259H								
Main Claimant:	NURHAYATI BINTE KAMARUDIN , ID: 584289801								
Vehicle Reg. No.:	FBA7543A	Date of Loss:	31/07/2018 18:00 - :59 [143 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566091	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	SLV4563H	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Brothers Motor (HQ) BLK 1016 YISHUN INDUSTRIAL PARK A #01-218, 768758 Yishun - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 18/08/2018]								
Driver/Custodian (Insured):	PAUL LIEW YONG-JIA (), NRIC: S7497217I, Tel: +6596800198								
Adj Asg. Remarks:	Liability 100%, SJE disagree - assign LKK, Contact : Mr Tat at 9643 2540								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBA7543A (566091)
[SLV4563H]
TP
NURHAYATI BINTE KAMARUDIN
Jul 31 2018 6:00PM
[BLUECAR EAST ASIA PTE LTD]
Brothers Motor

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1.	16/08/18 13:40	Accident Statement From: OD - Reg. No: SLV4563H, Claimant: BLUECAR EAST ASIA PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/08/18 13:43	FBA7543A E-file & Police Report	 Load PDF	
2	16/08/18 13:44	PRI from Centro-Legal Law	 Load PDF	
3	17/08/18 09:20	Survey Disagree on SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015137/NZ4D3E2

Date: 27/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000001
 Claimant Vehicle No: FBA7543A Insured Vehicle No: SLV4563H
 Date of Loss: 31/07/2018 Nature of Claim: TP Claim No: 566091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBA7543A**
 Make & Model: HONDA CB 400 F3WYB, 399cc (M) Engine No: NC23E3100145
 Reg. Date: 03/08/2006 (Man. Year: 2006) Chassis No: JH2NC39946M200128
 Colour: Grey Odometer: 141628 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60 R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Metzeler 6 mm Rear Left Side: Metzeler 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/08/2018
 Date Inspected: 20/08/2018 Inspected At: Brothers Motor (HQ)
 BLK 1016 YISHUN INDUSTRIAL PARK A
 #01-218
 Singapore 768758
 Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$4,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 27 Sep 2018)
Parts:	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA7543A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >