

22/03/2002

ASS. REC. BY:

REF:

CS / C7I18015138 / TIR0302

Special Instruction:

Survivor:
MURKIN

Taufich

ASSIGNMENT (Office)

From (Person):

Jouny Tay

of

CTI

Date/Time:

20/8/18 @ 1.62pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8ju 7657E

Insured:

SKC 3153B

at Workshop m/s

Hto Auto Engineering

Tel:

9730 5013

of

8pk 3007, Ubi Rd 1 #01 416

Policy No:

Claim No:

8NML8D03979C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/08/2018

CA / REV / REP. / REV 24 HRS

Cup

21/08/18 @ 11am

H.O.D. Endorsement:

Date/Time:

3.16pm 20/8/18

Person Contacted:

Tony

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
20/8/18 -	wksp arranged on 21/8/18 @ 11am.
	8ju 7657E - NA / DAI / 8014930 / h4
	SKC 3153B - NA / DAI / 8014930 / h4
13/9/18	Confirm L/S \$5,100.00 @ 5 day with Tony.
	Red: \$2100.2, 297.

(08/11/13) wef

ASS. REC. BY:

REF:

CTI

ASSIGNMENT

WE 20/9 Dec.

From: _____ Date: 21/08/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 8JU 7657E

at Workshop m/s HO Auto

of BIK 3007 Ubi Rd 1 # 01-416

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

11 am

Make of Veh: Tony @ 973 05013

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 925K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8JU 7657E Yr Regn: 2009, Dec

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic 1.8 c.c 1799

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 212422 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 311 MF1716309 \$203192

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 55 R11

R: 205 55 R11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I.

Survey held at HO Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Resurvey # 01-440

Date/Time, File Pass to?



Preli. Report

1) typist



Final Report

Date/Time, File Return to?

2)

Report Format : 7K

Lump Sum / I.B. (\$ 5100)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee: 210

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

210

RECEIVED 21 SEP 2010

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2018		20 Aug 2018 13:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VARGHESE GEORGE, ID: S1245637I		
Main Claimant:	CHUA CHIN TIAM, ID: S2595953A		
Vehicle Reg. No.:	SJU7657E	Date of Loss:	15/08/2018 18:00 - :59
Claim Type:	TP / SNM18D03979C02	Policy/Cover Note No.:	DMPCSN3096021802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKC3153B	Policy No. (Claimant):	MT/00278431
		Excess:	S\$0.00
Repairer:	Ho Auto Engineering (HQ) BLK 2 KAKI BUKIT AVE 2, #02-18/23 KAKI BUKIT AUTO HUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/08/2018]		
Driver/Custodian (Insured):	SOMHATHAI THAITAIR (55 / Female), NRIC: S2613645H, Tel: +6591050687		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.H76.107695.18 (sj)
Your Ref: SNM18D03979C02

20 August 2018

CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attention: Motor Claims Department – Lucas Lee

BY FAX: 6224 7175

email: claimsdept@sg.cntaiping.com
email: lucas.lee@sg.cntaiping.com

Dear Sirs,

ACCIDENT INVOLVING SJU 7657 E & SKC 3153 B & SHA 3097 B ON 15 AUGUST 2018 ALONG TAMPINES AVENUE 7 SLIP ROAD INTO TPE AT ABOUT 1800 HOURS

We refer to your email dated 20 August 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: HO AUTO ENGINEERING
Blk 3007 Ubi Road 1
#01-416
Singapore 408701
Contact Person: Mr Tony (9730-5013)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SJU 7657 E – By Email: hoautoengineering@yahoo.com.sg

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18015138/T1rd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 3153B	Veh. Inspected	SJU 7657E	
Policy No.	DMPCSN3096021802	Coverage (\$)	0.00	
Claim No.	SNM18D03979C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/08/2018	Inspection Date	21/08/2018	
Survey held at	HO AUTO ENGINEERING 2 KAKI BUKIT AVENUE 2 #02-18/23 KAK BUKIT AUTOHUB SINGAPORE 417921.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5953A
Vehicle Details	
Vehicle No.:	SJU7657E
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	R18A14016696
Chassis No.:	JHMF16309S203192
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$26,585.00
Original Registration Date:	28 Dec 2009
First Registration Date:	28 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$26,585.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2019
PARF Rebate Amount:	\$14,621.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,267.00
COE Rebate Amount:	\$2,317.00
Total Rebate Amount:	\$16,938.00

The information contained herein is correct as at 13 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/08/2018 14:47
Date Of Accident	15/08/2018 18:00
Exact Location Of Accident	TAMPINES AVE 7 SLIP RD INTO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU7657E
Insured/Policyholder	
Name Of Registered Owner	CHUA CHIN TIAM
NRIC No	S2595953A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93882553
Alternative Phone No	OFFICE-93882553
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00278431
Cover Note Number	-
Driver	
Name of Driver	PANG HOON KIEW
NRIC No	S7075445B
Date Of Birth	15/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	18/03/2005
Driving Experience	13 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91999190
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 317 TAMPINES ST 33 #10-62
Postcode	520317
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG TAMPINES AVE 7 AT THE SLIP RD INTO TPE, VEH INFRONT OF ME STOP, AS SUCH I MANAGE TO STOP, ALL OF A SUDDEN I FELT AN IMPACT FROM BEHIND. AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED I WAS INVOLVED IN A 3 CAR CHAIN COLLISION ACCIDENT. VEH B (BEARING NO SKC3153B) HIT ONTO MY VEH REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC3153B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA3097B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1	
-----------------------------	--

Name	PANG HOON KIEW
Approximate Age	
Injuries Sustain	BACK
Injured person in which vehicle?	SJU7657E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

TPE



A = SJU 7657E

B = SKC 3153B

C = SHA 3097B

Tampines Ave 7

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7075445B**

Name
PANG HOON KIEW

Birth Date **15 Jun 1970**

Issue Date **18 Mar 2005**

001329409G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7075445B**



Name

PANG HOON KIEW

彭云娇

Race
CHINESE

Date of birth
15-06-1970

Sex
F

Country/Place of birth
MALAYSIA



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars \leq 3000 kg with \leq 7 passengers, exclusive of the driver; and motor tractors / vehicles \leq 2500 kg

PASS DATE

18 Mar 2005



Licence No: S7075445B

NP 428A

5418571



NRIC No: **S7075445B**



Date of issue

30-01-2015

Address

**APT BLK 317 TAMPINES STREET 33
#10-62
SINGAPORE 520317**

Ho Auto Engineering

2 Kaki Bukit Ave 2, #02-18/23 (Kaki Bukit AutoHub), Singapore 417921
Hoautoengineering@yahoo.com.sg (Kindly reply all correspondence via email)
 H/P: 97305013 (Tony Ho)

Vehicle No.: SJU 7657 E

Model: Honda Civic

QTY	List Price:	Prices \$
1	Rear Boot	875 <i>bt</i>
2	Rear Boot Lamp @ \$285 each	570 <i>? each</i>
2	Rear Lamp @ \$425 each	850 <i>? each</i>
1	Rear Panel	650 <i>bt</i> <i>photo</i>
1	Rear Panel Inner Garnish	195 <i>de</i>
6	Inner Garnish Clip @ \$3 each	18 <i>wa</i>
1	Rear Boot Lock	425 <i>bt</i>
1	Rear Bumper	485 <i>de</i>
2	Rear Bumper Retainer @ \$42 each	84 <i>rec</i>
2	Rear Bumper Bracket @ \$38 each	76 <i>rec</i>
1	Rear Exhaust Box	850 <i>bt</i> <i>photo</i>
2	Rear Exhaust Box Holder @ \$53 each	106 <i>de</i>
Total:		5184
Less 20%:		4147.20
Nett Items		
QTY	List Price.	Prices \$
1	Civic Emblem	68 <i>rec</i>
2	(H) Emblem	75 <i>wa</i>
3	1.8 I.VTEC	115 <i>re</i>
4	1 Set Reverse Sensor	280 <i>200 dis</i>
5	Rear Number Plate	60 <i>x nn</i>
Total:		598
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div>		
<div style="border: 1px solid black; padding: 5px;"> <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>		
Labor Charges		
To respray painting and etc.		1100 <i>700</i>
Panel beating, remove and replacing above parts		950 <i>700</i>
To respray undercoating		100 <i>30</i>
To check wiring		50 <i>30</i>
To dismantle and refix reverse sensor		60 <i>30</i>
To dismantle and refix rear exhaust box		120 <i>80</i>
To dismantle and refix rear boot		80 <i>60</i>
Total:		2460
ESTIMATE PARTS AND LABOR GRAND TOTAL \$		7205.20

Rear Boot Inner Rubber \$225 cut 20%.

Tan Guan 97445749
wp 21/8/18 @ 1115
Lumpsum
sure/klumpsum
5 days.

7285.20

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		20 Aug 2018 13:52 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: VARGHESE GEORGE , ID: S12456371									
Main Claimant: CHUA CHIN TIAM , ID: S2595953A									
Vehicle Reg. No.: SJU7657E		Date of Loss: 15/08/2018 18:00 - :59 [103 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D03979C02		Policy/Cover Note No.: DMPCSN3096021802 (Comprehensive)							
Vehicle Reg. No. (Insured): SKC3153B		Policy No. (Claimant): MT/00278431							
		Excess: S\$0.00							
Repairer: Ho Auto Engineering (HQ) BLK 2 KAKI BUKIT AVE 2, #02-18/23 KAKI BUKIT AUTO HUB, 417921 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Claimant's Insurer: Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/08/2018]									
Driver/Custodian (Insured): SOMHATHAI THAITAIR (55 / Female), NRIC: S2613645H, Tel: +6591050687									
Adj Asg. Remarks: NO EST, ASSIGN MARCUS CHUA AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU7657E (SNM18D03979C02)
[SKC3153B]
TP
CHUA CHIN TIAM
Aug 15 2018 6:00PM
[VARGHESE GEORGE]
Ho Auto Engineering

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		▼		
Assessment Reports								1 per page		▼		✓	
No	Finalized On		National Assessment Centre Services (Ubi)						Thumbnail	Print			
1	16/08/18 14:58		Accident Statement					1	Load HTM				
Photos/Images								3 per page		▼		✓	
No	Finalized On		National Assessment Centre Services (Ubi)						Thumbnail	Print			
1	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
2	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
3	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
4	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
5	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
6	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
7	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
8	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
9	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
10	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
11	16/08/18 14:56		Accident Photo [Linked Accident Report Documents]					1	Load JPG		✓		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	21/09/18 15:09		General View					1	Load JPG		✓		
2	21/09/18 15:09		General View					1	Load JPG		✓		
3	21/09/18 15:09		General View					1	Load JPG		✓		
4	21/09/18 15:09		General View					1	Load JPG		✓		
5	21/09/18 15:09		General View					1	Load JPG		✓		
6	21/09/18 15:09		General View					1	Load JPG		✓		
7	21/09/18 15:09		General View					1	Load JPG		✓		
8	21/09/18 15:09		General View					1	Load JPG		✓		
9	21/09/18 15:09		General View					1	Load JPG		✓		
10	21/09/18 15:09		General View					1	Load JPG		✓		
11	21/09/18 15:09		General View					1	Load JPG		✓		
12	21/09/18 15:09		General View					1	Load JPG		✓		
13	21/09/18 15:09		General View					1	Load JPG		✓		
14	21/09/18 15:09		General View					1	Load JPG		✓		
15	21/09/18 15:09		General View					1	Load JPG		✓		
16	21/09/18 15:09		General View					1	Load JPG		✓		
17	21/09/18 15:09		General View					1	Load JPG		✓		
18	21/09/18 15:09		General View					1	Load JPG		✓		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
19	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/09/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/09/18 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
69	21/09/18 15:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	21/09/18 15:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	21/09/18 15:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	21/09/18 15:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	21/09/18 15:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/08/18 13:51	PRS		Load PDF	
2	20/08/18 13:51	OI GIA		Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/18 14:53	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 14:53	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/18 14:58	Accident Statement		Load HTM	
2	06/09/18 16:12	Addendum Sheet		Load JPG	<input checked="" type="checkbox"/>
3	06/09/18 16:21	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	16/08/18 14:56	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	16/08/18 14:53	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	16/08/18 14:53	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015138/T1RD3E2

Date: 24/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3096021802

Claimant Vehicle
No : SJU7657EInsured Vehicle
No : SKC3153B

Date of Loss: 15/08/2018

Nature of Claim: TP

Claim
No: SNM18D03979C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU7657E**

Make & Model: HONDA CIVIC, 1.8 (A)

Engine No: R18A14016696

Reg. Date: 28/12/2009 (Man. Year: 2009)

Chassis No: JHMF16309S203192

Colour: Black

Odometer: 212422 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,925.20	4,785.20	140.00	2.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,630.00	830.00	33.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,385.20	6,415.20	970.00	13.13
Approved Total (Overridden) (\$\$)		5,100.00		
Nett Amount (\$\$)	7,385.20	5,100.00	2,285.20	30.94

INSPECTION

Date of Assignment: 20/08/2018

Date Inspected: 21/08/2018 Inspected At:

Blk 3007, Ubi Rd 1 #01-416

Repairer : Ho Auto Engineering (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2018)
Parts:	143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU7657E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	875.00 FL	*875.00 FL
2	2		*REAR BOOT LAMP	Cracked	570.00 FL	*570.00 FL
3	2		*REAR LAMP	Cracked	850.00 FL	*850.00 FL
4	1		*REAR PANEL	Bent	650.00 FL	*650.00 FL
5	1		*REAR PANEL INNER GARNISH	Deformed	195.00 FL	*195.00 FL
6	6		*INNER GARNISH CLIP	Necessary	18.00 FL	*18.00 FL
7	1		*REAR BOOT LOCK	Bent	425.00 FL	*425.00 FL
8	1		*REAR BUMPER	Deformed	485.00 FL	*485.00 FL
9	2		*REAR BUMPER RETAINER	Necessary	84.00 FL	*84.00 FL
10	2		*REAR BUMPER BRACKET	Necessary	76.00 FL	*76.00 FL
11	1		*REAR EXHAUST BOX	Bent	850.00 FL	*850.00 FL
12	2		*REAR EXHAUST BOX HOLDER	Deformed	106.00 FL	*106.00 FL
13	1		*REAR BOOT INNER RUBBER	Cut	225.00 FL	*225.00 FL
14	1		*CIVIC EMBLEM	Necessary	68.00 FS	*68.00 FS
15	1		*(H) EMBLEM	Necessary	75.00 FS	*75.00 FS
16	1		*1.8 I-VTEC	Necessary	115.00 FS	*115.00 FS
17	1		*SET REVERSE SENSOR	Distorted	280.00 FS	*200.00 FS
18	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,007.00	5,867.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,081.80	1,081.80
Total Parts (\$\$)	4,925.20	4,785.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY PAINTING AND ETC	New	1,100.00	700.00
2	PANEL BEATING, REMOVE AND REPLACING ABOVE PARTS	New	950.00	700.00
3	TO RESPRAY UNDERCOATING	New	100.00	30.00
4	TO CHECK WIRING	New	50.00	30.00
5	TO DISMANTLE AND REFIX REVERSE SENSOR	New	60.00	30.00
6	TO DISMANTLE AND REFIX REAR EXHAUST BOX	New	120.00	80.00
7	TO DISMANTLE AND REFIX REAR BOOT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,460.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >