

22/03/2002

ASS. REC. BY:

REF:

CS3/EG1/8015/39/R/240302

Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG1

Date/Time:

20/8/18 @ 9.31am

Estimated Cost:

Bill to:

OD: ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 6196D

Insured:

GX 7166 X

at Workshop m/s

Albert Motor

Tel:

9845 2975 / 62731588
(Andrew) (Wesley)

of

Blk 1008 Bkt Merah #01-10 Lane 3

Policy No:

Claim No:

GX 7166 X

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/08/2018

CA / REV / REP. / REV 24 HRS

(up)

21/08/2018

H.O.D. Endorsement:

Date/Time:

11:00am @ 20/8/18

Person Contacted:

Ah San

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

FBE 6196D - X

GX 7166D

we f
ASS. REC. BY:

REF: EGI

ASSIGNMENT

From: _____ Date: 21/8/18

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: FBE 6196D

at Workshop m/s Albert Motor

of BIK 1008, Bldg Meruh Lane 3#01-10

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Andrew @ 98452975 /
wksp (Ah Sen) - 62731588

(Policy Condition) 1006 \$01/12

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBE 6196D Yr Regn: Jun / 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 3-M-W c.c 798

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB1021707AZS47306

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F: 120/102R17

R: 180/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 21/08/18 @ 0352pm

Survey held at ALBERT MOTOR

Des. of Damages: ☒ Fr / ☒ Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$5,000 - \$6,000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: 50

Transportation: S + RS, SI

Photos

Others

Report Format : PRO

Lump Sum / I.B.I. (\$))

TOTAL

50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18015139/R1z4d3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 20-08-2018



Code : EGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GX 7166X	Veh. Inspected	FBE 6196D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/08/2018	Inspection Date	
Survey held at	ALBERT MOTOR SUPPLY PTE LTD BLK 1008 #01-10, BUKIT MERAH LANE 3, SINGAPORE 159722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 20 August 2018 9:31 AM
To: admin-d@lkkauto.com
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: OI : GX7166X / TP : FBE6196D/LKK / DOA : 03/08/2018
Attachments: FBE6196D - SAS.pdf

Dear Nivitha / Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **ALBERT MOTOR SUPPLY PTE LTD,**

ADDRESS : BLK 1008 BUKIT MERAH
#01-10
SINGAPORE 159722

PERSON TO CONTACT : ANDREW @ 9845 2975

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE6196D		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	B.M.W.		
Vehicle Model :	F800R		
Chassis No. :	WB1021707AZS47306		
Propellant :	Petrol		
Engine No.:	802EA08575289		
Engine Capacity :	798 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	405 kg		
Unladen Weight :	199 kg		
Year Of Manufacture :	2009		
Original Registration Date :	25 Jun 2010		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,454.00		
COE Expiry Date :	24 Jun 2020		
Road Tax Expiry Date :	24 Sep 2018		
Inspection Due Date :	24 Mar 2019		
Intended Transfer Date :	24 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 24 Sep 2018. You may renew the road tax from 25 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 25 Sep 2018 to 24 Mar 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	102.00	-	102.00
Total Amount Payable :			127.00
Amount Payable (From 25 Sep 2018 to 24 Sep 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	204.00	-	204.00
Total Amount Payable :			229.00

You may print this page for reference.

OK Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7865F
Vehicle Details	
Vehicle No.:	FBE6196D
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	F800R
Primary Colour:	Orange
Manufacturing Year:	2009
Engine No.:	802EA08575289
Chassis No.:	WB1021707AZS47306
Maximum Power Output:	-
Open Market Value:	\$11,020.00
Original Registration Date:	25 Jun 2010
First Registration Date:	25 Jun 2010
Transfer Count:	2
Actual ARF Paid:	\$1,653.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,454.00
COE Rebate Amount:	\$372.00
Total Rebate Amount:	\$372.00

The information contained herein is correct as at 27 Aug 2018

OK

MSIS18102275 / STA INSPECTION PTE LTD - Boon Lay
ENTRY DATE & TIME: 07/08/2018 17:47
SUBMITTED BY: Woodford Richard Vincent

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 07/08/2018 18:08

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2018 17:47
Date Of Accident	03/08/2018 15:40
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE LORNIE RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE6196D
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD FAIZAL BIN ABD RAHMAN
NRIC No	S7727865F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87527630
Alternative Phone No	OTHERS-87527630
Vehicle Particulars	
Manufacturer	BMW
Model	F800R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MC/00465995
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD FARID BIN ABD RAHMAN
NRIC No	S7609599Z
Date Of Birth	28/03/1976
Occupation	INDOOR
Date Of Driving Pass	23/10/2012
Driving Experience	5 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87527630
Fax Number	
Contact Number	
Email Address	AKI_ANIKI@LIVE.COM

Address BLK 411 BUKIT BATOK WEST AVNUE 4
#08-182
Postcode 850411
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SIBLING
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 3
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name HONG KAH SOUTH NEIGHBOURHOOD POLICE POST
Police Station Address ROAD: BLK 510 JURONG WEST STREET 52 , POSTCODE: 640510 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-5648999 - FAX NO: 68655797
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT - VEHICLE FBE6198D TOWED TO IDAC JBL ON 7/08/2018 1710HRS

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ7391H
Vehicle Make/Model/Colour
Details Of Properties REAR LEFT
Vehicle Category PRIVATE CAR
Name of Driver NA
NRIC/Passport Number
Contact Number NA
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GX7166A
Vehicle Make/Model/Colour	PICK-UP
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD FARID BIN ABD RAHMAN
Approximate Age	
Injuries Sustain	REFER REPORT - ABRASIONS RIGHT ARM,KNEE,ANKLE
Injured person in which vehicle?	FBE6196D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 411 BUKIT BATOK WEST AVENUE 4 #08-182
Postcode	650411

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as in the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be/sit outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 4/8/18

12:00pm

Driver's Signature
(If driver is not the policyholder)


...

Reporting Company's Signature
Name: 4/8/18

...

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PIE

Refer police report.

(A) PBE 6196.D

(B) SKZ 7391.H

(C) GX 7166.A

DECLARATION

I/We declare the foregoing particulars are true in every respect.

7/8/18

Common Statement Pg. 1


**SINGAPORE
POLICE FORCE**


T/20180804/2060

Police Station Of Origin:
Hong Kah South NPP
810 Jurong West Street 52 #01-80
SINGAPORE 640510
Tel No: 1800-5648999

1 of 3

Report No. T/20180804/2060

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/08/2018 13:54		Vide Report No.: T/20180803/2147		Station Diary No.: 24	
Informant Particulars					
Name of Informant: MUHAMMAD FARID BIN ABD RAHMAN			Address: APT BLK 411 BUKIT BATOK WEST AVENUE 4 #08-182 SINGAPORE 650411		
ID Type / ID No.: NRIC NO / S7609599Z			Contact No.: Home/Office: Mobile: 87527630		
Nationality: STATELESS			Email:		
Sex: Male	Age: 42	Date of Birth: 26/03/1976	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: CLEANER SUPERVISOR			Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

General Information on the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 03/08/2018 15:40	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Changi before Lornie Road exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBE6198D	Motorcycle	BMW	F800	Green	Seriously Damaged	0
GX7166A	Pick-Up					0
SK27391H	Car					0

Details of Vehicle Insurance			
Vehicle No.	Insurance Company	Insurance No.	Effective / Expiry Date

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180804/2080

2 of 3

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-80
SINGAPORE 640510
Tel No: 1800-5848999

Report No. T/20180804/2080

CONTINUATION OF REPORT

Vehicle No.	Insurance Co.	Policy No.	Policy Start Date	Policy End Date
FBE6196D	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00465995	25/03/2018	24/03/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	Related Vehicle	ID No.	Contact No.
MUHAMMAD FARID BIN ABD RAHMAN	FBE6196D (Motorcycle)	S7609599Z	87527630
Hospital/Clinic	Date Treatment	Date Discharge	Degree of Injury
TAN TOCK SENG HOSPITAL	03/08/2018	03/08/2018	Serious
No. of Days granted Medical Leave		Degree of Injury	
03		Serious	

Brief Details.

On 03.08.2018 at about 1540 hrs, I was riding my motorcycle FBE6196D on lane 2 near to lane 1 markings. Subsequently, one black coloured Singapore registered car SKZ7391H which was travelling on lane 1, without signaling intention, suddenly changed lane to lane 2 in an abrupt manner and apply brake immediately after the lane change. I then swerved to the left to avoid the collision with SKZ7391H but the front of my motorcycle FBE6196D still collided onto the rear left of SKZ7391H. I then lost my balance and fell down on the road. After which, one Singapore registered pick-up, GX7166A which was travelling behind me then tried to avoid the collision of me lying on the road then swerved to the left and collided onto my motorcycle FBE6196D. I wish to state that after the collision, the driver of SKZ7391H then swerved his vehicle back to lane 1 and stop to check on his vehicle.

After the collision, I was conveyed to Tan Tock Seng hospital was given 3 days of medical leave. I received a call from Traffic Police IO Dylan to lodge a traffic accident report.

Common Statement Pg. 1

**SINGAPORE
POLICE FORCE**

T/20180804/2080

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-80
SINGAPORE 640510
Tel No: 1800-5648999.

3 of 3

Report No. T/20180804/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 66474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/
Sr Staff Sgt YAP HOW KIAT MICHAEL

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
04/08/2018 13:54Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt YUS. MASTARI KHAZALI
Contact No.: 85476214

Classification Of Case:

Authentication Stamp

SN 125



Signature :

Singapore Police Force

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

ERGO INSURANCE PTE LTD

Ref: CS3/EGI18015139/R1z4d3e2

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER
FIVE SINGAPORE 038985

Date: 07-09-2018



Code: EGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GX 7166X	Veh. Inspected	FBE 6196D
Policy No.		Coverage (\$)	0.00
Claim No.	GX7166X	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. F800R	c.c	798
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WB1021707AZS47306	Colour	GREEN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70Z R17	MICHELIN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55Z R17	MICHELIN	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.	
--	--

5. General Information

Accident Date	03/08/2018	Inspect Date / Time	21/08/2018 (03:52 PM)
Survey held at	ALBERT MOTOR SUPPLY PTE LTD BLK 1008 #01-10, BUKIT MERAH LANE 3, SINGAPORE 159722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

Report Ref No. CS3/EGI18015139/R1z4d3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.