

ASS. REC. BY:

REF: CS/FCI18015146/ Uqd3

Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Yvonne Yong

of

FCI

Date/Time:

17/8/18 @ 6.15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 772R

Insured:

SHA 3637T

at Workshop m/s

SME Motor

Tel:

6747 6106

of

1 Koki Bkt Ave 6 # 02-15 Autobay

Policy No:

Claim No:

D18006199MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

1037am @ 20/8/18

Person Contacted:

pei ying

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 772R - X
	SHA 3637T - CC1/AXA/700/634/M/1/1/17
28/8 @ 5:52pm	revert via email pre li advise.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJD772Rat Workshop m/s Sure

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 626.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJD772R Yr Regn: 1, 11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mercedes E300 c.c. 2996Colour: Black A/C: Insured / Std / NI / NASp. Reading: 119669 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120542A358695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/45-R17

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 27/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A4535x
4/10/18 Summit vehicle hasn't send in for repair.

RECEIVED 04 OCT 2018

Date/Time, File Pass to?



Preli. Report

1) 04/10/18 typist

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS, ____ \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

135

50

31

216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18015140/Uqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3637T	Veh. Inspected	SJD 772R
Policy No.		Coverage (\$)	0.00
Claim No.	D18006199MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/08/2018	Inspection Date	27/08/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006199MFSH

Date: 28/8/2018

Our Ref: CS/FCI18015140/Uqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJD 772R

Please be informed that we had conducted the inspection of the abovementioned vehicle 27/8/2018 at the premises of M/s SME Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,535.00</u>
Revised Estimate Amount	: S\$ <u>3,037.50</u>
"Check" Items Amount	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
n/s front portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-08-2018	Our Ref No. D18006199MFSH
Accident Date	15-08-2018	Claim Type. Third Party
Insured Vehicle	SHA3637T	Third Party Vehicle. SJD772R
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18 AUTOBAY @ KAKI BUKIT	
Contact Person.	PEIYING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 28 August 2018 5:52 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006199MFSH/1
Attachments: PRELI ADVISED SJD 772R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJD 772R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 20 August 2018 11:15 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006199MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 August 2018 6:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006199MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

LETTER OF UNDERTAKING

I/We, ALBERT KANG TEE JOO, the owner of vehicle no. SJD 772R

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, 2MB MOTOR PTE LTD

Signed and Acknowledge by:


Nric no. and signature of policyholder 57902763D

Company Stamp

15/08/2008
Date

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7334H
Vehicle Details	
Vehicle No.:	SJD772R
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 300
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	27295231730698
Chassis No.:	WDD2120542A358695
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$56,841.00
Original Registration Date:	03 Jan 2011
First Registration Date:	03 Jan 2011
Transfer Count:	1
Actual ARF Paid:	\$56,841.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jan 2021
PARF Rebate Amount:	\$34,104.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jan 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$47,890.00
COE Rebate Amount:	\$11,251.00
Total Rebate Amount:	\$45,355.00

The information contained herein is correct as at 27 Aug 2018

OK

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Article](#)

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!**How much is my car worth?**

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2000 Downpayment Monthly
From \$488 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by

3 vehicles

Mercedes-Benz e300

Advanced

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Search Selection

Mercedes-Benz e300

Any

Any

2011

Any

**Mercedes-Benz E-Class E300****\$64,800**

\$13,830 /yr

10-May-2011

2,996 cc

1 Owner. Well Maintained And Service By C&C Agent. Showroom Condition. Flexible Loan Avail. Call/SMS For Viewing Ap

Posted: 24-Aug-2018 Tags: 2011 Mercedes-Benz E300, Mercedes-Benz E300, Mercedes-Benz, E300, Used Mercedes-Benz

**Mercedes-Benz E-Class E300****\$63,800**

\$13,470 /yr

13-Apr-2011

2,996 cc

11

New Number Plate. Low Mileage Done. Low Depreciation. Well Maintain & Service By C&C Agent. Excellent Condition. (Be Instalment Around Monthly \$778). Call/SMS For Viewing Appoint...

Prime Cars Credit

Posted: 23-Aug-2018 Tags: 2011 Mercedes-Benz E300, Mercedes-Benz E300, Mercedes-Benz, E300, Used Mercedes-Benz

**Mercedes-Benz E-Class E300 Elegance****\$62,800**

\$13,060 /yr

25-May-2011

2,996 cc

High Loan Available! 1 Owner, Accident Free, Fully Serviced And Maintained By Agent, Original Paintwork, Pristine Interior Running Condition. Call Us Now To Make An Appointment Fo...

Posted: 21-Aug-2018 Tags: 2011 Mercedes-Benz E300, Mercedes-Benz E300, Mercedes-Benz, E300, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

For old advertisements, view **Expired ads**
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)
[Compare](#)

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-162 (08)

Claim Type: Third Party

Accident Date: 15/03/2018

TP Veh Reg No: SHA3637T

Estimate No: EST0004338

Date: 17 Aug 2018

Policy No: GA371464

Veh Reg No: SJD772R

Make/Model: M.BENZ E300

Chasis No: WDD2120542A358695

Engine No: 27295231730698

Reg. Date: 03/01/2011

Estimate Repair Cost to Vehicle No :SJD772R

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1 FRT BUMPER <i>Deep cut</i>	1 PC	1,360.00	<i>✓</i>
2 FRT BUMPER CLIP <i>rec</i>	10 PC	70.00	<i>✓</i>
3 FRT BUMPER CHROME SIDE <i>rec</i>	2 PC	160.00	<i>✓</i>
4 HEADLAMP LH <i>11</i>	1 PC	1,090.00	<i>✓</i>
5 FRT FENDER CHROME MOULDING LH <i>rec</i>	1 PC	35.00	<i>✓</i>
6 FRT SPORT RIM LH <i>cut</i>	1 PC	950.00	<i>✓</i>
		3,665.00	3,665.00
Labour			
7 WIRE CHECKING	1 UNIT	20.00	<i>✓</i>
8 LABOUR CHARGE	1 UNIT	450.00	<i>300</i>
9 SPRAY PAINTING	1 UNIT	400.00	<i>✓</i>
		870.00	870.00
Total			SS 4,535.00
Add GST @ 7%			317.45
Total Amount Payable			SS 4,852.45

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED FIFTY TWO AND CENTS FORTY FIVE ONLY

Not Allowed
2/11/18

h/SS
3 dy.
27/8/18
Take photo. After 14 days

For SME Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

AUTHORISED SIGNATURE

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015140/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3637T	Veh. Inspected	SJD 772R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006199MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	17/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E300 (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2120542A358695	Colour	BLACK	
Odometer	119669	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	MICHELIN	6 mm	
L/H Front Tyre	245/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	245/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	245/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2018	Inspection Date	27/08/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 772R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEEP CUT	1,360.00	1,360.00
10	FRT BUMPER CLIP	NECESSARY	70.00	70.00
2	FRT BUMPER CHROME SIDE	NECESSARY	160.00	160.00
1	HEADLAMP LH	NOT NECESSARY	1,090.00	-
1	FRT FENDER CHROME MOULDING LH	NECESSARY	35.00	35.00
1	FRT SPORT RIM LH	CUT	950.00	950.00
	LESS 10% DISCOUNT		-	-257.50
			3,665.00	2,317.50
	<u>LABOUR</u>			
	WIRE CHECKING.		20.00	20.00
	LABOUR CHARGE.		450.00	300.00
	SPRAY PAINTING.		400.00	400.00
			870.00	720.00
	GRAND TOTAL		4,535.00	3,037.50
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			3,037.50

Report Ref No. CS/FCI18015140/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.