

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Mehin Yang

of

SMO

Date/Time: 20/8/18 @ 3:24pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 5990P

Insured:

FF143T

at Workshop m/s

Faskeh Auto

Tel:

6746 5405

of

1 Keki Bukit Ave 6 #01-46/48

Policy No:

Claim No: CMTD1803576

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3:24pm @ 20/8/18

Person Contacted:

Nancy

Vehicle: ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

SKQ 5990P - CC3/MSG/17018201/Utd3 DUA: 21/9/17

FF143T - X

28/8 @ 4:03pm revert via email . pending estimate

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKQ5990Pat Workshop m/s FPof 11.30Insured: FF143T

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 152k

IDAC Accident Rpt: Consistent? : Yes or No

GA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ5990P Yr Regn: 12.14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA7Make: Jaguar XJ c.c. 1999Colour: black A/C: Insured / Std / NI / NASp. Reading: 26.8 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJAC12M1PPV77977Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or inorderBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: * F: 245/45ZR19R: 275/45ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/8/18 D.O.I. 20/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17A 119578 Rep 16800 Gys. 4th.
 came GA NO police report.

11/9/18 1/5 \$7000 Confirmed with Alu. (lod: 23221; 762)

RECEIVED 12 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 11/9 Typist

☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS, ____ \$

Photos

Others

TOTAL

450

Report Format: TPLump Sum / I.B.I.: (\$ 7000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18015146/Utd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 20-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FF 143T	Veh. Inspected	SKQ 5990P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803576	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/08/2018	Inspection Date	20/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, 20 August 2018 3:21 PM
To: Nancy Lam; 'Nivitha (LKK Auto)'; assignments@lkkauto.com
Cc: Gnoh, Pau Loong; Teo, Grace
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Without Prejudice

Our Claim Reference: CMTD1803576
Your Reference: SKQ5990P

Hi Nancy,

We acknowledged receipt of your claim documents.

Please be informed that Gnoh Pau Loong the handler of this case.

We have appointed LKK to conduct the survey on a without Prejudice and without any admission of liability basis.

Aside to LKK,

Please make arrangement to conduct the survey for SKQ5990P on a without Prejudice and without any admission of liability basis.

Please submit with your report to my colleague, Mr Gnoh Pau Loong.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, 20 August, 2018 3:11 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Our Reference: CMTD1803576
Your Reference: SKQ5990P

Dear Melvin,

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, August 20, 2018 3:05 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Our Reference: CMTD1803576
Your Reference: SKQ5990P

Without Prejudice

Date: 20th August 2018

Attention:
M/S FASTECH AUTO PTE LTD

Dear Nancy,

ACCIDENT INVOLVING SKQ5990P & FF143T ON 19.08.2018

We refer to your Notice of Accident dated 20/08/2018.

Please be informed that Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Monday, 20 August, 2018 10:55 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Hi Sir

My client claiming your insured FF 143T.

Please kindly arrange PRS for SKQ 5990P.

Date of accident 19.08.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 23 August 2018 4:07 PM
To: Admin-D (LKKAUTO); 'Ye, Yong Kang Melvin'; assignments
Cc: 'Gnoh, Pau Loong'; 'Teo, Grace'; SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKQ 5990P on 20/8/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 20 August 2018 3:26 PM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Teo, Grace' <grace.teo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Monday, 20 August 2018 3:21 PM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; assignments@lkkauto.com
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:SKQ5990P

Without Prejudice

Our Claim Reference: CMTD1803576
Your Reference: SKQ5990P

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 12:38
Date Of Accident	19/08/2018 18:20
Exact Location Of Accident	ALONG AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ5990P
Insured/Policyholder	
Name Of Registered Owner	LIU XIAOFEI
NRIC No	S7278799D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96524158
Alternative Phone No	OTHERS-96524158

Vehicle Particulars

Manufacturer	JAGUAR
Model	XJ-2.0 TSS SWB SR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA147100/1
Cover Note Number	

Driver

Name of Driver	LIU XIAOFEI
NRIC No	S7278799D
Date Of Birth	28/05/1972
Occupation	INDOOR
Date Of Driving Pass	08/10/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96524158
Fax Number	
Contact Number	OTHERS-96524158
Email Address	NOEMAIL

Address BLK 44 CHOA CHU KANG STREET 64 #21-18 SPORE 689105

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CHOA CHU KANG NPC

Police Station Address ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO WITH OWNER/POLICE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FF143T

Vehicle Make/Model/Colour K.T.M. 390 DUKE

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: S. Chinn
NRIC/TIN No.: S040277A

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report T/20180819/2114

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

04/08/2018 10:00 AM

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. A. M.
NRIC/FIN No: J040177A

Accident Photo





SINGAPORE POLICE FORCE



T/20180819/2114

1 of 4

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20180819/2114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2018 22:39	Vide Report No.: D/20180819/0119	Station Diary No.: 149
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: LIU XIAOFEI			Address: APT BLK 44 CHOA CHU KANG STREET 64 #21-18 SINGAPORE 689105		
ID Type / ID No.: NRIC NO / S7278799D			Contact No.: Home/Office: Mobile: 96524158		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 46	Date of Birth: 28/05/1972	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: Self Employed			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/08/2018 18:20	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AFTER LOWER DELTA SLIP RD INTO PIE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FF143T	Motorcycle	KTM	390 DUKE	White	Seriously Damaged	0
SKQ5990P	Car	JAGUAR	XJ 2.0 TSS SWB SR	Black	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKQ5990P	AXA INSURANCE SINGAPORE PTE LTD	GA147100	13/12/2017	12/12/2018



Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	unknown	ID No.	UNKNOWN
Related Vehicle	FF143T (Motorcycle)	Contact No.	unknown
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
Driver			
Name	LIU XIAOFEI	ID No.	S7278799D
Related Vehicle	SKQ5990P (Car)	Contact No.	96524158
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/08/2018 at about 1820hrs, I was traveling in V1 (SKQ5990P) Along AYE at the center lane. I was driving steadily and there were nothing amiss.

While I was driving (AYE TOWARDS TUAS DIRECTION, NR L/P 247 SINGAPORE), I suddenly felt an impact from the rear right of my vehicle V1. Via the side mirror, I then spotted V2 (FF143T) along with the rider sliding forward on the road thus I immediately stopped my vehicle. The rider of V2 was then being conveyed by ambulance.

I wish to state that via the CCTV footage of a witness (Wei Jian of HP:97951193) whom were driving behind of my vehicle at the time of incident, I observed that Rider of V2 collided onto the rear of my vehicle V1 suddenly and fall onto the road. I did not attempted to change lane when the accident happened.

I had handed over my In-Car CCTV's SD card to the attended traffic police namely SSGT Jofiliano of T100472. I am lodging this report under instruction of the traffic police for investigation purpose.

My vehicle V1 suffered from multiple scratches on the right rear bumper. V1's right rear tire were also puncture due to the accident.



**SINGAPORE
POLICE FORCE**



T/20180819/2114

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 4

Report No. T/20180819/2114

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180819/2114

4 of 4

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20180819/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 SIAU JING YANG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt RAZIZ BIN TAHAR

Contact No.: 65476200

Signature Of Informant:

Date/Time:

19/08/2018 22:39

Classification Of Case:

Authentication Stamp

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 8799D

Vehicle Details

Vehicle No.: SKQ5990P
 Vehicle to be Exported: No
 Intended De-registration Date: 20 Aug 2018
 Vehicle Make: JAGUAR
 Vehicle Model: XJ 2.0 TSS SWB SR
 Primary Colour: Black
 Manufacturing Year: 2014
 Engine No.: 040614210714204PT
 Chassis No.: SAJAC12M1FPV77977
 Maximum Power Output: 177.0 kW (237 bhp)
 Open Market Value: \$69,377.00
 Original Registration Date: 12 Dec 2014
 First Registration Date: 12 Dec 2014
 Transfer Count: 1
 Actual ARF Paid: \$96,879.00 48438

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 11 Dec 2024
 PARF Rebate Amount: \$72,659.00

Intended COE Rebate Details

COE Expiry Date: 11 Dec 2024
 COE Category: B - Car above 1600cc or 97kW (130bhp)
 COE Period(Years): 10
 QP Paid: \$74,389.00
 COE Rebate Amount: \$46,919.00
Total Rebate Amount: \$119,578.00

The information contained herein is correct as at 20 Aug 2018

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



\$2500 Downpayment Monthly
From \$588 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 View our cars

Browse by Category

Sort by Date Posted 20 results/page

Advanced Search Submit

5 vehicles

Jaguar XJ

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Jaguar XJ		Any	Any	2014	Any	Any	Any	Available
	Jaguar XJ	Jaguar XJ 3.0A SC LWB	\$185,800	\$21,770 /yr	26-Mar-2014	2,995 cc	26,000 km	Luxury	Available
Low Mileage, Full Agent Maintained. Luxury Champagne Gold With Beige Leather Interiors. Superb Power And Super Comfy, Making It An Excellent Choice For All Car Lovers. Euro Performance Asia Pte Ltd Posted: 20-Aug-2018 Tags: 2014 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar									
	Jaguar XJ	Jaguar XJ 3.0A SC LWB	\$179,000	\$19,700 /yr	28-Mar-2014	2,995 cc	30,000 km	Luxury	Available
Wearnes Unit With Full Service Records. STA And VICOM Evaluation Welcome. Vehicle In Showroom Condition By Professional Groomer. Elegant Black With Tan Brown Interior. Lowest Interest Rate. Lowest Mon... Shuang Hup Credit Posted: 17-Aug-2018 Tags: 2014 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar									
	Jaguar XJ	Jaguar XJ Diesel 3.0A SWB	\$143,800	\$16,320 /yr	15-May-2014	2,993 cc	68,000 km	Luxury	Available
Graded B by Fuel Type: Diesel (Euro 5 Engine and Above) 1 Owner Only! Cheapest In The Market! Only 1 In The Market! Low Mileage Done On The Car! 100% Accident Free! STA Evaluation Welcome! View To Believe! 100% Loan Available! High Trade In For Your Used C... ST Carz Pte Ltd Posted: 16-Aug-2018 Tags: 2014 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar									
	Jaguar XJ	Jaguar XJ 3.0A SC Premium Luxury LWB	\$179,800	\$18,950 /yr	30-Sep-2014	2,995 cc	38,000 km	Luxury	Available
Premium Edition, Done 38000Km, Soft Close Doors, All Round Electric Seats, Aircon Seats And Massage Function, LWB Model, Call For Viewing Now! Trade In And In House Loan Available. Posted: 12-Jul-2018 Tags: 2014 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar									

Car Buying Car Selling Car Ownership
Car Aftermarket On The Move Lifestyle

	Jaguar XJ	Jaguar XJ 3.0A SC LWB	\$191,800	\$20,010 /yr	08-Dec-2014	2,995 cc	65,000 km	Luxury	Available
1 Owner Only. Fully Serviced And Maintained By Wearnes. Under Wearnes Warranty. High ARF \$131,297. High Spec With Driver And Passenger Massage Function. Call To View Now. In-House Loan Available. Hui Hua Credit Pte Ltd Posted: 09-Jul-2018 Tags: 2014 Jaguar XJ, Jaguar XJ, Jaguar, XJ, Used Jaguar									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status
20 results/page

For old advertisements, view Expired ads

FASTECH AUTO PTE LTD

1 Kakit Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO:SKQ 5990 P

QTY	PARTICULAR
1 PCS	REAR BUMPER 2653.12
1 PCS	REAR BUMPER REFLECTOR O/S 152
1 PCS	REAR BUMPER SIDE HOLDER O/S 108
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REINFORCEMENT
1 PCS	TAILLAMP O/S 965
1 PCS	REAR FENDER O/S
1 PCS	REAR SPORT RIM O/S 1500
1 PCS	REAR SHOCK ABSORBER O/S
1 PCS	REAR LOWER ARM O/S
1 PCS	REAR KNUCKLE ARM O/S
1 PCS	REAR WHEEL HUB BEARING O/S 805
1 PCS	FRONT DOOR O/S
1 PCS	REAR TORSION ARM O/S
1 PCS	REAR LINKAGE O/S 166
1 PCS	REAR TYRE O/S 285.2

De/Deep cur	\$4,880.00	/
520	\$288.00	/
Best	\$265.00	/
ner	\$60.00	/
11	\$1,018.00	X
scr	\$988.00	/
2	\$6,085.00	X
oo/Ref	\$1,880.00	/
scr	\$2,500.00	X
Best/scr	\$1,015.00	/
scr	\$1,288.00	X
Doyle	\$680.00	/
11	\$4,015.00	X
scr	\$899.00	X
11	\$290.00	/
Torn	\$380.00	602
	\$26,531.00	

LABOUR CHARGES:

TOWING KING ROLLER	\$180.00	120
TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REFIX REVERSE SENSOR	\$100.00	50
TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00	X
TO TRANSFER FRONT DOOR MECHANISM	\$120.00	X
TO CONDUCT WHEEL ALIGNMENT	\$180.00	100
TO DISMENTLE & REPLACING REAR UNDERCARRIAGE	\$380.00	120
TO SPRAY RUST PROOFING	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$900.00	550
TO PUTTY & SPRAY PAINTING	\$1,500.00	650
TOTAL	\$30,221.00	

- * To Consultants hence notify
- * To repairer of the following:
- * To repairer - before/after spray painting
- * To repairer - damaged part(s) during resurvey
- * To repairer - are subject to confirmation
- * To repairer - survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and
- * is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7286.12
6921.81
8759.81

1848

not Authorized
1/5 7000
4 dy.
20/8/18
tok. ph. After repair

(5-1/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18015146/Utd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 14-09-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FF 143T	Veh. Inspected	SKQ 5990P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803576	Excess (\$)	0.00
Assign From	MELVIN YONG	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	JAGUAR XJ (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	SAJAC12M1FPV77977	Colour	BLACK
Odometer	86858	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 ZR19	PIRELLI	6 mm
L/H Front Tyre	245/45 ZR19	PIRELLI	6 mm
R/H Rear Tyre	275/40 ZR19	BRIDGESTONE	6 mm
L/H Rear Tyre	275/40 ZR19	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2018	Inspection Date	20/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 5990P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED / DEEP CUT	4,880.00	2,655.12
1	REAR BUMPER REFLECTOR O/S	BROKEN	288.00	152.00
1	REAR BUMPER SIDE HOLDER O/S	BENT	265.00	108.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	1,018.00	-
1	TAILLAMP O/S	SCRATCHED	988.00	965.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	6,085.00	-
1	REAR SPORT RIM O/S	DENTED / BENT	1,880.00	1,500.00
1	REAR SHOCK ABSORBER O/S	SERVICEABLE	2,500.00	-
1	REAR LOWER ARM O/S	BENT / TWISTED	1,015.00	1,015.00
1	REAR KNUCKLE ARM O/S	SERVICEABLE	1,288.00	-
1	REAR WHEEL HUB BEARING O/S	DAMAGED	680.00	665.00
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	4,015.00	-
1	REAR TORSION ARM O/S	SERVICEABLE	899.00	-
1	REAR LINKAGE O/S	TWISTED	290.00	166.00
	LESS 5% DISCOUNT		-	-364.31
			26,151.00	6,921.81
<u>SPECIAL NETT ITEMS</u>				
1	REAR TYRE O/S (60%)(SN)	TORN	380.00	228.00
			380.00	228.00
<u>LABOUR</u>				
	TOWING KING ROLLER.		180.00	120.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REFIX REVERSE SENSOR.		100.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER FRONT DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		180.00	100.00
	TO DISMENTLE & REPLACING REAR UNDERCARRIAGE.		380.00	120.00
	TO SPRAY RUST PROOFING.		100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER O/S AND FRONT DOOR O/S.		900.00	550.00

Report Ref No. CS/SMO18015146/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,500.00	650.00
			3,690.00	1,620.00
	GRAND TOTAL		30,221.00	8,769.81
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CS/SMO18015146/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.