

INS CASE OWNER

CC 3, CTI 180 15158, N/A 6/1

LKK
IDAC

Surveyor:

N/A

DOI:

ASSIGNMENT

15/8/2018

Date / Time:

15/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

SJT 6620 Y

Name of Insured

GAMAH BAH

Insured Tel No.

HP: 97635986

Excess Sec II :SS

D.O.A: 13/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.

SMM18064057 002

Policy No.

Imp USN1620881502

Make / Model :

T-Camper

Place of Accident :

Lower Delta PD

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SAD 6346 Y



INSRS:

WSP:

Tel :

Liability :

RMKS:

SMP 9.11



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

6/9
17H

SAD 6346 Y. X: SJT 6620 Y. X
LOD IN BY EMAIL

* Pending needed TP GIA on
registered name

24/9/18
Khachun

- File pass to me, kuan to close

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 3/8/19 Khachun

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

WSP

Sent By:

WSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

WSP SS 1,499.67 (3 days) Reduction: 42 %

FINAL SETTLEMENT

Date/Time:

Confirm with Tan Lee Yek

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lis :

Repair Cost:

SS 1,499.67

Loss of Rental (LOR):

SS 369.15 (3 days) X \$123.05

Loss of Use (LOU):

SS - (\$ - x - days)

Loss of Income (LOI):

SS 150 (\$ 50 x 3 days)

LOR only ☐ LOU only ☐

LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

Legal Cost

SS -

Total:

SS 2,018.82 Global Sum SS: 2,018.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 2,018.00

Name 1:

SMRT TMIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$ 400

PIR AGAINST OI - S.65(6) RTA

4 S.84(1) RTA

COPY SENT
24/9/18

25.11

Surveyor

NR2

REF:

SHD 63 CTI

TAX/08/18/2007

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: PIP % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 63467 Yr Regn: 19 DEC 20Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA MIUV HYBRID C.C. 1,798Colour: BROWN A/C: Insured / Std / NI / N.Sp. Reading: 37,613 T/Radio: Insured / Std / NI / N

Eng/No: _____

C/No: 3TDK83FU403578843Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALCON (CTI) YOKO (R)

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 13/8/18D.O.I. 15/8/18Survey held at SMGT WOODLANDSDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or6/5 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

CP/0 \$1,499.67 / Red \$1,107.67 / (42%)

18.8.18 / 10:35


18.8.18 / 14:35

15.8.18 / 14:35

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6346Y
 Tel No : TAX/08/18/2059
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TAN SIAM CHOON
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 13/08/2018 08:55:00 PM
 Accident Reported Date / Time : 14/08/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Naz
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle Issued? : No
 Accident Repair Job Card No : 000024097546
 Special Instruction to ARC, if any :
 OS/ SJT6620Y - CHINA TAIPING - LKK P/P
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR Muhd Nazril (LKK) & Email sur@lkkatto.com HP:98804220
 Prepared Date : 15/08/2018 10:11:34 AM



Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

Date

15.8.18

2nd witness

Date

Vehicle to Waga Date In: 15/8 Towing:
 Time In: 1800 Driver: Pol.
 Waga Job No: 08/0482
 Vehicle sent to SMRT Date In: 12/08 Towing:
 Time In: 1122 Driver: Hy.
 Received by (SMRT):

E 12 F
 KM 37613
 37648

Qe 17/8/18 13.50 Pass

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No. : JTDKB3FU403578843 Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	600.00
Total Spray Painting Charges	: 1,314.00	700.00
Total Material Charges	: 157.34	99.67
Other Charges	: 460.00	100.00
TOTAL	: 2,607.34	1,499.67
Sum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By		NAZ (LKK)
Arc / Surveyor Sign Off Date	: 15/08/2018 11:44:29 AM	15/08/2018 02:35:44 PM
	M	LKK

Prepared / Adjusted Date :
marks :
Prepared Date : 15/08/2018 11:44:29 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : GN-1208-0450 Invoice No :
Quotation Date : 20/8 Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPAIR RH PORTION	676.00 ✓	600.00
Total Labour	676.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
REPSRAY FRONT BUMPER	378.00 ✓	200.00
RESpray FRONT FENDER RH	378.00 ✓	200.00
RESpray RIM	180.00 ✓	100.00
RESpray FRONT DOOR RH	378.00 ✓	200.00
Total Spray Painting & Panel Beating	1,314.00	700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
CHECK WIRING AND SYSTEM FUNCTION	80.00	50.00
APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00
DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
REPLACE SUNDRY PARTS	100.00	0.00
WASH AND VACUUM	60.00	0.00
Total Other Costs	460.00	100.00

art 4 Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
119479			COVER, FR BUMPER	R ¹	495.50	100.00	0.00	Replace	Repair	No <i>R</i>
115470			SUPPORT, FR BUMPER RH	X ¹	76.90	25.00	57.68	Replace	Check	No <i>Y</i>
801470			FENDER SUB-ASSY, FR, RH	R ¹	933.10	100.00	0.00	Replace	Repair	No <i>R</i>
374471			EMBLEM, SIDE PANEL (HYBRID)	✓ ¹	52.90	25.00	39.67	Replace	Replace	No <i>✓</i>
611450			WHEEL, DISC FRONT	R ¹	1,555.10	100.00	0.00	Replace	Repair	No <i>R</i>
610477 C1			PANEL ASSY, FR DOOR RH	R ¹	725.90	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	✓ ¹	60.00	0.00	60.00	Replace	Replace	No <i>✓</i>
730470			LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	✓ ⁰	162.20	10.00	0.00	Replace	Not given	No <i>X</i>
939473			COVER, OUTER MIRROR HOLE, RH	R ¹	63.80	100.00	0.00	Replace	Repair	No <i>R</i>
910474			MIRROR ASSY, OUTER REAR VIEW, RH	X ⁰	1,373.50	10.00	0.00	Replace	Not given	No <i>X</i>
TOTAL MATERIALS							157.35	99.67		
TOTAL MATERIALS(Discounted)							157.34	99.67		

ded Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

99.67
600
+ 800

1499.67

CONFIRMED PART BY PART REPAIR \$1,499.67/3 DAYS

H
5/9/18

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6346Y
Ref. No : TAX/08/18/2059
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : TAN SIAM CHOON
Type of Accident : SIDE SWIPE
Date / Time of Accident : 13/08/2018 08:55:00 PM
Accident Reported Date / Time : 14/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097546
Special Instruction to ARC, if any :
TOS/ SJT6620Y - CHINA TAIPING - LKK
Prepared Date : 15/08/2018 10:11:34 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403578843

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	1,314.00	0.00
Total Material Charges :	4,369.50	4,369.50
Other Charges :	460.00	0.00
TOTAL :	6,819.50	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00 3.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	15/08/2018 11:44:29 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 15/08/2018 11:44:29 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	676.00	0.00
Total Labour	676.00 600	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00 200	0.00
TO RESPRAY FRONT FENDER RH	378.00 200	0.00
TO RESPRAY RIM	180.00 100	0.00
TO RESPRAY FRONT DOOR RH	378.00 200	0.00
Total Spray Painting & Panel Beating	1,314.00 700	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 50	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 50	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00 50	0.00
TO REPLACE SUNDRY PARTS	100.00 50	0.00
TO WASH AND VACUUM	60.00 50	0.00
Total Other Costs	460.00	0.00

NA2 LKX
15/8/18 1200
PIP
3 days
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No <i>YR</i>
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	No <i>?</i>
5380147080			FENDER SUB-ASSY, FR, RH	1	933.10	25.00	699.82	Replace	Replace	No <i>YR</i>
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No <i>NEC</i>
42611-47450			WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace	No <i>YR</i>
6761047780C1			PANEL ASSY, FR DOOR RH	1	725.90	25.00	544.42	Replace	Replace	No <i>YR</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>NEC</i>
8173047010			LAMP ASSY, SIDE MIRROR TURN SIGNAL, RH	1	162.20	10.00	145.98	Replace	Replace	No <i>X JV</i>
8793947360			COVER, OUTER MIRROR HOLE, RH	1	63.80	25.00	47.85	Replace	Replace	No <i>YR</i>
8791047450			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	10.00	1,236.15	Replace	Replace	No <i>X JV</i>
TOTAL MATERIALS								4,369.53	4,369.50	
TOTAL MATERIALS(Discounted)								4,369.50	4,369.50	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4
Singapore 757705
Tel : 65 6866 2647
Fax : 65 6368 7421
www.smrt.com.sg

China Taiping Insurance (S) Pte Ltd
c/o LKK Auto Consultants Pte Ltd
No. 51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 5 October 2018

Our Ref.: TAX/08/18/2059/LG

Dear Sirs,

**ACCIDENT ON 13/8/2018 INVOLVING SHD 6346Y & SJT 6620Y
ALONG LOWER DELTA RD TOWARDS RIVER VALLEY RD**

LETTER OF CLAIM

We claim on behalf of SMRT Taxis Pte Ltd, the owner and the hirer of taxi no.: SHD 6346Y.
Your insured's negligent driving has caused the above accident. As a result, our clients have
suffered the following losses:-

1. Cost of Repair	:	<u>\$1499.67</u>
2. Loss of Rental for <u>3</u> days @ S\$ <u>123.05</u> /day	:	<u>\$ 369.15</u>
3. Loss of Income for <u>3</u> days @ S\$ <u>60.00</u> /day	:	<u>\$ 180.00</u>
4. Police Report/ SAS Report/ LTA Search Fee	:	<u>\$ 7.00</u>
5. Survey Fee	:	<u>-</u>
Total Claims :		<u>\$2055.82</u>

We enclose the following documents:

<input checked="" type="checkbox"/> Repair Invoice	<input checked="" type="checkbox"/> Letter of Authorisation
<input type="checkbox"/> Survey Report	<input checked="" type="checkbox"/> LTA Search result
<input type="checkbox"/> Photographs _____ pcs	<input checked="" type="checkbox"/> Others :
<input checked="" type="checkbox"/> Investigation results	1. <u>vehicle laid-up report</u>
<input checked="" type="checkbox"/> Proof of Loss of Use/Rental/Income	2. <u>police investigation result</u>
<input checked="" type="checkbox"/> Police / SAS report of <u>SHD 6346Y</u>	3. _____

We look forward to your confirmation to settle our claims within 15 days from the date of this
letter. Payment by cheque shall be crossed and made payable to **SMRT TAXIS PTE LTD**.

Yours sincerely,
SMRT AUTOMOTIVE SERVICES PTE LTD


Tan Lee Gek
For Manager, Claims
Claims Department
DID: 6866 2647
Email: leegek@smrt.com.sg

FR-AS-CLM-02 REV 2



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/08/18/2059

From: SMRT Taxis Pte Ltd

Date: 17/08/2018

**ACCIDENT ON 13/08/2018 INVOLVING SHD 6346Y & SJT 6620Y
ALONG LOWER DELTA ROAD TOWARDS RIVER VALLEY ROAD**

This is to confirm that the daily rental rate for SHD 6346Y is \$123.05 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Accident Vehicle Laid-Up Report

Registration No. : SHD6346Y	Accident Case No. : TAX/08/18/2059
Make / Model : TOYOTA PRIUS GEN4	Ref. No. : 24097546

Date and Time Vehicle off-road for Accident Repair : 15.08.2018 09:55:00

Date and Time Repair Completed : 18.08.2018 08:04:21

Remarks :

Generated by : NGSIUCHING

Printed on : 18.08.2018



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV180900279
Date : 19.09.2018
Vehicle No. : SHD6346Y
Your Ref No. : TAX/08/18/2059
Our Ref No. : 24097546
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
COVER, FR BUMPER	1.00	\$ 495.50	(100.00)	\$ 495.50	\$ 0.00
SUPPORT, FR BUMPER RH	0.00	\$ 76.90	(25.00)	\$ 0.00	\$ 0.00
FENDER SUB-ASSY, FR , RH	1.00	\$ 933.10	(100.00)	\$ 933.10	\$ 0.00
EMBLEM, SIDE PANEL (HYBRID)	1.00	\$ 52.90	(25.00)	\$ 13.22	\$ 39.67
WHEEL, DISC FRONT	1.00	\$1555.10	(100.00)	\$1555.10	\$ 0.00
PANEL ASSY, FR DOOR RH	1.00	\$ 725.90	(100.00)	\$ 725.90	\$ 0.00
STICKER DECAL SMRT (DOOR)	1.00	\$ 60.00	(0.00)	\$ 0.00	\$ 60.00
LAMP ASSY, SIDE MIRROR TURN SIGNAL , RH	0.00	\$ 162.20	(10.00)	\$ 0.00	\$ 0.00
COVER, OUTER MIRROR HOLE , RH	1.00	\$ 63.80	(100.00)	\$ 63.80	\$ 0.00
MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1373.50	(10.00)	\$ 0.00	\$ 0.00
Sub-Total					\$ 99.67
Labour					
TO REPAIR RH PORTION	1.00	\$ 600.00	0.00	\$ 0.00	\$ 600.00
Others					
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT FENDER RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00



Authorised Signature
for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice


GST Reg No. : MR-8500001-7
CRN : 1990042802
Invoice No. : IV180900279
Date : 19.09.2018
Vehicle No. : SHD6346Y
Your Ref No. : TAX/08/18/2059
Our Ref No. : 24097546
Terms : 30 Days

Description	Qty	Unit Cost	Add \$	/ (Discount) Amount	Amount
TO RESPRAY FRONT DOOR RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
GRAND TOTAL					\$ 1,499.67

Remark :

Make/Model : PRIUS4
Accident Date : 13.08.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.


Authorized Signature
for SMRT Automotive Services Pte Ltd



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408855
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/45591/2018
Date : 30 August, 2018

TPX 108/18/2059

TAN SIAM CHOON
APT BLK 29 JALAN BAHAGIA
#05-360
SINGAPORE 320029

Dear Sir/Madam

ACCIDENT INVOLVING SHD6346Y/SJT6620Y ON 13.08.2018 AT 2105 HRS, ALONG LOWER DELTA ROAD

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SJT6620Y has committed an offence of Inconsiderate driving (accident) under Section 65(b) Of The Road Traffic Act Chapter 276, Failing to stop after accident under Section 84(1) Road Traffic Act, Chapter 276. Action has been initiated against the driver for the said offence.

3. If you have any queries, please contact the Investigation Officer, Yus Mastari I Khazali at telephone number 6547 6214.

Yours faithfully


RENEE LOH
FOR HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE



SINGAPORE POLICE FORCE



T/20180813/2205

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180813/2205

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/08/2018 23:40		Vide Report No.: A/20180813/0179		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN SIAM CHOON			Address: APT BLK 29 JLN BAHAGIA #05-360 HDB- KALLANG/WHAMPOA/NOVENA SINGAPORE 320029		
ID Type / ID No.: NRIC NO / S1378234B			Contact No.: Home/Office: Mobile: 81126613		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 19/09/1959	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:			

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 13/08/2018 20:55	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 LOWER DELTA ROAD RIVER VALLEY ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD6346Y	TAXI	TOYOTA				4
SJT6620Y	Car	TOYOTA				0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180813/2205

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180813/2205

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
ZENG ZI CONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
13/08/2018 23:40

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt TAN JEOK LENG
Contact No.: 65476144

Classification Of Case:

Authentication Stamp
NP168



**SINGAPORE
POLICE FORCE**

Signature:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/08/2018 08:59
Date Of Accident	13/08/2018 20:55
Exact Location Of Accident	LOWER DELTA RD TOWARDS RIVER VALLEY RD
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6346Y
Insured/Policyholder	
Name Of Registered Owner	198905369K
Co Reg No	D-18090213MFSH
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN SIAM CHOON
NRIC No	S1378234B
Date Of Birth	19/09/1959
Occupation	OUTDOOR
Date Of Driving Pass	23/10/1979
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **"Purposes"**).
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 30 August, 2018 2:42 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJT6620Y (OI : CAI - SNM18D04051C02) and SHD6346Y (TP : LKK REF - CC3/CTI18015158/Nua3) on 13/08/2018
Attachments: leeSZ_SNM18D04051C01-SJT6620Y-LKKDirectSettlementAccidentLtr_CLCR95.496.pdf; MJAS18107585-SJT6620Y.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 23 August, 2018 2:37 PM
To: Claims Dept of CTI
Cc: Jowyn Tay; Angie Foo; Vivian Lau (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJT6620Y (OI : CAI - TBA) and SHD6346Y (TP : LKK REF - CC3/CTI18015158/Nua3) on 13/08/2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079906

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.ctaiping.com

Co. Reg. No. 200208394E

Our Reference: **SNM18D04051/C01/0**

Date : **30 AUGUST 2018**

via Ordinary & Registered Mail

**GAN AH BAH
BLK 65 MARINE DRIVE
#10-178
SINGAPORE 440065**

Dear Sir / Madam

**ACCIDENT INVOLVING SJT6620Y AND SHD6346Y ON 13 AUGUST 2018
ALONG LOWER DELTA ROAD TOWARDS TIONG BAHRU ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD6346Y**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC3/CTI18015158/NUA3

Contact No : 68412360

via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0589A) - JZ ASSURE PTE LTD

F01/LKKDS-2013



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4
Singapore 757705
Tel : 65 6866 2647
Fax : 65 6368 7421
www.smrt.com.sg

China Taiping Insurance (S) Pte Ltd
c/o LKK Auto Consultants Pte Ltd
No. 51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Date: 5 October 2018

Our Ref.: TAX/08/18/2059/LG

Dear Sirs,

**ACCIDENT ON 13/8/2018 INVOLVING SHD 6346Y & SJT 6620Y
ALONG LOWER DELTA RD TOWARDS RIVER VALLEY RD**

LETTER OF CLAIM

We claim on behalf of SMRT Taxis Pte Ltd, the owner and the hirer of taxi no.: SHD 6346Y.
Your insured's negligent driving has caused the above accident. As a result, our clients have
suffered the following losses:-

1. Cost of Repair	:	<u>\$1499.67</u>
2. Loss of Rental for <u>3</u> days @ S\$ <u>123.05</u> /day	:	<u>\$ 369.15</u>
3. Loss of Income for <u>3</u> days @ S\$ <u>60.00</u> /day	:	<u>\$ 180.00</u>
4. Police Report/ SAS Report/ LTA Search Fee	:	<u>\$ 7.00</u>
5. Survey Fee	:	<u>-</u>
Total Claims :		<u>\$2055.82</u>

We enclose the following documents:

<input checked="" type="checkbox"/> Repair Invoice	<input checked="" type="checkbox"/> Letter of Authorisation
<input type="checkbox"/> Survey Report	<input checked="" type="checkbox"/> LTA Search result
<input type="checkbox"/> Photographs _____ pcs	<input checked="" type="checkbox"/> Others :
<input checked="" type="checkbox"/> Investigation results	1. <u>vehicle laid-up report</u>
<input checked="" type="checkbox"/> Proof of Loss of Use/Rental/Income	2. <u>police investigation result</u>
<input checked="" type="checkbox"/> Police / SAS report of <u>SHD 6346Y</u>	3. _____

We look forward to your confirmation to settle our claims within 15 days from the date of this
letter. Payment by cheque shall be crossed and made payable to **SMRT TAXIS PTE LTD**.

Yours sincerely,
SMRT AUTOMOTIVE SERVICES PTE LTD


Tan Lee Gek
For Manager, Claims
Claims Department
DID: 6866 2647
Email: leegek@smrt.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI18015158/Nka3

13 AUGUST 2019

GAN AH BAH
BLOCK 65 MARINE DRIVE
#10-178
SINGAPORE 440065

Dear Sir/Madam,

ACCIDENT INVOLVING SJT6620Y & SHD6346Y ON 13/08/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 23/8/2019, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA
Case Handler
DID: 6841 2360
FAX: 6741 4108
EMAIL: khanchna@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT

We, **SMRT TAXIS PTE LTD** ("the third party claimant") of **No. 60 Woodlands Industrial Park E4, Singapore 757705** (address), owner of **SHD 6346Y** (vehicle no.) hereby authorize **SMRT Automotive Services Pte Ltd** ("the workshop") to act for us with respect to our claim for repair costs and/or rental and/or loss of use ("claim") for our vehicle no. **SHD 6346Y** was damaged pursuant to the accident which occurred on **13/8/2018** (date) along **Lower Delta towards River Valley Road** (location) involving vehicle no/s. **SJT 6620Y** ("the accident").

I further authorize the workshop to settle the above mentioned claim in a manner as they deem fit and the cheque is to be made in favour of **SMRT TAXIS PTE LTD**.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 19 (day) of Sept (month) 2019 (year)



Signed by "the third party claimant"
(with company stamp if applicable)



Signed by "the workshop"
(with company stamp)



Date: 14/8/2018.

Our Ref. No.:

Letter of Authorisation

I, Tan Siam Choon (Name) (NRIC No.: S1378234-B) the registered hirer / relief driver / contract hirer of SMRT taxi registration number SHD 63464 hereby authorise **SMRT Automotive Services Pte Ltd** ("AutoSvs") to deal with all matters arising out of the accident between my taxi and SJT 66204 happened on 13/8/18 time along Lower Delta Rd (the "Accident") on my behalf, including but not limited to instituting and any claims or proceedings against such party or parties (as AutoSvs deems fit in its absolute discretion) in respect of any claim, demand, loss, cost, expense, liability, damages or action made against us or incurred or suffered by us.

Without prejudice to the foregoing, I further authorise AutoSvs to negotiate, resolve and settle any proceeding or claim arising out of the accidents, including but not limited to doing any act or executing any document or signing the Discharge Voucher on my behalf as may be required.

Name: Tan Siam Choon Signature: 28 2 28
NRIC No.: S1378234-B
Tel No.: 81126613
Address: Blk 29 Jalan Bahagia #05-360
S'pore 320029

Khanchana

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN1620881802 Claim No : SNM18D04051C02

Claimant : SMRT TAXIS PTE LTD

Amount : S\$2,018.00
DOLLARS TWO THOUSAND AND EIGHTEEN ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHD 6346Y
Insured Vehicle No. : SJT 6620Y

Date of Loss : 13/08/2018
Place of Accident : LOWER DELTA ROAD TOWARDS TIONG BAHRU ROAD

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : GAN AH BAH
Driver Name : GAN AH BAH

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 2,018.00
	=====
TOTAL	S\$ 2,018.00
	=====

Claimant Name :  NRIC No : Sxxxx 706F

Signature :  Date : 19 SEP 2019



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV180900279
Date : 19.09.2018
Vehicle No. : SHD6346Y
Your Ref No. : TAX/08/18/2059
Our Ref No. : 24097546
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
Parts					
COVER, FR BUMPER	1.00	\$ 495.50	(100.00)	\$ 495.50	\$ 0.00
SUPPORT, FR BUMPER RH	0.00	\$ 76.90	(25.00)	\$ 0.00	\$ 0.00
FENDER SUB-ASSY, FR , RH	1.00	\$ 933.10	(100.00)	\$ 933.10	\$ 0.00
EMBLEM, SIDE PANEL (HYBRID)	1.00	\$ 52.90	(25.00)	\$ 13.22	\$ 39.67
WHEEL, DISC FRONT	1.00	\$1555.10	(100.00)	\$1555.10	\$ 0.00
PANEL ASSY, FR DOOR RH	1.00	\$ 725.90	(100.00)	\$ 725.90	\$ 0.00
STICKER DECAL SMRT (DOOR)	1.00	\$ 60.00	(0.00)	\$ 0.00	\$ 60.00
LAMP ASSY, SIDE MIRROR TURN SIGNAL , RH	0.00	\$ 162.20	(10.00)	\$ 0.00	\$ 0.00
COVER, OUTER MIRROR HOLE , RH	1.00	\$ 63.80	(100.00)	\$ 63.80	\$ 0.00
MIRROR ASSY, OUTER REAR VIEW , RH	0.00	\$1373.50	(10.00)	\$ 0.00	\$ 0.00
Sub-Total					\$ 99.67
Labour					
TO REPAIR RH PORTION	1.00	\$ 600.00	0.00	\$ 0.00	\$ 600.00
Others					
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	0.00	\$ 120.00	0.00	\$ 0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	0.00	\$ 100.00	0.00	\$ 0.00	\$ 0.00
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$ 0.00	\$ 0.00
TO REPSRAY FRONT BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT FENDER RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	1.00	\$ 100.00	0.00	\$ 0.00	\$ 100.00

Authorised Signature
for SMRT Automotive Services Pte Ltd



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV180900279
Date : 19.09.2018
Vehicle No. : SHD6346Y
Your Ref No. : TAX/08/18/2059
Our Ref No. : 24097546
Terms : 30 Days

Description	Qty	Unit Cost	Add \$	/ (Discount) Amount	Amount
TO RESPRAY FRONT DOOR RH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
GRAND TOTAL					\$ 1,499.67

Remark :

Make/Model : PRIUS4
Accident Date : 13.08.2018

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.



Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/08/18/2059

From: SMRT Taxis Pte Ltd

Date: 17/08/2018

**ACCIDENT ON 13/08/2018 INVOLVING SHD 6346Y & SJT 6620Y
ALONG LOWER DELTA ROAD TOWARDS RIVER VALLEY ROAD**

This is to confirm that the daily rental rate for SHD 6346Y is \$123.05 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Accident Vehicle Laid-Up Report

Registration No. : SHD6346Y

Accident Case No. : TAX/08/18/2059

Make / Model : TOYOTA PRIUS GEN4

Ref. No. : 24097546

Date and Time Vehicle off-road for Accident Repair : 15.08.2018 09:55:00

Date and Time Repair Completed : 18.08.2018 08:04:21

Remarks :

Generated by : NGSIUCHING

Printed on : 18.08.2018

Enquire Transaction History

Log Date/Time:	15 Aug 2018 / 10:05:39	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	SJT6620Y		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ESASBAHO - BALQISH BINTE ABDUL HALIL	Business Transaction Reference No.:	20180815100539582328

Search Date / Time: 13 Aug 2018 20:55:00
Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Information displayed is correct as at the log date and time.

[Enquire Related Logs](#) [Back to List](#)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/45591/2018
Date : 30 August, 2018

TAX 108/18/2059

TAN SIAM CHOON
APT BLK 29 JALAN BAHAGIA
#05-360
SINGAPORE 320029

Dear Sir/Madam

ACCIDENT INVOLVING SHD6346Y/SJT6620Y ON 13.08.2018 AT 2105 HRS, ALONG LOWER DELTA ROAD

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SJT6620Y has committed an offence of Inconsiderate driving (accident) under Section 65(b) Of The Road Traffic Act Chapter 276, Failing to stop after accident under Section 84(1) Road Traffic Act, Chapter 276. Action has been initiated against the driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Yus Mastari I Khazali at telephone number 6547 6214.

Yours faithfully

RENEE LOH
FOR HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18015158/Nka3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-10-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 6620Y	Veh. Inspected	SHD 6346Y
Policy No.	DMPCSN1620881802	Coverage (\$)	0.00
Claim No.	SNM18D04051C02	Excess (\$)	0.00
Assign From		Assign Date	15/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403578843	Colour	BROWN
Odometer	37613	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/08/2018	Inspection Date	15/08/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6346Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.67
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SUPPORT ,FR BUMPER RH	SERVICEABLE	76.90	-
1	LAMP ASSY ,SIDE MIRROR TURN SIGNAL ,RH	SERVICEABLE	162.20	-
1	MIRROR ASSY ,OUTER REAR VIEW,RH	SERVICEABLE	1,373.50	-
1	COVER ,FR BUMPER	TO REPAIR SEE LABOUR	495.50	-
1	FENDER SUB-ASSY ,FR, RH	TO REPAIR SEE LABOUR	933.10	-
1	WHEEL ,DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
1	PANEL ASSY ,FR DOOR RH	TO REPAIR SEE LABOUR	725.90	-
1	COVER ,OUTER MIRROR HOLE ,RH	TO REPAIR SEE LABOUR	63.80	-
			5,498.90	99.67
LABOUR				
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF COVER ,FR BUMPER,FENDER SUB-ASSY ,FR, RH ,WHEEL ,DISC FRONT,PANEL ASSY ,FR DOOR RH AND COVER ,OUTER MIRROR HOLE ,RH .		676.00	600.00
	SPRAY PAINT.		1,314.00	700.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	50.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	50.00
	TO DO WHEEL ALIGNMENT /TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			2,450.00	1,400.00
GRAND TOTAL			7,948.90	1,499.67

Report Ref No. CC3/CTI18015158/Nka3q2



RECOMMENDED COST OF REPAIRS			1,499.67
-----------------------------	--	--	----------

Report Ref No. CC3/CTI18015158/Nka3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.