

Surveyor

REF:

CS3 / ALH18011087 / 1476-1

Special Instruction:

49: \$ 8100.00

Third Parties:

Claimant:

Surveyor:

KTO Automobile

Workshop:

Yeow Koon

ASSIGNMENT (Office)

From (Person): Bennie Tan of ALH Date/Time: 12082018

Estimated Cost: Bill to:

OD/FP Re-inspection / Evaluation

To Inspect Vehicle No: SKS 8000S Insured: SKK 663

at Workshop m/s Yeow Koon Motor Tel: 6785 3286

of Blk 9002 Tampines St 93 # 01-34

Policy No: Claim No: 0056791127SL-003

Sum Insured: Excess:

Make of Veh: D.O.A. 11-06-2018

(Client's Record)

24.08.2018 (Friday) @ 12pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 5 days)

Date/Time: 4/9/18 Submit Final Fig 4650 , 4 days (Red \$ 3450 / 42%; Original 5 days)

Date/Time	Action/Instruction
	SKS 8000S - CS3 / ALH18011087 / U240352
	SKK 663 - X
	DA: 11.06.2018
	RECEIVED 4 SEP 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 4/9/18 File Pass to Typist

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

1) \$ + RS \$

2) Photos

3) Others

TOTAL

John
4/9/2018

Catherine Chong (LKK Auto)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Monday, 13 August, 2018 7:47 AM
To: Tan, Bennie-WZ; Legiste Law Corporation
Cc: CS A Team; assignments; SUR
Subject: RE: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP *LKK REF: CS3/AIG18011087/Uz4d3s2

Hi Bennie,

Thank you for your email.

By copy to Assign Team,

Kindly assist. CS3/AIG18011087/Uz4d3s2

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Sunday, 12 August 2018 10:22 PM
To: Legiste Law Corporation <advocates@legiste.com.sg>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP

Your Ref: FMC.11957.18.45.GP

Our Ref: 0056791127SG-003

WITHOUT PREJUDICE

Dear Sir / Mdm

We refer to the above matter.

We will like to conduct physical re-inspection in view of the high cost of repair to your client's vehicle.

Kindly liaise with our appointed surveyor, LKK as soon as possible.

Per our email dated 29/06/2018, please forward us the following documents for our consideration:-

1. Coloured Accident Scene Photos
2. Video Footage (Per stated in your client's report)
3. Any Other Supporting Documents

We hereby reserve our rights to re-inspect your client's vehicle After Repair

Please quote our above Ref no in any of our future correspondence(s).

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Catherine Chong (LKK Auto)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Monday, 20 August, 2018 2:00 PM
To: Legiste Law Corporation; assignments
Cc: Tan, Bennie-WZ (Bennie-WZ.Tan@aig.com); SUR
Subject: FW: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP *LKK REF: CS3/AIG18011087/Uz4d3s2
Attachments: FMC11957-LKK_20180820134338.pdf
Importance: High

Without Prejudice

Hi Gina,

Thank you for your email.

We will arrange accordingly.

Hi Assign Team,

Kindly assist to arrange RI.

24-08-2018 - RI

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Legiste Law Corporation <advocates@legiste.com.sg>
Sent: Monday, 20 August 2018 1:54 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Bennie-WZ.Tan@aig.com
Subject: RE: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP *LKK REF: CS3/AIG18011087/Uz4d3s2
Importance: High

Dear Mdm

Please see attached.

Gina Pat
(secretary)
M/s Legiste Law Corporation
Tel: 6227 9909
Fax: 6227 2767

Legiste Law Corporation

ADVOCATES & SOLICITORS
NOTARIES PUBLIC
COMMISSIONERS FOR OATHS
INCORPORATED WITH LIMITED LIABILITY
Co. Regn. No. 200305183Z

24 Peck Seah Street
#04 - 06, Nehsons Building
Singapore 079314
Telephone +65-62279909 Facsimile +65-62272767
E-mail advocates@legiste.com.sg

FOK MUN CHEONG
TAN KIM KEE
NG LAI LENG

Your Ref CS3/AIG18011087/Uz4d3s2
Email chewht@lkkauto.com
Our Ref FMC.11957.18.45.GP

20th August 2018

URGENT

LKK Auto Consultants Pte Ltd
Block 51 Paya Ubi Industrial Park
Ubi Avenue 1 #02 - 25
Singapore 408933
Attn: Ms Chew Hsiao Tong

BY EMAIL ONLY

Dear Sirs

**ACCIDENT ON 11.06.18 INVOLVING SKS 8000S & SCK 66S
AT / ALONG RAFFLES AVENUE
CLAIMANTS: EXCLUSIVE LIMO & CAR RENTALS (Singapore UEN No. 52963858D)
ADDRESS: 30 RAFFLES PLACE #23 - 00 CALTEX HOUSE SINGAPORE 048622**


We refer to your email dated 13th August 2018, copy attached for your easy reference.

We have been informed by our clients that their motor-vehicle no. SKS 8000S will be available for your re-inspection either on 21st, 22nd or 24th August 2018 at 12pm at their appointed workshop particularized as follows:

Name	:	Yeow Koon Motor Spray Painting
Address	:	9002 Tampines Street 93 #01-34 Tampines Industrial Park A Singapore 528836
Contact Person	:	Mr Goh Beng Tee
Tel	:	6785 3286

Kindly revert.

Yours faithfully


Joseph Fok Mun Cheong
Legiste Law Corporation

enc
cc

AIG Asia Pacific Insurance Pte Ltd
Attn: Mr Bennie Tan
Ref: 0056791127SG-003
By Email (Bennie-WZ.Tan@aig.com) Only

Clients

Legiste Law Corporation

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Monday, 13 August 2018 7:47 AM
To: Tan, Bennie-WZ; Legiste Law Corporation
Cc: CS A Team; assignments; SUR
Subject: RE: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP *LKK REF: CS3/AIG18011087/Uz4d3s2

Hi Bennie,

Thank you for your email.

By copy to Assign Team,

Kindly assist. CS3/AIG18011087/Uz4d3s2

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Sunday, 12 August 2018 10:22 PM
To: Legiste Law Corporation <advocates@legiste.com.sg>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Our Ref: 0056791127SG-003 || Your Ref: FMC.11957.18.45.GP

Your Ref: FMC.11957.18.45.GP

Our Ref: 0056791127SG-003

WITHOUT PREJUDICE

Dear Sir / Mdm

We refer to the above matter.

We will like to conduct physical re-inspection in view of the high cost of repair to your client's vehicle.



















front bumper	Dis
front bumper side holder nls	cracked
set front bumper clips	rec
front bumper towing cover	mis
front bumper sensor nls	shorted
front bumper reinforcement	best
front bumper sponge	Torn
front bumper fog lamp nls	cracked
headlamp nls	cracked
headlamp outer garnish nls	cracked
front support panel	Repair
wiper washer tank	deformed
fog lamp chrome nls	grazed
front grille	SVC
front fender nls	Repair

4dy.

Claim Documents

*SKS8000S (0056791127SG)
[SCK66S]
TP

Jun 11 2018 12:00AM
[CHIN CHOY NGAI CHARLES]
Yeow Koon Motor Spray Painting

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/06/18 20:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	21/06/18 20:03	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	21/06/18 20:03	Dismantled Parts		Load JPG ✓
37	21/06/18 20:03	Dismantled Parts		Load JPG ✓
38	21/06/18 20:03	Dismantled Parts		Load JPG ✓
39	21/06/18 20:03	Dismantled Parts		Load JPG ✓
40	21/06/18 20:03	Dismantled Parts		Load JPG ✓
41	21/06/18 20:03	Dismantled Parts		Load JPG ✓
42	21/06/18 20:03	Dismantled Parts		Load JPG ✓
43	21/06/18 20:03	Dismantled Parts		Load JPG ✓
44	21/06/18 20:03	Dismantled Parts		Load JPG ✓
45	21/06/18 20:03	Dismantled Parts		Load JPG ✓
46	21/06/18 20:03	Dismantled Parts		Load JPG ✓
47	21/06/18 20:03	Dismantled Parts		Load JPG ✓
48	21/06/18 20:03	Dismantled Parts		Load JPG ✓
49	21/06/18 20:03	Dismantled Parts		Load JPG ✓
50	21/06/18 20:03	Dismantled Parts		Load JPG ✓
51	23/06/18 10:19	Reinspection Photo		Load JPG ✓
52	23/06/18 10:19	Reinspection Photo		Load JPG ✓
53	23/06/18 10:19	Reinspection Photo		Load JPG ✓
54	23/06/18 10:19	Reinspection Photo		Load JPG ✓
55	23/06/18 10:19	Reinspection Photo		Load JPG ✓
56	23/06/18 10:19	Reinspection Photo		Load JPG ✓
57	23/06/18 10:19	Reinspection Photo		Load JPG ✓
58	23/06/18 10:19	Reinspection Photo		Load JPG ✓
59	23/06/18 10:19	Reinspection Photo		Load JPG ✓
60	23/06/18 10:19	Reinspection Photo		Load JPG ✓
61	23/06/18 10:19	Reinspection Photo		Load JPG ✓
62	23/06/18 10:19	Reinspection Photo		Load JPG ✓
63	23/06/18 10:19	Reinspection Photo		Load JPG ✓
64	23/06/18 10:19	Reinspection Photo		Load JPG ✓
Documentation			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/06/18 10:30	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011087/UZ4D3S2
Date: 23/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100501971
Claimant Vehicle No: SKS8000S Insured Vehicle No: SCK66S
Date of Loss: 11/06/2018 Nature of Claim: TP Claim No: 0056791127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS8000S
Make & Model: TOYOTA VELLFIRE, 2.4 V (A) Engine No: HIDDEN
Reg. Date: 01/01/1990 (Man. Year: 1990) Chassis No: ANH208329487
Colour: Black Odometer: 209594 km
Engine Capacity: 2362 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/06/2018
Date Inspected: 20/06/2018 Inspected At: Yeow Koon Motor Spray Painting (HQ)
BLK 9002 TAMPINES ST 93 #01-34 TAMPINES IND
PARK A
Singapore 528836
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER /	Distorted	0.00 F	*- F
2	1		*FRONT BUMPER SIDE HOLDER N/S /	Cracked	0.00 F	*- F
3	1		*SET FRONT BUMPER CLIPS /	Necessary	0.00 F	*- F
4	1		*FRONT BUMPER TOWING COVER /	Missing	0.00 F	*- F
5	1		*FRONT BUMPER SENSOR N/S /	Shorted	0.00 F	*- F
6	1		*FRONT BUMPER REINFORCEMENT /	Bent	0.00 F	*- F
7	1		*FRONT BUMPER SPONGE /	Torn	0.00 F	*- F
8	1		*FRONT BUMPER FOG LAMP N/S /	Cracked	0.00 F	*- F
9	1		*HEADLAMP N/S /	Cracked	0.00 F	*- F
10	1		*HEADLAMP OUTER GARNISH N/S /	Cracked	0.00 F	*- F
11	1		*FRONT SUPPORT PANEL X	Repair	0.00 F	*- F
12	1		*WIPER WASHER TANK /	Deformed	0.00 F	*- F
13	1		*FOG LAMP CHROME N/S /	Grazed	0.00 F	*- F
14	1		*FRONT GRILLE X	Serviceable	0.00 F	*- F
15	1		*FRONT FENDER N/S X	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2018 09:04
Date Of Accident	11/06/2018 18:15
Exact Location Of Accident	RAFFLES AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS8000S
Insured/Policyholder	
Name Of Registered Owner	EXCLUSIVE LIMO & CAR RENTALS
Co Reg No	52963858D
Email Address	JOHNNY@EXCLUSIVELIMO.COM.SG
Mobile Phone No	(LOCAL) +65-91018983
Alternative Phone No	OFFICE-91018983

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLIRE
Exact Purpose for which vehicle was being used at time of accident	CHAUFFEURING SERVICE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5073047127-02
Cover Note Number	CLASSIC

Driver

Name of Driver	WAN KAI YIN, JEREMY
NRIC No	S7930728I
Date Of Birth	03/10/1979
Occupation	INDOOR
Date Of Driving Pass	20/11/2000
Driving Experience	17 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86618000
Fax Number	
Contact Number	
EEmail Address	JWANS@GMAIL.COM

Address	BLK 505 TAMPINES CENTRAL 1 #03-341
Postcode	520505
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Sketch Plan.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCK66S
Vehicle Make/Model/Colour	MERCEDES BENZ GLC250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHIN CHOY NGAI CHARLES
NRIC/Passport Number	S1163182G
Contact Number	UNKNOWN
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Vehicle No: 5K55005

Report Date & Start Time: 12/06/18 9:25

Report No: MT

D.O.A: 11/06/2018

Time: 18:13 hrs

Make/Model: TOYOTA Yaris FIRE

Reporting Type: TP

End Time:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



12/06/18 9:25

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


12/06/18 9:25

Thomas Chen (S098390)
Customer Care Executive
Motor Service Center

Witnessed by Reporting Centre Personnel

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I had came out from Mandarin Oriental and while I was driving straight in my lane, Vehicle B suddenly encroached into my lane and side swiped the front left of my car.

Declaration

(We declare the foregoing particulars are true in every respect)

 
 5/12/2018 9:35
 Policyholder's Signature, Date & Time


 5/12/2018 9:35
 Driver's Signature (if driver is not the policyholder) / Date & Time


 Tharun Chinn (S095890)
 Customer Care Executive
 Motor Service Centre
 Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2018 13:20
Date Of Accident	11/06/2018 18:15
Exact Location Of Accident	RAFFLES AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCK66S
Insured/Policyholder	
Name Of Registered Owner	CHIN CHOY NGAI CHARLES
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	GLC250
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100501971-01
Cover Note Number	

Driver

Name of Driver	CHIN CHOY NGAI CHARLES
NRIC No	S1163182G
Address	12 JALAN JINTONG

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

ON 11 JUNE 2018 AT ABOUT 6.15PM, I WAS DRIVING ALONG THE INNERMOST LANE OF RAFFLES AVENUE IN DIRECTION OF MANDARIN ORIENTAL HOTEL. I NOTICED A BLACK MPV WAS TAXING TO TURN OUT OF HOTEL SIDE-ROAD TO MY PATH. AS I WAS ABOUT TO PASS THE MPV, IT SUDDENLY DUCKED OUT TO TURN RIGHT AND CLIPPED MY CAR RIGHT REAR TYRE AND BACK BUMPER, CAUSING AN IMPACTFUL DENT TO MY VEHICLE. THE MPV HAD DENT ON ITS FRONT LEFT BUMPER. THE DRIVER OF MPV (MR WANKAI YIN JEREMY, S7930728I) OFFERED TO SETTLE PRIVATELY WHICH I DECLINED. IN CONCLUSION, MR WAN SHOULD STOP AT THE SIDE-ROAD JUNCTION BEFORE TURNING RIGHT TO MAIN ROAD OF RAFFLES AVENUE.

Attachment(s)

Are accident photos available for attachment?	YES
-----------------------------------------------	-----