

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18015190/U240302

Special Instruction:

Survivor:

Marcus

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIA

Date/Time:

21/8/18 @ 9:33am

Estimated Cost:

Bill to:

OD / ☒ TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLB 7428B

Insured:

SLW 6483L

at Workshop m/s

Khek Joo Motor

Tel:

96166658 / 678554258

of

Blk 9004 Tampines 87 93#01-94

Policy No:

29089136MCY

Claim No:

567782

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/08/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:42am 21/8/18

Person Contacted:

Mr. Ng

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLB 7428B - X

SLW 6483L - X

(08/11/13) wef

ASS. REC. BY: morcuREF: MSIG

ASSIGNMENT

From: _____ Date: 21/8/2018

Estimated Cost: _____

On TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: S1B 7428Bat Workshop m/s Khek Joo Motorof 81K 9004 - tamping 81-93 # 01-94

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

SIA / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS WpMA 45954

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S1B 7428B Yr Regn: 6111Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMW 523i c.c. 2497Colour: shw A/C: Insured / Std / NI / NASp. Reading: 160673 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAFP 32070C 866195Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55-R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/8/18D.O.I. 21/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No settling. PRS</u>
	<u>2-3/c.</u>
<u>24/8/18</u>	<u>submit PRS report.</u>

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

120

Transportation:

____ S + RS, ____ SI

Photos

Others

10

TOTAL

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		21 Aug 2018 09:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BORNEO MOTORS (SINGAPORE) PTE LTD , Co. Reg. No.: 196700086Z			
Main Claimant:	HOO SIO FOOI , ID: S7871269D			
Vehicle Reg. No.:	SLB7428B	Date of Loss:	18/08/2018 00:00 - :59 [85 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 567782	Policy/Cover Note No.:	29089136MCY (Comprehensive) Coverage: 01/07/2018 - 30/06/2019	
Vehicle Reg. No. (Insured):	SLW6483L	Policy No. (Claimant):		
		Excess:		
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/08/2018]			
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Insured non-reporting Contact : Mr Ng Wee Khiang @ 9616 6658			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015190/Uz4d3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-08-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLW 6483L	Veh. Inspected	SLB 7428B	
Policy No.	29089136MCY	Coverage (\$)	0.00	
Claim No.	567782	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/08/2018	Inspection Date	21/08/2018	
Survey held at	KHEK JOO MOTOR WORKSHOP BLK 9004 TAMPINES IND. PARK 1 #01-94 SINGAPORE 528836			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 10:53
Date Of Accident	18/08/2018 15:50
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT BEFORE EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB7428B
Insured/Policyholder	
Name Of Registered Owner	HOO SIO FOOI
NRIC No	S7871269D
Email Address	GLENNLHL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92708298
Alternative Phone No	OFFICE-92708298

Vehicle Particulars

Manufacturer	BMW
Model	523I-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80435798QMX
Cover Note Number	

Driver

Name of Driver	LIM HOCK LIN
NRIC No	S7935824Z
Date Of Birth	13/11/1979
Occupation	INDOOR
Date Of Driving Pass	02/12/1998
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97807049
Fax Number	
Contact Number	
EMail Address	GLENNLHL@GMAIL.COM

Address	28 FLORA DRIVE #01-53
Postcode	506951
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HOO SIO FOOI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW6483L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SW 64832

ON 18/8/18, WHILE DRIVING ALONG PIE TOWARDS CHANGI AIRPORT, A
VEHICLE ~~HIT ME~~ SLW 6483L (DRIVER: JING HUI S9126277J) HIT
MY VEHICLE SLB 7428B (DRIVER: LIM HOOR L2N S7935824Z) FROM BEHIND.
THE LOCATION IS BEFORE FUNDS EXIT NEAR LAMPPOST 437/18A @ ISSOHR.
TRAFFIC WAS SLOW MOVING AT THAT TIME, I WAS WITH MY WIFE
IN THE CAR DURING THE ACCIDENT, NO BODY WAS INJURED, NOT RAINING.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1269D
Vehicle Details	
Vehicle No.:	SLB7428B
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	08977745N52B25AF
Chassis No.:	WBAFP32070C866195
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$44,497.00
Original Registration Date:	28 Jun 2011
First Registration Date:	28 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$44,497.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2021
PARF Rebate Amount:	\$26,698.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$19,256.00
Total Rebate Amount:	\$45,954.00

The information contained herein is correct as at 23 Aug 2018

OK






































...CLAIM SUBFOLDER...(Pending for Survey Report)








































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2018		21 Aug 2018 09:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BORNEO MOTORS (SINGAPORE) PTE LTD , Co. Reg. No.: 196700086Z								
Main Claimant:	HOO SIO FOOI , ID: S7871269D								
Vehicle Reg. No.:	SLB7428B	Date of Loss:	18/08/2018 00:00 - :59 [85 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 567782	Policy/Cover Note No.:	29089136MCY (Comprehensive) Coverage: 01/07/2018 - 30/06/2019						
Vehicle Reg. No. (Insured):	SLW6483L	Policy No. (Claimant):							
		Excess:							
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 22/08/2018]								
Adj Asg. Remarks:	Third Party Pre-Repair Survey. Insured non-reporting Contact : Mr Ng Wee Khiang @ 9616 6658								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB7428B (567782)**
[SLW6483L]
TP
HOO SIO FOOI
Aug 18 2018 12:00AM
[BORNEO MOTORS (SINGAPORE) PTE LTD]
Khek Joo Motor Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/08/18 09:31	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	22/08/18 09:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
57	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
58	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
59	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
60	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
61	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
62	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
63	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
64	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
65	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
66	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
67	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
68	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
69	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
70	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
71	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
72	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
73	22/08/18 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/18 17:15	TP PRI	 Load PDF	
2	20/08/18 17:15	E-FILE REPORT (SLB7428B)	 Load PDF	
3	20/08/18 17:58	TP LIST OF SJE & OUR REJECTION REPLY & NOMINATED LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015190/UZ4D3E2

Date: 27/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29089136MCY

Claimant Vehicle No : SLB7428B

Insured Vehicle No : SLW6483L

Date of Loss: 18/08/2018

Nature of Claim: TP

Claim No: 567782

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB7428B**

Make & Model: BMW 523i, 2.5 (A)

Reg. Date: 28/06/2011 (Man. Year: 2011)

Colour: Silver

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 08977745N52B25AF

Chassis No: WBAFP32070C866195

Odometer: 160673 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/08/2018

Date Inspected: 21/08/2018 Inspected At:

Khek Joo Motor Workshop (HQ)
BLK 9004 TAMPINES STREET 93 #01-94
Singapore 528838

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts:	143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7428B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >