

ASS. REC. BY:

REF:

CS/FC118015194/Krbn2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

W9 Eileen Lee

of

FCI

Date/Time: 21082018 1053am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 1173

Insured:

SHC 2248D

at Workshop m/s

K. Kim Hin

Tel:

64527018

of

160 Sin Ming Driv # 02-20

Policy No:

Claim No:

D18006221MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

21082018 11-47am

Person Contacted:

Shumun

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GX 1173 - X

SHC 2248D - NS/INC15014529 / Hlvbn2

DUP: 220315

ASS. REC. BY:

REF: 1021

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 84k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 8/18

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GX 127JYr Regn: 01, 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: NIS Cobstarc.c 3153Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading 268420

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JN1SF 4123 Z 0851634Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NIS / Rim / STD A/Rim orTyre Size: F: 195R15 X 8R: 155R12 X 8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. 9 mm

Rear

R/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 17/8/18D.O.I. 21/8/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/8

File pass to Catherine

18/10/18

Kenneth continued LR &amp; 2650 with Simon. (Red 3872.90, 592)

MV: 84k, LTA: 8761.00, NV: 8 3239.00

RECEIVED 22 OCT 2018

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2) \_\_\_\_\_



: Prell. Report



: Final Report

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐

: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Fixtures

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 2650)145505017262

**MOTOR SURVEY ASSIGNMENT**

|                           |                                                             |                                    |
|---------------------------|-------------------------------------------------------------|------------------------------------|
| <b>Date</b>               | 20-08-2018                                                  | <b>Our Ref No.</b> D18006221MFSH   |
| <b>Accident Date</b>      | 17-08-2018                                                  | <b>Claim Type.</b> Third Party     |
| <b>Insured Vehicle</b>    | SHC2248D                                                    | <b>Third Party Vehicle.</b> GX127J |
| <b>Survey Location</b>    | 160 Sin Ming Drive #02-20SIN MING AUTOCITY                  |                                    |
| <b>Contact Person.</b>    | SHUMAN                                                      |                                    |
| <b>Contact No.</b>        | 64527018/ 96222116                                          | <b>Fax No.</b> 64583895            |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                    |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                    |
| <b>Contact Person</b>     | NA                                                          | <b>Fax No.</b> 68416315            |
| <b>Contact Number.</b>    | NA                                                          |                                    |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                         |                                |
|--------------------------|-------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | K. KIM HIN AUTO PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                      | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | EILEEN LEE              |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                              |                         |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                             |                         |
| Owner ID Type:                                                                                                                                               | Company                 |
| Owner ID:                                                                                                                                                    | 0321D                   |
| <b>Vehicle Details</b>                                                                                                                                       |                         |
| Vehicle No.:                                                                                                                                                 | GX127J                  |
| Vehicle to be Exported:                                                                                                                                      | No                      |
| Intended De-registration Date:                                                                                                                               | 17 Aug 2018             |
| Vehicle Make:                                                                                                                                                | NISSAN                  |
| Vehicle Model:                                                                                                                                               | CABSTAR                 |
| Primary Colour:                                                                                                                                              | Silver                  |
| Manufacturing Year:                                                                                                                                          | 2003                    |
| Engine No.:                                                                                                                                                  | QD32185874              |
| Chassis No.:                                                                                                                                                 | JN1SF4F23Z0851634       |
| Maximum Power Output:                                                                                                                                        | -                       |
| Open Market Value:                                                                                                                                           | \$21,153.00             |
| Original Registration Date:                                                                                                                                  | 06 Jan 2004             |
| First Registration Date:                                                                                                                                     | 06 Jan 2004             |
| Transfer Count:                                                                                                                                              | 1                       |
| Actual ARF Paid:                                                                                                                                             | \$1,058.00              |
| <b>Intended PARF Rebate Details</b>                                                                                                                          |                         |
| PARF Eligibility:                                                                                                                                            | No                      |
| PARF Eligibility Expiry Date:                                                                                                                                | -                       |
| PARF Rebate Amount:                                                                                                                                          | \$0.00                  |
| <b>Intended COE Rebate Details</b>                                                                                                                           |                         |
| COE Expiry Date:                                                                                                                                             | 30 Sep 2018             |
| COE Category:                                                                                                                                                | C - Goods Vehicle & Bus |
| COE Period(Years):                                                                                                                                           | 5                       |
| PQP Paid:                                                                                                                                                    | \$31,858.00             |
| COE Rebate Amount:                                                                                                                                           | \$761.00                |
| <b>Total Rebate Amount:</b>                                                                                                                                  | <b>\$761.00</b>         |
| <b>Message</b>                                                                                                                                               |                         |
| Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle. |                         |

The information contained herein is correct as at 17 Aug 2018

OK

## Date:

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 29974

Date : 20-Aug-2018

PAGE : 1

Vehicle Insured : SHC 2248 D  
Accident Date : 17-Aug-2018

Our Ref : 180527 (FIRST) / SHUMAN

RICHARDS CAR RENTAL PTE LTD  
Singapore

ESTIMATED COST OF REPAIR FOR NISSAN CABSTAR 3153cc (2004) GX127J

|                                            |             |          |   |
|--------------------------------------------|-------------|----------|---|
| 1 pc rear number plate lamp                | 71.30       | n        | X |
| 2 pcs tail lamp assy (lh/rh) <i>niscnt</i> | @ S\$148.70 | 297.40   | n |
| 2 pcs tail lamp bracket (lh/rh)            | @ S\$ 56.30 | 112.60   | n |
| 1 pc tailgate                              | 1,399.70    |          | n |
|                                            |             | 1,881.00 |   |
|                                            | Less 10% :  | -188.10  |   |
|                                            |             | 1,692.90 |   |

1 pc rear number plate  
1 pc reverse sensor (set)  
1 pc tailgate stainless steel panel  
1 pc tailgate "13"pax sticker  
1 pc tailgate "70km/hr" sticker

|          |    |      |
|----------|----|------|
| 40.00    | sn | 20sn |
| 220.00   | sn | 20sn |
| 3,500.00 | sn | 40sn |
| 25.00    | sn | 15sn |
| 25.00    | sn | 15sn |

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

To remove and refit reverse sensor assy.

To putty and respray on affected portions.

To focus taillamps. To check rear wiring and lighting operation.

1604.70

10%

1444.23 (s/parts)

1050 (s/s items)

830 (Labour)

\$3324.23

20%

\$2659.44

Total : S\$ 6,522.90

Singapore Dollars Six Thousand Five Hundred and Twenty Two and Cents Ninety Only

Lumpsum \$2650/- ✓

Note: Amount quoted above is subject to prevailing

**LIK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile      |                              |                 |                            |                                                                                     |
|------------------------------------------------------------------------|------------------------------|-----------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                            |                              |                 | Ref : CS/FCI18015194/Krbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                  |                              |                 | Date : 25-10-2018          |  |
|                                                                        |                              |                 | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                      |                              |                 |                            |                                                                                     |
| Insured Veh.                                                           | SHC 2248D                    | Veh. Inspected  | GX 127J                    |                                                                                     |
| Policy No.                                                             |                              | Coverage (\$)   | 0.00                       |                                                                                     |
| Claim No.                                                              | D18006221MFSH                | Excess (\$)     | 0.00                       |                                                                                     |
| Assign From                                                            | EILEEN                       | Assign Date     | 21/08/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                          |                              |                 |                            |                                                                                     |
| Make & Model                                                           | NISSAN CABSTAR               | c.c             | 3153                       |                                                                                     |
| Engine No.                                                             | HIDDEN                       | Year of Reg.    | 2004                       |                                                                                     |
| Chassis No.                                                            | JN1SF4F23Z0851634            | Colour          | SILVER                     |                                                                                     |
| Odometer                                                               | 268420                       | Steering        | IN ORDER                   |                                                                                     |
| Brakes                                                                 | IN ORDER                     | Modification    | NIL                        |                                                                                     |
| General                                                                | GOOD                         |                 |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                          |                              |                 |                            |                                                                                     |
|                                                                        | Size                         | Make            | Balance                    |                                                                                     |
| R/H Front Tyre                                                         | 195 R15X8                    | MICHELIN        | 9 mm                       |                                                                                     |
| L/H Front Tyre                                                         | 195 R15X8                    | MICHELIN        | 9 mm                       |                                                                                     |
| R/H Rear Tyre                                                          | 155 R12X8 (D)                | MICHELIN        | 9/9 mm                     |                                                                                     |
| L/H Rear Tyre                                                          | 155 R12X8 (D)                | MICHELIN        | 9/9 mm                     |                                                                                     |
| <b>4. Description of Damages</b>                                       |                              |                 |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                     |                              |                 |                            |                                                                                     |
| DAMAGES SEE DETAILS.                                                   |                              |                 |                            |                                                                                     |
| <b>5. General Information</b>                                          |                              |                 |                            |                                                                                     |
| Accident Date                                                          | 17/08/2018                   | Inspection Date | 21/08/2018                 |                                                                                     |
| Survey held at                                                         | 160 SIN MING DRIVE #02-20    |                 |                            |                                                                                     |
| Repairer                                                               | K KIM HIN AUTOMOTIVE PTE LTD |                 |                            |                                                                                     |
| <b>5a. Remarks</b>                                                     |                              |                 |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.                              |                              |                 |                            |                                                                                     |
| B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.        |                              |                 |                            |                                                                                     |
| C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                              |                 |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                     |                              |                 |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                    |                              |                 | <b>4 Working Days</b>      |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 127J**

| Qty                                                                         | Description of Parts                                                                           | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                                                                                                |             |                           |                   |
| 1                                                                           | REAR NUMBER PLATE LAMP (N)                                                                     | SERVICEABLE | 71.30                     | -                 |
| 2                                                                           | TAIL LAMP ASSY (LH/RH) @\$148.70 (N)                                                           | N/S CRACKED | 297.40                    | 148.70            |
| 2                                                                           | TAIL LAMP BRACKET (LH/RH) @\$56.30 (N)                                                         | N/S BENT    | 112.60                    | 56.30             |
| 1                                                                           | TAILGATE (N)                                                                                   | BENT        | 1,399.70                  | 1,399.70          |
|                                                                             | LESS 10% DISCOUNT                                                                              |             | -188.10                   | -160.47           |
|                                                                             |                                                                                                |             | 1,692.90                  | 1,444.23          |
| <b>SPECIAL NETT ITEMS</b>                                                   |                                                                                                |             |                           |                   |
| 1                                                                           | REAR NUMBER PLATE (SN)                                                                         | BENT        | 40.00                     | 20.00             |
| 1                                                                           | SET REVERSE SENSOR (SN)                                                                        | SHORTED     | 220.00                    | 200.00            |
| 1                                                                           | TAILGATE STAINLESS STEEL PANEL (LOCAL REPAIR) (SN)                                             | DENTED      | 3,500.00                  | 800.00            |
| 1                                                                           | TAILGATE "13" PAX STICKER (SN)                                                                 | NECESSARY   | 25.00                     | 15.00             |
| 1                                                                           | TAILGATE "70KM/HR" STICKER (SN)                                                                | NECESSARY   | 25.00                     | 15.00             |
|                                                                             |                                                                                                |             | 3,810.00                  | 1,050.00          |
| <b>LABOUR</b>                                                               |                                                                                                |             |                           |                   |
|                                                                             | TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS. |             | 400.00                    | 360.00            |
|                                                                             | TO REMOVE AND REFIT REVERSE SENSOR ASSY.                                                       |             | 80.00                     | 50.00             |
|                                                                             | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.                                                     |             | 500.00                    | 400.00            |
|                                                                             | TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.                                |             | 40.00                     | 20.00             |
|                                                                             |                                                                                                |             | 1,020.00                  | 830.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                                                |             | <b>6,522.90</b>           | <b>3,324.23</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                |             |                           | <b>2,650.00</b>   |

Report Ref No. CS/FCI18015194/Krbn2

MARKET VALUE: \$4,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$761.00=NETT VALUE: \$3,239.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.