

ASS. REC. BY:

REF: CS3/FCI18014388/G.R.D.3/1

Special Instruction:

Surveyor:

From (Person):

ASSIGNMENT (Office)

of FCI

Date/Time:

21/8/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

3JT 5004H

Insured:

3HB 2998C

at Workshop n/s:

Asia Motorsports

Tel:

67453811

of

568 Geylang Road

Policy No:

Claim No:

D1800 59 23MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/8/2018

Insp: 16 Puki Bkt Rd 4 #01-53

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement

Date/Time:

3:05pm 7/8/18

Person Contacted:

Mr. Joo

Vehicle:

IN/OUT

Date/Time:

Action/Instruction (X) Estimate

3JT 5004H - X

3HB 2998C - CS/FCI16023231/b

NOA: 27/11/2016

8/8/18

Diminished

22/8

Received estimate.

27/8 4.10 pm

- Fax mark estimate to repairer.

30/8/18

Simon confirm with repair the repair cost.

31/8/18

Confirm L/s \$7200 @ 8 days.

Red: \$12301.40, 64%.



30/8/2018

RECEIVED 31 AUG 2018

AND.

REF: Fci

c8688m

ASSIGNMENT

(2019)

15 Oct 2009

From: Date:

Estimated Cost:

DE ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop in/s of: Asi a motorsparts

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

\$24K.

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

07/8 Estimate Given later.

Notes Submit PLS Report.

Veh No:

ST T5004H

Vs Reg:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota wish

cc 1797

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp Reading:

146442

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

8GE 2000c 9661

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/50 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Linglong

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I

07-08-18

Survey held at:

w/s

3:45pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation

Report Format:

Lump Sum / I.B.I. (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

) S + RS + SI

) Prelim

) Other

)

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 14:57
Date Of Accident	06/08/2018 10:20
Exact Location Of Accident	TAMPINES AVENUE 2 / TAMPINES STREET 23
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT5004H
Insured/Policyholder	
Name Of Registered Owner	MAGNIFICENT CARS PTE LTD
Co Reg No	201728688M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98751683
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096017145 CLASSIC
Cover Note Number	
Driver	
Name of Driver	SI HAN KEONG ANDY
NRIC No	S7408635G
Date Of Birth	21/03/1974
Occupation	OUTDOOR
Date Of Driving Pass	22/06/2000
Driving Experience	18 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98751683
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 180B RIVERVALE CRESCENT #13-365
 Postcode 542180
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : POK LLEE LIN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB2998C
 Vehicle Make/Model/Colour HYUNDAI SONATA NF 2.0 CRDI
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver GOH AH CHWEE
 NRIC/Passport Number S1316459B
 Contact Number 81289934
 Address
 Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SI HAN KEONG ANDY
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJT5004H
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name POK LLEE LIN (PASSENGER)
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJT5004H
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: trackb@singnet.com.sg
Name:
NRIC/FIN No.:

- 6 AUG 2018

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



Refer to
Police Report

DECLARATION
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- 6 AUG 2018

IDAG KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933

Tel: 67416697 Fax: 67492305


Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #3



6/8/2018
10:20 AM

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180806/2095

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 4

Report No. T/20180806/2095

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/08/2018 14:30		Vide Report No.:	Station Diary No.: 23
Informant's Particulars			
Name of Informant: SI HAN KEONG ANDY		Address: APT BLK 180B RIVERVALE CRESCENT #13-365 SINGAPORE 542180	
ID Type / ID No.: NRIC NO / S7408635G		Contact No.: Home/Office: Mobile: 98751683	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 44	Date of Birth: 21/03/1974	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Grab Driver		Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/08/2018 10:20	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TAMPINES AVENUE 2 TAMPINES STREET 23 heading towards Tampines st 32				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB2996C	Car	HYUNDAI	Sonata	Yellow	Slightly Damaged	0
SJT5004H	Car	TOYOTA	Wish	Silver	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180806/2095

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 4

Report No. T/20180806/2095

CONTINUATION OF REPORT

Driver			
Name	Goh Ah Chwee	ID No.	S1316459B
Related Vehicle	SHB2998C (Car)	Contact No.	81289934
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SI HAN KEONG ANDY	ID No.	S7408635G
Related Vehicle	SJT5004H (Car)	Contact No.	98751683
Hospital/Clinic	Y M Chan Clinic and Surgery	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	06/08/2018	Date Discharge	06/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	PoK LLee Lin	ID No.	S1406248J
Related Vehicle	SJT5004H (Car)	Contact No.	90371108
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/08/2018	Date Discharge	06/08/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 6/8/2018 at around 10.20am, I was driving my car bearing SJT5004H Toyota Wish silver in colour along Tampines 23 heading towards Tampines St 32. While approaching the cross junction I kept to the right lane of the two lane road as I am making a right turn to Tampines Avenue 2. At the cross junction, the traffic light was red so I stopped my car like the two other cars in front of mine. While I was waiting for the traffic lights to change I suddenly felt an impact from the rear. I then got out to make a check and spotted a taxi bearing registration number SHB2998C Hyundai Sonata yellow in colour had collided to the rear of my car. I have a passenger at the point of accident that was sitting at the front seat. At that point there was no immediate injury on either party. Later both of us felt aching and we went for doctor consultation at Y M Chan Clinic and Surgery and both was given a 3 day of medical certificate.

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180806/2095

Police Station Of Origin:
Eunos NPP
529 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No T/20180806/2095

CONTINUATION OF REPORT

Individual Statement



SINGAPORE
POLICE FORCE



T/20180806/2095

4 of 4

Report No. T/20180806/2095




Police Station Of Origin:
Eunos NPP
829 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sr Staff Sgt ANWAR BIN ZAINAL 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 06/08/2018 14:30
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168 	

D.O.A. 6/8/2018
Bal = 1yr 2-3mths

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8688M
Vehicle Details	
Vehicle No.:	SJT5004H
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	2ZR0430476
Chassis No.:	ZGE200009661
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,954.00
Original Registration Date:	15 Oct 2009
First Registration Date:	15 Oct 2009
Transfer Count:	3
Actual ARF Paid:	\$21,954.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2019
PARF Rebate Amount:	\$12,074.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,109.00
COE Rebate Amount:	\$2,060.00
Total Rebate Amount:	\$14,134.00

10,977

The information contained herein is correct as at 21 Aug 2018

OK M.V. \$24,000
- Rebate \$14,134
Repair Margin \$9,866

Estimate Repair For Vehicle SJT 5004 H (Toyota Wish)

Attn: Edison Loo Fax = 67465110 from Simon

Item	Description Parts	Qty		Price list
1	Rear bumper	1	\$ 658	1,658.00 DD
2	Rear bumper frame damper L/R @ \$49.45	2	\$	98.90 XNS
3	Rear bumper bracket L/R @ \$48.42	2	\$	96.84 DD
4	Rear bumper side retainer L/R @ \$92.30	2	\$	184.60 DIS
5	Rear tail gate	1	\$ 1417	1,670.80 DD
6	Rear tail gate tail lamp L/R @ \$324.00	2	\$	648.00 XNN
7	Rear tail gate inner handle	1	\$	77.80 XNN
8	Rear tail gate opener	1	\$	228.40 XNN
9	Rear tail lamp L/R @ \$465.10	2	\$	930.20 CRA
10	Rear tail gate damper L/R @ \$276.40	2	\$	552.80 XNN
11	Rear wiper motor assy	1	\$	528.00 XNN
12	Rear tail gate license lamp chrome moulding	1	\$	330.00 XNN
13	Rear tail gate lock	1	\$	363.80 BT
14	Rear fender inner garnish L/R @ \$848.00	2	\$	1,696.00 XNN
15	Rear end panel	1	\$	627.30 BUC
16	Rear end panel top garnish	1	\$	296.60 CRA
17	Rear tail gate weather-strip	1	\$	283.60 DD
18	Rear tail gate inner board	1	\$	540.00 CRA
19	Rear fender RH	1	\$	1,294.00 XR
20	Rear tail gate windscreen glass	1	\$	1,988.50 XNN
21	Rear fender under shield RH	1	\$	174.10 V CRA
22	Rear fender air vent L/R @ \$145.00	2	\$ 214H-CRA	290.00 145
23	Rear exhaust silencer box	1	\$	923.00 DD
24	Rear exhaust silencer rubber hook @ \$39.50	3	\$	118.50 DIS
			\$	15,599.74
	Less 25%		\$	3,899.94
			\$	11,699.80

S/NETT ITEM

25	Rear bumper reflector lamp L/R @ \$197.00	2	CRA	\$	394.00 200
26	Rear compartment top cover board	1		\$	320.00 XNN
27	Rear bumper clips	1		\$	42.00 35 NEC
28	Rear fender glass moulding RH	1		\$	108.20 XNN
29	Rear windscreen inner seal kit	1		\$	194.00 150 NEC
30	Rear tail gate emblem	1		\$	48.00 NEC
31	Rear tail gate stickers	1		\$	480.00 280 NEC
32	Rear number plate with casing	1 set		\$	60.00 XNN
33	Rear tail gate view camera	1		\$	567.00 XNN
34	Rear tail gate license lamp @ \$59.20	2		\$	118.40 XNN
35	Rear bumper reverse sensor @ \$185.00	4		\$	740.00 280 short
	Parts Total :		\$		14,771.40

LABOUR CHARGES & MISC

36	Check wiring, lighting, & centre locking system	\$	50.00 30
37	Remove rear damaged parts, knock out dents, straighten, floor panel, cutting, welding, remove & reinstall necessary fittings to facilitate.	\$	2,000.00 1,000
38	Putty & Spray painting on rear portion.	\$	1,600.00 1,100
39	Anti-rust proofing on affected panel, & re-seal body panel joint.	\$	120.00 90
40	To remove & reinstall rear windscreen glass.	\$	120.00
41	To remove & reinstall rear fender quarter glass to assist repairs.	\$	80.00 X
42	To transfer rear tail gate mechanism & components.	\$	80.00 60
43	Remove & refix interior upholstery, trims garnish, lining, wire, etc. to assist repairs.	\$	80.00 80
44	To reinstall rear bumper reverse sensor & view camera..	\$	120.00 80
45	To replace, straighten & re-align rear exhaust pipe.	\$	150.00 70
46	To supply rear windscreen & fender glass sealant	\$	50.00 15
	Labour Total :	\$	4,530.00

Sub Total : \$ 19,301.40

Lump sum repair adjustment
Estimated time required for repairs

\$ 15,400.00
Estimated time required for 10 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18014388/Grd3s2-1

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-10-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2998C	Veh. Inspected	SJT 5004H
Policy No.		Coverage (\$)	0.00
Claim No.	D18005923MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	21/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZGE200009661	Colour	SILVER
Odometer	146442	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50R17	LING LONG	6 mm
L/H Front Tyre	215/50R17	LING LONG	6 mm
R/H Rear Tyre	215/50R17	LING LONG	6 mm
L/H Rear Tyre	215/50R17	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2018	Inspection Date	07/08/2018
Survey held at	16 KAKI BUKIT RD 4 #01-53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5004H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,658.00	658.00
2	REAR BUMPER FRAME DAMPER L/R @ \$49.45	NO SUCH PARTS	98.90	-
2	REAR BUMPER BRACKET L/R @ \$48.42	DENTED	96.84	96.84
2	REAR BUMPER SIDE RETAINER L/R @ \$92.30	DISTORTED	184.60	184.60
1	REAR TAIL GATE	DENTED	1,670.80	1,417.00
2	REAR TAIL GATE TAIL LAMP L/R @ \$324.00	NOT NECESSARY	648.00	-
1	REAR TAIL GATE INNER HANDLE	NOT NECESSARY	77.80	-
1	REAR TAIL GATE OPENER	NOT NECESSARY	228.40	-
2	REAR TAIL LAMP L/R @ \$465.10	CRACKED	930.20	930.20
2	REAR TAIL GATE DAMPER L/R @ \$276.40	NOT NECESSARY	552.80	-
1	REAR WIPER MOTOR ASSY	NOT NECESSARY	528.00	-
1	REAR TAIL GATE LICENCE LAMP CHROME MOULDING	NOT NECESSARY	330.00	-
1	REAR TAIL GATE LOCK	BENT	363.80	363.80
2	REAR FENDER INNER GARNISH L/R @ \$848.00	NOT NECESSARY	1,696.00	-
1	REAR END PANEL	BUCKLED	627.30	627.30
1	REAR END PANEL TOP GARNISH	CRACKED	296.60	296.60
1	REAR TAIL GATE WEATHER-STRIP	DENTED	283.60	283.60
1	REAR TAIL GATE INNER BOARD	CRACKED	540.00	540.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,294.00	-
1	REAR TAIL GATE WINDSCREEN GLASS	NOT NECESSARY	1,988.50	-
1	REAR FENDER UNDER SHIELD RH	CRACKED	174.10	174.10
2	REAR FENDER AIR VENT L/R @ \$145.00	O/S CRACKED / N/S NOT NECESSARY	290.00	145.00
1	REAR EXHAUST SILENCER BOX	DENTED	923.00	923.00
3	REAR EXHAUST SILENCER RUBBER HOOK @ \$39.50	DISTORTED	118.50	118.50
	LESS 25% DISCOUNT		-3,899.94	-1,689.63
			11,699.80	5,068.91
SPECIAL NETT ITEMS				
2	REAR BUMPER REFLECTOR LAMP L/R @ \$197.00 (SN)	CRACKED	394.00	200.00
1	REAR COMPARTMENT TOP COVER BOARD (SN)	NOT NECESSARY	320.00	-

Report Ref No. CS3/FCI18014388/Grd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIPS (SN)	NECESSARY	42.00	35.00
1	REAR FENDER GLASS MOULDING RH (SN)	NOT NECESSARY	108.20	-
1	REAR WINDSCREEN INNER SEAL KIT (SN)	NECESSARY	194.00	150.00
1	REAR TAIL GATE EMBLEM (SN)	NECESSARY	48.00	48.00
1	REAR TAIL GATE STICKERS (SN)	NECESSARY	480.00	280.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	60.00	-
1	REAR TAIL GATE VIEW CAMERA (SN)	NOT NECESSARY	567.00	-
2	REAR TAIL GATE LICENCE LAMP @ \$59.20 (SN)	NOT NECESSARY	118.40	-
4	REAR BUMPER REVERSE SENSOR @ \$185.00	SHORTED	740.00	280.00
1	REAR WINDSCREEN & FENDER GLASS SEALANT (SN)	NECESSARY	50.00	50.00
			3,121.60	1,043.00
	LABOUR			
	CHECK WIRING, LIGHTING & CENTRE LOCKING SYSTEM.		50.00	30.00
	REMOVE REAR DAMAGED PARTS, KNOCK OUT DENTS, STRAIGHTEN, FLOOR PANEL, CUTTING, WELDING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		2,000.00	1,000.00
	PUTTY & SPRAY PAINTING ON REAR PORTION.		1,600.00	1,100.00
	ANTI-RUST PROOFING ON AFFECTED PANEL & RE-SEAL BODY PANEL JOINT.		120.00	90.00
	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS.		120.00	120.00
	TO REMOVE & REINSTALL REAR FENDER QUARTER GLASS TO ASSIST REPAIRS.	NOT NECESSARY	80.00	-
	TO TRANSFER REAR TAIL GATE MECHANISM & COMPONENTS.		80.00	60.00
	REMOVE & REFIX INTERIOR UPHOLSTERY, TRIM GARNISH, LINING, WIRE, ETC. TO ASSIST REPAIRS.		160.00	80.00
	TO REINSTALL REAR BUMPER REVERSE SENSOR & VIEW CAMERA.		120.00	80.00
	TO REPLACE, STRAIGHTEN & RE-ALIGN REAR EXHAUST PIPE.		150.00	70.00
			4,480.00	2,630.00
	GRAND TOTAL		19,301.40	8,741.91

Report Ref No. CS3/FCI18014388/Grd3s2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CS3/FCI18014388/Grd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.