

ASS. REC. BY:

REF:

CS3/MSG18015201/7124302

Special Instruction:

Survivor:

menhen

Taulich

From (Person):

Elaine Ngu

ASSIGNMENT (Office)

of

MSG

Date/Time:

20/8/18 @ 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

811 5256P

Insured:

GBE 9204

at Workshop m/s

A- Tel Automotive

Tel:

6384 5206

of

8 Kalci Bkt Ave 4 # 05-27

Policy No:

MSD/VCC/17/002004

Claim No:

MSD/V/18-001128

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/08/2018

CA / REV / REP. / REV 24 HRS

kup?

Date/Time:

10:28am @ Antelle

Person Contacted:

Michael

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(X) Estimate

811 5256P-CS3/INC/2007101/Gdn-1

DOA: 13/4/2012

GBE 9204-NA/MSG18004362/K4

DOA: 6/3/2018

Dismantle: 23/8/2018

Signature

Taufik

REF:

MSL6

ASSIGNMENT

From: Date

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

'WP' . PRS'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SSL5256P

Yr Regn: Dec / 2008

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Lancer.

C.C. 1584

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 121437

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM8STCS3A84 010785

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195/60R15

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 21/5/18

Survey held at

A-Tec Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s, 4/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No GIA.

SSW 47884 Repair

8.khi Bukit Ave 4 #05-27

Estimated repair range \$4,000 - \$5,000

Signature
6/9/2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: PRS.

Lump Sum / L.B.I: (\$

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee

Transportation

) \$ + RS. \$

) Photos

) Other:

TOTAL

120

10

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18015201/T1z4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-08-2018	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBE 920U	Veh. Inspected	SJL 5256P
Policy No.	MSD/VCC/17/002004	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	21/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/08/2018	Inspection Date	21/08/2018
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2018		20 Aug 2018 15:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	KST AUTO RENTAL PTE LTD , Co. Reg. No.: NA		
Main Claimant:	COVE RENTALS PTE LTD , Co. Reg. No.: 201626878M		
Vehicle Reg. No.:	SJL5256P	Date of Loss:	16/08/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VCC/17/002004 (Comprehensive) Coverage: 29/08/2017 - 28/08/2018
Vehicle Reg. No. (Insured):	GBE920U	Policy No. (Claimant):	
		Excess:	
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/08/2018]		
Adj Asg. Remarks:	SJE Disagree Please appoint LKK and contact Ms Peggie @ 6384 5206. Liability (Non-reporting)		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[➤ Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SJL5256P
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	MITSUBISHI
Vehicle Model :	LANCER 1.6 A
Chassis No. :	JMYSTCS3A8U010785
Propellant :	Petrol
Engine No. :	4G18JT2871
Engine Capacity :	1584 cc
Maximum Power Output :	79.0 kW (105 bhp)
Maximum Laden Weight :	1600 kg
Unladen Weight :	1162 kg
Year Of Manufacture :	2008
Original Registration Date :	01 Dec 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$10,455.00
COE Expiry Date :	30 Nov 2018
Road Tax Expiry Date :	30 Nov 2018
PARF Eligibility Expiry Date :	30 Nov 2018
Inspection Due Date :	30 Nov 2019
Intended Transfer Date :	24 Aug 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6878M
Vehicle Details	
Vehicle No.:	SJL5256P
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	4G18JT2871
Chassis No.:	JMYSTCS3A8U010785
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,131.00
Original Registration Date:	01 Dec 2008
First Registration Date:	01 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$13,131.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2018
PARF Rebate Amount:	\$6,565.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,455.00
COE Rebate Amount:	\$270.00
Total Rebate Amount:	\$6,835.00

The information contained herein is correct as at 27 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)








CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Aug 2018		20 Aug 2018 15:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KST AUTO RENTAL PTE LTD , Co. Reg. No.: NA								
Main Claimant:	COVE RENTALS PTE LTD , Co. Reg. No.: 201626878M								
Vehicle Reg. No.:	SJL5256P	Date of Loss:	16/08/2018 00:00 - :59 [116 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001128	Policy/Cover Note No.:	MSD/VCC/17/002004 (Comprehensive) Coverage: 29/08/2017 - 28/08/2018						
Vehicle Reg. No. (Insured):	GBE920U	Policy No. (Claimant):							
		Excess:							
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 21/08/2018]								
Adj Asg. Remarks:	SJE Disagree Please appoint LKK and contact Ms Peggie @ 6384 5206. Liability (Non-reporting)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL5256P (MSC/V/18-001128)
[GBE920U]
TP
COVE RENTALS PTE LTD
Aug 16 2018 12:00AM
[KST AUTO RENTAL PTE LTD]
A-Tec Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Letters/Correspondences							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print
1	20/08/18 12:28	Non Reporting Letter to OI					1	Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
2	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
3	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
4	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
5	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
6	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
7	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
8	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
9	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
10	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
11	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
12	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
13	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
14	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
15	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
16	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
17	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
18	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
19	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
20	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
21	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
22	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
23	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
24	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
25	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
26	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
27	24/08/18 15:50	General View					1	Load JPG	<input checked="" type="checkbox"/>
28	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
29	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
30	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
31	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
32	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
33	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>
34	04/09/18 11:18	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	04/09/18 11:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/18 10:56	SJE DISAGREE LKK	 Load PDF	
2	20/08/18 12:24	PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015201/T1Z4D3E2

Date: 10/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/17/002004		
Claimant Vehicle No :	SJL5256P	Insured Vehicle No :	GBE920U		
Date of Loss:	16/08/2018	Nature of Claim:	TP	Claim No:	MSC/V/18-001128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5256P		Engine No:	4G18JT2871
Make & Model:	MITSUBISHI LANCER, 1.6 (A)		Chassis No:	JMYSTCS3A8U010785
Reg. Date:	01/12/2008 (Man. Year: 2008)		Odometer:	171437 km
Colour:	Silver			
Engine Capacity:	1584 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	20/08/2018	
Date Inspected:	21/08/2018	Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier Singapore 415875
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts: 143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL5256P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >