

Our Ref : T 0818/ SHD6907D /WT(st)

Your Ref :

Date : 03-Sep-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
Yishun Industrial Park A
Singapore 768732

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHD6907D YOUR INSURED SLX3952P
AND OTHER 4 VEHICLES ON 18.08.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : SHD6907D which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SLX3952P we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair		\$	620.60
2	<u>6</u> days Loss of Rental @	\$	115.00	per day
3	Survey Report Fees	<i>(Surveyed by M/s LKK)</i>		
4	GIA / LTA Search Fee	\$	7.49	
5	GIA / Police Report Fees	\$	-	
6	Towing Fees	\$	-	
Sub Total :			\$	1,318.09

HIRER'S CLAIM

7	<u>6</u> days Loss of Income @	\$	80.00	per days
Total Claims:			\$	1,798.09

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 6 pcs
- b) LTA search slip/s of : SLX3952P
- c) GIA / Police report/s of : SHD6907D
- d) Letter of authority from owner / hirer / operator
- (X) Photocopie/s of Accident Scene Photo/s () Traffic Compound () PIR
- () Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Ian

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax : 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****i 40 SHD6907D , SLX3952P , SDJ51C , S... ON 18-Aug-18 13:00
PIE TWDS CHANGI BEFORE LORNIE EXIT**

I / We

HO KAM CHEIN(Hirer) NRIC No.: **S1284162J**

and/or

(Relief) NRIC No.:

Taxi Number

SHD6907D

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "**ComfortDelGro Engineering Pte Ltd**".

Date

19-Aug-2018

Name of Hirer

HO KAM CHEIN

Hirer NRIC

S1284162J

Signature :



Address

**279 CHOA CHU KANG AVENUE 3 #0...
680279**

Contact No.

97894691

Workshops

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO
SHD6907D

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
08.10.2015

CHASSIS CODE
KMHLB41UMGU078433

INV. NO/DATE
91392713 30.08.2018

JOB NO.
305201932

ODOMETER READING

DATE/TIME IN
18.08.2018 14:00

Description : 3P 18.08.2018

S/No	Part No.	Qty	Unit Price	%Disc	Net
PART REQUISITION					
0001	04-01-0103-0738	1	140VC COVER-RR BUMPER LWR	20.00	180.00
			SUB-TOTAL	:	180.00

JOB NATURE

0001	L		PANEL BEATING	200.00	200.00
0002	23-502		SPRAYPAINT ON AFFECTED AREA	200.00	200.00
			SUB-TOTAL	:	400.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91392713	620.60	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO
SHD6907D

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
08.10.2015

CHASSIS CODE
KMHLB41UMGU078433

INV. NO/DATE
91392713 30.08.2018

JOB NO.
305201932

ODOMETER READING

DATE/TIME IN
18.08.2018 14:00

Items total		580.00
Add GST @	7.000 %	40.60
Invoice amount		620.60

Issued by : KATHERINETAN 30.08.2018 11:46:05
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91392713	620.60	

Our Ref: CT18080525

Date: 30 August 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 18/08/2018 @ 13:00 hrs
ALONG PIE TWDS CHANGI BEFORE LORNIE EXIT
INVOLVING SLX3952P, SDJ51C, SLU9140S, SKT9094J, SLA812B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD6907D** (the "Taxi"). The Taxi was hired to **HO KAM CHEIN IC NO S1284162J** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SHPD 6907D

DATE	NAME OF DRIVER	MILEAGE READING				MILEAGE TRAVELLED (KM)	HOURS OPERATED (TM)		DATE	NAME OF DR
							FROM	TO		
15 8 18	CRONKY	408	443		126	1700	2118			
16 8 18	HO	408	780		338	0601	1909			
17 8 18	HO	409	057		277	0602	1555			
17 8 18	CRONKY	409	305		248	1723	0101			
18 8 18	HO	409	592		267	0608	1412			
18/8	Accident				7A	1400	/			
23/8	repair		W		7M	1130	/			

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLX3952P	18 Aug 2018 / 13:00:00	Successful	A12	AXA INSURANCE PTE LTD

Previous

OK



