

ASS. REC. BY:

REF: CS/FCT18015219/Usbn2

Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person): WS May chua

of

FCA

Date/Time: 21/08/2018 2:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STV 7573H

Insured:

SHA 2840D

at Workshop m/s

Lee Sheng Auto

Tel:

6747 7397

of

Blk 1 Kaki Bukit Ave 6 # 01-58

Policy No:

Claim No:

D18006199MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/08/2018

CA / REV / REP. / REV 24 HRS DS

H.O.D. Endorsement:

Date/Time: 21/08/2018 3:13pm

Person Contacted:

Ms. Lee

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

STV 7573H - X

SHA 2840D - C3 / FTH 18001367 / Kimbag 2

DA: 21/08/2018

23/08/18

@ 14:48 p.m. revert pending estimate from reporter to May Chua  
via email.

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 75-73Hat Workshop m/s Lee Shing

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28

IDAG Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 30 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 12419475

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJU 75-73H Yr Regn: 21 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Tyuta cany c.c. 2362Colour: Black A/C: Insured / Std / NI / NASp. Reading: 201653 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRO53BK 4007037515

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/8/18 D.O.I. 21/8/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

None N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/9/18 Confirmed 2/5 @ 1400 with Mr Lee

07/09/18 Confirmed HS \$ 1,400/- @ 3 days with Marcus  
(\$2,075.03 Rd - 60%)

RECEIVED 10 SEP 2018

Date/Time, File Pass to?

10/09/18

1) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos

Others

TOTAL

130

50

38

218

Report Format :

Lump Sum / I.B.I.: (\$ 1,400/- HS)

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	17-08-2018	<b>Our Ref No.</b> D18006195MFSH
<b>Accident Date</b>	16-08-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA2840D	<b>Third Party Vehicle.</b> SJV7573H
<b>Survey Location</b>	1 KAKI BUKIT AVENUE 6 #01-58/60	
<b>Contact Person.</b>	MS LEE EK CHEN	
<b>Contact No.</b>	67477397/ 0	<b>Fax No.</b> 67457138
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	LEE SHENG AUTO PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**onefm**  
**913**  
GOOD TIMES. GREATEST HITS

**Post an Advertisement**

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Up To 90% Loan! One Owner.



Receipts Proven For Past  
Servicing Records. Low Mileage  
Done. Call Now!  
SKL Automobile StarAd

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category ▼

Sort by

11 vehicles

Toyota Camry

Advanced

Make Model Price Depreciation Reg Date Eng Cap Mil

**Search Selection**

Toyota Camry

Any

Any

2010

Any

**Toyota Camry 2.0A****\$29,800**

\$11,610 /yr

14-Jan-2010

1,998 cc

6 Months Road Tax Till Jan'19, Excellent Short Term Usage And Also Can Be Considered For COE Renewal, No Repairs N  
Powerful Yet Fuel Economical Performance, 100% Accident Free, Spa...

Posted: 21-Aug-2018 Tags: 2010 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.4A****\$38,000**

\$11,410 /yr

24-Sep-2010

2,362 cc

17

Hurry! Drive Away This Best Selling Japanese Luxury Sedan, Fantastic Condition Inside Out, Low Mileage, Must View To  
In Available, Accident Free, Quality Cars You Can Trust...

Posted: 19-Aug-2018 Tags: 2010 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.0A****\$29,800**

\$9,740 /yr

06-May-2010

1,998 cc

14

New SMA Plate, Accident Free, Verry Kept, Sparking Paint, Wear And Tear Parts Replace, 4 New Yokohama Tyres, New /  
Service, New Road Tax, Warranty, Welcome Test Drive, Bank ...

Posted: 18-Aug-2018 Tags: 2010 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

**Toyota Camry 2.0A****\$30,600**

\$10,440 /yr

08-Apr-2010

1,998 cc

One Owner Only! Agent Maintained. Exceptionally Smooth And Good Running Condition. With Navigation Map, Reverse C  
Low Mileage At About 16.5k Km Yearly. Excellent Value Buy Wit...

Posted: 18-Aug-2018 Tags: 2010 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Compare

Toyota Camry 2.4A

**\$31,800**

\$9,980 /yr

13-May-2010

2,362 cc

14

In Available. High Trade In With Low Down Payment. No Further Repair Needed, Buy With A Piece Of Mind. Tes

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 23 August 2018 2:48 PM  
**To:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'  
**Cc:** 'SUR'; 'Catherine Chong (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18006195MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJV 7573H on 21/08/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 21 August 2018 3:13 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006195MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Tuesday, 21 August, 2018 2:10 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18006195MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note:** All the accident reports are uploaded into CWS for your perusal.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

&gt; Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 16 Aug 2018 / 18:24:28

Receipt Date/Time : 16 Aug 2018 / 18:24:28

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180816-001953

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA2840D				
As at 16 Aug 2018/12:00:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHA2840D Enquiry Fee 20180816182305760726	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
xxxxxxxxxxxx2776		Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	6989W
<b>Vehicle Details</b>	
Vehicle No.:	SJV7573H
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2AZE155850
Chassis No.:	MR053BK4007037515
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$29,264.00
Original Registration Date:	08 Feb 2010
First Registration Date:	08 Feb 2010
Transfer Count:	1
Actual ARF Paid:	\$29,264.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2020
PARF Rebate Amount:	\$16,095.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$23,180.00
COE Rebate Amount:	\$3,380.00
<b>Total Rebate Amount:</b>	<b>\$19,475.00</b>

The information contained herein is correct as at 23 Aug 2018

OK

# LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. USG ENTERPRISE  
632B PUNGGOL DRIVE #13-663  
EDGEDALE GREEN S 822632

Attention : Motor Claim Department

Estimate : ES000727

Date : 16/08/2018  
Vehicle Num. : SJV 7573H  
Make/Model : TOYOTA CAMRY  
Chassis/Eng# :  
Accident Date : 16/08/2018  
Claim No. :  
Reference :  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	REAR BUMPER		787.00
2.	2 PCS	REAR BUMPER RETAINER	10.84	21.68
3.	2 PCS	REAR BUMPER BRACKET	34.50	69.00
4.	1 PC	REAR END PANEL		715.00
5.	1 PC	REAR LAMP		586.70
6.	1 PC	REAR BUMPER REFLECTOR		115.00
List Total S\$ :				2,294.38
25.00% Discount S\$ :				573.60
				1,720.78
1.	1 SET	SPECIAL NETT ITEMS : REVERSE SENSOR		250.00
Special Nett Total S\$ :				250.00
LABOUR :				500.00
KNOCKING, CUTTING, JACKING WELDING ETC				500.00
SPRAY PAINTING				100.00
TO CHECK WIRING AND SYSTEM FUNCTION				120.00
TO APPLY RUST-PROOFING ON AFFECTED AREA				
Labour Total S\$ :				1,220.00

Total S\$ : 3,190.78

LEE SHENG AUTO PTE LTD

revised.  
P-966.78  
252  
725.08  
S.N 200  
labour - \$30

not authorized  
labour  
L/S \$1400/-  
3 day.  
21/8/18  
take photo after repair  
3,475.03



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015219/Usbn2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-09-2018



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2840D	Veh. Inspected	SJV 7573H
Policy No.		Coverage (\$)	0.00
Claim No.	D18006195MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	21/08/2018

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053BK4007037515	Colour	BLACK
Odometer	201653	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	6 mm
L/H Front Tyre	215/60 R16	MICHELIN	6 mm
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--------------------------------------------------------------------------------

#### 5. General Information

Accident Date	16/08/2018	Inspection Date	21/08/2018
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		

#### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7573H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DISTORTED	787.00	566.10
2	REAR BUMPER RETAINER @\$10.84	BENT	21.68	21.68
2	REAR BUMPER BRACKET @\$34.50	NOT NECESSARY	69.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	715.00	-
1	REAR LAMP	NOT NECESSARY	586.70	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	115.00	-
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	DENTED	289.00	289.00
2	TAIL LAMP BRACKET @\$45.00 (ADDITIONAL)	CRACKED	90.00	90.00
	LESS 25% DISCOUNT		-668.35	-241.69
			2,005.03	725.09
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR (SN)	SHORTED / TORN	250.00	200.00
			250.00	200.00
<b>LABOUR</b>				
	KNOCKING,CUTTING,JACKING WELDING ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		500.00	400.00
	SPRAY PAINTING.		500.00	400.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		100.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	120.00	-
			1,220.00	830.00
<b>GRAND TOTAL</b>			<b>3,475.03</b>	<b>1,755.09</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,400.00</b>

Report Ref No. CS/FCI18015219/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.