

JAS Tan

cc. 4, Asm. 15232, KHA3

LKK: 64349
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

21/8/2018

Date / Time:

26/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE

SDJ 7000D

SPM002KP



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

97623233

Make / Model:

LEXUS ES250

Excess Sec II :SS

D.O.A:

31/7/2018

Place of Accident:

CK AREA

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

IP8522C



INSRS:

WSP:

Tel:

Liability:

RMKS:

kmkist
6483764
6423767



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

30/8

W

IP8522C X

SDJ 7000D. (A1140) (042) / aw : 21/11/18

INTERVIEW FOUND
OFFICER TO OI. THE COMPLAINANT ACCIDENT
DURING A WAS DRIVING A RIGHT TURN
WITH GREEN LIGHT WHEN COLLIDED TO TP.
INFORMED HIM OF TP CASE, AGREE TO
GIVE A LETTER NCD ISSUES.

14/6 - GIVE LETTER A BULK TO OI.
- CHECK A WS IF THEY SUBMIT TO LAMINAR 2 -
THE AMOUNT GIVEN IS INDEPENDENT / BASED ON
SURVEYOR MARKING 2
HOW MUCH IS THE AMOUNT 2.
- FILE PASS ADMIN TO CLOSE.

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	08/10/18 - vic
After call ltr to OI:	21/10/18 - vic
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup):	
After call ltr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE Date/Time: 21/8 Sent By: JH	
FINALIZATION Date/Time: Confirm with: Confirm by:	
Repair Cost: S\$ (days) Reduction: %	Email: Call:
FINAL SETTLEMENT Date/Time: Confirm with: Email: Call:	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 5	If NO or B 28, Ass. Lia: (OI) (WAS) (U-TURN)
Repair Cost: S\$	
Loss of Rental (LOR): S\$ (days)	
Loss of Use (LOU): S\$ (\$ x days)	
Loss of Income (LOI): S\$ (\$ x days)	
LOR only LOU only LOR + LOU LOR + LOI (Tick only one)	
GIA/LTA Search: S\$	
Medical: S\$	
Disbursement: S\$ (e.g. Tow/ Independent)	
Legal Cost: S\$	
Total: S\$ Global Sum S\$:	
FINAL PAYMENT Date/Time: Confirm with: Email: Call:	
Payee 1: S\$ Name 1:	
Payee 2: (Strike if N.A.) S\$ Name 2:	
Payee 3: (Strike if N.A.) S\$ Name 3:	

(08/11/13) wef

REF: AXA

ASS. REC. BY:

ASSIGNMENT

From:

Date: 21/08/18

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FP 8522C

at Workshop m/s

Kim Keat

of BIK 10, AMK Ind. Park 2A#05-34

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$4.5/c

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: 12/12

Person Contacted:

Vehicle: IN / OUT

Veh No:

FP 8522C Yr Regn: 01, 98

Type: M.Car / ☒ Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha RXZ c.c. 133

Colour:

M. Grey / White A/C: Insured / Std / NI / NA

Sp. Reading:

23031 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

BMC . 231490

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F:

2.50 x 18

R:

2.50 x 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Viva

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. mm

L/Bal. mm

D.O.A. 31/7/18

D.O.I. 21/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8 File pass to Catherine

L/S A2550 with 4 repair days.

(red - \$1417.80 / 36%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9025E

Vehicle Details

Vehicle No.: FP8522C
Vehicle to be Exported: No
Intended De-registration Date: 21 Aug 2018
Vehicle Make: YAMAHA
Vehicle Model: RXZ
Primary Colour: Blue
Manufacturing Year: 1997
Engine No.: 3B5231490
Chassis No.: ZMC231490
Maximum Power Output: -
Open Market Value: \$3,175.00
Original Registration Date: 16 Jan 1998
First Registration Date: 16 Jan 1998
Transfer Count: 5
Actual ARF Paid: \$477.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Dec 2022
COE Category: D - Motorcycle
COE Period(Years): 5
PQP Paid: \$2,693.00
COE Rebate Amount: \$2,348.00
Total Rebate Amount: \$2,348.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Aug 2018

OK

KIM KEAT MOTOR CO
Blk 10 Ang Mo Kio Industrial Park 2A
Avenue5 #05-34 AMK Autopoint
Singapore 568047

Not Withheld
U1 Sup @ 2550h
Recovery After Paint
(4 days)

20 Aug 2018

AXA Insurance Pte Ltd.
Survey Dept.

Re: Quotation for damaged to FP8522C

Item	Description of Parts	Qty	Amount	
1.	Mirror RH	1pc	38.00	✓
2.	Brake Lever	1pc	15.00	✓
3.	Handle Bar RH	1pc	85.00	✓
4.	Weight RH	1pc	15.00	✓
5.	Meter Assy Comp.	1pc	680.00	x
6.	Stay	1pc	85.00	✓
7.	Top Cowl Assy	1pc	185.00	✓
9.	Front Signal Lamp RH	1pc	38.00	✓
10.	Fork Tube L&R	2pcs	280.00	✓
11.	Fork Seal Set L&R	2set	55.00	✓
12.	Steering Stem	1pc	185.00	✓
13.	Steering Cone Bearing Assy	1set	55.00	✓
14.	Brake Disc Front	1pc	280.00	✓
15.	Fuel Tank	1pc	580.00	✓
16.	Brake Pedal	1pc	55.00	✓
17.	Footrest Assy Front RH	1pc	38.00	✓
18.	Muffler	1pc	685.00	✓
19.	Tail Cowl	1pc	125.00	✓
20.	Tail Lamp Comp.	1Pc	98.00	✓
21.	Mudguard	1pc	135.00	✓
Total			\$ 3712.00	
Less 10%			- 371.20	
Sub-total			\$ 3340.80	
Nett Item				
22.	Number Plate Front	1pc	12.00	✓
23.	Number Platte Rear	1pc	15.00	✓
24.	Fork Oil	1bottle	10.00	✓
25.	To Repspray Top Cowl, Fuel Tank and Tail Cowl		280.00	2401
26.	Transport Fee		30.00	✓
27.	Labour		280.00	1801
Grand Total			\$ 3967.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

09 OCTOBER 2018

**CHEW AH GUAN
BLOCK 436 CHOA CHU KANG AVENUE 4
#12-497
SINGAPORE 680436**

By Post & By Email

Dear Sir/Madam,

**OUR REF : CC4/ASM18015232/Kha3
YOUR REF : SDJ 7000D
ACCIDENT INVOLVING SDJ 7000D AND FP 8522C ALONG CHOA CHU KANG
AVENUE 4 ON 31.07.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KIM KEAT MOTOR CO., acting on behalf of the owner of FP 8522C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FP 8522C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

agchew@yahoo.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Tuesday, 9 October, 2018 2:58 PM
To: agchew@yahoo.com
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SDJ 7000D_ACCIDENT INVOLVING SDJ 7000D AND FP 8522C ALONG CHOA CHU KANG AVENUE 4 ON 31.07.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

09 OCTOBER 2018

CHEW AH GUAN
BLOCK 436 CHOA CHU KANG AVENUE 4
#12-497
SINGAPORE 680436

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18015232/Kha3
YOUR REF : SDJ 7000D
ACCIDENT INVOLVING SDJ 7000D AND FP 8522C ALONG CHOA CHU KANG AVENUE 4 ON 31.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s KIM KEAT MOTOR CO., acting on behalf of the owner of FP 8522C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FP 8522C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

<< Service Request Details

Claim

S8M00QKP

Reference

None 

Loss Date

July 31, 2018

Request Date

August 20, 2018

Due Date

August 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

20082018 @ 216pm
Victor veh in.

Kim Keat
Blk 10 AM * Ind Park 2A #05-34

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FP8522C

Make

TPVD YAMAHA

Model

RXZ

Service Address

...

Primary Contact/Insured

CHEW AH GUAN

BLK 436 CHOA CHU KANG AVE 4, #12-497, 680436, Singapore

68610007

agchew@yahoo.com

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18015232/Kga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Date : 01-07-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDJ 7000D	Veh. Inspected	FP 8522C	
Policy No.	VPA/P1954944	Coverage (\$)	0.00	
Claim No.	S8M00QKP	Excess (\$)	0.00	
Assign From		Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA RXZ	c.c	133	
Engine No.	HIDDEN	Year of Reg.	1998	
Chassis No.	ZMC231490	Colour	METALLIC GREY /WHITE	
Odometer	23031	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	2.50X18	VIVA	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	2.50X18	VIVA	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2018	Inspection Date	21/08/2018	
Survey held at	KIM KEAT MOTOR CO. BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #05-34 AMK AUTO POINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHØRISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FP 8522C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MIRROR RH (CONSISTENT)	MISSING	38.00	38.00
1	BRAKE LEVER (CONSISTENT)	DISTORTED	15.00	15.00
1	HANDLE BAR RH (CONSISTENT)	BENT	85.00	85.00
1	WEIGHT RH (CONSISTENT)	DENTED	15.00	15.00
1	METER ASSY COMP (CONSISTENT)	SERVICEABLE	680.00	-
1	STAY (CONSISTENT)	DISTORTED	85.00	85.00
1	TOP COWL ASSY (CONSISTENT)	CRACKED	185.00	185.00
1	FRONT SIGNAL LAMP RH (CONSISTENT)	CRACKED	38.00	38.00
2	FORK TUBE L&R (CONSISTENT)	DISTORTED	280.00	280.00
2	SET FORK SEAL SET L&R (CONSISTENT)	NECESSARY	55.00	55.00
1	STEERING STEM (CONSISTENT)	DISTORTED	185.00	185.00
1	SET STEERING CONE BEARING ASSY (CONSISTENT)	NECESSARY	55.00	55.00
1	BRAKE DISC FRONT (CONSISTENT)	WARPED	280.00	280.00
1	FUEL TANK (CONSISTENT)	DENTED	580.00	580.00
1	BRAKE PEDAL (CONSISTENT)	DISTORTED	55.00	55.00
1	FOOTREST ASSY FRONT RH (CONSISTENT)	BENT	38.00	38.00
1	MUFFLER (CONSISTENT)	DENTED	685.00	685.00
1	TAIL COWL (CONSISTENT)	CRACKED	125.00	125.00
1	TAIL LAMP COMP (CONSISTENT)	BROKEN	98.00	98.00
1	MUDGUARD (CONSISTENT)	DISTORTED / CUT	135.00	135.00
	LESS 10% DISCOUNT		-371.20	-303.20
			3,340.80	2,728.80
SPECIAL NETT ITEMS				
1	NUMBER PLATE FRONT (SN) (CONSISTENT)	DENTED	12.00	12.00
1	NUMBER PLATE REAR (SN) (CONSISTENT)	BENT	15.00	15.00
1	BOTTLE FORK OIL (SN) (CONSISTENT)	NECESSARY	10.00	10.00
			37.00	37.00
LABOUR				
	TO RESPRAY TOP COWL, FUEL TANK AND TAIL COWL		280.00	240.00
	TRANSPORT FEE.		30.00	30.00

Report Ref No. CC4/ASM18015232/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR.		280.00	180.00
			590.00	450.00
	GRAND TOTAL		3,967.80	3,215.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00

Report Ref No. CC4/ASM18015232/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SAM00QEP
Reference	EC4/ASM1101523D/Kga3o2 
Loss Date	31 July 2018
Report Date	1 Aug 2018 10:11:52 AM
Request Date	30 November 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Next Invoice >

Vehicle Information	
Incident Vehicle Registration #	FP8522C
Make	TPVD YAMAHA
Model	RKZ
Service Address	

...

Primary Contact/Insured	
Primary Contact	CHEW AH GUAN
Address	BLK 436 CHOA CHU KANG AVE 4, #12-497, 480436, Singapore
Phone	68610007
Email	agchew@yahoo.com

Claim Handler	
Handler	TAN Jis
Phone	6568804844
Email	jis.tan@jaa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Marks Notes

Document Type

Document SubType

 Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019

